

JUL 08 1985

Docket No. 030-28738
Control No. 03945

Hazleton Radiology Associates
ATTN: Romeo C. Ouano, M.D.
Northeastern Building
Hazleton, Pennsylvania 18201

Gentlemen:

This is in reference to your application dated June 7, 1985 for a byproduct material license. In order to continue our review, we need the following additional information:

1. Your radiation safety program in item 10 does not include emergency procedures. It is recommended that such procedures contain:
 - a. Instructions to be followed if the source shutter is stuck in the open position.
 - b. Instructions to be followed in the case of accidents which may compromise the source integrity.
 - c. Your radiation safety officer's name, his office phone number, and a phone number to be used during off-duty hours.

Please submit a copy of your emergency procedures and confirm that they will be posted in your facility.

We will continue our review upon receipt of this information. Please reply in duplicate to my attention at the Region I office and refer to Mail Control No. 03945.

Sincerely,

Original Signed By:
John D. Kinneman

John D. Kinneman, Chief
Nuclear Materials Safety Section A
Division of Radiation Safety
and Safeguards

RI:DRSS *[Signature]*
Piccone/mlb
7/3/85

RI:DRSS
Kinneman
7/8/85

OFFICIAL RECORD COPY

ML 967PICCONE7/2/85 - 0001.0.0
07/02/85

8509190636 850823
REG1 LIC30
37-20861-01 PDR

M110