


To: Peter B. Block, Presiding Officer  
Atomic Safety and Licensing Board  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Subject: NRC Staffs' motion for reconsideration in the matter of  
Ralph L. Tetrick.

It is expected that the Licensed Operators at Turkey Point verify plant conditions when one or more annunciators are received in the control room prior to taking corrective actions. In the case of Question #63, I fully expect the Operators to verify the decrease in the Spent Fuel Pool level and the increase in the Containment Sump level by the indicators located within the surveillance area of the control room. This action would only take seconds and could preclude erroneously sounding the containment evacuation alarm. During refueling outages, there are numerous jobs going on simultaneously inside the containment. Requiring all personnel to evacuate the area unnecessarily could pose a larger safety hazard than would the increased radiation levels at the refueling stations for those few seconds. In addition, the Training Departments question bank has been revised concerning the correct answer to Question #63.

  
Brian J. Stamp  
Acting Operations Supervisor  
Turkey Point Operations Department