

APPENDIX A  
NOTICE OF VIOLATION

Rockville General Hospital  
Rockville, Connecticut 06066

Docket No. 030-09938  
License No. 06-13001-02

As a result of the inspection conducted on August 15, 1985, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

10 CFR 35.14(e)(2) requires that the leak tests performed on sealed reference sources pursuant to 10 CFR 35.14(e) be capable of detecting the presence of 0.005 microcuries of radioactive material.

Contrary to the above, as of August 15, 1985, the sensitivity of the dose calibrator used to test a 200 microcurie cesium-137 reference source was not sufficient to detect the presence of 0.005 microcuries of radioactive material.

This is a Severity Level V violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Rockville General Hospital is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8512060188 851122  
REG1 LIC30  
06-13001-02 PDR

OFFICIAL RECORD COPY

DL ROCKVILLE - 0003.0.0  
11/07/85