



Carolina Power & Light Company

06 FEB 10 1986 11:11  
Brunswick Steam Electric Plant  
P. O. Box 10429  
Southport, NC 28461-0429  
February 5, 1986

FILE: B09-13510C  
SERIAL: BSEP/86-0103

Dr. J. Nelson Grace, Administrator  
U.S. Nuclear Regulatory Commission  
Suite 2900  
101 Marietta Street NW  
Atlanta, GA 30323

BRUNSWICK STEAM ELECTRIC PLANT UNIT 2  
DOCKET NO. 50-324  
LICENSE NO. DPR-62  
SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8 AND  
PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (2-SR-86-001)


Dear Dr. Grace:

During power operation of Unit 1, concurrent with an ongoing Unit 2 maintenance/refueling outage, a Unit 2 designated fire barrier LCO was initiated on January 6, 1986, for a fire door in the units' common emergency ac Diesel Generator (D/G) Building.

The subject fire door, No. 112, is located at fire barrier penetration seal No. DG-2-031 on the 23-foot elevation of the building. Door No. 112 is the northwest access to the respective room of D/G No. 4. The LCO was initiated to repair a hole in the door structure. On January 13, 1986, the specified seven-day time frame of the LCO was exceeded. Required repairs to the door were made, and on January 14, 1986, at 1900, the door was returned to service. During the time period the subject LCO was in effect, appropriately stationed fire watches were maintained.

Very truly yours,

8602180080 860205  
PDR ADOCK 05000324  
S PDR

  
C. R. Dietz, General Manager  
Brunswick Steam Electric Plant

RMP/mbh

Enclosure

cc: NRC Document Control Desk

1/0  
IE19