

DEC 3 - 1985

Herron Testing Laboratories,
Incorporated
Department of Radiography
ATTN: John L. Herron
President
5405 East Schaaf Road
Cleveland, OH 44131

License No. 34-00681-03
License No. 34-00681-06

30-5636
-14654

Gentlemen:

This refers to the routine safety inspection conducted by Mr. D. R. Gibbons of this office on November 18, 1985, of activities authorized by NRC Byproduct Material Licenses No. 34-00681-03 and No. 34-00681-06 and to the discussion of our findings with you and selected members of your staff at the conclusion of the inspection.


The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. G. Wiedeman, Chief
Nuclear Materials Safety
Section 1

8512060308 851203
REG3 LIC30
34-00681-03 PDR

Enclosure: Appendix, Notice
of Violation

cc w/enclosure:
DCS/RSB(RIDS)
RIII

Gibbons/mj
12/02/85

yes

RIII

Wiedeman

yes

12/3/85

JE07
11