

Appendix

NOTICE OF VIOLATION

Herron Testing Laboratories
Incorporated

License No. 34-00681-03
License No. 34-00681-06

As a result of the inspection conducted on November 18, 1985, and in accordance with the "General Policy and Procedures for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1985), the following violations were identified:

License No. 34-00681-03

1. 10 CFR 34.24 requires that each radiation survey instrument be calibrated at intervals not to exceed three months, and a record be maintained of the results of each instrument calibration for two years after the date of the calibration.

Contrary to this requirement, the licensee failed to maintain the calibration results of survey instrument Serial No. 193 that was calibrated on August 6, 1985.

This is a Severity Level V violation (Supplement VI).

2. 10 CFR 20.407(b) requires that you submit to the Commission within the first quarter of each calendar year, a report of exposures recorded for individuals under your licensed program for the preceding calendar year.

Contrary to this requirement, as of November 18, 1985, you had not submitted the required report for calendar year 1984.

This is a Severity Level V violation (Supplement IV).

License No. 34-00681-06

3. License Condition No. 13 requires the licensee to test sealed sources containing byproduct material for leakage and/or contamination at intervals not to exceed six months.

Contrary to this requirement, the licensee failed to test sealed sources containing byproduct material for leakage and/or contamination at six month intervals. Specifically, as of the day of the inspection, November 18, 1985, the licensee had not tested sealed source Serial No. 8293 since February 5, 1985, and had not tested sealed source Serial No. 5680 since April 2, 1985, intervals exceeding six months.

This is a Severity Level IV violation (Supplement VI).

4. License Condition No. 16 requires the licensee to conduct a physical inventory every six months to account for all gauges received and possessed under the licensee.

8512060310 851203
REG3 LIC30
34-00681-03 PDR


Contrary to this requirement, the licensee failed to conduct physical inventories to account for all gauges received and possessed under the license during 1984 and to the day of the inspection, November 18, 1985.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

DEC 3 - 1985

Dated _____


Darrel G. Wiedeman, Chief
Nuclear Materials Safety
Section 1