

TOLEDO EDISON  
DAVIS-BESSE NUCLEAR POWER STATION UNIT NO. 1  
SEISMIC CATEGORY I PIPING  
SYSTEM SUPPORT AND HANGER DISCREPANCIES

-- SUMMARY REPORT --

REVISION 14  
OCTOBER 22, 1985

8512060317 851028  
PDR ADOCK 05000346  
S PDR

## TABLE OF CONTENTS

### Dispositioned Footnotes

Section 1.0	Auxiliary Feedwater Pump Turbine Steam Supply Piping System
Section 2.0	Auxiliary Feedwater System
Section 3.0	Low Pressure Injection System
Section 4.0	High Pressure Injection System
Section 5.0	Borated Water Storage Tank Supply System
Section 6.0	Service Water System
Section 7.0	Containment Sump - ECCS Supply System
Section 8.0	Hydrogen Dilution System
Section 9.0	Pressurizer Relief System
Section 10.0	Pressurizer Surge System
Section 11.0	Containment Spray System
Section 12.0	Miscellaneous Waste Drain System
Section 13.0	Spent Fuel Pool Piping System
Section 14.0	Makeup Water Treatment System
Section 15.0	Pressurizer Spray System
Section 16.0	Reactor Coolant System
Section 17.0	Quench Tank Drain System
Section 18.0	Component Cooling Water System
Section 19.0	Steam Generator Drain System
Section 20.0	Containment Building Vent System
Section 21.0	Refueling Canal System
Section 22.0	Hanger Location Discrepancies

DISPOSITIONED FOOTNOTES

- (1) Meets interim allowables, but not long-term allowables.
- (2) Re-work is necessary to meet long-term allowables.
- (3) Meets long-term allowables.
- (4) Meets long-term allowables, but nevertheless re-work will be completed.

SECTION 1.0

AUXILIARY FEEDWATER PUMP

TURBINE STEAM SUPPLY PIPING SYSTEM



REV. 14

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D IND	RESP
EBD-19-H147	SWAY STRUT PULLED FROM WALL	03/01/85	85-0016	Y	SJO
A3	LOOSE ANCHOR BOLTS NUTS	03/13/85	85-0019	Y	GNF
EBD-19-H34	DEFORMED STANCHION	03/13/85	85-0019	Y	GNF
EBD-19-H32	NON-CODE WELD ON WRAPPER PLATE TO PIPING WELD	03/27/85	85-0026	Y	SJO
EBD-19-H58	DEFECTIVE MECHANICAL SNUBBER	04/11/85	85-0032	Y	SJO
EBD-19-H58	EXCESSIVE LATERAL MOVEMENT OF SUPPORT	04/11/85	SR85-79	Y	SJO
EBD-19-H144	HYDRAULIC SNUBBER PISTON ROD BROKEN	04/18/85	85-0038	Y	SJO
EBD-19-H136	TWELVE (12) ANCHOR BOLTS IN LIEU OF SEVEN (7) SPECIFIED	04/30/85	85-0042	Y	GNF
EBD-19-H54	WELD DETAIL INACCURATE	04/30/85	85-0043	Y	GNF
EBD-19-H142	LOOSE ANCHOR BOLT NUT	05/01/85	85-0045	Y	GNF
EBD-19-H51	WALL INTERFERENCE WITH SUPPORT MEMBER	05/08/85	85-0052A	Y	RAA
EBD-19-H132	LOOSE ANCHOR BOLTS, BASEPLATE GAP	05/16/85	85-0019A	Y	GNF
EBD-19-H32	LOOSE ANCHOR BOLTS, SNUBBER PIPE CLAMP MIS-ALIGNED, WASHERS MISSING	05/16/85	85-0019A	Y	SJO
EBD-19-H28	PIPE SADDLES DEFORMED	05/16/85	85-0019A	Y	SJO
EBD-19-H25	SHEARED BOLT	05/16/85	85-0019A	Y	SJO
EBD-19-H26	WALL CRACK	05/16/85	85-0019A	Y	SJO
EBD-19-H14	SNUBBER PIPE CLAMP MIS-ALIGNED	05/16/85	85-0019A	Y	SJO
EBD-19-H135	LOOSE ANCHOR BOLTS, ONE BOLT DID NOT TORQUE	05/16/85	85-0019A	Y	GNF
EBD-19-H66	LOOSE ANCHOR BOLTS	05/16/85	85-0019A	Y	GNF
EBD-19-H50	RESTRAINT PULLED FROM WALL	05/16/85	85-0019A	Y	GNF
EBD-19-H49	SWAY STRUT PULLED FROM WALL	05/16/85	85-0019A	Y	GNF
EBD-19-H142	RESTRAINT PULLED FROM WALL	05/16/85	85-0019A	Y	GNF
EBD-19-H67	LOOSE ANCHOR BOLTS	05/16/85	85-0019A	Y	GNF

REV. 14

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D RESP IND
EBD-19-H145	SWAY STRUT JAM NUT LOOSE, LOOSE ANCHOR BOLT	05/17/85	85-0067	Y SJO
EBD-19-H52	SWAY STRUT JAM NUT LOOSE	05/17/85	85-0068	Y SJO
EBB-2-H20	SUPPORT NOT SHOWN ON HANGER LOCATION DRAWING	05/17/85	85-0069	Y SJO
EBD-19-H14	SNUBBER PIPE CLAMP MIS-ALIGNED, LOOSE ANCHOR BOLTS	05/17/85	85-0070	Y SJO

REV. 14

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D	RESP IND
EBD-19-H51	ANCHOR BOLT INSTALLED AT AN ANGLE, BASEPLATE GAP	04/30/85	85-0044	Y	GNF
EBD-19-H59	BOLTS LONGER THAN SPECIFIED, GROUT 2" THICK IN LIEU OF 1"	05/02/85	85-0046	Y	GNF
EBD-19-H59	REMOTE RESERVOIR NOT SHOWN ON DRAWING	05/08/85	85-0048	Y	RAA
EBD-19-H51	INCORRECT SPRING SETTING	05/08/85	85-0052	Y	RAA
EBD-19-H50	CHIPPED CONCRETE AROUND BASEPLATE	05/08/85	85-0053	Y	GNF
EBD-19-H143	FIREPROOFING BROKEN AWAY	05/09/85	85-0054	Y	TWH
EBD-19-H147	ANCHOR BOLT INSTALLED AT AN ANGLE	05/09/85	85-0055	Y	GNF
EBD-19-H154	SHIM SIZE NOT PER DRAWING	05/09/85	85-0056	Y	RAA
EBD-19-H62	FIREPROOFING BROKEN AWAY	05/09/85	85-0057	Y	TWH
EBD-19-H60	WRONG SIZE SPRING HANGER	05/09/85	85-0058	Y	RAA
EBD-19-H141	BOOT SEAL TORN	05/10/85	85-0059	Y	TWH
EBD-19-H58	EXCESSIVE LATERAL MOVEMENT OF SUPPORT	05/10/85	SR85-79	Y	SJO
EBD-19-H55	BASEPLATE ANCHOR BOLT WASHERS SIZE QUESTIONABLE	05/10/85	SR85-79	Y	GNF
EBD-20-H1	LOOSE ANCHOR BOLTS NUTS, BASEPLATE GAP	05/16/85	85-0064	Y	GNF
A3	BASE PLATE GAP	05/16/85	85-0065	Y	GNF
EBD-19-H142	BASE PLATE GAP	05/16/85	85-0066	Y	GNF
EBD-19-H144	BASE PLATE GAP	05/16/85	85-0066	Y	GNF
EBD-19-H145	BASE PLATE GAP	05/16/85	85-0066	Y	GNF
EBD-19-H147	BASE PLATE GAP	05/16/85	85-0066	Y	GNF
EBD-19-H70	SWAY STRUT JAM NUT LOOSE	05/21/85	85-0092	Y	SJO
EBD-19-H14	ALL THREAD ROD USED IN LIEU OF BOLTS	05/21/85	85-0092	Y	GNF
EBD-19-H20	ALL THREAD ROD USED IN LIEU OF BOLTS	05/21/85	85-0092	Y	GNF
EBD-19-H38	HANGER LOCATION DRAWING INCORRECT	05/21/85	85-0092	Y	SJO
EBD-19-H39	HANGER LOCATION DRAWING INCORRECT	05/21/85	85-0092	Y	SJO

REV. 14-

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D	RESP IND
EBD-19-H132	BOLTS USED NOT REFLECTED ON DRAWING	05/21/85	85-092	Y	GNF
EBD-19-H28	CRACKED FIREPROOFING	05/21/85	NA	Y	TWH
EBD-19-H29	CRACKED FIREPROOFING	05/21/85	NA	Y	TWH
EBD-19-H34	MISSING FIREPROOFING	05/21/85	NA	Y	TWH
EBD-19-H35	CRACKED FIREPROOFING	05/21/85	NA	Y	TWH
EBD-19-H38	CRACKED FIREPROOFING	05/21/85	NA	Y	TWH
EBD-19-H39	CRACKED FIREPROOFING	05/21/85	NA	Y	TWH
A221	CRACKED FIREPROOFING	05/21/85	NA	Y	TWH
EBD-20-H1	SWAY STRUT PIPE CLAMP MIS-ALIGNED	05/21/85	SR85-79	Y	SJO
EBD-19-H21	TWO (2) BOLTS NOT MARKED FOR TORQUE TEST	05/21/85	SR85-79	Y	GNF
EBD-19-H25	UPPER GUIDE ANGLE BENT	05/22/85	85-0071	Y	RAA
EBD-19-H132	FIREPROOFING BROKEN	05/22/85	85-0072	Y	TWH
EBD-19-H133	FIREPROOFING BROKEN	05/22/85	85-0072	Y	TWH
EBD-19-H13	SWAY STRUT JAM NUT LOOSE	05/24/85	85-0074	Y	SJO
EBD-19-H13A	SWAY STRUT JAM NUT LOOSE	05/24/85	85-0074	Y	SJO
EBD-19-H15	SWAY STRUT JAM NUT LOOSE	05/24/85	85-0074	Y	SJO
EBD-19-H16	SWAY STRUT JAM NUT LOOSE	05/24/85	85-0074	Y	SJO
EBD-19-H74	FLASHING MISSING ON INSULATION	05/24/85	85-0074	Y	SJO
EBD-19-H19	THREE (3) OF FOUR (4) PINS HAVE NAILS IN LIEU OF LOTTER KEYS	05/24/85	85-0074	Y	SJO
EBD-19-H20	WASHER MISSING, NO FREE ROTATION ON BUSHING	05/24/85	85-0074	Y	SJO
EBD-19-H26	INSUL DMN, STRAPS LOOSE & MISSING	05/24/85	85-0074	Y	SJO
EBD-19-H32	SNUBBER PIPE CLAMP MIS-ALIGNED, SNUBBER JAM NUT LOOSE	05/24/85	85-0074	Y	SJO
EBD-19-H33	SWAY STRUT ROTATES ON EXTENSION THREADS NOT BUSHING	05/24/85	85-0074	Y	SJO

REV. 14

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D IND	RESP
EBD-19-H36	STRAPS LOOSE, INSULATION DOWN, (ALSO H37)	05/24/85	85-0074	Y	SJD
EBD-19-H37	CORRESPONDS TO EBD-19-H36 ON 85-0074	05/24/85	85-0074	Y	SJD
EBD-19-H133	SWAY STRUT PIPE CLAMP MIS-ALIGNED	05/24/85	85-0074	Y	SJD
EBD-19-H65	SWAY STRUT MIS-ALIGNED	05/29/85	85-0082	Y	SJD
EBD-19-H10	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H8	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H6	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H66	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H65	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H150	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H67	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H135	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H74	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H21	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H22	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H23	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H24	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H133	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H132	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H131	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H12	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H26	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
EBD-19-H72	BASEPLATE GAP	06/06/85	85-0090	Y	GNF
A362	BASEPLATE GAP	06/06/85	85-0090	Y	GNF

REV. 14

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D RESP IND
EBD-19-H49	BASEPLATE GAP	06/06/85	85-091	Y GNF
EBD-19-H50	BASEPLATE GAP	06/06/85	85-091	Y GNF
EBD-19-H52	BASEPLATE GAP	06/06/85	85-091	Y GNF
EBD-19-H53	BASEPLATE GAP	06/06/85	85-091	Y GNF
EBD-19-H54	BASEPLATE GAP	06/06/85	85-091	Y GNF
EBD-19-H55	BASEPLATE GAP	06/06/85	85-091	Y GNF
EBD-19-H56	BASEPLATE GAP	06/06/85	85-091	Y GNF
EBD-19-H51	BASEPLATE GAP	06/06/85	85-091	Y GNF
EBD-19-H141	CONCRETE CRACKS	06/06/85	SR85-74	Y GNF
EBD-19-H47	CONCRETE CRACKS	06/06/85	SR85-74	Y GNF
EBD-19-H48	CONCRETE CRACKS	06/06/85	SR85-74	Y GNF
A3	CONCRETE CRACKS	06/06/85	SR85-74	Y GNF
EBD-19-H133	ANGLE NOT WELDED PER DRAWING	07/10/85	85-0092A	Y SJD
EBD 19-H132	WASHERS #1 x #2 DISHED (CONCAVE)	07/11/85	85-0092A	Y GNF

REV. 14

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D IND	RESP
EBD-19-H49	ANCHOR BOLTS PULLED OUT	05/14/85	85-0060	Y	GNF
EBD-19-H136	ONE INACTIVE BOLT	05/15/85	85-0042A	Y	GNF
EBD-19-H49	SWAY STRUT PIPE CLAMP MIS-ALIGNED	05/16/85	85-0093	Y	SJD
EBD-19-H47	BASEPLATE ANCHOR BOLT WASHERS NOT SHOWN ON DRAWING	05/16/85	SR85-79	Y	GNF
EBD-19-H52	SNUBBER REAR BUSHING NOT FREE TO MOVE	05/16/85	SR85-79	Y	SJD
EBD-19-H150	PIPE CLAMP BOLTS LOOSE	05/21/85	85-0092	Y	SJD
EBD-19-H67	CLEARANCE GAP ON RESTRAINT NOT PER DRAWING	05/21/85	85-0092	Y	SJD
EBD-19-H38	SHIM WELDED TO SUPPORT NOT PER DRAWING	05/21/85	SR85-79	Y	SJD
EBD-19-H39	SHIM WELDED TO SUPPORT NOT PER DRAWING	05/21/85	SR85-79	Y	SJD
EBD-19-H17	SWAY STRUT END BEARING DOES NOT MOVE FREELY	05/23/85	85-0092	Y	SJD
EBD-19-H14	CONCRETE AROUND BASEPLATE IS CHIPPED	05/23/85	SR85-73	Y	GNF
EBD-19-H132	CONCRETE CRACKS IN WALL	05/23/85	SR85-73	Y	GNF
EBD-19-H67	CONCRETE CRACKS IN WALL	05/23/85	SR85-73	Y	GNF
EBD-19-H68	CONCRETE CRACKS IN WALL	05/23/85	SR85-73	Y	GNF
EBD-19-H12	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y	GNF
EBD-19-H148	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y	GNF
EBD-19-H65	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y	GNF
EBD-19-H26	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y	GNF
EBD-19-H22	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y	GNF
EBD-19-H20	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y	GNF
EBD-20-H1	LOOSE SWAY STRUT JAM NUT	06/05/85	85-0088	Y	SJD
EBD-20-H1	BROKEN FIREPROOFING	06/05/85	85-0089	Y	TWH
EBD-19-H154	BROKEN FIREPROOFING	06/05/85	85-0089	Y	TWH
EBD-19-H18	SWAY STRUT ROTATES ON THREADS	06/06/85	85-0092	Y	SJD

REV. 14

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D IND	RESP
EBD-20-H1	LOOSE SWAY STRUT JAM NUT	06/06/85	85-0092	Y	SJO
EBD-19-H16	SWAY STRUT JAM NUT LOOSE, PIPE CLAMP LOOSE	06/11/85	85-0094	Y	SJO
EBD-19-H13A	SWAY STRUT EYELET CONTACTS PIPE CLAMP	06/11/85	85-0094	Y	SJO



DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/CR NUMBER	DISPOSITION
A004	LOWER RIGHT NUT LOOSE	08/02/85	85-0124	USE-48-18 (1), REWORK-A00 2 PLATES AND 2 ANCHORSOLTS (2)
EBD-19-H101	LEVELING NUTS INSTALLED IMPROPERLY	08/21/85	85-0138	USE-48-18 (3)
JA-EBD-19-H81	NON-STANDARD PIPE CLAMP BWAY STRUT DIM INACCURATE	09/05/85	85-0220	USE-48-18 (3)
JA-EBD-19-H80	WLDG UNDSZ, BOLT SPACING OFF	09/06/85	85-0249	USE-48-18 (3)
JA-EBD-19-H478	3/8" PLATE IN LIEU OF 1/2", INTERFERENCE WITH DUCT SUPPORT, WLDG UNDSZ	09/06/85	85-0252	USE 48 18 (3)
JA-EBD-19-H479	WLD DEFECTS & UNDSZ	09/07/85	85-0274	USE-48-18 (3)
JA-EBD-19-H134	NO INSPECTION HOLE IN STRUT, NON STD PIPE CLAMP	09/07/85	85-0282	USE-48-18 (3)
JA-EBD-19-H100	3/4" STUD IN LIEU OF RED WD WLDG NOT PER DWG	09/09/85	85-0292	
A-309	LOOSE BOLT	09/09/85	85-0296	USE-48-18 (3)
JA-EBD-19-H103	WLD UNDSZ, MEMBER SIZE INCORRECT	09/09/85	85-0301	USE-48-18 (3)
JA-EBD-19-H108	BASEPLATE GAP, WLDG NOT PER DWG	09/09/85	85-0302	
JA-EBD-19-H102	3/8" PLATE IN LIEU OF 1/2", WLD NOT PER DWG, WLD UNDSZ	09/09/85	85-0303	
JA-EBD-19-H84	WEHRS MISSING, WLDG NOT PER DWG, GROUT BROKEN	09/09/85	85-0304	USE 48 18 (3)
JA-EBD-19-H101	WLDG UNDSZ, WLD NOT PER DWG, MISSING JAM NUTS, THDS STAKED, CLMP TWIST	09/09/85	85-0308	USE-48-18 (3), REWORK-A00, CLAMP (4)
JA-EBD-19-H124	MISSING JAM NUT, CHIPPED CONCRETE	09/10/85	85-0310	USE-48-18 (3)
JA-EBD-19-H125	WLDG UNDSZ, WLD DETAILS INCORRECT	09/10/85	85-0311	
JA-EBD-19-H105	THDS STAKED, MISSING JAM NUT, STRUT DIM INCORRECT, WLD UNDSZ,	09/10/85	85-0312	USE-48-18
JA-EBD-19-H87	DWG INCORRECT & LACKS DIMENSIONS, WLD UNDSZ, WLD DETAILS INCORRECT	09/10/85	85-0313	
JA-EBD-19-H76	NON-STD CLAMP, WLD NOT PER DWG, MEMBER DEFLECTED	09/10/85	85-0319	

14

14

DAVIS - BEEBE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
3A-E80-19-H106	ADD END BUSHING BINDING, LOCKT DIM INCOR. WLD 09/10/85 UNDSZ		85-0325	USE-A6-18 (T)
3A-E80-19-H65	ROD EYE BUSHING BINDING LOCK RING ON LOAD BOLT MISSING	09/10/85	85-0330	REWORK-40 JUST CLAMP, ADD RING (4)
3A-E80-19-H104	JAM NUTS & SPACER MISSING, WLD UNDSZ, THDS STAKED	09/10/85	85-0332	USE-A6-18 (T), REWORK-40J, PIVOT (4)
3A-E80-2-H36	WLD BTS NOT ON DWG, NON-BTD CLAMP, WLD UNDSZ, BROUT THKNSS, SPACER LOOSE	09/10/85	85-0334	USE-A6-18 (T)
3A-E80-19-H77	THDS STAKED, WLD ALL AROUND VS 2 SIDES, MISSING JAM NUT, NON-BTD CLAMP	09/10/85	85-0335	USE-A6-18 (T)
3A-E80-2-H37	MEMBER SZ & LOC DIM NOT PER DWG, WLD DETAILS INCOR	09/10/85	85-0371	
3A-E80-19-H127	BASEPLATE GAP, MISSING WLDs, INTERFERENCE, DIM INCOR	09/10/85	85-0377	
3A-E80-19-H123	JAM NUTS MISSING	09/10/85	85-0378	USE-A6-18 (T)
3A-E80-19-H85	WLDs NOT PER DWG, STRUCT MEMBER ANGLE INCOR	09/10/85	85-0340	
3A-E80-2-H19	WLD UNDSZ, BASEPLATE GAP	09/11/85	85-0342	USE-A6-18 (T)
3A-E80-19-H130	BASEPLATE GAP, WLD UNDSZ	09/11/85	85-0346	USE A6 18 (T)
3A-E80-19-H131	WLD UNDSZ	09/11/85	85-0347	USE-A6-18 (T)
3A-E80-2-H30	MOD. CLAMP, NO JAM NUT, PLATE GAP, MOVE WELD	09/11/85	85-0348	USE-A6-18 (T)
3A-E80-2-H27	JAM NUT ONE END, THREAD STAKED, UNDERSIZE WELD, MOD. CLAMP	09/11/85	85-0350	USE-A6-18 (T)
3A-E80-19-H126	THINNER PLATE, WELD DETAIL & UNDERSIZE, CLEARANCE	09/11/85	85-0353	USE-A6-18 (T)
3A-E80-19-H129	PLATE GAP, WELD DETAIL	09/11/85	85-0354	
3A-E80-19-H87	NO LOCKNUT, THD. STAKED, STIFF PL. NOT ON DWG	09/11/85	85-0358	
3A-E80-19-H86	CLEARANCE	09/11/85	85-0361	
3A-E80-19-H82	BAR ATTACHED TO SUPPORT, NO LOCKNUTS	09/11/85	85-0362	USE-A6-18 (T)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTOR FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NO./SR NUMBER	DISPOSITION
3A-E80-19-H151	WELDED, WELD DETAIL & UNDERSIZE, NO WASHER	09/12/85	85-0349	USE-A8-18 (3), REWORK-ADJUST (4)
3A-E80-19-H75	WELD DETAIL, THREAD STAKED, STRUT BINDS, DIMS'S, NONSTD. CLAMP, JAM NUT MISSING	09/12/85	85-0363	USE-A8-18 (3)
3A-E88-2-H21	ADD'L WELD, WELD DETAIL & UNDERSIZE, DIMENSIONS, CLEARANCE, GROUT THICK, EMBED	09/12/85	85-0364	
3A-E80-19-H108	NO WASHER, NO JAM NUT, THREAD STAKED	09/12/85	85-0370	USE-A8-18 (3)
3A-E88-2-H22	WELD SITE, TRVL SCALE MISSING, PLATE GAP, CONC. GOUGE	09/12/85	85-0372	USE-A8-18 (3)
3A-E88-2-H23	WELD DETAIL, CLEARANCE, PL. NOT DETAILED	09/12/85	85-0373	
3A-E88-2-H25	WELD UNDERSIZE, PLATE GAP	09/12/85	85-0374	
3A-E88-2-H28	PLATE GAP, WELD UNDERSIZE	09/12/85	85-0378	USE A8 18 (3)
3A-E88-2-H29	NON-STD. CLAMP, THDS STAKED, ALL-AROUND VS. 2 SIDE WLD, BASEPLATE GAP	09/12/85	85-0380	USE-A8-18 (3)
3A-E88-2-H31	MOD. CLAMP, CLAMP STUD MOV'T, THREAD STAKED, UNDERSIZE WELD, NO WASHER	09/12/85	85-0381	
3A-E80-19-H151	WLDG UNDSZ, WSHRS MISSING	09/12/85	85-0383	
3A-E80-19-H107	JAM NUT LOOSE, END BUSHING JAMMED, WLDG MISSING & UNDERCUT	09/13/85	85-0385	
3A-E88-2-H16	WLD DEFECTS, ITEMS NOT PER SPEC. BASEPLATE DIM INCORRECT	09/13/85	85-0390	USE-A8-18 (3)
33C-HCC-R1-H15	WLD ST NOT ON DWG, NO GROUT, WSHR MISSING	09/13/85	85-0391	USE-A8-18 (3)
3A-E88-2-H18	WELD DEFECTS	09/13/85	85-0393	USE A8 18 (3)
3A-E88-2-H17	BASEPLATE GAPS, WLD DEFECTS	09/13/85	85-0394	USE-A8-18 (3)
3A-E88-2-H10	WLD DEFECTS, CONCRETE CRACKS	09/13/85	85-0396	USE A8 18 (3)
3A-E80-19-H120	DETAIL 'A' INCOR DIM, NO WELD VS WELD PRESENT	09/14/85	85-0398	USE-A8-18 (3)
3A-E80-19-H118	THD ENGAGEMENT, STRUT JAMMED	09/14/85	85-0399	USE-A8-18 (3) REWORK-REPLACE BUSHING (4)

14

14

14

DAVIS - BESSE FIRING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	WCR/BR NUMBER	DISPOSITION
JA-E80-19-H117	THDS STAKED, ANCHOR BOLTS LACK THD ENGAGEMENT	09/14/85	85-0401	USE AG-18 (3)
JA-E80-19-H111	WGRS MISSING, WLOS NOT PER DWG & UNDSZ	09/14/85	85-0414	
JA-E80-19-H122	ITEM DIM INCORRECT, WLOS UNDSZ & NOT PER DWG	09/14/85	85-0421	USE-AG-18 (3)
JA-E80-19-H119	WLOS UNDSZ & NOT PER DWG	09/14/85	85-0422	
JA-E80-19-H110	STANCHION CLEARANCE, WELDS NOT PER DWG	09/14/85	85-0429	
JA-E80-19-H153	THDS STAKED, NO SIGHT HOLE IN TOP OF STRUT	09/16/85	85-0431	USE-AG-18 (3)
JA-E88-2-H8	THDS STAKED ON SWAY STRUT JAM NUT	09/16/85	85-0432	USE-AG-18 (3)
JA-E88-2-H9	SITUATION DOESN'T ALLOW FOR DWG WLD THDS STRIPPED ON BASEPLATE NUTS/BOLTS MISSING	09/16/85	85-0433	
JA-E88-2-H6	WGRS MISSING, STRUT BOUND, THDS STAKED, BASEPLATE GAP	09/16/85	85-0434	
JA-E88-2-H7	BASEPLATE GAP UNACCEPTABLE	09/16/85	85-0435	USE AG 18 (3)
JA-E80-19-HA39	BASEPLATE GAP UNACCEPTABLE DIMENSION NOT PER DWG	09/16/85	85-0436	
JA-E80-19-HA38	WELDS UNDSZ	09/16/85	85-0437	USE AG 18 (3)
JA-E88-2-H25	BASEPLATE NOT PER DWG BASEPLATE GAP UNACCEPTABLE	09/16/85	85-0438	USE-AG-18 (3)
JA-E80-19-H152	BASEPLATE GAP UNACCEPTABLE THDS STAKED, 6" DIM NOT PER SPEC	09/16/85	85-0439	USE-AG-18 (3)
JA-E80-19-H109	BASEPLATE DIM UNDSZ, STANCHION CLEARANCE NOT PER DWG, WLOS UNDERCUT & NOT PER DWG	09/17/85	85-0440	
JA-E80-19-H116	ALL-ROUND WLOS NOT POSS, STRUT BOLT HAS BEEN STAKED	09/17/85	85-0441	USE-AG-18 (3)
JA-E88-2-H3	WLOS NOT PER DWG, THDS STAKED ON SWAY STRUT JAM NUT, STRUT BOUND UP	09/17/85	85-0450	USE-AG-18 (3), REWORK-REPLACE CORRODED END (4)
JA-E88-2-H2	THDS STAKED, STRUT BOUND UP, ITEM #2 HAS DEFORMED AREA	09/17/85	85-0451	
JA-E80-19-H91	ITEM #1 HAS STRUCTURAL DAMAGE, WLOS UNDSZ	09/17/85	85-0460	

14

14

DAVIS - BEHSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
3A-E8D-19-H69	WLDG CRACKED, ITEM #4 NOT PER DWG, WLD UNDSZ	09/17/85	85-0461	
3A-E8B-2-H5	SWAY STRUT BOUND UP, THDS STAKED	09/17/85	85-0463	
3A-E8B-2-H4	JAM NUTS LOOSE, WLDG UNDSZ	09/17/85	85-0466	USE-46-18 (3), REWORK-TIGHTEN JAM NUT (4)
3A-E8B-2-H74	THDS STAKED, PIPE CLAMP LOOSE, WLD UNDSZ	09/17/85	85-0467	
3A-E8B-2-H64	WCHRG INSTALLED WRONG, THDS STAKED, BASEPLATE GAP UNACCEPTABLE	09/17/85	85-0468	
3A-E8B-2-H12	PIPE CLAMP MIS-ALIGNED, WLD MISSING, THDS STAKED	09/17/85	85-0470	USE-46-18 (3), REWORK-ADJUST CLAMP (4)
3A-E8B-2-H14	CONCRETE FALLING OUT, WLDG UNDSZ & NOT PER DWG	09/17/85	85-0471	
3A-E8B-2-H13	STRUT BOUND UP, THDS STAKED, WLD NOT PER DWG, "M" DIM INCORRECT	09/17/85	85-0472	USE-46-18 (3), REWORK-REPLACE ROD END (4)
3A-E8B-2-H15	WLD UNDSZ, ITEM #7 INCORRECT DIM	09/17/85	85-0473	
3A-E8B-2-H11	JAM NUT LOOSE, STRUT BOUND UP, WLD NOT PER DWG	09/17/85	85-0474	USE-46-18 (3), REWORK-TIGHTEN JAM NUT (4)
3A-E8D-19-H88	BASEPLATE GAP UNACC, LOCK NUTS MISSING, THDS STAKED	09/17/85	85-0475	USE-46-18 (3)
3A-E8B-2-H1	SWAY STRUT BOUND UP & THDS STAKED, WLD NOT PER DWG	09/17/85	85-0476	
3A-E8B-2-H20	NON-STD CLAMP INSTALLED, WLD NOT PER DWG	09/17/85	85-0484	
3A-E8D-19-H121	BOLT NOT VERY, BOLT ROTATES, DIM MISSING FROM DWG, WLD NOT PER DWG, DIM DIFFERENCES	09/18/85	85-0489	
3A-E8D-19-H96	NO LOCK NUTS, SHB-CLAMP ORIENTATION EXCEEDS RECOM	09/18/85	85-0494	USE-46-18 (3), REWORK-ADJUST (4)
3A-E8D-19-H94	BOM DESCRIPT, WLD NOT COMPLETE PER DWG, CLEARANCE 1/32" VS 1/16"	09/18/85	85-0496	USE-46-18 (3)
3A-E8D-19-H95	LOCKNUTS MISSING	09/18/85	85-0497	USE-46-18 (3)
3A-E8D-19-H98	BASEPLATE GAPS, STRUT OFFSET, MISSING LOCK NUT, STRUT BODY LOOSE	09/18/85	85-0498	USE-46-18 (3), REWORK-ADJUST CLAMP AND STRUT (4)

DAVIS - BESSIE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NOB/SR NUMBER	DISPOSITION
3A-E80-19-H98	WLD MISSING ON FLG, WLD UNDER, CLEARANCE NOT PER DWG	09/18/85	85-0499	USE-A8-18 (3)
6C-E80-14-H234	BASEPLATE DIM NOT ON DWG, SWAY STRUT SOUND, PIPE CLAMP MIS-ALIGNED WITH STRUT	09/18/85	85-0507	USE-A8-18 (3), REWORK-ADJUST (4)
3A-E80-19-H117	BASEPLATE DIM INCOR, WLD UNDER, CLEARANCE NOT PER DWG, UNDERCUT	09/18/85	85-0508	USE A8 18 (3)
3A-E80-19-H115	DIM PROBLEMS, WLD 3-SIDES VS ALL-ROUND ON LUGS, WLD UNDER	09/18/85	85-0509	USE A8 18 (3)
3A-E80-19-H97	STANCHION DAMAGED	09/18/85	85-0510	USE-A8-18 (3)
3A-E80-19-H93	THOS STAKED, STRUT OFFSET, LOCKNUT MISSING, WLD NOT PER DWG, 3 XSHRS/ANCHOR BLT	09/18/85	85-0511	USE-A8-18 (3), REWORK-ADJUST (4)
3A-E80-19-H90	WLD UNDER	09/18/85	85-0512	USE-A8-18 (3)
3A-E80-19-H112	TAP BOLTS REPLACED BY STUDS, WLD DETAIL, DIMENSION PROBLEMS	09/20/85	85-0545	
M-1114-H16	DIM NOT PER DWG, STRUT SOUND UP	09/25/85	85-0685	USE-A8-18 (3)
M-1114-H3	WLD & DIM NOT PER DWG	09/25/85	85-0688	USE A8 18 (3)
M-1114-H5	LOCKNUT & BOLT MISSING, DIM NOT PER DWG	09/25/85	85-0689	USE A8 18 (3)
M-1114-H40	STRUT SOUND UP	09/25/85	85-0704	
M-1114-H22	NOT FULL BASEPLATE BEARING, DIM & WLD NOT PER DWG, UNACC BOLT EDGE DISTANCE	09/25/85	85-0707	
M-1114-H2	DIM NOT PER DWG, LOCKWIRES NOT INSTALLED	09/25/85	85-0708	USE-A8-18 (3), REWORK-INSTALL LOCKWIRE (4)
M-1114-H1	WLD NOT PER DWG, LOCKWIRE NOT INSTALLED	09/25/85	85-0713	USE A8 18 (3), REWORK-INSTALL LOCKWIRE (4)
M-1114-H6	DIMEN, WELD, & CLEARANCE NOT PER DWG.	09/26/85	85-0727	
M-1114-H7	BOLT ANGLED, MISSING NUTS.	09/26/85	85-0728	USE-A8-18 (3)
M-1114-H47	DIMEN NOT PER DWG, MISSING LOCKWIRE, ROTATED CLAMP.	09/26/85	85-0729	USE A8 18 (3), REWORK-ADJUST CLAMP (4)
M-1114-H8	DIMEN & WELD NOT PER DWG.	09/27/85	85-0767	

DAVIS - BEESSE FIRING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	WCR/SR NUMBER	DISPOSITION
M-1114-H23	DIMEN & WELDS NOT PER DWG.	09/28/85	85-0775	USE-48-18 (7), REWORK-INSTALL LOCKWIRE (4)
M-1114-H24	DIMEN, WELDS, & BOLT NOT PER DWG. BOLT SPACING VIOLATION.	09/28/85	85-0776	
M-1114-H25	DIMEN & WELD NOT PER DWG, MISSING LOCKWIRE.	09/28/85	85-0786	
M-1114-H26	SMOOTHER UNSATISFACTORY.	09/30/85	85-0796	
M-1114-H29	WELDS & DIMEN NOT PER DWG. BRACKET NOT ROTATED PER DWG.	09/30/85	85-0798	
M-1114-H4	PIPE ELEVATION INCORRECT, SPACERS ADDED TO CLAMP	10/01/85	85-0747	USE-48-18 (3)
M-1114-H37	WLD UNDSZ, MISSING SPACER, BASEPLATE BEARING UNSAT	10/03/85	85-0839	
M-1114-H17	BOLT SPACING VIOLATION, BASEPLATE BEARING UNSAT	10/03/85	85-0840	
M-1114-H36	BASEPLATE BEARING UNSAT	10/03/85	85-0841	USE-48-18 (7)
M-1114-H11	BOLT SPACING NOT PER SPEC, BASEPLATE BEARING UNSAT & NOT PER DWG	10/03/85	85-0843	
M-1114-H32	WLD NOT PER DWG, BOLT #4 REQUIRED & FULL TURNS	10/03/85	85-0844	
M-1114-H15	BASEPLATE GAP	10/07/85	85-0922	USE-48-18 (3)
M-1114-H15	BASEPLATE GAP	10/07/85	85-0922	USE-48-18 (3)
M-1114-H38	UNDSZ WLD, INTERFERENCE WITH STRUT, MIN. BOLT SPACING VIOLATION	10/07/85	85-0944	
M-1114-H41	BASEPLATE GAP, WLD UNDSZ, STRUT GIVEN, INCORRECT	10/07/85	85-0945	
DA-E8D-10-H147	3/4" BOLTS VS. 1/2", BASEPLATE GAP, WLD UNDSZ, SIGHT HOLE MISSING	10/07/85	85-0946	
M-1114-H17	BASEPLATE GAP, WLD UNDSZ, MIN BOLT SPACING VIOLATION	10/07/85	85-0947	
DA-E8D-19-H133	WLD DETAIL INCORRECT, PIPE CLAMP WASHERS TOO THICK, GAP IN FIREPROOFING	10/08/85	85-0955	

14

14



DAVIS - BESSIE FIRING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
3A-E80-19-H76	WLD DETAIL NOT ON DWG, WLD DETAIL INCORRECT	10/08/85	85-0956	
3A-E80-19-H132	3/4" BOLT VS 1/2", ADDITIONAL WASHER PLATES, MEMBER SIZE INCORRECT, WELD DETAIL	10/08/85	85-0957	
M1114/H20	WLD DETAIL INCORRECT, LOOSE JAM NUT, BOLT MIN. DIST. VIOLATION	10/08/85	85-0959	
A221	WEEP HOLE CUT IN STANCHION, FIREPROOFING CRACKED, DIMEN INCORRECT	10/08/85	85-0962	
3A-E80-19-H47	DIMENSIONS WELD DETAIL & UNDERSIZE	10/09/85	85-0975	
3A-E80-19-H136	WELD DETAIL	10/09/85	85-0976	
3A-E80-19-H53	DIMENSIONS WELD SYMBOL WELD DETAIL & SIZE	10/09/85	85-0977	
3A-E80-19-H53	WELD DETAIL & SIZE ANCHOR EMBED	10/09/85	85-0978	
3A-E80-19-H49	DIMENSIONS BUSHET INSTALLED HILTI VS. SHELL TYPE	10/09/85	85-0979	
3A-E80-19-H51	C.L. SETTING	10/09/85	85-0980	
3A-E80-19-H13	DIMENSION WELD DETAIL & UNDERSIZE THD STAKED BOLT LOOSE ON STRUT	10/09/85	85-0981	
3A-E80-19-H54	WELD DETAIL	10/09/85	85-0982	
3A-E80-19-H52	PL GAP DIMENSIONS	10/09/85	85-0985	
3A-E80-19-H50	WELD DETAIL PL GAP HILTI VS. SHELL	10/09/85	85-0987	
3A-E80-19-H134	DIMENSIONS, THD STAKED, WELD DETAIL	10/09/85	85-0993	
3A-E80-19-H57	WELD DETAIL	10/09/85	85-0994	



DAVIS - WEBER PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
3A-EBD-19-H23	WELD DETAIL & SIZE, DIMENSION, BOLT SPACE	10/09/85	85-1000	
3A-EBD-19-H20	WELD DETAIL, B/M PROBLEM, THREAD STAKED, DIMENSION	10/09/85	85-1001	
3A-EBD-19-H56	DIMENSION CLEARANCE ANCHOR BOLT SPACE	10/09/85	85-1002	
3A-EBD-19-H08	WELD DETAIL & SIZE	10/09/85	85-1007	
3A-EBD-19-H22	DIMENSION PL. GAP WAS NOT LOOSE SPACER THREAD ENGAGE.	10/09/85	85-1009	
M1114/H43	PL. GAP DIMENSION NOT LOOSE	10/09/85	85-1010	
M1114/H18	DIMENSION, STRUT BUSHING NO MOVEMENT	10/09/85	85-1011	
A-362	ANCHOR BOLT SPACE, WELD SIZE	10/09/85	85-1012	
3A-EBD-19-H10	PL. GAP, DIMENSION, NO PL. THICK ON DRAWING, WELD DETAIL, INTERFERE	10/09/85	85-1013	
3A-EBD-19-H142	3/4" BOLT VS. 1/2", PL. GAP, WELD DETAIL	10/09/85	85-1014	
3A-EBD-20-H1	WELD DETAIL, THREAD STAKED	10/09/85	85-1015	
3A-EBD-19-H4	B/M PROBLEM, PL. THICK, WELD DETAIL	10/09/85	85-1016	
3A-EBD-20-H2	WELD DETAIL	10/09/85	85-1017	
A-001	BOLT SPACE, WELD SIZE	10/09/85	85-1025	
3A-EBD-19-H59	WELD DETAIL & SIZE	10/09/85	85-1026	
3A-EBD-19-H9	ATTACHMENT NOT CENTERED ON PLATE, SPRING SETTINGS	10/09/85	85-1028	
3A-EBD-19-H11	MEMBER LENGTH, WELD SIZES	10/09/85	85-1029	
3A-EBD-19-H34	ADDITIONAL MEMBER INSTALLED	10/09/85	85-1030	

DAVIS - 86386 PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	WCR/SR NUMBER	DISPOSITION
3A-E80-19-H35	SWAY STRUT PROBLEMS	10/09/85	85-1031	
3A-E80-19-H57	WELD DEFECTS, MEMBER LENGTHS ANCHOR BOLT SPACING	10/09/85	85-1032	
3A-E80-19-H25	ANCHOR BOLTS SIZE INCREASED	10/09/85	85-1033	
3A-E80-19-H33	STAKED THREADS SWAY STRUT	10/09/85	85-1034	
3A-E80-19-H30	WELD SIZES	10/09/85	85-1035	
3A-E80-19-H38	WELD SIZES, MEMBER SIZE	10/09/85	85-1036	
3A-E80-19-H32	WELD SIZE	10/09/85	85-1037	
3A-E80-19-H60	WELD SIZES & TYPES, DIMENSION CHANGES	10/09/85	85-1041	
3A-E80-19-H72	WELDS, SPRING, WASHERS AT ANCHORS	10/09/85	85-1046	
M-1114-H42	BOLT SPACING, WELD & STRUT PROBLEMS	10/09/85	85-1048	
3A-E80-19-H68	DIMENSIONS & WELD SIZES	10/09/85	85-1050	
M-1114-H29	DIMENSIONS & WELDS	10/10/85	85-1051	
M-1114-H27	PIPE CLAMP	10/10/85	85-1052	
3A-E80-19-H16	DIMENSIONS & STRUT PROBLEMS	10/10/85	85-1053	
3A-E80-19-H17	ADDITIONAL WELD AT STRUT BRACKET	10/10/85	85-1054	
3A-E80-19-H150	SNUBBER, BASE PLATE & WELD PROBLEMS	10/10/85	85-1055	
3A-E80-19-H144	WELD SIZES & SNUBBER PROBLEMS	10/10/85	85-1056	
3A-E80-19-H12	DIMENSIONS, WELD SIZE, SNUBBER PROBLEMS	10/10/85	85-1065	
3A-E80-19-H21	NO WASHERS FOR ANCHOR BOLTS	10/10/85	85-1078	
3A-E80-19-H69	WELDS AND DIMENSIONS	10/10/85	85-1079	
3A-E80-19-H71	WELDS, ANCHOR BOLTS, SNUBBER PART NO.	10/10/85	85-1083	
3A-E80-19-H15	WELD DETAIL & SIZE	10/11/85	85-1100	
3A-E80-19-H8	DIMENSIONS, S-W PROBLEM, WELD DETAIL	10/11/85	85-1101	

DAVIS - BESSIE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NO./SER NUMBER	DISPOSITION
JA-EBD-19-H141	COND. CRACK, CLEARANCE	10/11/85	85-1102	
C-800-9489	PL. GAP, DIMENSION, EDGE DIST	10/11/85	85-1110	
JA-EBD-19-H149	WELD SIZE, PIN-PIN, SPACER BOLT LOOSE	10/11/85	85-1128	
JA-EBD-19-H14	STD VS. TAP BOLT, DIMENSIONS, WELD DETAIL & SIZE, NON STD CLAMP, SPACER MISSING	10/12/85	85-1131	
JA-EBD-19-H135	HILTI VS. TAP BOLT, WELD DETAIL & SIZE, DIMENSIONS, ADDITIONAL HOLES	10/12/85	85-1132	
JA-EBD-19-H145	HILTI BOLT, DIMENSIONS, WELD SIZE	10/12/85	85-1133	
JA-EBD-19-H18	WELD DETAIL, DIMENSIONS, CONDUIT CONTACT	10/12/85	85-1134	
JA-EBD-19-H19	WELD DETAIL, CLEARANCE W/ PIPING, ATTACH TO HGR, THREAD STAKED, NONSTD END BRACK	10/12/85	85-1135	
JA-EBD-19-H66	NOT PER DRAWING	10/14/85	85-1136	
EBD-1-H4	BEAM ATT WELD & PIN SIZE, CLAMP BOLT	10/16/85	85-1207	
JA-EBD-19-H65	BOLT SPACING, PLATE GAPS, WELD SIZE, SPALLING	10/17/85	85-1241	
EBB-1-855	1-WELD REDUCED, 1-WELD LENGTH INCREASE	10/17/85	85-1242	
EBB-1-859	WELD SIZE, SNUGGER LEAK-RES. EMPTY	10/17/85	85-1246	
A004	BASEPLATE GAPS, WELD UNDERSIZE	10/18/85	85-1262	
EBB-1-H2	ADDITIONAL WELD	10/18/85	85-1284	
EBB-1-H3	WELDS UNDERSIZE, BASEPLATE SIZE, WELD SYMBOL MISSING, NUTS ARE Y.N. OR THD. STK.	10/18/85	85-1287	
EBB-1-850	CORROSION ON SNUGGER PISTON ROD	10/18/85	85-1288	
EBB-1-855	WELD UNDERSIZE, BASEPLATE SIZES, WELD SYMBOL MISSING	10/18/85	85-1289	
EBB-1-858	WELD TYPE CHANGED, RUST IS PRESENT ON SNUGGER BEARINGS PREVENTING FREE MVT.	10/19/85	85-1313	
JA-EBD-19-H67	ANCHOR BOLTS 5/8" NOT 1/2", BOLT SPACING IT-2 SHORTENED 1/4", WELDS USIZED, SPALL	10/19/85	85-1316	

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/CR NUMBER	DISPOSITION
EBB-1-H1	PIPE CLAMP - NO SPACER, STK. THD. GAP AT SPACER	10/19/85	85-1336	
EBB-1-867	ADDED WELD, WELD DETAIL NOT SHOWN ON DETAIL DRAWING	10/19/85	85-1337	
EBB-1-H5	WELD DETAIL NOT ON DRAWING, WELD TYPE CHANGE, 10/19/85 GAPS ON CLAMP NOT PER DRAWING		85-1338	

SECTION 2.0

AUXILIARY FEEDWATER SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NO./SR NUMBER	DISPOSITION
EBD-14--76	CONCRETE CHIPPED	05/08/85	85-0049	USE-AS-IS (3), REWORK-REGROUT (4)
EBD-14--80	BASEPLATE GAP/CONCRETE CHIPPED	05/08/85	85-0050	USE-AS-IS (1), REWORK-ADD SHIMS (2)
EBD-14--89	BASEPLATE GAP	05/08/85	85-0051	USE-AS-IS (1), REWORK-ADD SHIMS (2)
EBD-14--54	BOLT SIZE INCORRECT	05/23/85	85-0073	USE-AS-IS (3)
EBD-14--69	LOOSE BOLT	05/24/85	85-0075	USE-AS-IS (3)
EBD-14--68	ONE BOLT WILL NOT TORQUE	05/28/85	85-0076	USE-AS-IS (3)
EBD-14--67	BOLT TYPE INCORRECT	05/28/85	85-0077	USE-AS-IS (3)
EBD-14--77	BOLT SIZE & QUANTITY INCORRECT	06/25/85	85-0102	USE-AS-IS (1), REWORK-ADD NEW ANCHOR BOLTS (2)
EBD-14--91	BOLT SIZE INCORRECT	07/10/85	85-0108	USE-AS-IS (3)
EBD-14--90	INADEQUATE WELD REPAIR OF BASEPLATE	08/22/85	85-0140	USE-AS-IS (3)
M1155/45	WELD ALL AROUND VS. 3 SIDES, SNUBBER BUSHINGS BINDING, BORIC ACID ACCUM.	09/03/85	95-0185	USE-AS-IS (3), REWORK-REPLACE SNUB (4)
M1155/44	WELDED 3 SIDES VS. 1 SIDE	09/03/85	95-0187	USE-AS-IS (3)
6C-EBB-4-H12	BASEPLATE GAP INSTALLATION CRITERIA VIOLATED	09/04/85	85-0198	USE-AS-IS (3)
6C-EBB-4-H4	WELDS UNDERSIZE, UNDERCUT, OVERLAP, CLEARANCE IS 1/32"	09/04/85	85-0202	USE AS IS (3)
M1155/46	1 WSHR NEEDED EA SIDE VS 1 WSHR 1 SIDE ACTUAL	09/04/85	95-0203	USE AS IS (3), REWORK-INST. WASHER (4)
6C-EBB-4-H3	CLEARANCES WRONG SIZE, WRONG SIZE HILTI BOLT	09/04/85	85-0204	USE-AS-IS (3)
6C-EBB-4-H16	GAP WRONG SIZE, ITEM #2 DEFORMED, WELD DEFECTS	09/04/85	85-0205	
6C-EBB-4-H8	WELD UNDERCUT > 1/32" GAP WRONG SIZE	09/04/85	85-0206	USE-AS-IS (3)
6C-EBB-4-H15	BASE OF RES. LEAKING WELDS NOT PER DWG WELD UNDERSIZE	09/04/85	85-0207	

DAVIS - BEEBE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
M1155/H2	GAPS OVERSIZE	09/04/85	85-0210	USE-48-18 (3)
M1155/H3	WLD NOT PER DWG BASEPLATE GAPS	09/05/85	85-0216	
M1155/H1	NUTS ON PIPE CLAMP DOES NOT HAVE FULL ENGAGEMENT	09/05/85	85-0217	REWORK-TIGHTEN NUTS (4)
6C-E88-4-H9	WLD UNDSZ, ARC STRIKE, BASE METAL REDUCTION BASEPLATE GAP, ID TAG INCORRECT	09/05/85	85-0221	USE-48-18 (7), REWORK-REPLACE TAG (4)
6C-E88-4-H11	ANCHOR BOLTS HAVE 3/4 WASHERS, BASEPLATE GAP, ARC STRIKES, UNDERCUT > 1/32"	09/05/85	85-0222	USE-48-18 (7), REMOVE ARC STRIKES
6C-E88-4-H10	UNDERCUT > 1/32", WLD UNDSZ, POROSITY IN WELD, JAM NUT MISSING, SPACER LOOSE	09/05/85	85-0223	USE-48-18 (7)
6C-E88-4-H17	5/8" ANCHOR BOLTS IN LIEU OF 1/2", BOLT CUT OFF, BASEPLATE UNDSZ, ARC STRIKES	09/05/85	85-0224	USE-48-18 (7), REWORK-REMOVE ARC STRIKES (4)
6C-E88-14-H13	WLD UNDSZ, BOLTS AT ANGLE & INCORRECT, BASEPLATE GAP, HILTI BOLTS IN LIEU OF TAP	09/05/85	85-0225	
6C-E88-14-H10	CLAMP BOLT THDS STAKED CLAMP BOLT SPACER LOOSE JAM NUT MISSING	09/05/85	85-0227	USE-48-18 (3)
6C-E88-14-H95	PIPE CLAMP NOT PER DWG, BOLT THDS NOT ENGAGED	09/05/85	85-0238	
6C-E88-14-H97	BASEPLATE GAP, WLD UNDSZ, WELD DETAIL INCORRECT	09/06/85	85-0235	
6C-E88-14-H1	WLD UNDSZ, UNDERCUT > 1/32"	09/06/85	85-0245	
6C-E88-14-H14	WLD UNDSZ	09/06/85	85-0260	
6C-E88-14-H4	UNDERCUT > 1/32", NUT THDS NOT ENGAGED	09/06/85	85-0265	
6C-E88-14-H95	WELD UNDSZ & UNDERCUT PRESENT, DOUBLE NUTTED BOLTS, JAM NUTS MISSING	09/06/85	85-0266	USE-48-18 (3)
6C-E88-4-H2	WLD UNDSZ, MEMBER 82 INCOR, THDS STAKED, MEMB JAM NUT, 8 DIM INCOR	09/07/85	85-0280	USE-48-18 (7)
A223	WELD UNDSZ & UNDERCUT PRESENT, BASEPLATE GAP	09/07/85	85-0281	
6C-E88-14-H8	"8" DIMENSION INCORRECT, THDS STAKED, MISSING JAM NUT, WELD DETAIL INCORRECT	09/07/85	85-0283	

14

DAVIS - BESSIE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SA NUMBER	DISPOSITION
60-E50-14-H6	"S" DIMENSION INCOR & SPACER LOOSE, THDS STAKED, MISSING JAM NUT	09/07/85	85-0284	USE-A8-18 (3)
60-E50-14-H5	WLDG NOT PER DWG, WLD UNDSZ, MISSING JAM NUT	09/07/85	85-0285	USE-A8-18 (3)
60-E50-14-H7	WLD UNDSZ & UNDERCUT, ARC STRIKES, WLDG NOT PER DWG, THDS STAKED, MISSING JM NTS	09/07/85	85-0286	
60-E50-14-H9	THDS STAKED, MISSING JAM NUTS, WLDG NOT PER DWG	09/09/85	85-0294	USE-A8-18 (3)
60-E50-14-H3	WLDG NOT PER DWG & UNDSZ, MISSING JAM NUTS, THDS STAKED	09/10/85	85-0270	
60-E50-14-H2	MISSING JAM NUTS & WLD, WELD DETAIL INCORRECT	09/10/85	85-0271	USE-A8-18 (3)
60-E50-14-H12	WLD UNDSZ	09/10/85	85-0293	USE-A8-18 (3)
60-E50-4-H14	NONSTD CLAMP, WELD UNDERSIZE, DIMENSIONS, B.O.M PROBLEM, LOCKNUT MISSING	09/12/85	85-0375	USE-A8-18 (3)
60-E50-14-H34	BASEPLATE GAPS, NUTS NOT PER SPEC, NON-STD PIPE CLAMP	09/13/85	85-0384	
60-E50-14-H35	BOTH SWAY STRUTS LOCKED & NO WSHRS, NO WELDS VS WELDS PRESENT	09/14/85	85-0400	USE-A8-18, (3) REMARK-INSTALL WASHERS (4)
60-E50-14-H22	WLDG NOT PER DWG, #3 WRONG DIM, NO PIN TO PIN DIM ON DWG	09/17/85	85-0469	
60-E50-14-H19A	PIN TO PIN DIM NOT INDICATED ON DWG	09/17/85	85-0479	USE-A8-18 (3), REMARK
60-E50-14-H18	ITEMS INCORRECT DIM'S, WLD NOT PER DWG	09/17/85	85-0480	USE-A8-18 (3)
60-E50-14-H33	NO CONCRETE ANCHORS SPEC'D, ITEMS INCOR DIM, WLDG NOT PER DWG	09/17/85	85-0481	
A-146	STIFF PLATES THICKER	09/18/85	85-0485	USE-A8-18 (3)
60-E50-14-H23	PIN-PIN DIM NOT ON DWG	09/18/85	85-0486	USE-A8-18 (3)
60-E50-14-H66	ANCHOR BOLT EDGE DIST DIFF FROM DWG, BASEPLATE GAP, THDS STAKED & NOT VISIBLE	09/18/85	85-0490	USE-A8-18 (3), REMARK-ADJUST (4)
60-E50-14-H94	STUDS & BOLTS STAKED, 'S' DIM DIFF FROM CATALOG, NO SIGHT HOLE	09/18/85	85-0491	USE-A8-18 (3)

14

14



DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
6C-EBD-14-H91	1" HILTI VS 7/8 RED HEAD, WELD NOT PER DWG	09/18/85	85-0492	USE-AG-18 (3)
6C-EBD-14-H58	THDED ROD L&L NUTS, THDED ROD VS TAP BLTS, THDS STAKED, SPACER TACKED TO CLAMP	09/18/85	85-0493	USE-AG-18 (3)
6C-EBD-14-H61	THDS STAKED, BASEPLATE THICK NOT ON DWG, WLD NOT PER DWG, WLD UNDSZ	09/18/85	85-0495	USE-AG-18 (3)
6C-EBD-14-H21	LOCKNUT LOOSE, STRUT TURN BY HAND, PIN-PIN NOT ON DWG	09/18/85	85-0502	USE-AG-18 (3), REWORK-ADJUST (4)
6C-EBD-14-H20	WLDs NOT PER DWG, NO THD IN INSPECTION HOLE, NO INSPECTION HOLE	09/18/85	85-0503	
6C-EBD-14-H174	PIPE CLAMP NOT TIGHT, SWAY STRUT LOOSE, ONLY ONE NUT/STRUT, PIN-PIN NOT ON DWG	09/18/85	85-0504	USE-AG-18 (3), REWORK-TIGHTEN (4)
6C-EBD-14-H238	PIN-PIN NOT ON DWG	09/18/85	85-0506	USE-AG-18 (3)
6C-EBD-14-H37	STRUT BODY LOOSE, WGR & LOCKNUTS MISSING, THDS STAKED, STRUT OFFSET	09/19/85	85-0517	USE-AG-18 (3), REWORK-ADJUST (4)
4-224	FULL LENGTH VS STITCH WLD ON DWG	09/19/85	85-0518	USE-AG-18 (3)
6C-EBD-14-H71	THDS STAKED, PLATE GAP, ARC STRIKE	09/19/85	85-0522	USE-AG-18 (3), REWORK-REMOVE ARC STRIKES (4)
6C-EBD-14-H53	BASEPLATE GAP	09/19/85	85-0523	
4-8	ANCHOR TO BE REMOVED	09/19/85	85-0524	REWORK (NON-SEISMIC)
6C-EBD-137-H18	WLD DETAIL, PLATE GAP	09/19/85	85-0525	USE-AG-18 (3)
6C-EBD-14-H56	PLATE GAP, SPACER LOOSE, THDS STAKED, CLAMP ID WRONG	09/19/85	85-0526	
6C-EBD-14-H70	ANCHOR BOLT MISSING	09/19/85	85-0527	USE-AG-18 (3)
6C-EBD-14-H38	WLD NOT ON DWG, THD STAKED	09/19/85	85-0528	USE-AG-18 (3)
6C-EBD-14-H15	NO BILL/MAT'L, WLD DETAIL NOT PER DWG, THDS STAKED, LOCKNUTS LOOSE	09/19/85	85-0529	
6C-EBD-14-H48	INSTALLED SECTION VS DWG, WLD DETAIL, CLEARANCE	09/20/85	85-0536	
6C-EBD-14-H57	PLATE GAP, THD STAKED, CLAMP ID WRONG	09/20/85	85-0537	USE-AG-18 (3)

114

114

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
6C-E8D-14-H47	PLATE GAP, ITEM # MISSING ON DWG, WLD UNDSZ	09/20/85	85-0538	
6C-E8D-14-H455	SPACER LOOSE, THD STAKED, CLAMP ID WRONG, WLD DETAIL, ITEM ROTATED	09/20/85	85-0539	USE-48-18 (3)
6C-E8D-14-H48	THDS STAKED, THICKER BASEPLATE THAN DWG, BOLTS NOT TO DWG	09/20/85	85-0542	USE-48-18 (3)
6C-E8D-14-H39	PLATE GAP, WLD NOT DETAIL, ITEM # CALLOUT ON DWG	09/20/85	85-0543	
A-262	WLD UNDSZ	09/20/85	85-0544	
6C-E8D-14-H41	WLD MISSING, UNDSZ & NOT PER DWG	09/20/85	85-0549	
6C-E8D-14-H43	THDS ROD, WLD UNDSZ & DETAIL, BASE METAL REDUCTION	09/20/85	85-0550	USE-48-18 (3)
6C-E8D-14-H44	BASEPLATE GAP, THD STAKED, LOCKNUT NOT TIGHT, CLAMP END BOUND UP, CLAMP ID WRONG	09/20/85	85-0551	USE 48 18 (3), REWORK-TIGHTEN LOCKNUT (4)
6C-E8D-14-H47	BASEPLATE GAP, ANCHOR BOLT WRONG SZ, WLD DETAIL AND UNDSZ	09/20/85	85-0555	
6C-E8D-14-H49	WLD UNDSZ & DETAIL, PLATE GAP, SHIM NOT ON DWG	09/20/85	85-0560	
6C-E8D-14-H92	WLD DETAIL & UNDSZ	09/20/85	85-0563	
6C-E8D-14-H75	WELD HOLE MISSING, WLD DETAIL	09/20/85	85-0564	
6C-E8D-14-H46	WELD, SPACER LOOSE, WLD DETAIL & UNDSZ, THD STAKED	09/20/85	85-0566	USE-48-18 (3)
6C-E8D-14-H17	WLD DETAIL, DIM DISCREP	09/20/85	85-0567	
6C-E8D-14-H37A	LOCKNUTS MISSING, CLAMP DEFORMED, STRUT BOUND UP	09/20/85	85-0568	
6C-E8D-14-H16	STRUT LOCKED, PIN-PIN NOT ON DWG, DIM PROBLEMS, WLD UNDSZ	09/20/85	85-0570	USE 48 18 (3)
6C-E8D-14-H318	WLD UNDSZ, LOCKNUT MISSING, THD STAKED, STRUT BOUND UP	09/20/85	85-0571	
6C-E8D-14-H34	ANCHOR BOLT MISSING, ANCHOR SZ, BASEPLATE GAP, BASEPLATE THICKNESS	09/20/85	85-0577	

14

14

SYSTEM: AUXILIARY FEEDWATER

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SP NUMBER	DISPOSITION
60-E80-14-H42	NO WLD DETAIL ON DWG, BASEPLATE THICKNESS, WLD DETAIL & UNDSZ	09/20/85	85-0578	
60-E80-14-H36	WLD UNDSZ, THD STAKED, WLD DETAIL, TRAPEZIE OFFSET, JAM NUT LOOSE	09/20/85	85-0579	USE-A8-18 (3), REWORD-TIGHTEN JAM NUT (4)
60-E80-14-H25A	LOCKNUT MISSING, ANCHOR IN CONTACT W/CONDUIT, WLD DETAIL	09/21/85	85-0597	
60-E80-14-H31	WLD DETAIL & UNDSZ	09/21/85	85-0601	USE-A8-18 (3)
60-E80-14-H60	WLD UNDSZ	09/21/85	85-0602	USE-A8-18 (3)
60-E80-14-H74	THD STAKED, ROD END BUSHING JAMMED	09/21/85	85-0606	
60-E80-14-H76	THD STAKED, LOCKNUT LOOSE, CLAMP LOOSE	09/21/85	85-0607	
60-E80-14-H45	SPACERS WELDED, NO JAM NUTS	09/21/85	85-0608	USE-A8-18 (3)
60-E80-14-H25	NO LOCKNUT, THD STAKED, STRUT CLAMP MIS-ALIGNED	09/21/85	85-0609	USE-A8-18 (3), REWORK-ADJUST CLAMP (4)
60-E80-14-H26	NO WSHR, WLD DETAIL, THD ENGAGEMENT, CLEARANCE	09/21/85	85-0610	
60-E80-14-H24	NO LOCKNUT, THD STAKED, REAR BRACKET BUSHING MISSING	09/21/85	85-0614	
60-E80-14-H87	WLD UNDSZ	09/21/85	85-0615	USE-A8-18 (3)
60-E80-14-H80	SHIMS BEHIND BASEPLATE, WLD DETAIL & UNDSZ, UNDERCUT	09/21/85	85-0616	
M-1114-H45	DIMENSION, WLD DETAIL, NO LOCKNUT	09/27/85	85-0626	USE A8 18 (3)
60-E80-14-H81	WLD DETAIL & UNDSZ	09/23/85	85-0631	USE A8 18 (3)
60-E80-14-H83	WLD DETAIL & UNDSZ	09/23/85	85-0632	
60-E80-14-H89	THD STAKED	09/23/85	85-0633	USE-A8-18 (3)
60-E80-14-H86	WLD DETAIL	09/23/85	85-0634	USE-A8-18 (3)
60-E80-14-H90	SHIM NOT ON DWG	09/23/85	85-0635	
60-E80-14-H85	THD STAKED, SHOP WLD UNDSZ, BRACE NOT ON BOM	09/23/85	85-0636	USE-A8-18 (3)

DAVIS - BESSIE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
60-E80-14-H84	THD STAKED, WLD DETAIL	09/23/85	85-0637	USE-48-18 (3)
6A-H80-272-H1	THD STAKED, SPACER TACKED, WLD DETAIL	09/23/85	85-0639	USE-48-18 (3)
60-E80-14-H64	BASEPLATE GAP, SUPPORT MOD NOT ON DWG	09/23/85	85-0640	
6A-H80-22-H4	THD STAKED, PLATE GAP	09/23/85	85-0642	USE-48-18 (3)
6A-H80-272-H2	JAM NUT LOOSE, THD STAKED	09/23/85	85-0643	USE-48-18 (3), REWORK-TIGHTEN NUT (4)
60-E80-14-H78	WLD DETAIL	09/23/85	85-0645	
60-E80-14-H77	HILTI BOLT VS TAP BOLT ON DWG, WLD DETAIL	09/23/85	85-0646	
60-E80-14-H88	WLD DETAIL, PLATES NOT ON DWG, INTERNAL DWG DISCREP	09/23/85	85-0647	
60-E80-14-H72	WLD DETAIL, BASEPLATE GAP	09/23/85	85-0648	
60-E80-14-H79	JAM NUT MISSING, WLD UNDSZ & DETAIL	09/23/85	85-0649	
M-1114-H21	THD ENGAGEMENT, BOLT GAP, DIMENSIONS, SPACER MISSING, NO LOCKNUT	09/23/85	85-0651	
60-E80-14-H65	THD STAKED, THD ENGAGEMENT, BENT LOAD BOLT	09/23/85	85-0652	
60-E80-14-H27	TAP BOLT MISSING, PLATE GAP	09/23/85	85-0653	
60-E80-14-H59	PLATE GAP, WLD SZ, SHIM NOT ON DWG, BOM QUANTITY DISCREP	09/23/85	85-0654	USE-48-18 (3)
41-H80-35-H13	THD STAKED, JAM NUT MISSING, PLATE GAP	09/24/85	85-0667	USE-48-18 (3)
41-H80-35-H9	PLATE THICK, DIMENSION, WLD DETAIL	09/24/85	85-0668	USE-48-18 (3)
6A-H80-272-H3	WLD DETAIL & UNDSZ, DIMENSION, JAM NUT LOOSE	09/24/85	85-0669	USE-48-18 (3)
6A-H80-22-H3	DIMENSION, WLD NOT ON DWG, CLEARANCE, WLD DETAIL	09/24/85	85-0670	
A-213	WLD UNDSZ, WSHR6 UNDER NUT	09/24/85	85-0671	
6A-H80-22-H6	BOLT & SPACER LOOSE, NO LOCKNUT, THD STAKED, WLD NOT ON DWG, WLD DETAIL	09/24/85	85-0672	
6A-H80-22-H7	WLDG NOT PER DWG, THDS STAKED, LOCK NUTS MISSING, CONG CRACKED	09/25/85	85-0676	USE 48 18 (3)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
6A-HBD-272-H6	BASEPLATE GAP, WLD & DIMS NOT PER DWG	09/25/85	85-0687	
6A-HBD-272-H4	DIM NOT PER DWG, PIPE CLAMP, THDS STAKED, SPRING CAN DAMAGED	09/25/85	85-0701	USE AS IS (3)
6A-HBD-272-H5	THDS STAKED, WLDs & DIM & ITEM #4 NOT PER DWG	09/25/85	85-0703	USE AS IS (3)
6A-HBC-35-H55	WLDs & DIM NOT PER DWG, BOLT SPACING VIOLATION	09/26/85	85-0720	USE AS IS (3)
A-216	BASEPLATE GAP UNACC, ANCHOR BOLT INSTALLED @ ANGLE	09/26/85	85-0722	
6A-HBD-22-H5	THDS STAKED, DIMEN & WELD NOT PER DWG, GAPS & SPACING UNACC, MISSING NO. ON BOM	09/26/85	85-0737	
6A-HBD-22-H2	DIMEN & WELDS NOT PER DWG, CONC SPALLED.	09/26/85	85-0740	
6A-HBC-35-H52	DIMEN, WELDS, & BOLTS NOT PER DWG.	09/26/85	85-0746	
A-217	BOLTS NOT PER DWG, BASEPLATE GAP UNACC.	09/26/85	85-0748	
6A-HBD-24-H2	MISSING WASHERS, WELDS NOT PER DWG, DAMAGED MEMBERS.	09/27/85	85-0761	USE AS IS (3)
6A-HBD-22-H8	BASEPLATE GAP UNACC, WELDS NOT PER DWG, THDS STAKED.	09/27/85	85-0766	
6A-HBD-24-H1	DIMEN & WELDS NOT PER DWG, BASEPLATE GAP UNACC.	09/28/85	85-0785	
6A-HBC-35-H34	WLDs NOT PER DWG, CONCRETE BROKEN OUT, ANCHOR BOLTS NOT PER DWG	10/03/85	85-0806	USE AS IS (3)
6A-HBC-35-H32	WLDs NOT PER DWG, THDS STAKED, DIM NOT PER DWG	10/03/85	85-0807	
6A-HBC-35-H33	WLDs NOT PER DWG, THDS STAKED, DIM NOT PER DWG	10/03/85	85-0808	
M-1114/H9	C-C SPACING, UNDERBITE WELD, SPACER MISSING, "S" DIM.	10/03/85	85-0851	
M-1114/H31	BOLT SPACE, CLEARANCE, DIMENSIONS, WELD DETAIL	10/03/85	85-0852	
M-1114/H35	PLATE GAP, DIMENSIONS, WELD	10/03/85	85-0853	

14

14

14

DAVIS - BESSIE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-1114/H74	CLEARANCE, BOLT SPACING	10/03/85	85-0854	
M-1114/H12	ANCHOR BOLT TORQUE, PLATE GAP	10/03/85	85-0835	USE AS IS (3), REWORK-REMOVE WOOD SHIM (4) 14
M1114/H10	DIMENSIONS, WELD DETAIL & UNDERSIZE	10/03/85	85-0856	
M-1114/H14	PLATE GAP, DIMENSIONS, CLAMP BOLT LOOSE, LOCKNUT LOOSE	10/04/85	85-0867	
M-1114/H39	PLATE GAP, STRUT ANGLE	10/04/85	85-0888	
M-1114/H44	WELD DETAIL, PIN-PIN DIM.	10/04/85	85-0889	
6A-HBC-35-H31	B/M PROBLEMS, WELD DETAIL, DIMENSIONS, CLEARANCE, WASHER MISSING, PLATE GAP	10/05/85	85-0913	
6C-E3D-14-H28	WELDS, LUG CLEARANCES	10/16/85	85-1226	14

SECTION 3.0

LOW PRESSURE INJECTION SYSTEM

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
308-1-413	ROD END ATTACHMENT LOAD PIN IS LOOSE	08/21/85	85-0139	
308-FCB-2-H1	MISSING JAM NUT, R CLAMP TWISTED, THDS ON BOLTS UPSET	08/30/85	85-0148	USE-48-18 (3)
308-CCB-6-H9	PART OF SUPPORT FLANGE REMOVED, WELD UNDERSIZE, GAP CLEARANCE.	09/02/85	85-0159	
308-CCA-4-H4	LOOSE ANCHORBOLT, ROD END BINDING, INTERFERENCE WITH ADJACENT SUPPORT,	09/02/85	85-0161	USE 48 18 (3)
308-CCB-6-H10	ATTACHMENT NOT PER DWG., WELD UNDERSIZE, SHIMMER HEAD BOLT LOOSE	09/02/85	85-0162	
308-CCB-6-H2	BOLTS STAKED IN PLACE	09/02/85	85-0163	USE-48-18 (3)
308-CCB-6-H4	GREASE FITTINGS CUT OFF OF ROD ENDS	09/02/85	85-0164	USE-48-18 (3)
308-CCB-6-H11	WELD UNDERSIZE	09/02/85	85-0166	USE-48-18 (3)
308-CCA-4-H2	NON STANDARD PIPE CLAMP, MISSING WELD, SUPPORT INTERFERES W/ANOTHER SUPPORT.	09/03/85	85-0166	USE-48-18 (3)
308-CCA-4-H3	NON-STD PIPE CLAMP, MISSING 1/2 UNDERSZ WLDG, EDGE DISTANCE LESS THAN MINIMUM.	09/03/85	85-0176	USE 48 18 (3)
308-CCB-5-H4	UNDERSIZE WELD, AS-BUILT WELD TYPE NOT PER DWG.	09/03/85	85-0178	
308-CCB-5-H401	BOLTS HAVE ONE NUT ONLY CLEARANCE GAP AND SHIMS INACCURATE.	09/03/85	85-0179	
308-CCA-4-H10	NON-STD COMPS 3/4" BLTS VS SPEC'D 5/8" MEMBER LONGER THAN DESIGN WELD UNDERSZ	09/03/85	85-0184	USE 48 18 (3)
308-CCB-6-H8	WELD UNDERSZ AS-BUILT MEMBER LENGTH AND ANGLE NOT PER DWG.	09/03/85	85-0186	USE-48-18 (3)
308-CCA-6-H6	BOLT DOES NOT HAVE FULL THREAD	09/03/85	85-0189	USE-48-18 (3)
308-CCB-6-H6	WELD DETAIL MISSING FROM DWG SHIMMER ELEVATION INCORRECT	09/03/85	85-0190	USE 48 18 (3)
308-CCA-4-H9	POOR QTY WLDG NON-STD COMPONENTS USED MEMBER LOCATIONS INACCURATE.	09/03/85	85-0191	

14

14

14

14



REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BA NUMBER	DISPOSITION
37B-CCB-6-H7	WLD UNDER WLD DTL NOT PER DWG MISSNG WLDs BASEPLATE GAP CLRNC GAP NOT PER DWG	09/07/85	85-0192	USE AS IS (3)
37B-CCB-6-H3	ANCHORS HAVE > 2 WASHERS	09/04/85	85-0195	USE-AS-IS (3)
37B-CCA-6-H7	HTLTIES W/O WASHERS, GAPS IN BASEPLATE, LOWER BASEPLATE NEEDS GROUT	09/04/85	85-0197	USE-AS-IS (3)
37B-CCB-2H6	NO WLDs NEEDED VS ACTUAL WELDS SWAY STRUT HAS NO MOVEMENT	09/04/85	85-0211	
37C-CCA-4-H601	SHIM PLATE SOULGED, EXCESSIVE GAP, GAP COCKED	09/04/85	85-0214	
37B-HCB-11-H3	WASHERS MISSING, SWAY STRUT DOES NOT ROTATE	09/07/85	85-0273	
37A-BCB-8-H3	BASEPLATE GAP, BUSHING BINDING, LOCATION DIMENSION NOT PER DWG	09/10/85	85-0309	USE-AS-IS (3), REWORK-ADJUST CLAMP (4)
37B-BCB-10-H29	THDS STAKED, 1/8" DIM INCOR, INCORRECT SHUDBER ID, SHUDBER INSTALLED AT ANGLE	09/10/85	85-0315	USE-AS-IS (3) REWORK-ADJUST CLAMP (4)
37B-BCB-10-H28	BOLTS DOUBLENUTTED W/THD DAMAGE, MISSING WELD ON SADDLE	09/10/85	85-0316	
A-164	NUTS DO NOT HAVE FULL ENGAGEMENT	09/10/85	85-0322	USE-AS-IS (3)
37A-BCB-8-H5	NO LOCKNUT, WELD DETAIL	09/12/85	85-0362	USE-AS-IS (3)
37B-BCB-10-H9	WLD NOT PER DWG, JAM NUT THDS STAKED, BUSHING BOUND UP	09/17/85	85-0442	USE-AS-IS (3)
37B-BCB-10-H6	BASEPLATE GAP EXCEEDS REQD, WLDs NOT POSS PER DWG, U BOLT THDS STAKED	09/17/85	85-0443	
37B-BCB-10-H1	WLDs NOT POSS PER DWG, JAM NUTS THDS STAKED, BUSHINGS BOUND UP	09/17/85	85-0444	USE-AS-IS (3)
37B-BCB-10-H14	JAM NUTS THDS STAKED, SWAY STRUT BUSHING BOUND UP	09/17/85	85-0445	USE-AS-IS (3)
37B-BCB-10-H13	JAM NUTS MISSING, WLD ONE SIDE VS PRESENT ALL-ROUND	09/17/85	85-0446	USE-AS-IS (3)
37B-BCB-10-H15	WASHER & JAM NUTS MISSING	09/17/85	85-0447	USE-AS-IS (3)

REV. 1A

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
33B-60B-10-H16	ITEM #4 WELD NOT PER DWG	09/17/85	85-0448	USE-48-19 (3)
33B-60B-10-H8	JAM NUTS MISSING, THDS STAKED	09/17/85	85-0449	USE-48-18 (3)
33B-60B-10-H17	JAM NUTS MISSING, THDS STAKED	09/17/85	85-0452	USE-48-18 (3)
33B-60B-10-H12	WLD NOT PER DWG	09/17/85	85-0454	USE-48-18 (3)
33B-60B-10-H7	WLD UNSZ, WLD NOT PER DWG	09/17/85	85-0455	USE-48-18 (3), REWORK-REMOVE ARC STRIVE (4)
33B-60B-10-H18	NO JAM NUT, THD STAKED	09/17/85	85-0457	USE-48-18 (3)
33B-60B-2-H5	JAM NUTS MISSING, BUSHING SOUND UP	09/17/85	85-0458	USE-48-18 (3)
33B-60B-10-H5	JAM NUTS MISSING, SPACER BOLT LOOSE, BASEPLATE GAP EXCEED REQS	09/17/85	85-0459	USE 48 18 (3), REWORK-TIGHTEN BOLT (4)
33B-60B-10-H4	JAM NUTS MISSING, THDS STAKED, BASEPLATE GAP EXCEED REQS	09/17/85	85-0477	USE-48-18 (3)
33B-60B-10-H18	JAM NUTS MISSING, THDS STAKED	09/17/85	85-0547	
33B-60B-2-H2	WLD UNSZ, NO JAM NUTS, THD STAKED, PIPE CLAMP MOVED, SWAY STRUT BUSHING SOUND	09/18/85	85-0500	USE-48-18 (3), REWORK-ADJUST CLAMP (4)
33B-60B-2-H4	JAM NUT MISSING, THD STAKED, STRUT BUSHING SOUND	09/18/85	85-0501	USE-48-18 (3)
33B-60B-2-H3	RED HEADS VS WEJ-ITS, FLARE BEVEL VS FILLET WELD, WLD NOT PER DWG	09/18/85	85-0505	USE-48-18 (3)
33B-60B-2-H1	THDS STAKED, LUG WLD & JAM NUTS MISSING	09/18/85	85-0516	USE-48-18 (3)
A-040	HILTI INSTALLED VS WEJ-ITS ON DWG	09/20/85	85-0546	
33B-60B-1-H4	WLD UNSZ, WEHRS MISSING, DIMENSION DISCREP	09/20/85	85-0556	USE 48 18 (3)
33B-60B-1-H38	THD STAKED, DIMENSION	09/20/85	85-0557	USE 48 18 (3)
33B-60B-1-H10	DIMENSION, THD STAKED	09/20/85	85-0558	USE-48-18 (3)
33B-60B-1-H6	NO WEHR, THD STAKED, CLAMP BOLT LOOSE, DIMENSIONS	09/20/85	85-0559	USE-48-18 (3), REWORK-TIGHTEN NUT (4)
33B-60B-1-H8	CLEARANCE, EXTRA WLD, WLD UNSZ	09/20/85	85-0569	

14

14

14

DAVIS - BEESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/CR NUMBER	DISPOSITION
33C-BCB-10-H20	NO JAM NUTS, THD STAKED	09/20/85	85-0572	USE-46-18 (3)
33C-BCB-10-H21	NO JAM NUTS, THDS STAKED	09/20/85	85-0573	USE-46-18 (3)
33C-BCB-10-H23	WLD UNDSZ	09/20/85	85-0574	
33C-BCB-7-H1	DIMENSIONS, WLD DETAIL, PIPE CLAMP LOOSE	09/20/85	85-0580	USE-46-18 (3), REWORK-REPLACE SPACER, TIGHTEN NUT (4)
33B-BCB-1-H7	WEAR ON WELD, WLD UNDSZ, WSHRS MISSING, PLATE GAP, DIMENSIONS	09/20/85	85-0583	
33B-BCB-1-H7	DIMENSIONS, SPACERS TACKED, THD STAKED	09/20/85	85-0587	
33B-BCB-1-H9	WLD UNDSZ	09/20/85	85-0588	USE-46-18 (3)
33A-BCB-4-H6	PLATE GAP, WLD DETAIL & UNDSZ	09/21/85	85-0593	
33B-BCB-1-H6	JAM NUT LOOSE, THD STAKED, DIMENSION	09/21/85	85-0595	
34-HCB-4-H10	BOLT SPACING, WLD DETAIL	09/21/85	85-0598	
34-HCB-9-H21	WLD DETAIL	09/21/85	85-0599	USE-46-18 (3)
34-HCB-9-H30	NO WSHR, DIMENSIONS, WLD UNDSZ	09/21/85	85-0600	USE-46-18 (3)
33A-HCB-3-H14	DIMENSION, THD STAKED	09/21/85	85-0603	USE-46-18 (3)
33A-HCB-3-H15	PLATE NOT ON DWG	09/21/85	85-0604	USE-46-18 (3)
33A-HCB-3-H2	INSUFF THD ENGAGEMENT	09/21/85	85-0605	REWORK-ADJUST (4)
33C-BCB-10-H24	NO JAM NUT, THD STAKED	09/21/85	85-0611	USE-46-18 (3)
33C-BCB-10-H25	NO JAM NUT, THD STAKED	09/21/85	85-0612	USE-46-18 (3)
33C-BCB-10-H19	NO JAM NUT, THD STAKED, SPRING SETTING	09/21/85	85-0613	
33B-BCB-1-H13	CLEARANCE	09/21/85	85-0617	
33B-BCB-1-H11	CLEARANCE, WLD DETAIL	09/21/85	85-0618	
33B-BCB-1-H37	NO WSHRS, CLAMP BOLT LOOSE, THD STAKED, WLD UNDSZ	09/21/85	85-0619	USE-46-18 (3)
33B-HCB-1-H39	THREAD STAKED, PIPE CLAMP GAP	09/21/85	85-0620	USE-46-18 (3)

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NOV/85 NUMBER	DISPOSITION
33B-HCB-1-H19	THREAD STAKED	09/21/85	85-0621	USE-48-18 (3)
33B-HCB-1-H16	BOX DIMENSION, TWO STAKED, CONCRETE CRACKED	09/21/85	85-0622	USE-48-18 (3)
33B-HCB-1-H15	NO WSHRS, JAM NUT LOOSE, WLD DETAIL & UNDSZ, STRUT DAMAGE, STRUT BOUND UP	09/21/85	85-0623	
33A-HCB-7-H15	ADDED PLATE NOT ON DWG	09/23/85	85-0625	USE-48-18 (3)
34-HCB-9-H31	MISSING LOCKNUT, TWO STAKED, MISSING WSHR	09/23/85	85-0627	USE-48-18 (3)
A-173	DIMENSIONAL, WLD UNDSZ	09/23/85	85-0628	
34-HCB-9-H16	LOCKNUT MISSING, STRUT BINDING, WLD DETAIL	09/23/85	85-0629	
A-044	BOLT LENGTH & BASEPLATE GAP, WLD UNDSZ & DETAIL, EXTRA PLATE	09/23/85	85-0630	
33B-HCB-1-H14	DIMENSION, WLD DETAIL & UNDSZ, CLEARANCE	09/23/85	85-0638	
A-045	BASEPLATE GAP, ANCHOR BOLT TYPE, DWG DETAIL	09/23/85	85-0641	
33A-HCB-8-H7	ANGLE BEARING, STIFF PLATE ADDED TO ANGLE, TWO ENGAGEMENT	09/23/85	85-0656	
33A-HCB-8-H10	INTERNAL DWG DISCREP, BOLT NOT TIGHT, PLATE GAP	09/23/85	85-0657	
33A-HCB-8-H15	WLD UNDSZ, DIMENSION	09/23/85	85-0658	
33A-HCB-7-H7	PLATE GAP, DIMENSION, PLATE THICKNESS	09/23/85	85-0659	
33A-HCB-8-H9	PLATE GAP, STRUT BOUND, NO WSHRS	09/23/85	85-0660	
33C-HCB-9-H14	JAM NUT STRIPPED, NO JAM NUT, TWO STAKED, SHIM ON CLAMP	09/24/85	85-0662	USE-48-18 (3)
33C-HCB-9-H15	NO JAM NUT, TWO STAKED	09/24/85	85-0663	USE-48-18 (3)
33C-HCB-9-H12	NO JAM NUT	09/24/85	85-0664	USE-48-18 (3)
33C-HCB-9-H17	ADDITIONAL WELD, WLD DETAIL	09/24/85	85-0665	USE-48-18 (3)
33C-HCB-10-H22	JAM NUTS MISSING	09/25/85	85-0673	USE-48-18 (3)
33B-HCB-6-H1	JAM NUTS MISSING	09/25/85	85-0674	USE-48-18 (3)

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33A-HCB-7-H5	EDGE BOLT SPACING VIOLATIONS, ITEM #7 DIM NOT PER DWG	09/25/85	85-0675	
33A-HCB-7-H1	WASERS MISSING, 4 WASERS/BOLT, LOOSE NUT	09/25/85	85-0681	USE AS IS (7), REMOVE-TIGHTEN NUT (4)
33A-HCB-7-H4	WLDG NOT PER DWG	09/25/85	85-0686	USE AS IS (7)
33A-HCB-8-H14	WLDG NOT PER DWG	09/25/85	85-0695	
33A-HCB-8-H9	NO BEARING SURFACE AT BASEPLATE, WLDG NOT PER DWG	09/25/85	85-0696	
33B-HCB-10-H34	CONC CRACKS, WLDG NOT PER DWG, ADD'L SHIMS, GREATER BOLT EDGE DISTANCE	09/25/85	85-0700	
33B-HCB-8-H13	JAM NUTS MISSING & SPACERS, THDS STAKED	09/25/85	85-0702	USE AS IS (7)
33C-HCB-7-H2	GAPS UNACC, DIM NOT PER DWG, SPACER MISSING, ORIENT NOT PER DWG	09/25/85	85-0716	
33B-HCB-73-H21	GAPS UNACC, MISSING JAM NUTS, THDS STAKED, WLD NOT PER DWG	09/25/85	85-0717	USE AS IS (7)
33B-HCB-75-H3	BASEPLATE GAPS UNACC, WLDG NOT PER DWG	09/25/85	85-0718	
34-HCB-9-H17	DIM NOT PER DWG	09/26/85	85-0721	
A-054	BASEPLATE GAPS UNACC, VOID IN CONC, WELDS & DIMEN NOT PER DWG.	09/26/85	85-0736	
33C-HCB-7-H6	DIMEN NOT PER DWG.	09/26/85	85-0734	USE AS IS (7)
33B-HCB-10-H27	MISSING PCN12 & JAM NUTS, THDS STKG, STRUT BOUND, DIMEN NOT PER DWG.	09/26/85	85-0736	
33B-HCB-10-H26	MISSING JAM NUTS, CLAMP NOT SEATED PROPERLY, STRUT BOUND.	09/26/85	85-0739	USE AS IS (7)
A-071	DIMEN NOT PER DWG.	09/26/85	85-0741	
33B-HCB-75-H5	WELDS & CLAMP, NOT PER DWG.	09/26/85	85-0745	
33C-HCB-7-H1	WELDS & DIMEN NOT PER DWG, LOOSE CLEVIS, SHUGGER DAMAGED.	09/26/85	85-0749	
33B-HCB-75-H2	WELDS NOT PER DWG, ARC STRIKES	09/26/85	85-0750	USE AS IS (7), REMOVE-REMOVE ARC STRIKE (4)

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/9R NUMBER	DISPOSITION
175-HCC-25-H4	WELDS NOT PER DWG.	09/26/85	85-0751	USE-46-18 (2)
175-HCC-26-H13	WELDS NOT PER DWG.	09/27/85	85-0759	USE 46 18 (2)
175-HCC-34-H1	DIMEN & WELD NOT PER DWG.	09/27/85	85-0760	
175-HCC-7-H10	DIMEN & WELDS NOT PER DWG.	09/27/85	85-0764	
175-HCC-35 H17	BOLTS NOT PER DWG. LOOSE BOLT. ITEM #4 ON WELD.	09/27/85	85-0766	
175-HCC-35-H1	WELD NOT PER DWG.	09/27/85	85-0768	USE 46 18 (3)
175-HCC-35-H7	WELD NOT PER DWG.	09/27/85	85-0770	USE 46 18 (3)
175-HCC-35-H27	WELD NOT PER DWG.	09/27/85	85-0771	USE 46 18 (3)
175-HCC-35-H22	WELD NOT PER DWG.	09/27/85	85-0772	USE 46 18 (3)
175-HCC-35-H6	WELD NOT PER DWG.	09/27/85	85-0773	USE 46 18 (3)
175-HCC-7-H11	DIMEN & WELDS NOT PER DWG. MISSING WASHERS.	09/27/85	85-0774	USE 46 18 (3)
175-HCC-34-H5A	WELDS & DIMEN NOT PER DWG. MISSING LOCKWIRE. MATERIALS NOT PER BOM.	09/28/85	85-0777	
M-1166-H1	DIMEN NOT PER DWG. THD ENGAGE UNACC.	09/28/85	85-0778	
175-HCC-1-H21	THDS OF ROD NOT VISIBLE. WELDS NOT PER DWG.	09/28/85	85-0779	USE 46 18 (3). REWORK-ADJUST ROD (4)
175-HCC-1-H22	WELDS NOT PER DWG. GREASE FITTINGS DAMAGED. SHUTTER LEAKING.	09/28/85	85-0780	
175-HCC-35-H18	BASEPLATE GAPS UNACC. WELDS NOT PER DWG.	09/28/85	85-0782	
175-HCC-26-H12	WELDS NOT PER DWG.	09/28/85	85-0785	USE-46-18 (3)
174-HCC-8-H1	WELDS NOT PER DWG. BASEPLATE GAP UNACC.	09/28/85	85-0784	
4-084	DIMEN NOT PER DWG.	09/28/85	85-0786	
4-087	WELDS & DIMEN NOT PER DWG.	09/28/85	85-0787	
174-HCC-9-H18	WELDS NOT PER DWG.	09/28/85	85-0789	
175-HCC-7-H5	WELDS & DIMEN NOT PER DWG. IMPROPER SPRING SETTING.	09/30/85	85-0790	

14

14

14

14

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BA NUMBER	DISPOSITION
A-41	WELDS NOT PER DWG. BOLT #7 COULD NOT BE TORQUED, STUDS CUT.	09/30/85	85-0791	
33C-808-7-H4	BOLTS, DIMEN. & WELDS NOT PER DWG. ITEMS NOT PER BOM.	09/30/85	85-0792	
33C-808-7-H10	MISSING WELDS & DIMEN. CLEARANCE NOT PER DWG.	09/30/85	85-0793	
33B-808-1-H17	WELD NOT PER DWG.	09/30/85	85-0794	USE AS IS (3)
33B-808-1-H18	DIMEN & WELDS NOT PER DWG.	09/30/85	85-0795	
33B-808-1-H32	WELDS NOT PER DWG.	09/30/85	85-0797	USE AS IS (3)
33B-H00-34-H2	CLAMP ROTATED, THDS STAKED.	09/30/85	85-0799	USE AS IS (3)
35-H00-27-H20	DIMEN & ITEMS NOT PER DWG.	09/30/85	85-0800	
35-H00-27-H21	WELDS & DIMEN NOT PER DWG.	10/01/85	85-0801	
34-H08-9-H19	WELDS NOT PER DWG. HEAVY CORROSION. DIMENSIONS NOT PER DWG	10/03/85	85-0804	USE AS IS (3), REWORK-REMOVE RUST & PAINT
34-H08-9-H20	WELDS NOT PER DWG & DEFECTS	10/03/85	85-0805	USE AS IS (3)
33B-808-1-H41	WELDS NOT PER DWG	10/03/85	85-0809	
33B-808-1-H2	WSHRS MISSING. BASEPLATE GAP UNACC, WELDS NOT PER DWG	10/03/85	85-0810	
33B-808-1-H1	WELDS NOT PER DWG. BASEPLATE GAP UNACC	10/03/85	85-0811	
33B-808-1-H40	PLATE DIMENSIONS NOT PER DWG	10/03/85	85-0812	USE AS IS (3)
A-222	BASEPLATE NOT ACC. NO THD ENGAGEMENT ON BOLTS. CONCRETE SPALLING	10/03/85	85-0826	
33B-808-10-H31	WSHRS MISSING. WELDS UNDER	10/03/85	85-0827	
33B-808-10-H37	WELDS NOT PER DWG. ITEMS NOT PER BOM	10/03/85	85-0828	
33B-808-10-H33	DIM NOT PER DETAIL	10/03/85	85-0829	USE AS IS (3)
33B-808-1-H23	BOLT STKD & THDS IN SHEAR. LOCK NUT LOOSE, WELDS NOT PER DWG. NO ID ON SPRING CAN	10/03/85	85-0834	
33B-H00-34-H5	BOLTS NOT PER BOM. WELDS NOT PER DWG	10/03/85	85-0836	

14

14

14

14

14

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
33B-HCC-34-H4	FROZEN LOCKNUT, BOLT SPACING, DIM & WLDG NOT PER DWG	10/03/85	85-0837	
33B-GCB-1-H26	WLDG & DIM NOT PER DWG & BOM, THDS STAKED	10/03/85	85-0838	USE AG 18 (3)
33B-GCB-10-H40	BASEPLATE GAP UNACC, ARC STRIKES ON PIPE NEAR WELD	10/03/85	85-0840	USE AG 18 (3), REMARK-REMOVE ARC STRIKES 14
4-167	CONC CRACKED	10/03/85	85-0845	
33B-GCB-1-H36	WSHR MISSING, ITEM #4 NOTCHED	10/03/85	85-0846	USE AG 18 (3) 14
4-211	GUSSET PLATES, WLDG & PIPE SADDLE NOT PER DWG, BASEPLATE GAP UNACC	10/03/85	85-0847	
33B-GCB-10-H36	DIMENSIONS, WELD DETAIL & UNDERSIZE	10/03/85	85-0848	USE AG 18 (3) 14
33C-GCB-7-H12	DIMENSIONS, WELD DETAIL & Y/M PROB.	10/03/85	85-0849	
33B-GCB-10-H41	WELD DETAIL	10/03/85	85-0857	USE AG 18 (3) 14
33B-GCB-10-H38	WELD SIZE, TRUNNION LENGTH & THICK	10/04/85	85-0867	
33B-GCB-10-H42	TRUNNION LENGTH & THICK	10/04/85	85-0868	
4-043	DIMENSION, WELD DETAIL	10/04/85	85-0869	
33B-GCB-10-H1	BOLT NOT INSTALLED, PLATE WELD TO EMBELL, WELD DETAIL & UNDERSZ, ITEM ROTATED	10/04/85	85-0868	
33B-GCB-1-H27	MISALIGNMENT OF 7 DEG., THD STAKED, DIMEN. INCORRECT	10/05/85	85-0923	USE AG 18 (3) 14
33B-GCB-1-H24	BASEPLATE GAP, LOOSE JAMNUT, STRUT @ 6 DEG. ANGLE & IS BOUND UP	10/05/85	85-0924	
33B-GCB-1-H33	MEMBER LOCATION DIMENSIONS INCORRECT	10/05/85	85-0925	
33B-GCB-10-H32	WELDS UNDERSZ	10/05/85	85-0926	
33B-GCB-1-H34	WLD MISSING, THDS STAKED, STRUT BOUND	10/05/85	85-0927	
33B-GCB-1-H25	MISSING WASHERS, WLD DETAIL MISSING, WLD UNDERSZ, SWAY STRUT BOUND/LOOSE	10/05/85	85-0928	
33B-GCB-1-H31	THDS STAKED, MEMBER DIMEN. INCORRECT	10/05/85	85-0929	



REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
328-808-10-H35	DWG DETAILS INCORRECT	10/05/85	85-0970	
A59	LACK FULL AND ENDS., BASEPLATE 34P. MEMBER INSTALLED NOT PER DWG.	10/08/85	85-0963	
330-HCC-129-H2	ANCHORBOLT TYPES CHANGED WELD LENGTH SHORTENED	10/17/85	85-1269	
330-HCC-129-H2	1 13/16" GROUT WELDS UNDERSIZED OR NOT SYMBOL SHOWN, SUPPORT CONFIG. CHANGE	10/17/85	85-1270	
M-1166-H2	WELD UNDERSIZE, WELD TYPE CHANGED	10/17/85	85-1271	
330-HCC-129-H3	INSTALLED AS 4" CHANNELS NOT TYPED, WELDS	10/17/85	85-1274	

SECTION 4.0

HIGH PRESSURE INJECTION SYSTEM

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
330-CCB-2-H47	WELD UNDERSIZE, PIPE CLAMP DETAIL	08/30/85	85-0149	USE-48-18 (3)
330-CCB-2-H40	WELD DETAIL, BOLT LOCATION ON ANGLE INCORRECT	08/30/85	85-0151	USE-48-18 (3)
330-CCB-2-H45	WELDS UNDERSIZE AND CONTAIN AREAS OF UNDERCUT, WELD SIZE MISSING	09/02/85	85-0152	USE-48-18 (3)
330-CCB-2-H43	WELDS UNDERSIZE, WELD SIZE MISSING	09/02/85	85-0153	USE-48-18 (3)
330-CCB-2-H46	PLATE DIM INCORRECT, MEMBER SIZES INCORRECT, BOLT LOCATION NOT PER DWG	09/02/85	85-0154	
330-CCB-2-H44	GAP DIM INACCURATE	09/02/85	85-0155	USE-48-18 (3)
330-CCB-2-H260	MEMBER SIZES INCORRECT, 1 SIDE WELD VS. DESIGNED 3 SIDES.	09/02/85	85-0156	USE-48-18 (3)
330-CCB-2-H36	WELD UNDER SIZE AND CONTAINS AREAS OF UNDERCUT	09/02/85	85-0157	USE-48-18 (3)
330-CCB-2-H41	ONE SIDE WELD VS. 3 SIDES	09/02/85	85-0158	USE-48-18 (3)
A-256	WELD UNDERSIZE	09/02/85	85-0160	USE-48-18 (3)
330-CCB-2-H51	SPRING SETTING QUESTIONABLE	09/02/85	85-0165	USE-48-18 (3)
330-CCB-2-H50	UNDERSIZE WELD, NUT DOES NOT HAVE FULL THREAD ENGAGEMENT.	09/02/85	85-0177	USE-48-18 (3)
330-CCB-2-H37	MISSING WELD SYMBOL, BOLT LOCATION INACCURATE	09/03/85	85-0167	USE-48-18 (3)
330-CCB-2-H38	ANCHORBOLT LOCATION INACCURATE	09/03/85	85-0168	USE-48-18 (3)
330-CCB-2-H72	CLEARANCE GAP INCORRECT, WELD UNDERSIZE.	09/03/85	85-0169	
330-CCB-2-H27	MEMBER SIZE IS INACCURATE, WELDS MISSING	09/03/85	85-0170	USE-48-18 (3)
330-CCB-2-H30	SUP MEMBER LOCAT. IS INACCURATE, WLD MISSING & POOR QTY WLDs, 3 WASHERS/1 BOLT	09/03/85	85-0171	USE-48-18 (3)
330-CCB-2-H49	WELDS UNDERSIZE, NO CLEARANCE & PAINT ON GRAPHITE SURFACE	09/03/85	85-0172	USE-48-18 (3)
330-CCB-2-H48	WELDS UNDERSIZE, WELDS ONE SIDE VS. 3, PAINT ON GRAPHITE SURFACE	09/03/85	85-0173	USE-48-18 (3)
330-CCB-2-H42	WELD UNDER, WELD SI NOT ON DWG, BOLT DOES NOT HAVE FULL THREAD ENGAGEMENT	09/03/85	85-0174	USE-48-18 (3)

14

14

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
A-157	WELD UNDERSIZE. WELD NOT ON DWG.	09/03/85	85-1175	USE AG 17 (3)
33C-CCB-2-H52	LOOSE ANCHOR BOLT. WELDS UNDERSIZE.	09/03/85	85-0180	USE-48-18 (3)
33C-CCB-2-H53	WELDS UNDERSIZE	09/03/85	85-0181	USE-48-18 (3)
33C-CCB-2-H55	ITEM I.D. ON DWG INCORRECT	09/03/85	85-0182	USE-48-18 (3)
33C-CCB-2-H56	CLANCE GAPS NOT PER DWG MISSING WELD NUT DOES NOT HAVE FULL THREAD ENGAGEMENT.	09/03/85	85-0183	USE-48-18 (3), REWORK-SHM (4)
33C-CCB-2-H54	WELDS UNDSZ. STRUCT MEMBER LENGTHS & INSTALLED ANGLES NOT PER DWG.	09/03/85	85-0183	USE-48-18 (3)
33C-CCB-2-H34	FLD WELDS NOT WELDED PER DWG	09/04/85	85-0196	USE-48-18 (3)
A255	UNDERSIZE WELD	09/04/85	85-0199	USE-48-18 (3)
33C-CCB-2-H33	FIELD WELDS UNDERSIZE. FIELD WELDS NOT WELDED PER DWG.	09/04/85	85-0200	USE-48-18 (3)
33C-CCB-2-H35	ANCHORS HAVE > 2 WASHERS. BEARING GAP WRONG DIM.	09/04/85	85-0201	
33C-CCB-2-H29	WELDS UNDERSIZE WELD MISSING	09/04/85	85-0208	USE-48-18 (3)
33C-CCB-2-H28	LOAD FLANGE ANGLED	09/04/85	85-0209	USE-48-18 (3)
33C-HCB-2-H40	SHIMS WRONG. CLEARANCE IS REVERSE OF DETAIL DWG.	09/04/85	85-0213	USE-48-18 (3)
33C-HCB-2-H42	WLD UNDSZ. MEMBER SIZE LARGER THAN DRAWING	09/05/85	85-0215	USE-48-18 (3)
33C-CCB-2-H14	WLD UNDSZ. MEMBERS LONGER THAN SPECIFIED	09/05/85	85-0216	USE-48-18 (3)
33C-CCB-2-H7	BASEPLATE GAP. WLD UNDSZ & NOT PER DWG. 1/2" DROP IN ANCHORS	09/05/85	85-0229	USE-48-18 (3)
33C-HCC-124-H6	BUSHING FROZEN. MISSING JAM NUT. CLAMP BOLT THDS STAKED. WLD NOT PER DWG	09/05/85	85-0230	USE 48-18 (3)
33CCB-2-H8	DIMENSIONS NOT PER DWG	09/05/85	85-0271	USE-48-18 (3)
33C-HCC-124-H4	SPACERS INACCURATE. WLD PROBLEMS	09/05/85	85-0272	USE-48-18 (3)

DAVIS - BESSIE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
33C-CCB-2-H20	WLD UNDSZ	09/05/85	85-0233	
33C-HCC-91-H1	BASEPLATE GAP, WLDs WRONG SIZE	09/05/85	85-0235	USE-48-18 (3)
33C-HCC-124-H5	SPACERS & JAM NUT MISSING, WELD PROBLEMS	09/05/85	85-0236	USE-48-18 (3), REWORK-400 BUSHING SPACERS (4)
33C-CCB-19-H1	NON-STD PIPE CLAMP, BASEPLATE GAP, INTERFERENCE WITH CONDUIT	09/05/85	85-0237	
A-192	WELDS NOT PER DWG	09/05/85	85-0241	USE-48-18 (3)
A-053	BASEPLATE GAPS, WLD UNDSZ, FULL PEN WELD NOT FLUSH	09/06/85	85-0228	
33C-HCB-2-H41	WLDs NOT PER DWG, GROUT CRACKED, WASHERS MISSING	09/06/85	85-0243	USE-48-18 (3)
33C-HCB-2-H37	JAM NUT MISSING	09/06/85	85-0246	USE-48-18 (3)
33C-HCB-2-H39	WLD UNDSZ & DETAILS INCORRECT, VOID IN GROUT	09/06/85	85-0247	USE-48-18 (3)
33C-HCB-2-H38	WLD DETAIL INCORRECT	09/06/85	85-0248	USE-48-18 (3)
33C-CCB-12-H1	BUTT WELD IN LIEU OF FILLET, 2 NUTS INSTALLED PER ANCHORBOLT	09/06/85	85-0251	
33C-CCB-2-H19	BASEPLATE GAP, WLD UNDSZ & INCORRECT DETAIL	09/06/85	85-0253	USE-48-18 (3)
A-046	WELD UNDSZ	09/06/85	85-0254	USE-48-18 (3)
A-048	WELD UNDSZ	09/06/85	85-0255	
A-047	WELD UNDSZ	09/06/85	85-0256	USE-48-18 (3)
A-190	ANCHORBOLTS HAVE 3 WASHERS, BASEPLATE GAPS	09/06/85	85-0257	
33C-HCB-2-H6	NO WASHERS ON TAP BOLTS, 1/2" STUD IN LIEU OF 1/2" TAP BOLT, WLD UNDSZ	09/06/85	85-0258	USE-48-18 (3)
33C-HCC-124-H7	WELD UNDSZ & DETAIL INCORRECT	09/06/85	85-0259	USE-48-18 (3)
33C-HCB-2-H40	WLD UNDSZ	09/06/85	85-0261	
33C-HCC-91-H2	BEAMS WRONG SIZE	09/06/85	85-0268	USE-48-18 (3)
33C-HCC-91-H3	NO WASHERS, BASEPLATE GAP, WLD UNDSZ	09/06/85	85-0269	

14

14

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33C-COB-2-H13	WELD NOT PER DWG	09/07/85	85-0276	
33C-COB-2-H21	SEAM NOT PER DWG	09/07/85	85-0277	USE-43-18 (3)
33C-COB-2-H21	NON STANDARD CLAMP, MISSING JAM NUT, WLD UNDSZ, THDS STAKED, GROUT CRACKED/BROKN	09/09/85	85-0291	
33C-COB-2-H24	WLDs UNDSZ, DETAIL NOT CORRECT, TWO NUTS PER STUD	09/09/85	85-0300	USE-46-18 (3)
A-051	WELDS UNDSZ	09/09/85	85-0305	USE-46-18 (3)
33C-COB-2-H16	DIM NOT ON DWG, MISSING JAM NUTS, NON STANDARD CLAMP, CLEVIS CONTACTING CLAMP	09/09/85	85-0307	USE-46-18 (3), REWORK-INSTALL SPACER (4)
33C-COB-2-H11	WLD UNDSZ, 1/2" TAP BOLTS IN LIEU OF 1/2" STUDS, WLD DETAIL NOT PER DWG	09/10/85	85-0314	USE-46-18 (3)
33C-COB-2-H9	ARC STRIKES PRESENT, WLD UNDSZ, DIM NOT PER DWG	09/10/85	85-0317	
A-050	WLDs UNDSZ	09/10/85	85-0318	USE-46-18 (3)
33C-COB-2-H10	WASERS MISSING, BOLTS IN LIEU OF STUDS (4 IN LIEU OF 6), WLD NOT PER DWG	09/10/85	85-0320	
33C-COB-2-H12	STRUT DIM INCORRECT, THDS STAKED, NON-BTD CLAMP, MISSING JAM NUT & WELD	09/10/85	85-0321	USE-46-18 (3)
33A-OCB-8-H4	MISSING WASHERS, WLD UNDSZ, DIM NOT PER DWG	09/10/85	85-0326	
33A-OCB-8-H2	WLD DETAIL NOT PER DESIGN, MEMBER LOCAT DIM NOT PER DWG	09/10/85	85-0327	USE-46-18 (3)
33A-OCB-8-H6	PIPE CLAMP LOOSE, WLD OVERSI BY 1/8"	09/10/85	85-0328	USE-46-18 (3), REWORK TIGHTEN CLAMP (4)
33A-OCB-8-H11	WLD ALL AROUND VS 2 SIDES	09/10/85	85-0329	USE-46-18 (3)
33C-COB-12-H2	WLD NOT PER DWG, BASEPLATE GAP, LOCKNUTS FROZEN, ITEMS MISSING FROM BOM	09/10/85	85-0331	
33C-COB-19-H3	MEMBER DIM & LOC INCORRECT, WLD DETAILS INCORRECT, WASHERS MISSING	09/10/85	85-0333	
33C-COB-2-H15	NON-BTD CLAMP, JAM NUT MISSING, MISSING WELD	09/10/85	85-0339	

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	WCR OR NUMBER	DISPOSITION
33C-CCB-2-H17	DIVISION, UNDERCUT, HOLE IN MEMBER, WELD DETAIL, NO COCKNUT, NON STD CLAMP	09/11/85	85-0355	
33C-HCC-91-H6	WELD DETAIL	09/11/85	85-0359	USE-48-18 (3)
33C-HCC-91-H6	WELD DETAIL	09/11/85	85-0360	USE-48-18 (3)
33C-HCC-91-H9	WELD DETAIL & UNDERSIZE	09/12/85	85-0365	USE-48-18 (3)
33C-HCC-91-H10	WELD DETAIL, SS HD BOLT VS. HEX	09/12/85	85-0366	USE-48-18 (3)
33C-HCC-91-H8	WELD DETAIL & UND. SIZE	09/12/85	85-0367	USE-48-18 (3)
33C-HCC-91-H7	WELD DETAIL	09/12/85	85-0368	USE-48-18 (3)
33C-HCC-91-H4	WELD DETAIL, BIGGER WELD, HBR ASSEMBLY LOOSE	09/12/85	85-0375	USE-48-18 (3), REWORK-ADJUST (4)
33C-CCB-19-H2	CONC. CHIP, WELD QUALITY, NONSTD CLAMP, NO COCKNUT, DIMENSIONS	09/12/85	85-0377	
33C-HCC-91-H12	ORIENTATION ON DWG, WELD DETAIL & UNDERSIZE, COPING, CLEARANCE	09/12/85	85-0379	USE-48-18 (3)
A-054	PIPE HOLE MADE W/TORCH NOT DRILL, WLOS NOT PER DWG & UNDZ, SUPP NOT PER DWG	09/13/85	85-0388	
33C-HCC-91-H13	WELD DEFECTS	09/13/85	85-0392	USE-48-18 (3)
33C-HCC-91-H14	WLD UNDZ, BASEPLATE SPACING VIOLATION	09/14/85	85-0397	
33C-HCC-91-H15	WLOS NOT PER DWG, CORROSION ON BASEPLATE NUTS	09/17/85	85-0467	
33C-CCB-2-H13A	1/8" DIM NOT PER CATALOG LOCKNUTS & WASHERS MISSING	09/18/85	85-0487	USE-48-18 (3)
33C-CCB-19-H13	HBR BINDING, JAM NUTS MISSING	09/18/85	85-0488	USE-48-18 (3), REWORK-ADJUST (4)
33C-CCB-19-H9	ITEMS REVERSED ON DWG, WLD UNDZ, WLD DETAIL NOT POSS	09/19/85	85-0519	
33C-CCB-19-H11	WLD UNDZ, GAPS, WLD DETAIL MISSING ON DWG, CLEARANCE, NO WASHER	09/19/85	85-0520	
A-055	SADDLE LENGTH, WLD UNDZ, DWG DETAIL DISCREP	09/19/85	85-0521	USE 48 18 (3)

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33C-CCB-2-H1	DIMS. WLD DETAIL, SADDLE LENGTH, DWG REFERENCE	09/20/85	85-0533	
33C-CCB-19-H7	WLD UNDSZ, WLD DETAIL, SHIMS NOT ON DWG, BASEPLATE THICKER THAN DWG	09/20/85	85-0540	
33C-CCB-2-H2	EXTRA GROUT, CLEARANCE, DIMENSION PROBLEMS, NO WSHRS, WLD DETAIL	09/20/85	85-0541	
33C-CCB-2-H5	DIMENSIONS, MISC STRUT DISCREP, WLD DETAIL	09/20/85	85-0547	
33C-CCB-3-H2	DIM DISCREP, WLD DETAIL	09/20/85	85-0552	USE-48-18 (3)
A-56	DIMENSION DISCREP	09/20/85	85-0553	USE-48-18 (3)
A-57	DIMENSION DISCREP	09/20/85	85-0554	
33C-CCB-2-H4	LOCKNUT & WSHR MISSING, WLD DETAIL	09/20/85	85-0561	USE 48 18 (3)
33C-CCB-3-H1	DIM PROBLEMS, WLD DETAILS, ARC STRIKE, BASEPLATE CRACK	09/20/85	85-0576	
33C-CCB-2-H3	WLD DETAIL, DIM PROBLEM	09/20/85	85-0584	
33C-CCB-19-H5	WLD UNDSZ	09/20/85	85-0585	USE-48-18 (3)
33C-CCB-19-H8	WLD UNDSZ DETAIL, PLATE GAP	09/20/85	85-0586	USE 48 18 (3)
33C-CCB-2-H6	DIMENSIONS, THD STAKED, STRUT LACKS MOV'T	09/20/85	85-0589	USE-48-18 (3)
33C-CCB-19-H6	WLD UNDSZ, MAT'L NOT ON BOM	09/21/85	85-0594	
33C-CCB-3-H4	DIMENSION, MORE WELD, THD STAKED	09/21/85	85-0596	USE-48-18 (3)
33C-CCB-2-H23	SHIM DIM, PLATE GAP, WLD DETAIL & UNDSZ	09/23/85	85-0644	
33C-CCB-2-H22	ANCHOR BOLT SPACING WITH OTHER BOLT, DIMENSIONS, PLATE BEARING	09/23/85	85-0650	
33C-CCB-3-H6	WLD DETAIL, DIMENSIONS	09/23/85	85-0655	
31-HCC-36-H9	WELDS NOT PER DWG.	09/23/85	85-0742	USE 48 18 (3)
31-HCC-36-H2	PLATE GAP, WLD DETAIL	09/24/85	85-0666	
31-HCC-36-H5	BOLT SPACING, WELDS & DIMENSIONS NOT PER DWG	09/25/85	85-0679	USE-48-18 (3)

14

14

14



REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION	
31-HCC-36-H6	WLD UNDSZ	09/25/85	85-0680	USE-A8-18 (3)	
31-HCC-36-H3	WGRS MISSING, BASEPLATE GAP UNACC. WLDG PER DWG NOT POSSIBLE	09/25/85	85-0681		
31-HCC-36-H4	WGRS MISSING, ITEMS 2&3 AND DIMENSIONS NOT PER DWG	09/25/85	85-0682	USE-A8-18 (3)	
33C-COB-2-H18	WLDG NOT PER DWG, GAPS UNACC, MISSING WGRS & LOCKNUTS	09/25/85	85-0649	USE A8 18 (3)	14
33C-COB-3-H3	NOT FULL BASEPLATE BEARING, DIM & WLDG NOT PER DWG	09/25/85	85-0705		
31-HCC-36-H10	DIMEN & WELD NOT PER DWG.	09/25/85	85-0709	USE A8 18 (3)	14
31-HCC-36-H8	WLDG & ITEM #3 NOT PER DWG	09/25/85	85-0710	USE A8 18 (3)	
31-HCC-36-H7	BASEPLATE GAP UNACC, ITEM #5 NOT PER DWG	09/25/85	85-0712		
33C-COB-19-H12	WLDG & DIM NOT PER DWG, STRUT BOUND UP, BOLT SPACING VIOLATION	09/25/85	85-0719		
31-HCC-36-H11	BOLT SPAC, THDS, DIL, BRACKETS NOT PER DWG, BASEPLATE GAP UNACC.	09/26/85	85-0723	USE A8 18 (3)	14
31-HCC-36-H12	BOLT SPAC & WELDS NOT PER DWG, THDS STAKED, MISSING LOCK NUTS.	09/26/85	85-0724	USE-A8-18 (3)	
31-HCC-36-H13	WELDS & DIMEN NOT PER DWG, THDS STAKED, MISSING LOCK NUTS.	09/26/85	85-0725	USE-A8-18 (3)	
31-HCC-36-H14	GAP UNACC, DIMEN & WELDS NOT PER DWG, PIN STAKED, STRUT BOUND.	09/26/85	85-0730		
31-HCC-36-H16	WELD NOT PER DWG.	09/26/85	85-0731	USE A8 18 (3)	14
31-HCC-36-H17	WELD & DIMEN NOT PER DWG.	09/26/85	85-0732		
31-HCC-36-H18	WELD & DIMEN NOT PER DWG.	09/26/85	85-0733	USE A8 18 (3), REWORK-REPLACE ROD (4)	14
31-HCC-36-H19	WELDS & DIMEN NOT PER DWG, PINS & THDS STAKED.	09/26/85	85-0735	USE-A8-18 (3)	
31-HCC-36-H18	WELDS & DIMEN NOT PER DWG, 400 L PLATE NOT ON DWG.	09/26/85	85-0736	USE A8 18 (3)	14

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
A-68	WELDS NOT PER DWG, CONC CHIPPED.	09/27/85	85-0762	
31-HCC-36-H20	ABANDONED ANCHORS, WELDS & DIMEN NOT PER DWG.	09/27/85	85-0763	
A-191	GROUT LOOSE, DIMENSIONS, WRAPPER THICK, PLATE THICK	10/04/85	85-0861	
M-1117-H27	DIMENSIONS	10/11/85	85-1116	
M-1117-H26	ADDITIONAL PLATE, DIMENSION	10/11/85	85-1117	
M-1117-H9	DIMENSION	10/11/85	85-1119	
M-1117-H10	ANCHOR BOLT C-C DIMENSION, DIMENSION	10/11/85	85-1120	
M-1117-H11	ANCHOR BOLT C-C DIMENSION, DIMENSION	10/11/85	85-1121	
M-1117-H12	ANCHOR BOLT C-C DIMENSION, DIMENSION	10/11/85	85-1122	
M-1117-H25	TACK WELD, B/M PROBLEM	10/11/85	85-1123	
35-HCC-21-H6	PLATE GAP, DIMENSION	10/11/85	85-1129	
35-HCC-21-H14	PLATE GAP	10/11/85	85-1130	
35-HCC-21-H10	WELD VS TACK ON SHIM	10/12/85	85-1136	
35-HCC-21-H15	WELD DETAIL & SIZE, DIMENSION	10/12/85	85-1137	
35-HCC-21-H9	WELD DETAIL, DIMENSION	10/12/85	85-1138	
35-HCC-21-H12	FL. GAP, WELD DETAIL	10/12/85	85-1139	
35-HCC-21-H11	EDGE DISTANCE, WELD DETAIL, DIMENSION	10/12/85	85-1140	
C-6004-511	DIMENSIONS FOR ANCHOR BOLT LOCATION	10/12/85	85-1144	
35-HCC-75-H8	WELD SIZE	10/12/85	85-1145	
M-1117/H3	DRAWING DETAIL	10/12/85	85-1146	
35-HCC-21-H7	DIMENSIONS, WELD SIZE	10/12/85	85-1147	
M-1117/H5	DIMENSION	10/12/85	85-1148	
M-1117/H7	DIMENSION, C-C BOLT SPACE	10/12/85	85-1149	

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
TS-HCC-21-H6	WELD DETAIL	10/12/85	85-1152	
M-1117/H4	C-C BOLT SPACE, DIMENSION, BOLT DETAIL, CLAMP BOLT LOOSE	10/12/85	85-1153	
M-CCB-11-3-H	MATERIAL & CONFIGURATION --- DETAIL A	10/12/85	85-1154	
M-CCB-11-3-H	MATERIAL & CONFIGURATION -- DETAIL B	10/12/85	85-1155	
M-1117/H6	C-C BOLT SPACE, NO WEEP-HOLD, DIMENSION	10/12/85	85-1156	
31-HCC-75-H6	DIMENSIONS, WELD DETAIL	10/14/85	85-1166	
A-212	FILLET WELD CHANGED TO FLARE BEVEL	10/14/85	85-1167	
A-205	SHIMS UNDER BASE PLATE	10/14/85	85-1168	
35-HCC-21-H16	MEMBER LENGTHS SHORTENED WELD SIZE	10/14/85	85-1170	
A-308	PIPE LOCATION	10/22/85	85-1375	

SECTION 5.0

BORATED WATER STORAGE TANK SUPPLY

(COMMON SUCTION FOR HPI AND LPI SYSTEMS)

DAVIS - BESSIE PIPING & SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33B-603-2-H7	WLD UNDSZ, WLD MISSING, SFR SETTING OFF	09/05/85	85-0219	USE-48-18 (3)
33A-H03-1-H1	ANCHOR BOLTS OFF, BASEPLATE GAPS, JAM NUT NOT INSTALLED	09/05/85	85-0234	USE-48-18 (3)
33B-603-2-H11	WELD NOT PER SPEC	09/05/85	85-0239	
33B-603-2-H10	WLDG UNDERSIZE	09/05/85	85-0240	USE-48-18 (3)
33B-603-2-H8	ITEMS NOT PER DWG, BEAM UNDSZ	09/05/85	85-0242	USE-48-18 (3)
33A-H03-2-H19	ANCHOR BOLTS DEFORMED, BASEPLATE BOWED	09/05/85	85-0262	USE-48-18 (3), REMARK-INSTALL BEVELED WASHERS (4)
33A-H03-2-H18	PIPE TO PLATE WELD INACCURATE	09/05/85	85-0263	USE-48-18 (3)
33B-603-2-H9	WELD UNDSZ, SWAY STRUT BINDING	09/06/85	85-0244	USE-48-18 (3)
33A-H03-2-H20	WLD UNDSZ	09/06/85	85-0250	USE-48-18 (3)
33A-603-4-H3	WASHERS INTERFERE WITH WELD, JAM NUT MISSING	09/06/85	85-0264	
33A-H03-2-H21	WLD UNDSZ	09/06/85	85-0267	USE 48 18 (3)
33A-603-4-H2	ACTUAL WELD VS NO WELD SPECIFIED	09/06/85	85-0272	USE-48-18 (3)
33A-603-4-H1	GAP > 1/8", NO WELD SPECIFIED VS. ACTUAL WELD	09/07/85	85-0275	USE-48-18 (3)
33A-H03-2-H22	WASHERS NOT INSTALLED PER PROC. EDGE DIM NOT PER DWG	09/07/85	85-0278	USE-48-18 (3)
33A-603-4-H5	ROD END BUSHING BIND, WLDG NOT PER DWG	09/09/85	85-0287	USE-48-18 (3)
33A-603-4-H4	THDS STAKED, MISSING JAM NUT	09/09/85	85-0288	USE-48-18 (3)
33A-H03-2-H17	WLDG NOT PER DWG	09/09/85	85-0289	
33A-603-2-H17A	ROD END BUSHING BIND, MISSING JAM NUT, WLD NOT PER DWG, SWAY STRUT INTERFERENCE	09/09/85	85-0290	
33B-H03-3-H12	WLD UNDSZ	09/09/85	85-0295	USE-48-18 (3)
33A-H03-3-H9	3/8" PLATE IN LIEU OF 1/4", WLDG UNDSZ & NOT PER DWG	09/09/85	85-0297	USE-48-18 (3)
33A-H03-3-H6	WLD UNDSZ	09/09/85	85-0298	USE 48 18 (3)

DAVIS - RESSE PIPING / SUPPORTS  
INSPECTOR FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NR/BR NUMBER	DISPOSITION
33A-HCB-2-H17	WLD NOT PER DWG	09/09/85	85-0309	
33A-HCB-2-H33	WLD UNDSZ, SWAY STRUT BINDING, MEMBER DIM INCOR, INTERFERENCE W/OTHER SUPPORT	09/09/85	85-0306	USE-A8-18 (3)
A-037	BOLTS HAVE 3 WASHERS, BASEPLATE GAP, WLD UNDSZ	09/10/85	85-0323	
A-038	BOLTS HAVE 3 WASHERS, BASEPLATE GAP, WLD UNDSZ	09/10/85	85-0324	
33A-HCB-2-H4	NO WASHERS, MISSING JAM NUT, THDS STAKED, DIM NOT PER SPEC	09/11/85	85-0343	
33A-HCB-2-H16	18" DIM NOT PER SPEC, LOCKNUT & JAM NUTS MISSING	09/11/85	85-0344	USE-A8-18 (3), REWORK-TIGHTEN NUTS (4)
33A-HCB-2-H5	18" DIM NOT PER SPEC, THDS STAKED, LOCKNUT MISSING	09/11/85	85-0345	USE-A8-18 (3)
33A-HCB-2-H29	WELD UNDERSIZE	09/11/85	85-0350	USE-A8-18 (3)
33A-HCB-2-H27	PLATE GAP, NO LOCK NUT	09/11/85	85-0351	USE-A8-18 (3)
3A-E80-19-H108	WELD DETAIL & UNDERSIZE, APC STRIKE, UNDERCUT, DIMENSION	09/12/85	85-0369	USE-A8-18 (3)
33A-HCB-2-H38	WELD UNDERSIZE & DETAIL, DIMENSIONS, AND STAKED, FIG 95 ROTATED	09/12/85	85-0371	USE-A8-18 (3)
33A-HCB-2-H9	BASEPLATE GAP, THDS STAKED, WLD UNDSZ	09/14/85	85-0402	USE A8-18 (3)
33A-HCB-2-H44	ANCHOR BOLTS NOT TORQUED, WLD UNDSZ	09/14/85	85-0403	USE-A8-18 (3) REWORK - STAMP HANGER # ON SUPPORT (4)
33A-HCB-2-H12	BASEPLATE GAP, THDS STAKED	09/14/85	85-0404	USE-A8-18 (3) REWORK-ADJUST CLAMP (4)
33A-HCB-2-H11	THDS STAKED, WLD UNDSZ	09/14/85	85-0405	USE-A8-18 (3) REWORK
33A-HCB-2-H15	GROUT THCK NOT PER DWG, WLD UNDSZ	09/14/85	85-0406	
33A-HCB-2-H10	BASEPLATE GAP, WLD UNDSZ & NOT PER DWG	09/14/85	85-0407	USE-A8-18 (3)
33A-HCB-2-H31	NO DWG SPECS ON BASEPLATE, WLD UNDSZ	09/14/85	85-0408	USE-A8-18 (3) REWORK-

DAVIS - 82886 PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33A-HCB-2-H1	ANCHORS NOT PER DWG	09/14/85	85-0409	USE-48-18 (3)
33A-HCB-2-H14	WLD UNDSZ, THDS STAKED	09/14/85	85-0410	USE-48-18 (3)
33A-HCB-2-H30	BASEPLATE GAP, WLD NOT PER DWG	09/14/85	85-0411	USE-48-18 (3)
33A-HCB-2-H26	ITEM UNDSZ	09/14/85	85-0412	
33A-HCB-2-H24	WLD UNDSZ	09/14/85	85-0413	USE-48-18 (3)
33A-HCB-2-H32	WLD NOT PER DWG	09/14/85	85-0415	USE-48-18 (3)
33A-HCB-2-H25	WLD NOT PER DWG	09/14/85	85-0416	USE-48-18 (3) REWORK-REMOVE ARC STRIKE (4)
33A-HCB-2-H3	WHRB & JAM NUTS MISSING, LUGS UNDSZ, THDS STAKED, WLD UNDSZ	09/14/85	85-0417	
33A-HCB-2-H23	ITEM #1 WRONG DIM, SHIMS INSTALLED INCOR, WLD UNDSZ	09/14/85	85-0418	USE-48-18 (3)
33A-HCB-2-H8	THDS STAKED, CLAMP INCOR DIM	09/14/85	85-0419	USE-48-18 (3)
33A-HCB-2-H13	WLD NOT PER DWG & UNDSZ, BASEPLATE GAP	09/14/85	85-0420	

SECTION 6.0

SERVICE WATER SYSTEM



DAVIS - BEBBE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
41-HBB-7-H1	WLDs NOT PER DWG	09/14/85	85-0423	USE-AG-18 (3), REWORK-TIGHTEN (4)
41-HBB-7-H3	DETAILS & ITEMS INCORRECT	09/14/85	85-0424	
41-HBB-7-H2	DETAILS INCORP, LOCK NUTS MISSING, CLAMP MISALIGNED	09/14/85	85-0425	USE-AG-18 (3) REWORK-ADJUST CLAMP (4)
41-HBC-35-H40	WLDs NOT PER DWG, LOOSE JAM NUT	09/14/85	85-0426	USE-AG-18 (3) REWORK-TIGHTEN JAM NUT (4)
41-HBC-35-H39	WLDs NOT PER DWG	09/14/85	85-0427	USE-AG-18 (3)
41-HBC-35-H41	WLDs NOT PER DWG, STRUT IS BOUND	09/14/85	85-0428	USE-AG-18 (3)
41-HBC-35-H36	WLDs NOT PER DWG	09/17/85	85-0462	USE-AG-18 (3)
41-HBB-7-H4	WLD SYMBOL NOT ON DWG, CLEARANCE, WLD DETAIL	09/19/85	85-0501	
41-HBB-7-H5	WLD DETAIL, LOCKNUT MISSING, STRUT BINDING, INSTALLED SECTION VS DWG	09/19/85	85-0533	
41-HBB-7-H6	WLD DETAIL, STRUT BINDING, LOCKNUT MISSING, PLATE THICKNESS	09/19/85	85-0534	
41-HBC-35-H38	WLD DETAIL, BILL OF MAT'L DISCREP	09/20/85	85-0548	USE-AG-18 (3)
A-197	BASEPLATE GAP	09/20/85	85-0575	
41-HBC-35-H50	NO WLD SYMBOL ON DWG	09/20/85	85-0581	USE-AG-18 (3)
A-312	WLD UNDET, PLATE GAP	09/20/85	85-0582	
41-HBC-35-H49	DIMENSION	09/21/85	85-0592	USE-AG-18 (3)
41-HBC-35-H12	THDS STAKED, WLDs NOT PER DWG, BOLTS BENT, ORIENTATION DISCREP ON DWG	09/25/85	85-0676	USE-AG-18 (3), REWORK-REPLACE BOLTS (4)
41-HBC-35-H8	THDS STAKED, WLDs NOT PER DWG	09/25/85	85-0677	
A-141	WEHRS MISSING, BASEPLATE GAP, WLDs NOT PER DWG	09/25/85	85-0684	
41-HBC-35-H3	WEHRS MISSING, BASEPLATE GAP, THDS STAKED	09/25/85	85-0690	USE-AG-18 (3)
41-HBC-35-H2	THDS STAKED	09/25/85	85-0691	USE-AG-18 (3)

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
41-HBC-35-H1	BOLTS INSTALLED IN EMBED PLATE, WLOS UNDER	09/25/85	85-0692	USE AS IS (J)
41-HBC-35-H5	THDS STAKED, WASRS MISSING, ITEM #3 NOT PER DWG	09/25/85	85-0693	USE AS IS (J)
41-HBC-35-H10	WLOS NOT PER DWG	09/25/85	85-0697	USE AS IS (J)
41-HBC-35-H54	THDS STAKED, DIM NOT PER DWG, LOOSE SPACER	09/25/85	85-0714	USE-AS-IS (J)
41-HBC-35-H53	THDS STAKED, CLAMP JAMMED	09/25/85	85-0715	USE-AS-IS (J)
A-198	NO WELD DET.	09/26/85	85-0744	
41-HBC-44-H1	BASEPLATE GAP UNACC.	09/26/85	85-0752	USE-AS-IS (J)
41-HBC-35-H7	WELDS & DIMEN NOT PER DWG, MISSING WASHERS, DAMAGED STEEL MEMBER.	09/26/85	85-0753	
41-HBC-44-H2	DIMEN & WELDS NOT PER DWG.	09/26/85	85-0754	
41-HBC 35-H104	BASEPLATE GAP UNACC, WELD NOT PER DWG.	09/26/85	85-0755	
41-HBC-35-H11	THDS STAKED, DIMEN NOT PER DWG.	09/27/85	85-0765	USE-AS-IS (J)
A-7	WELD ALL-ROUND VS TWO SIDES	09/30/85	85-0781	USE AS IS (J)
41-HBC-46-H52	MEMBER SIZE, WELD DETAIL	10/04/85	85-0868	
41-HBC-47-H53	THD STAKED, DIMENSIONS	10/04/85	85-0870	
41-HBC-47-H10	THD STAKED	10/04/85	85-0871	
A-150	SADDLE PLATE THICK	10/04/85	85-0872	
A-155	SADDLE PLATE THICK, WELD UNDERSIZE	10/04/85	85-0873	
A-151	WELD NOT GROUND & UNDERSIZE	10/04/85	85-0874	
A-152	PLATE SIZE, WELD UNDERSIZE	10/04/85	85-0875	
A-149	SADDLE PLATE THICK	10/04/85	85-0876	
A-150	SADDLE PLATE THICK	10/04/85	85-0877	
41-HBC-47-H52	MEMBER SIZE, WELD SIZE 1/4 DETAIL	10/04/85	85-0878	
A-159	WELD UNDERSIZE	10/04/85	85-0879	

14

14

SYSTEM: SERVICE WATER  
DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BA NUMBER	DISPOSITION
A-156	PLATE DIMENSION, WELD UNDERSIZE	10/04/85	85-0880	
41-HBC-46-H10	THD STAKED	10/04/85	85-0881	
A-160	WELD UNDERSIZE	10/04/85	85-0882	
41-HBC-46-H32	SHIM DETAIL	10/05/85	85-0896	
41-HBC-46-H33	SHIM DETAIL	10/05/85	85-0897	
41-HBC-47-H33	SHIM DETAIL	10/05/85	85-0898	
41-HBC-47-H32	PLATE GAP, 6 BOLTS VS. 10, 2 BOLTS VS. 4, WELD DETAIL & UNDERSZ	10/05/85	85-0899	
41-HBC-46-H34	SHIM DETAIL, WELD DETAIL	10/05/85	85-0900	
41-HBC-47-H34	WELD DETAIL	10/05/85	85-0901	
41-HBC-46-H37	SHIM DETAIL	10/05/85	85-0902	
41-HBC-46-H36	SHIM DETAIL	10/05/85	85-0903	
41-HBC-46-H35	SHIM DETAIL	10/05/85	85-0904	
41-HBC-47-H35	PLATE GAP, WELD DETAIL & UNDERSIZE	10/05/85	85-0905	
41-HBC-46-H25	SHIMS NOT PER SPEC	10/07/85	85-0948	
41-HBC-47-H24	WLD DETAIL NOT ON DWG, EXCESS WLD METAL	10/07/85	85-0949	USE AS IS (3)
41-HBC-46-H24	SHIMS NOT PER SPEC	10/07/85	85-0950	
41-HBC-47-H23	BASEPLATE GAP, WLD MISSING	10/07/85	85-0951	
41-HBC-47-H25	BASEPLATE GAP, SHIMS NOT PER SPEC	10/07/85	85-0952	
41-HBC-46-H50	CLEARANCE WELD DETAIL & UNDERSIZE B/M PROBLEMS	10/07/85	85-0974	
41-HBC-46-H29	SHIM SIZE NOT ON DWG, WLD MISSING ON SHIM	10/08/85	85-0965	
41-HBC-46-H31	SHIM SIZE NOT ON DWG, WLD MISSING ON SHIM	10/08/85	85-0966	
41-HBC-47-H30	SHIM NOT SHOWN ON DWG,	10/08/85	85-0967	

DAVIS - BESSE PIPING / SUPPORT  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR / SF NUMBER	DISPOSITION
41-HBC-46-H30	SHIM SIZE NOT ON DWG. WLD MISSING ON SHIM	10/08/85	85-0968	
41-HBC-47-H15	WLD DETAIL INCORRECT, MEMBER LOCATION NOT PER DWG.	10/08/85	85-0969	
41-HBC-46-H15	SHIM SIZE NOT ON DWG. WLD DETAIL INCORRECT	10/08/85	85-0970	USE 46 18 (3)
41-HBC-47-H16	WELD DETAIL & SIZE CLEARANCE	10/09/85	85-0994	
41-HBC-47-H11	B/M PROBLEM DIMENSIONS WELD DETAIL & SIZE UNDERCUT	10/09/85	85-0986	
41-HBC-46-H28	SHIM DETAIL	10/09/85	85-0989	
41-HBC-47-H27	LUG SIZE DIMENSION	10/09/85	85-0990	
41-HBC-46-H27	SHIM DETAIL	10/09/85	85-0991	
41-HBC-47-H26	WELD DETAIL & SIZE, UNDERCUT, PL. GAP	10/09/85	85-0992	
41-HBC-46-H22	WELD DETAIL & SIZE, DIMENSION	10/09/85	85-0995	
41-HBC-47-H22	WELD DETAIL & SIZE	10/09/85	85-0996	
41-HBC-47-H49	WELD DETAIL, PL. GAP, DIMENSION	10/09/85	85-0997	
41-HBC-46-H49	WELD DETAIL	10/09/85	85-0998	
41-HBC-47-H29	BOLT SPACE WELD DETAIL & SIZE PL. GAP SHIM INSTALLED	10/09/85	85-1005	
41-HBC-46-H26	WELD SIZE SHIM DETAIL LUG SIZE	10/09/85	85-1006	
41-HBC-46-H1	WELD DETAIL	10/09/85	85-1018	
41-HBC-47-H1	WELD DETAIL, CLEARANCES	10/09/85	85-1019	
41-HBC-46-H47	WELD SIZE	10/09/85	85-1039	

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	WCR/BR NUMBER	DISPOSITION
41-HBC-47-H46	WELD SIZE	10/09/85	85-1040	
41-HBC-46-H46	WELD SIZES	10/09/85	85-1042	
41-HBC-47-H45	WELD SIZES	10/09/85	85-1043	
41-HBC-47-H45	WELD SIZES	10/09/85	85-1044	
41-HBC-47-H47	BASE PLATE SHIMS & GAPS, WELDS	10/09/85	85-1045	
41-HBC-47-H7	WELD PROBLEMS	10/10/85	85-1066	
41-HBC-47-H6	WELD PROBLEMS	10/10/85	85-1067	
41-HBC-47-H18	WELD SIZES ON LUGS	10/10/85	85-1068	
41-HBC-47-H19	WELD SIZES	10/10/85	85-1069	
41-HBC-46-H18	WELD MISSING	10/10/85	85-1070	
41-HBC-46-H19	WELDS ON LUGS	10/10/85	85-1071	
41-HBC-46-H20	WELD SIZES & TYPES	10/10/85	85-1072	
41-HBC-47-H21	WELD SIZES	10/10/85	85-1073	
41-HBC-46-H21	WELD SIZES, END OF BEAM CLIPPED	10/10/85	85-1074	
41-HBC-46-H7	CONFLICTING INFORMATION ON WORK WITH DRAWINGS FOR MEM 6 & WELD	10/10/85	85-1077	
41-HBC-47-H4	SHIMS UNDER BASE PLATE	10/10/85	85-1084	
41-HBC-47-H9	WELD SIZE, DIMENSIONS	10/10/85	85-1085	
41-HBC-47-H3	WELD SIZES, DIMENSIONS	10/10/85	85-1086	
41-HBC-47-H51	WRAPPER PLATE THK. INCREASED	10/10/85	85-1087	
41-HBC-46-H4	SHIM DETAIL	10/10/85	85-1092	
41-HBC-46-H13	WELD DETAIL	10/10/85	85-1093	
41-HBC-46-H2	WELD DETAIL, DIMENSION	10/10/85	85-1094	
41-HBC-47-H12	WELD DETAIL	10/10/85	85-1095	

DAVIS - BEGGE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
41-HBC-47-H13	DIMENSION, WELD DETAIL	10/10/85	85-1096	
41-HBC-47-H20	WELD SIZE & DETAIL	10/10/85	85-1108	
41-HBC-47-H17	3 WASHERS ON BOLT, PL. GAP, WELD DETAIL & SIZE	10/11/85	85-1107	
41-HBC-46-H38	MEMBER SIZE, ANCHOR BOLT, PLATE GAP, WELD DETAIL, DIMENSION QUANTITIES VS. B/M	10/15/85	85-1176	
41-HBC-47-H41	SHIM DETAIL	10/15/85	85-1181	
41-HBC-47-H40	DRAWING CONFLICT/ SHIM	10/15/85	85-1182	
41-HBC-46-H40	DRAWING CONFLICT/SHIM	10/15/85	85-1183	
41-HBC-46-H39	SHIM DETAIL, DRAWING CONFLICT/ SHIM	10/15/85	85-1184	
41-HBC-47-H39	SHIM DETAIL, DRAWING CONFLICT/ SHIM	10/15/85	85-1185	
41-HBC-47-H38	SHIM DETAIL, DRAWING CONFLICT/SHIM	10/15/85	85-1186	
41-HBC-46-H44	SHIM DETAIL	10/15/85	85-1187	
41-HBC-47-H43	SHIM DETAIL	10/15/85	85-1188	
41-HBC-47-H42	SHIM DETAIL	10/15/85	85-1189	

SECTION 7.0

CONTAINMENT SUMP -- ECCS SUPPLY

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
37B-HCB-1-H4	WASHERS MISSING, WLOS NOT PER DWG	09/13/85	85-0386	USE-AB-18 (3)
37A-GCB-8-H12	PIPE CLAMP NOT TIGHT, WLD UNDSZ	09/13/85	85-0387	USE-AB-18 (3), REWORK-TIGHTEN (4)
37B-HCB-1-H2	ITEMS NOT PER DWG, NO WASHERS UNDER ANCHOR BOLTS	09/13/85	85-0395	USE-AB-18 (3), REWORK-ADJUST (4)
37C-GCB-7-H7	WLOS NOT PER DWG	09/17/85	85-0456	USE-AB-18 (3)
37C-GCB-7-H9	WLD SYMBOLS NOT SPEC'D VS WLOS PRESENT	09/17/85	85-0463	
37A-GCB-8-H13	ITEM #15 NOT PER DWG	09/17/85	85-0464	USE AB 18 (3)
37C-GCB-7-H8	BASEPLATE UNACC, SWAY STRUT BOUND	09/17/85	85-0476	USE AB 18 (3)
37B-HCB-1-H3	BASEPLATE UNACC BEARING SURFACE	09/17/85	85-0482	USE AB 18 (3)
108-HCC-69-H22	NUT MISSING	09/19/85	85-0515	REWORK-REPLACE NUT (4)
A323	MIN. BOLT SPACING VIOLATION	10/07/85	85-0938	
46-HBB-2-H4	IMPROPER SHIM, UNDSZ & MISSING WLOS, CLR GAP INCORRECT, WLD DETAIL MISSING	10/07/85	85-0939	
46-HBB-2-H1	WLOS UNDSZ, BOLT LOCATION INCORRECT	10/07/85	85-0943	
46-HBB-2-H2	NO WELD SYMBOL	10/09/85	85-0988	



SECTION 8.0

HYDROGEN DILUTION SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
29-HCB-73-H5	JAM NUT MISSING. CLAMP NEEDS REALIGN. BUSHING FREE TO ROTATE	09/19/85	85-0514	
29-HBB-15-H10	ITEMS 1&2 NOT PER DWG. WLDS NOT PER DWG	10/03/85	85-0813	
29-HBB-15-H9	WLDS NOT PER DWG. BASEPLATE GAP	10/03/85	85-0831	
29-HCB-43-H1	WLDS NOT PER DWG. WLD GAPS. SLAG ON WLDS. CAULKING UNDER BASEPLATE.	10/03/85	85-0833	
29-HBB-15-H8	WSHR MISSING, DIM NOT PER DWG	10/03/85	85-0633	
29-HBB-15-H7	DIMENSIONS	10/04/85	85-0863	USE AS IS (3)

SECTION 9.0

PRESSURIZER RELIEF SYSTEM

SYSTEM: PRESSURIZED RELIEF SYSTEM

DAVIS - 60000 PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
30-00A-B-H4	THD STAKED	10/05/85	85-0909	
30-00A-B-H5	PLATE GAP, WELD UNDERSIZE, THD STAKED	10/05/85	85-0910	
30-00C-B-H9	PLATE GROUTED, WELD DETAIL & UNDERSIZE, WASHER MISSING, NO I.D. TAG	10/05/85	85-0911	
30-00C-B-H16	PLATE GROUTED, DIMENSION, WELD DETAIL & UNDERSI. CLAMP BOLT/SPACER LOOSE, THD STK	10/05/85	85-0912	
30-00C-B-H5	WELD DETAIL & UNDERSIZE, CONCRETE SPALLING	10/05/85	85-0914	
30-00C-B-H13	PLATE GROUTED, PLATE GAP, WELD DETAIL & SIZE, FLUID LEAK	10/05/85	85-0919	
30-00C-B-H10	BLT ANGLE, PL. GAP, NO SNAPPING, STRUT BINDING, CL. SPACER BOLT LOOSE	10/05/85	85-0920	
30-00C-B-H6	PL. OVERLAPS CONC., PL GAP & GROUTED, WELD DET. & UNDERSI, THD STKD, LOOSE NUT,	10/05/85	85-0921	
30-00C-B-H4	THDS STAKED, BASEPLATE 6X8 VS 10 X 10, WLOS UNDST	10/07/85	85-0935	
30-00C-B-H3	THDS STAKED, 5/8" HILTI VS. 1/2" WET-IT, WLD MISSING, CLAMP SPACER LOOSE	10/07/85	85-0936	
30-00C-B-H17	MISSING BUSHING WASHERS, LOOSE SPACERS, WLOS UNDST, MIN. THD ENGAGEMENT	10/07/85	85-0941	
30-00C-B-H1	GROUT ALONG BASEPLATE, WLD DETAILS INCORRECT	10/08/85	85-0960	
30-00C-B-H2	BOLT MIN. DIST. VIOLATION, GROUT ALONG BASEPLATE	10/08/85	85-0961	
M1140/H1	BOLT MIN. DIST. VIOLATION, LOOSE JAM NUT, BASEPLATE GAP	10/08/85	85-0964	
30-00A-B-H6	PL. THICK	10/09/85	85-1020	
A-304	WELD DETAIL & SIZE	10/09/85	85-1021	
A-307	WELD SIZE	10/09/85	85-1022	
FBX-M-00B-25-1	MATERIAL CHANGE, WELD ADDED, DIMENSIONS	10/22/85	85-1387	

SECTION 10.0

PRESSURIZER SURGE SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SA NUMBER	DISPOSITION
PSU-H1	BASEPLATE GAP, SPRING LOAD COLUMN MISALIGNED	10/07/85	85-0937	
TA-EBD-19-H154	WLDG UNDSZ, SHIM TACK WELDED	10/07/85	85-0940	
PSU-R1	WLDG UNDSZ, BASEPLATE GP. MISSING ID TAG	10/07/85	85-0942	
PSU-R3	BASEPLATE GAP, WLD UNDSZ	10/08/85	85-0958	
PSU-R2	TAG PL-GAP THREAD STAKED CLAMP BOLT LOOSE	10/09/85	85-1003	

SECTION 11.0

CONTAINMENT SPRAY SYSTEM

DAVIS - BESSIE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	WORKER NUMBER	DISPOSITION
34-HCB-4-H17	BARB NOT PER DWG, ITEM NOT PER DWG, WLDG NOT PER DWG, PIPE BOUSED	10/07/85	85-0814	
34-HCB-4-H21	SUPP NOT PAINTED, WLDG ARE: UNDSZ, NOT POSS, & NOT PER DWG	10/03/85	85-0815	
34-HCB-4-H27	WLDG NOT PER DWG	10/03/85	85-0816	
34-HCB-4-H33	WLDG NOT PER DWG, THOS STAKED	10/03/85	85-0817	
34-HCB-4-H35	WLDG NOT PER DWG	10/03/85	85-0818	USE AS IS (3)
34-HCB-4-H22	ANCHOR BOLTS STAKED, WLDG UNDSZ & NOT PER DWG	10/03/85	85-0819	
34-HCB-4-H34	WLDG NOT PER DWG	10/03/85	85-0820	
30-BCC-8-H6	WGRS INSTALLED INCORR, BASEPLATE GAP GROUTED	10/03/85	85-0821	
30-BCC-8-H7	WLDG UNDSZ, PIPE CLAMP BINDING, BASEPLATE DIM INCORR	10/03/85	85-0822	USE AS IS (3), REWORK-ADJUST CLAMP (4)
34-HCB-4-H5	WLDG NOT PER DWG & NOT POSS	10/03/85	85-0823	
34-HCB-4-H7	WLDG NOT PER DWG	10/03/85	85-0824	
34-HCB-4-H6	WLDG NOT PER DWG & NOT POSS	10/03/85	85-0825	USE AS IS (3)
34-HCB-4-H28	SPACERS TACK WELDED, ITEMS D&S DON'T HAVE FULL THO ENGAGEMENT	10/03/85	85-0830	USE AS IS (3), REWORK-ADJUST RODS (4)
34-HCB-4-H4	WLDG NOT PER DWG & UNDSZ, SLAG ON WLDG	10/03/85	85-0832	
34-HCB-4-H44	PLATE SPE, DIMENSIONS, NO SIGHT HOLE, CLAMP LOCATION, WELDSZ VS. DWG, "3" DIMENSIO	10/03/85	85-0858	
34-HCB-4-H15	WELD DETAIL	10/03/85	85-0859	
34-HCB-4-H16	CLEARANCE, WELD DETAIL & UNDERSIZE	10/04/85	85-0860	
34-HCB-4-10	WELD DETAIL, SLAG	10/04/85	85-0862	
34-HCB-4-H8	WELD DETAIL, BASE METAL REDUCTION, SLAG, UNDSZ, OVERLAP, CLEARANCE	10/04/85	85-0864	
34-HCB-4-H42	WELD DETAIL & SIZE, CLEARANCE	10/04/85	85-0865	
34-HCB-4-H4-WE	LD DETAIL & SIZE	10/04/85	85-0866	USE AS IS (3)

14

14

14

14



DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
34-HCB-4-H29	NO TACK WELD	10/04/85	85-0867	
A-77	CAULKING COVERS GAP	10/04/85	85-0869	
34-HCB-4-H11	ARC STRIKE, WELD DETAIL & UNDERSIZE, CLEARANCE	10/05/85	85-0906	
34-HCB-4-H32	DWG SHOWS NO WELD SIZE, DIMENSIONS, WELD DETAIL, FLUID LEAKAGE	10/05/85	85-0908	
34-HCB-4-H40	WELD DETAIL & SIZE, NO SITE HOLE, TWO STAKED, LOOSE NUT	10/05/85	85-0913	
34-HCB-4-H14	WELD DETAIL & SIZE	10/05/85	85-0916	
34-HCB-4-H30	MEMBER SIZE, WELD DETAIL, CLEARANCE	10/05/85	85-0917	USE AS IS (3)
34-HCB-4-H13	WELD DETAIL & SIZE	10/05/85	85-0918	
34-HCB-4-H20	BASEPLATE 1/2" VS 1", 4 BOLTS VS 6, UNDERSZ MISSING WELDS	10/07/85	85-0934	
34-HCB-4-H19	UNDERSZ WLD, WLD DETAIL NOT ON DWG, MEMBER SIZE INCORRECT	10/07/85	85-0953	
34-HCB-4-H41	WELD DETAIL & SIZE	10/09/85	85-0963	
34-HCB-4-H18	PL. GAP	10/11/85	85-1115	

SECTION 12.0

MISCELLANEOUS WASTE DRAIN SYSTEM

Page No. 1  
10/05/85

SYSTEM: MISC WASTE DRAIN

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/ER NUMBER	DISPOSITION
unidentified	EXTRA HANGER	10/04/85	85-0891	

SECTION 13.0

SPENT FUEL POOL PIPING SYSTEM

Page No. 1  
10/25/85

SYSTEM: SPENT FUEL POOL PIPING

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
unidentified	EXTRA HANGER	10/04/85	85-0892	USE AS IS (3)
A-219	ANCHOR LOCATION	10/04/85	85-0894	

14

SECTION 14.0

MAKEUP WATER TREATMENT SYSTEM

Page No. 1  
10/08/85

SYSTEM: MAKEUP WATER TREATMENT SYSTEM

DAVIS - BESSIE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SP NUMBER	DISPOSITION
10B-HCB-27-H7	HEADHEAD VS. WEJIT WELD DETAIL DIMENSION EXTRA HOLES IN PLATE	10/08/85	85-1004	

SECTION 15.0

PRESSURIZER SPRAY SYSTEM



REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
PS-H7	WELD SIZE, UNDERCUT, PL-GAP	10/09/85	85-1023	
PS-H6	WELD DETAIL & SIZE, PL. GAP, UNDERCUT	10/09/85	85-1024	
PS-H5	PIPE CLAMP	10/10/85	85-1057	
PS-H4	PIPE CLAMP	10/10/85	85-1058	
PS-H21	BASE PLATE GAPS	10/10/85	85-1059	
PS-H20	WELD TYPES, DIMENSIONS, GROUT ADDED	10/10/85	85-1060	
PS-H27	DIMENSIONS FOR PIPE OFFSET	10/10/85	85-1061	
PS-H10	WELD TYPE, BASE PLATE & BOLTS	10/10/85	85-1062	
PS-H9	WELDS, SLAG & GROUT	10/10/85	85-1063	
PS-H8	WELD TYPE & GROUT ADDED	10/10/85	85-1064	
PS-H22	PIPE CLAMP	10/10/85	85-1075	
PS-H27	WELDS & SNUBBER PROBLEMS	10/10/85	85-1076	
PS-H19	BENT ROD, ANCHOR BOLT SPACING	10/10/85	85-1080	
PS-H18	WELD, SNUBBER SETTING, PIPE OFFSET, BASE PLATE	10/10/85	85-1081	
PS-H17	WELDS, PIPE OFFSET, SNUBBER ASS	10/10/85	85-1082	
PS-H1	WELD DETAIL & SIZE, PL. GAP	10/10/85	85-1097	
PS-H2	TORQUE FAILS 1 BOLT, WELD DETAIL, PL. GAP	10/10/85	85-1098	
PS-H3	PL. GAP, WELD DETAIL	10/10/85	85-1099	
PS-H13	GROUT, THREAD ENGAGEMENT, 3 WASHER DN BOLT, PL GAP, WELD SYMBOL	10/10/85	85-1104	
PS-H12	GROUT, WELD SYMBOL	10/10/85	85-1105	
PS-H14	GROUT, MILTI VS. WEJ-IT, WELD SYMBOL	10/10/85	85-1106	
PS-H11	GROUT	10/10/85	85-1107	
PS-H23	WELD DETAIL	10/10/85	85-1110	

DAVIS - BESSIE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
PS-H33	PL. GAP, WELD SYMBOL	10/10/85	85-1111	
PS-H34	MIN. EDGE DIST, GROUTED, THREAD STAKED	10/10/85	85-1112	
PS-H31	GROUT, WELD DETAIL	10/11/85	85-1114	
PS-H35	WLD DETAIL, LOCKNUT LOOSE	10/11/85	85-1118	
PS-H30	C-C ANCHOR SPACING, WLD DETAIL & SIZE	10/11/85	85-1124	
PS-H29	GROUT, WELD DETAIL & SIZE, CLAMP BEARING, SPACER MISSING, GREASE FITTING DAMAGE	10/11/85	85-1125	
PS-H15	WELD SIZE, P-P DIMENSIONS, DIMENSIONS, TAG	10/11/85	85-1126	
PS-H16	DIMENSION, DRAWING NOTE, THREAD ENGAGEMENT, GROUT	10/11/85	85-1127	
PS-H37	DIMENSION, WELD DETAIL, GREASE FITTING DAMAGE	10/12/85	85-1141	
PS-H28	WELD SIZE & DETAIL, GREASE FITTING DAMAGE, EXTRA PLATE	10/12/85	85-1142	
PS-H36	ANCHOR BOLT NO TORQUE, PC GAP, WELD DETAIL & SIZE, BOLT MISSING, GREASE FIT, DAM	10/11/85	85-1143	

SECTION 16.0

REACTOR COOLANT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	WCR/SR NUMBER	DISPOSITION
40-CCB-16-45	THREAD ENGAGE, WELD DETAIL & SIZE, HULTI VS. WEJ-IT, DIMENSIONS	10/12/85	85-1150	
40-CCB-16-41	DIMENSION	10/12/85	85-1151	
40-CCB-16-H2	CLEARANCE, DIMENSION, WELD DETAIL	10/14/85	85-1159	
40-CCB-16-H3	PL. GAP, ANCHOR BOLT NO TORQUE, DIMENSION, WELD DETAIL	10/14/85	85-1160	
40-CCB-16-H4	THREAD STAKED, "W" DIMENSION	10/14/85	85-1161	
40-CCB-16-H8	DIMENSION, WELD DETAIL	10/14/85	85-1162	
A-260	THREAD ENGAGE, WELD DETAIL, DIMENSION	10/14/85	85-1163	
40-CCB-23-H1	BOLT SPACING, WELDS, CLEARANCE DIMENSIONS	10/16/85	85-1224	
40-CCB-16-H7	WELDS, DIMENSIONS	10/16/85	85-1225	
A-261	WELDS, PIPE LOCATIONS	10/16/85	85-1227	
40-CCA-16-H1	BOLT EDGE DISTANCE, WELD SIZE, PLATE SHAPE	10/16/85	85-1235	
40-CCA-16-H2	BOLT EDGE DISTANCE, GROUT THK, OVERSIZE SHIM ADDED, WELDS UNDERSIZED LOG FLAN REV	10/17/85	85-1260	
40-CCB-23-H2H1	LTI BOLTS, INSTALLED, DIM'S SHORTENED CLEARANCES INCREASED	10/17/85	85-1261	
40-CCB-16-H6	IT-2 LENGTH DECREASED, IT-10 SIZE INCR, WELDS UNDERSIZED	10/17/85	85-1262	
M-1113-H3	BOLT SPRING, PIPE STRAP TRIMMED	10/17/85	85-1263	
M-1113-H2	1/8" GAP NOT PER DRAWING	10/17/85	85-1272	
M-1113-H1	STRAP TRIMMED, BASEPLATE WELDED IN LIEU OF 2-BOLTS.	10/17/85	85-1273	
31-CCB-16-H9	BASEPLATE GAPS, WELD UNDERSIZE, MATERIAL SIZE CHANGE	10/18/85	85-1307	
31-CCB-16-H10	BASEPLATE WARPAGE, WELD UNDERSIZE, MATERIAL SIZE CHANGE	10/18/85	85-1308	
M-1113-H7	ANCHOR BOLT SPACING	10/19/85	85-1314	

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	WCR/SR NUMBER	DISPOSITION
M-1113-H9	ANCHORBOLT SPACING & PLATE GAPS	10/19/85	85-1315	
M-1113-H11	1-BOLT IS 3/4" NOT 5/8". BOLT SPACING BASEPLATE GAPS	10/19/85	85-1316	
M-1113-H12	GAP NOT PER DRAWING	10/19/85	85-1317	
M-1113-H13	ANCHOR BOLT SPACING	10/19/85	85-1318	
M-1113-H15	WELD UNDERSIZED	10/19/85	85-1319	
M-1113-H17	BOLT SPACING, WELDS UNDERSIZED, PLATE SIZE NOT PER DRAWING	10/19/85	85-1320	
M-1113-H18	WELDS UNDERSIZED	10/19/85	85-1321	
M-1113-H20	INSTALLATION NOT PER DRAWING, WELD DELETED	10/19/85	85-1322	
M-1113-H21	LOOSE NUT ON U-BOLT	10/19/85	85-1323	
M-1113-H22	INSTALLATION NOT PER DRAWING	10/19/85	85-1324	
31-CCB-23-H4	STRUT "W" INCREASE 1/2" STAKED THD. ON ROD ALL CLAMP THD. ARE STAKED	10/19/85	85-1325	
FSK-M-CCA-3-H1	WELD NOT PER STANDARD DETAIL	10/19/85	85-1327	
FSK-M-CCA-3-2-	REV. PIPE LOC. & CLEARANCE	10/21/85	85-1350	
FSK-M-CCA-3-2-	SUPPORT CONFIGURATION	10/21/85	85-1351	
31-CCA-18-H4	UNDERSIZE WELD, GROUT THICKNESS	10/21/85	85-1352	
31-CCA-18-H8	1-ANCHORBOLT NOT FULL THREAD ENGAGEMENT SPRING CAN SPACING, WELDS, PLATE GAPS	10/21/85	85-1353	
31-CCB-18-H11	HILTI BOLTS NOT WEJ-ITS, WELDS UNDERSIZED, DIM. 'S AND MAT'L LENGTHS	10/21/85	85-1354	
31-CCB-23-H5	CLEARANCE INCREASED, WELD DELETED	10/21/85	85-1355	
31-CCA-18-H13	STRUT "W" DECREASED & DIM. 'S, PLATE SIZE REDUCED 1/4"	10/21/85	85-1356	
31-CCB-23-H3	BOLT SPACING, WELDS UNDERSIZED GROUT THICKNESS	10/21/85	85-1357	

14

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
31-CCA-18-H9	WELD TYPES, SECTION A-A NOT PER DRAWING. BASE PLATE GAPS	10/21/85	85-1355	
31-CCA-18-H12	BOLT EDGE DISTANCE, PIPE LOCATION	10/21/85	85-1359	
31-CCA-18-H12	BOLTS INSTALLED WITH 3-WASHERS. PLATE GAPS, WELDS UNDERSIZED, LOCATING DIM.'S	10/21/85	85-1360	
FB-M-CCA-3-2	BASEPLATE GAPS	10/21/85	85-1361	
M-1113-H32	BOLT SPACING, WELD DELETED	10/21/85	85-1372	
M-1113-H30	ANCHOR BOLT SPACING	10/21/85	85-1373	
M-1113-H26	BOLT SPACING, WELD UNDERSIZED	10/21/85	85-1374	
31-CCA-18-H10	CLEARANCE REDUCED, WELDS UNDERSIZED	10/22/85	85-1388	
31-CCA-18-H11	WELDS UNDERSIZED	10/22/85	85-1389	
31-CCA-18-H5	WELDS UNDERSIZED	10/22/85	85-1390	
31-CCA-18-H6	SHUDDER SETTING	10/22/85	85-1391	

14

SECTION 17.0

QUENCH TANK DRAIN SYSTEM

Page No. 1  
10/25/85

SYSTEM: QUENCH TANK DRAIN

DAVIS - BESSIE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
40-HCB-22-H2	WELD DETAIL	10/14/85	85-1165	
40-HCB-22-H1	ANCHORBOLT SPACING, WELDS, PIPE LOC. DIMENSIONS	10/16/85	85-1204	
A-3FT	ANCHORBOLT, WELDS, DIMENSIONS	10/16/85	85-1205	
40-HCB-22-H3	ANCHORBOLT LOCATION, WELD, GAP DIMENSION	10/16/85	85-1206	



SECTION 18.0

COMPONENT COOLING WATER SYSTEM

DAVIS - BESSIE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
A-124	WELD CHANGES, BOLT SPACING VIOLATIONS AND STIFFENER DIMENSIONS	10/14/85	85-1169	
36-HBB-12-H4	MEMBER LENGTHS AND WELD SIZES AND CONFIGURATIONS	10/14/85	85-1171	
36-HBB-12-H7	DIMENSIONS, WELD DETAIL & SIZE	10/15/85	85-1177	
36-HBB-12-H9	ANCHOR BOLTS, PLATE SIZE DIMENSION	10/16/85	85-1199	
36-HBB-1-H4	BASEPLATE GAPS, MEM. WELDS & DIMENSIONS	10/16/85	85-1209	
A-126	WRAPPER PLATE LENGTH, DRAWING ERRORS	10/16/85	85-1210	
36-HBB-12-H8	ANCHOR BOLTS, WELDS	10/16/85	85-1215	
A-125	WELDS, GROUT MISSING (PARTIAL)	10/16/85	85-1229	
36-HBB-1-H3	WELDMENTS UNDERSIZED	10/16/85	85-1230	
36-HBB-12-H3	WELDS AND CLEARANCE DIMENSION	10/16/85	85-1231	
A-122	BOLT LOCATIONS, WELDS UNDERSIZED, DIMENSIONS	10/17/85	85-1249	
A-335	LOC. DIM.'S WELDS UNDERSIZED BOLT LOC. SUPPORT EL.	10/17/85	85-1268	
36-HBB-4-H204	WELDS UNDERSIZED, PLATES TACK WELDED TO SUPPORT, BASE PLATE GAPS	10/18/85	85-1279	
36-HBB-3-H205	ANCHOR BOLTS W/3-WASHERS, WELDS ARE UNDERSIZE, BASE PLATE GAPS	10/18/85	85-1280	
36-HBB-3-H112	MATERIAL SIZE REDUCED, PLATE GAPS, LOOSE L.NUT	10/18/85	85-1281	
36-HBB-40-H1	WELDS UNDERSIZE & ADDITIONAL WELD	10/18/85	85-1285	
36-HBB-4-H206	WELDS UNDERSIZE, BASE PLATE GAPS, ANCHOR BOLT W/3-WASHERS	10/18/85	85-1286	
36-HBB-3-H106	MATERIAL SIZE DECREASED	10/18/85	85-1291	
36-HBB-3-H203	WELDS UNDERSIZE, PLATES ADDED UNDER CHANNELS	10/18/85	85-1292	
36-HBB-4-H206	WELDS UNDERSIZE	10/18/85	85-1293	

Page No. 2  
10/05/85

SYSTEM: COMPONENT COOLING WATER

DAVIS - BESSIE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
36-HBB-3-H204	WELDS UNDERSIZE, SPACERS ADDED, BOLT SPACING	10/18/85	85-1294	
36-HBB-3-H206	WELDS UNDERSIZED, 1-ANCHOR BOLT NUT BOT. OUT & 3/4" INST. NOT 5/8"	10/18/85	85-1295	
36-HBB-3-H207	WELDS UNDERSIZED, INSTALLED BOLTS ARE 3/4" NOT 5/8" ALL W/3-WASHERS	10/18/85	85-1296	
36-HBB-3-H209	5/8" SPACERS ADDED, WELDS UNDERSIZED, BOLT SPACING	10/18/85	85-1297	
36-HBB-3-H211	MATERIAL SIZE INCREASED, WELDS UNDERSIZED WEST IT-2 NOT PER DRAWING	10/18/85	85-1298	
36-HBB-4-H209	PLATES ADDED, WELDS UNDERSIZED, BOLT EDGE DISTANCE INCREASED	10/18/85	85-1299	
36-HBB-4-H208	BOLT SPACING, WELD DELETED	10/18/85	85-1300	
36-HBB-4-207	WELDS UNDERSIZED	10/18/85	85-1301	
36-HBB-3-H210	PLATES ADDED, WELDS UNDERSIZED, BOLT SPACING, 3-HILTI'S & 1-WEL-IT INST.	10/18/85	85-1302	
36-HBB-3-H201	3-WASHERS ON ANCHOR BOLTS, PLATE GAPS	10/18/85	85-1303	
36-HBB-4-200	MATERIAL CHANGED, WELD UNDERSIZED	10/18/85	85-1304	
36-HBB-4-H202	3-WASHERS ON ANCHOR BOLTS	10/18/85	85-1305	
36-HBB-12-H6	WELD DELETED, PLATE CUT TO AVOID INTF. SNUBBER PLATE & TAG PLAGE DO NOT AGREE	10/18/85	85-1306	
36-HBB-3-H111	MATERIAL SIZE REDUCED, NOT FULL THD. ENGAGEMENT 1-BOLT	10/19/85	85-1328	
36-HBB-4-H214	WELDS UNDERSIZED	10/19/85	85-1331	
36-HBB-4-H217	WELDS UNDERSIZED	10/19/85	85-1332	
36-HBB-3-H219	WELD UNDERSIZED, IT-3 POATED 180 DEGREES	10/19/85	85-1333	
36-HBB-4-H216	WELDS UNDERSIZE	10/19/85	85-1334	
36-HBB-3-H224	WELD SYMBOL MISSING, WELD UNDERSIZED, ANCHOR BOLT SIZE INCREASED	10/19/85	85-1335	

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	WCR/BR NUMBER	DISPOSITION
36-HBB-3-H218	WELD UNDERSIZED, HOLES EXIST IN IT-1, ANCHOR BOLTS TRIMMED	10/19/85	85-1339	
36-HBB-4-215	WASHER PLATE THK. DECREASED, WELD UNDERSIZED, ANCHOR BOLTS TRIMMED	10/19/85	85-1340	
36-HBB-4-H213	3 WASHER ON ANCHOR BOLTS, UNDERSIZE WELDS, WASHER PLATE THK. REDUCED	10/19/85	85-1341	
36-HBB-3-H217	ANCHOR BOLTS NOT PER CATALOG	10/19/85	85-1342	
36-HBB-3-H220	ANCHOR BOLTS TRIMMED, WELDS ARE UNDERSIZE AND NOT PER DRAWING	10/21/85	85-1347	
36-HBB-3-H222	BASEPLATE SIZE INCREASED, WELDS ARE UNDERSIZED	10/21/85	85-1348	
36-HBB-3-H214	BASEPLATE SIZE INCREASED, WELD UNDERSIZED, PLATE ADDED FOR STABILITY	10/21/85	85-1349	
36-HBB-3-H216	WELD NOT ON DRAWING, UNDERSIZED WELD	10/21/85	85-1362	
36-HBB-3-H116	1/2" HILTI'S INSTALLED NOT WEJ-ITS, BOLT-1 TRIMMED, BAR ADDED TO STABILIZE SPT.	10/21/85	85-1364	
36-HBB-4-H211	BOLT WITH NO WASHER, PLATE GAPS, WELDS UNDERSIZED	10/21/85	85-1365	
36-HBB-3-H215	BOLTS NOT PER DRAWING, PLATE GAPS, WELDS UNDERSIZED	10/21/85	85-1367	
36-HBB-4-H210	PLATE GAPS, BOLT TRIMMED, WELDS UNDERSIZED	10/21/85	85-1368	
36-HBB-3-H213	PLATE SIZE INCREASED, WELD DELETED	10/21/85	85-1369	
36-HBB-4-H221	WELDS NOT PER DRAWING & UNDERSIZED	10/21/85	85-1370	
36-HBB-4-H220	WELDS NOT PER DRAWING	10/21/85	85-1371	

SECTION 19.0

STEAM GENERATOR DRAIN SYSTEM

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
M-1147-H7	ANCHOR SPACING, SHIM INSTALLED, EMBED,	10/15/85	85-1170	
M-1147-H4	DIMENSIONS	10/15/85	85-1173	
7-EBB-5-H7	WELD SIZE & DETAIL	10/15/85	85-1174	
M1147-H5	DIMENSION, WELD DETAIL	10/15/85	85-1175	
M1147-H6	DIMENSION	10/15/85	85-1176	
7-EBB-5-H8	THREAD STAKED, BASE PLATE GROUTED, GREASE FITTING DAMAGE	10/15/85	85-1179	
7-EBB-5-H7	NO WASHER, BASE PL. GROUTED, DIMENSION, WELD SIZE, SNAP RING DAMAGED	10/15/85	85-1180	
M1147-H8	ADDITIONAL ANGLE	10/15/85	85-1190	
7-EBB-5-H12	WELDS, GAP	10/16/85	85-1196	
7-EBB-5-H10	ANCHORBOLTS, WELDS, LOOSE CLAMP BOLT	10/16/85	85-1197	
7-EBB-5-H14	WELD SIZE	10/16/85	85-1198	
7-EBB-5-H16	ANCHORBOLT, WELDS, STAKED THREAD	10/16/85	85-1201	
7-EBB-5-H15	ARC STRIKE ON PIPE, WELDS	10/16/85	85-1202	
M-1147-H2	ANCHORBOLT SPACING, ADDED WELD	10/16/85	85-1203	
7-EBB-5-H13	PIN TO PIN, WELDS, CLAMP TO PIPE DIMENSION	10/16/85	85-1206	
7-EBB-5-H17	WELDMENTS UNDERSIZED	10/16/85	85-1211	
M-1147-H1	ANCHORBOLT EMB., BASEPLATE GAPS, DIMENSIONS	10/16/85	85-1212	
M-1147-H9	ANCHORBOLT & BASEPLATE SIZE, WELDS, DIMENSIONS	10/16/85	85-1213	
M-1147-H10	ADDED WELD	10/16/85	85-1214	
7-EBB-5-H18	WELDS UNDERSIZE	10/16/85	85-1216	
7-EBB-5-H11	PLATE GROUTED, WELDS, SNUGGER & CLAMP	10/16/85	85-1218	
M-1147-H13	ANCHORBOLT EMB, WELDS, DIMENSIONS	10/16/85	85-1219	

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-1147-H14	ATTACHMENT LOCATION ON BASEPLATE	10/16/85	85-1220	
M-1147-H12	WELD, BOLT EMB., DIMENSIONS, PLATE SIZE	10/16/85	85-1221	
M-1147-H15	ANCHORBOLT SPACING, WELD, PIPE LOCATION	10/16/85	85-1222	
M-1147-H11	ANCHORBOLT EMB. AND EDGE DISTANCE	10/16/85	85-1223	
7-ESB-5-H4	WELDS, GAP INCREASED	10/16/85	85-1232	
7-ESB-5-H5	WELDS, MATERIAL SIZE	10/16/85	85-1233	
7-ESB-5-H6	WELDS UNDERSIZED	10/16/85	85-1234	
M-1147-H17	BOLT EMB. & LOCATIONS, WELD DETAIL	10/17/85	85-1243	
M-1147-H16	BOLT THREAD ENGAGEMENT & LOCATION DIMENSION & LENGTH	10/17/85	85-1244	
M-1147-H18	WELD TYPE, MEM. LOCATION DIMENSION & LENGTH	10/17/85	85-1245	
7-ESB-5-H27	WELDS UNDERSIZED, LOCATING DIMENSIONS	10/17/85	85-1246	
7-ESB-5-H26	BOLT SIZE, WELD LENGTH, GAPS INCREASED	10/17/85	85-1250	
7-ESB-5-H9	WELDS UNDERSIZE, PIPE CLEARANCES	10/17/85	85-1252	
M-1147-H19	BASE PLATE SIZE, SUPPORT DIMENSIONS, WELD TYPES	10/17/85	85-1253	
7-ESB-5-H33	WELD SYMBOL MISSING, WELDS UNDERSIZE, SUPPORT DIMENSIONS	10/17/85	85-1254	
7-ESB-5-H20	WELD UNDERSIZE, MEMBER LENGTH SHORTENED	10/17/85	85-1256	
7-ESB-5-H21	WELDS UNDERSIZED AND MISSING SYMBOL	10/17/85	85-1257	
7-ESB-5-H74	WELD LENGTH DECREASED	10/17/85	85-1258	
7-ESB-5-H32	WELDMENTS UNDERSIZED	10/17/85	85-1259	
7-ESB-5-H24	W4 INSTALLED INSTEAD OF M4-4 MEM'S WELDS UNDERSIZED, GAPS INCREASED	10/17/85	85-1264	
7-ESB-5-H25	STANCHION LENGTH INCREASED 1/4"	10/17/85	85-1265	
7-ESB-5-H23	W4 INSTALLED INSTEAD OF M4-2 MEM'S WELD UNDERSIZED, MEM. LTH. CLAMP 5 SIX.	10/17/85	85-1266	

Page No. 3  
10/25/85

SYSTEM: STEAM GENERATOR DRAIN

DAVIS - BESSE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
7-EBS-5-H22	W4 INSTALLED INSTEAD OF M4-2 MEM. S WELD UNDERSIZED MEM. LTH. CLAMP 5-DIM.	10/17/85	85-1267	14



SECTION 20.0  
CONTAINMENT BUILDING VENT SYSTEM

SYSTEM: CONTAINMENT BUILDING VENT SYSTEM

DAVIS - BESSIE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 1A

SUPPORT NUMBER	DESCRIPTION	DATE	NUR/SR NUMBER	DISPOSITION
40-HCB-12-H2	MATERIAL CHANGE, WELD, STRUT ANGLE	10/16/85	85-1200	
40-HCB-12-H4	WELD TYPE & SIZE, MEM. LENGTH SHORTENED	10/17/85	85-1247	
40-HCB-12-H7	WELD LENGTH SHORTENED & MEM'S SHORT BOLT LOC.	10/18/85	85-1277	
40-HCB-12-H6	LOC. OF ATT. ON BASEPLATE GAPS, WELDS	10/18/85	85-1278	

14

SECTION 21.0  
REFUELING CANAL SYSTEM

Page No. 1  
10/25/85

SYSTEM: REFUELING CANAL SYSTEM

DAVIS - BESSIE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/CR NUMBER	DISPOSITION
A-049	ANCHOR BOLT SPACING	10/22/85	85-1386	

14

SECTION 22.0  
HANGER LOCATION DISCREPANCIES

SYSTEM HANGER LOCATION DISCREPANCIES

DAVIS - BESSLE PIPING / SUPPORTS  
INSPECTION FINDINGS

REV. 14

SUPPORT NUMBER	DESCRIPTION	DATE	NCR. NR NUMBER	DISPOSITION
33A-908-2-H5	HANGER LOCATION	10/19/85	85-1312	
88C-H00-91-H10	HANGER LOCATION	10/21/85	85-1397	
33C-H00-91-H5	HANGER LOCATION	10/21/85	85-1394	
33C-H00-91-H3	HANGER LOCATION	10/21/85	85-1395	
33C-008-12-H3	HANGER LOCATION	10/21/85	85-1396	
33C-008-12-H1	HANGER LOCATION	10/21/85	85-1397	
HL-1330	HANGER LOCATION	10/21/85	85-1398	
33B-908-10-H18	HANGER LOCATION	10/22/85	85-1381	
33B-908-10-H17	HANGER LOCATION	10/22/85	85-1382	
A-221	HANGER LOCATION	10/22/85	85-1383	
33-008-7-H2	HANGER LOCATION	10/22/85	85-1384	
33A-H08-2-H14	HANGER LOCATION	10/23/85	85-1420	
33A-H08-2-H6	HANGER LOCATION	10/23/85	85-1421	
41-H90-53-H54	HANGER LOCATION	10/23/85	85-1422	
60-650-14-H93	HANGER LOCATION	10/23/85	85-1423	
33C-008-2-H36	HANGER LOCATION	10/23/85	85-1424	
A-255	HANGER LOCATION	10/23/85	85-1425	

14