

Docket No. 50-346

License No. NPF-3


Serial No. 1-589

November 4, 1985



JOE WILLIAMS, JR.
Senior Vice President - Nuclear
(419) 249-2300
(419) 249-5223


Mr. James G. Keppler
Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137



Dear Mr. Keppler:

Enclosed is Revision 15 of the Seismic Category I Piping System Support and Hanger Discrepancies Summary Report for the Davis-Besse Nuclear Power Station Unit No. 1. Toledo Edison is updating this report weekly and submitting it to your office to keep your Staff notified of any new discrepancies, regardless of significance, which are identified during our reinspection of piping system hangers or supports. For historical purposes, this report also continues to list discrepancies for which the associated Nonconformance Report (NCR) or Surveillance Report (SR) has been dispositioned by Engineering.

Very truly yours,


JW:TJB:lah
enclosure

TEO

cc: DB-1 NRC Resident Inspector
D. Danielson, NRC Region III
I. N. Jackiw, NRC Region III

8512060325 851104
PDR ADDCK 05000346
S PDR

NOV 12 1985

IE 27
1/1