

TOLEDO EDISON
DAVIS-BESSE NUCLEAR POWER STATION UNIT NO. 1
SEISMIC CATEGORY I PIPING
SYSTEM SUPPORT AND HANGER DISCREPANCIES

-- SUMMARY REPORT --

REVISION 15
OCTOBER 29, 1985

8512060328 851104
PDR ADOCK 05000346
S PDR

TABLE OF CONTENTS

Dispositioned Footnotes

Section 1.0	Auxiliary Feedwater Pump Turbine Steam Supply Piping System
Section 2.0	Auxiliary Feedwater System
Section 3.0	Low Pressure Injection System
Section 4.0	High Pressure Injection System
Section 5.0	Borated Water Storage Tank Supply System
Section 6.0	Service Water System
Section 7.0	Containment Sump - ECCS Supply System
Section 8.0	Hydrogen Dilution System
Section 9.0	Pressurizer Relief System
Section 10.0	Pressurizer Surge System
Section 11.0	Containment Spray System
Section 12.0	Miscellaneous Waste Drain System
Section 13.0	Spent Fuel Pool Piping System
Section 14.0	Makeup Water Treatment System
Section 15.0	Pressurizer Spray System
Section 16.0	Reactor Coolant System
Section 17.0	Quench Tank Drain System
Section 18.0	Component Cooling Water System
Section 19.0	Steam Generator Drain System
Section 20.0	Containment Building Vent System
Section 21.0	Refueling Canal System
Section 22.0	Hanger Location Discrepancies
Section 23.0	Main Feedwater System

DISPOSITIONED FOOTNOTES

- (1) Meets interim allowables, but not long-term allowables.
- (2) Re-work is necessary to meet long-term allowables.
- (3) Meets long-term allowables.
- (4) Meets long-term allowables, but nevertheless re-work will be completed.

SECTION 1.0

AUXILIARY FEEDWATER PUMP

TURBINE STEAM SUPPLY PIPING SYSTEM

REV. 15

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D RESF IND
EBD-19-H147	SWAY STRUT PULLED FROM WALL	03/01/85	85-0016	Y SJO
A3	LOOSE ANCHOR BOLTS NUTS	03/13/85	85-0018	Y GNF
EBD-19-H34	DEFORMED STANCHION	03/13/85	85-0019	Y GNF
EBD-19-H32	NON-CODE WELD ON WRAPPER PLATE TO PIPING WELD	03/27/85	85-0026	Y SJO
EBD-19-H38	DEFECTIVE MECHANICAL SNUBBER	04/11/85	85-0032	Y SJO
EBD-19-H39	EXCESSIVE LATERAL MOVEMENT OF SUPPORT	04/11/85	85-0032	Y SJO
EBD-19-H144	HYDRAULIC SNUBBER PISTON ROD BROKEN	04/18/85	85-0038	Y SJO
EBD-19-H136	TWELVE (12) ANCHOR BOLTS IN LIEU OF SEVEN (7) SPECIFIED	04/30/85	85-0042	Y GNF
EBD-19-H54	WELD DETAIL INACCURATE	04/30/85	85-0043	Y GNF
EBD-19-H142	LOOSE ANCHOR BOLT NUT	05/01/85	85-0045	Y GNF
EBD-19-H51	WALL INTERFERENCE WITH SUPPORT MEMBER	05/08/85	85-0052A	Y RAA
EBD-19-H132	LOOSE ANCHOR BOLTS, BASEPLATE GAP	05/16/85	85-0019A	Y GNF
EBD-19-H32	LOOSE ANCHOR BOLTS, SNUBBER PIPE CLAMP MIS-ALIGNED, WASHERS MISSING	05/16/85	85-0019A	Y SJO
EBD-19-H28	PIPE SADDLES DEFORMED	05/16/85	85-0019A	Y SJO
EBD-19-H25	SHEARED BOLT	05/16/85	85-0019A	Y SJO
EBD-19-H26	WALL CRACK	05/16/85	85-0019A	Y SJO
EBD-19-H14	SNUBBER PIPE CLAMP MIS-ALIGNED	05/16/85	85-0019A	Y SJO
EBD-19-H135	LOOSE ANCHOR BOLTS, ONE BOLT DID NOT TORQUE	05/16/85	85-0019A	Y GNF
EBD-19-H66	LOOSE ANCHOR BOLTS	05/16/85	85-0019A	Y GNF
EBD-19-H50	RESTRAINT PULLED FROM WALL	05/16/85	85-0019A	Y GNF
EBD-19-H49	SWAY STRUT PULLED FROM WALL	05/16/85	85-0019A	Y GNF
EBD-19-H142	RESTRAINT PULLED FROM WALL	05/16/85	85-0019A	Y GNF
EBD-19-H67	LOOSE ANCHOR BOLTS	05/16/85	85-0019A	Y GNF

REV. 15

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D IND	RESP
EBD-19-H145	SWAY STRUT JAM NUT LOOSE, LOOSE ANCHOR BOLT	05/17/85	85-0067	Y	SJO
EBD-19-H62	SWAY STRUT JAM NUT LOOSE	05/17/85	85-0068	Y	SJO
EBB-2-H20	SUPPORT NOT SHOWN ON HANGER LOCATION DRAWING	05/17/85	85-0069	Y	SJO
EBD-19-H14	SNUBBER PIPE CLAMP MIS-ALIGNED, LOOSE ANCHOR BOLTS	05/17/85	85-0070	Y	SJO

REV. 15

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D RESP IND
EBD-19-H51	ANCHOR BOLT INSTALLED AT AN ANGLE, BASEPLATE GAP	04/30/85	85-0044	Y GNF
EBD-19-H59	BOLTS LONGER THAN SPECIFIED, GROUT 2" THICK IN LIEU OF 1"	05/02/85	85-0046	Y GNF
EBD-19-H59	REMOTE RESERVOIR NOT SHOWN ON DRAWING	05/08/85	85-0048	Y RAA
EBD-19-H51	INCORRECT SPRING SETTING	05/08/85	85-0052	Y RAA
EBD-19-H50	CHIPPED CONCRETE AROUND BASEPLATE	05/08/85	85-0053	Y GNF
EBD-19-H143	FIREPROOFING BROKEN AWAY	05/09/85	85-0054	Y TWH
EBD-19-H147	ANCHOR BOLT INSTALLED AT AN ANGLE	05/09/85	85-0055	Y GNF
EBD-19-H154	SHIM SIZE NOT PER DRAWING	05/09/85	85-0056	Y RAA
EBD-19-H62	FIREPROOFING BROKEN AWAY	05/09/85	85-0057	Y TWH
EBD-19-H60	WRONG SIZE SPRING HANGER	05/09/85	85-0058	Y RAA
EBD-19-H141	BOOT SEAL TORN	05/10/85	85-0059	Y TWH
EBD-19-H58	EXCESSIVE LATERAL MOVEMENT OF SUPPORT	05/10/85	85-0059	Y SJO
EBD-19-H55	BASEPLATE ANCHOR BOLT WASHERS SIZE QUESTIONABLE	05/10/85	85-0059	Y GNF
EBD-20-H1	LOOSE ANCHOR BOLTS NUTS, BASEPLATE GAP	05/16/85	85-0064	Y GNF
A3	BASE PLATE GAP	05/16/85	85-0065	Y GNF
EBD-19-H142	BASE PLATE GAP	05/16/85	85-0066	Y GNF
EBD-19-H144	BASE PLATE GAP	05/16/85	85-0066	Y GNF
EBD-19-H145	BASE PLATE GAP	05/16/85	85-0066	Y GNF
EBD-19-H147	BASE PLATE GAP	05/16/85	85-0066	Y GNF
EBD-19-H70	SWAY STRUT JAM NUT LOOSE	05/21/85	85-0092	Y SJO
EBD-19-H14	ALL THREAD ROD USED IN LIEU OF BOLTS	05/21/85	85-0092	Y GNF
EBD-19-H20	ALL THREAD ROD USED IN LIEU OF BOLTS	05/21/85	85-0092	Y GNF
EBD-19-H38	HANGER LOCATION DRAWING INCORRECT	05/21/85	85-0092	Y SJO
EBD-19-H39	HANGER LOCATION DRAWING INCORRECT	05/21/85	85-0092	Y SJO

REV. 15

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D RESP IND
EBD-19-H132	BOLTS USED NOT REFLECTED ON DRAWING	05/21/85	85-092	Y GNF
EBD-19-H28	CRACKED FIREPROOFING	05/21/85	NA	Y TWH
EBD-19-H29	CRACKED FIREPROOFING	05/21/85	NA	Y TWH
EBD-19-H34	MISSING FIREPROOFING	05/21/85	NA	Y TWH
EBD-19-H35	CRACKED FIREPROOFING	05/21/85	NA	Y TWH
EBD-19-H38	CRACKED FIREPROOFING	05/21/85	NA	Y TWH
EBD-19-H39	CRACKED FIREPROOFING	05/21/85	NA	Y TWH
A221	CRACKED FIREPROOFING	05/21/85	NA	Y TWH
EBD-20-H1	SWAY STRUT PIPE CLAMP MIS-ALIGNED	05/21/85	85-79	Y SJO
EBD-19-H21	TWO (2) BOLTS NOT MARKED FOR TORQUE TEST	05/21/85	85-79	Y GNF
EBD-19-H25	UPPER GUIDE ANGLE BENT	05/22/85	85-0071	Y RAA
EBD-19-H132	FIREPROOFING BROKEN	05/22/85	85-0072	Y TWH
EBD-19-H133	FIREPROOFING BROKEN	05/22/85	85-0072	Y TWH
EBD-19-H13	SWAY STRUT JAM NUT LOOSE	05/24/85	85-0074	Y SJO
EBD-19-H13A	SWAY STRUT JAM NUT LOOSE	05/24/85	85-0074	Y SJO
EBD-19-H15	SWAY STRUT JAM NUT LOOSE	05/24/85	85-0074	Y SJO
EBD-19-H16	SWAY STRUT JAM NUT LOOSE	05/24/85	85-0074	Y SJO
EBD-19-H74	FLASHING MISSING ON INSULATION	05/24/85	85-0074	Y SJO
EBD-19-H19	THREE (3) OF FOUR (4) PINS HAVE NAILS IN LIEU OF COTTER KEYS	05/24/85	85-0074	Y SJO
EBD-19-H20	WASHER MISSING, NO FREE ROTATION ON BUSHING	05/24/85	85-0074	Y SJO
EBD-19-H26	INSUL DMN, STRAPS LOOSE & MISSING	05/24/85	85-0074	Y SJO
EBD-19-H32	SNUGGER PIPE CLAMP MIS-ALIGNED, SNUGGER JAM NUT LOOSE	05/24/85	85-0074	Y SJO
EBD-19-H33	SWAY STRUT ROTATED ON EXTENSION THREADS NOT BUSHING	05/24/85	85-0074	Y SJO

REV. 15

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP D RESP IND
EBD-19-H36	STRAPS LOOSE, INSULATION DOWN, (ALSO H37)	05/24/85	85-0074	Y SJO
EBD-19-H37	CORRESPONDS TO EBD-19-H36 ON 85-0074	05/24/85	85-0074	Y SJO
EBD-19-H133	SWAY STRUT PIPE CLAMP MIS-ALIGNED	05/24/85	85-0074	Y SJO
EBD-19-H65	SWAY STRUT MIS-ALIGNED	05/29/85	85-0082	Y SJO
EBD-19-H10	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H8	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H6	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H66	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H65	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H150	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H67	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H135	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H74	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H21	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H22	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H23	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H24	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H133	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H132	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H131	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H12	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H26	BASEPLATE GAP	06/06/85	85-0090	Y GNF
EBD-19-H72	BASEPLATE GAP	06/06/85	85-0090	Y GNF
A362	BASEPLATE GAP	06/06/85	85-0090	Y GNF

REV. 13

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP D RESP IND
EBD-19-H49	BASEPLATE GAP	06/06/85	85-091	Y GNF
EBD-19-H50	BASEPLATE GAP	06/06/85	85-091	Y GNF
EBD-19-H52	BASEPLATE GAP	06/06/85	85-091	Y GNF
EBD-19-H53	BASEPLATE GAP	06/06/85	85-091	Y GNF
EBD-19-H54	BASEPLATE GAP	06/06/85	85-091	Y GNF
EBD-19-H55	BASEPLATE GAP	06/06/85	85-091	Y GNF
EBD-19-H56	BASEPLATE GAP	06/06/85	85-091	Y GNF
EBD-19-H51	BASEPLATE GAP	06/06/85	85-091	Y GNF
EBD-19-H141	CONCRETE CRACKS	06/06/85	SR85-74	Y GNF
EBD-19-H47	CONCRETE CRACKS	06/06/85	SR85-74	Y GNF
EBD-19-H48	CONCRETE CRACKS	06/06/85	SR85-74	Y GNF
A3	CONCRETE CRACKS	06/06/85	SR85-74	Y GNF
EBD-19-H133	ANGLE NOT WELDED PER DRAWING	07/10/85	85-0092A	Y EJO
EBD 19-H132	WASHERS #1 x #2 DISHED (CONCAVE)	07/11/85	85 0092A	Y GNF

REV. 15

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D RESP IND
EBD-19-H49	ANCHOR BOLTS PULLED OUT	05/14/85	85-0060	Y GNF
EBD-19-H136	ONE INACTIVE BOLT	05/15/85	85-0042A	Y GNF
EBD-19-H49	SWAY STRUT PIPE CLAMP MIS-ALIGNED	05/16/85	85-0093	Y SJO
EBD-19-H47	BASEPLATE ANCHOR BOLT WASHERS NOT SHOWN ON DRAWING	05/16/85	SR85-79	Y GNF
EBD-19-H32	SNUBBER REAR BUSHING NOT FREE TO MOVE	05/16/85	SR85-79	Y SJO
EBD-19-H150	PIPE CLAMP BOLTS LOOSE	05/21/85	85-0092	Y SJO
EBD-19-H67	CLEARANCE GAP ON RESTRAINT NOT PER DRAWING	05/21/85	85-0092	Y SJO
EBD-19-H38	SHIM WELDED TO SUPPORT NOT PER DRAWING	05/21/85	SR85-79	Y SJO
EBD-19-H39	SHIM WELDED TO SUPPORT NOT PER DRAWING	05/21/85	SR85-79	Y SJO
EBD-19-H17	SWAY STRUT END BEARING DOES NOT MOVE FREELY	05/23/85	85-0092	Y SJO
EBD-19-H14	CONCRETE AROUND BASEPLATE IS CHIPPED	05/23/85	SR85-73	Y GNF
EBD-19-H132	CONCRETE CRACKS IN WALL	05/23/85	SR85-73	Y GNF
EBD-19-H67	CONCRETE CRACKS IN WALL	05/23/85	SR85-73	Y GNF
EBD-19-H68	CONCRETE CRACKS IN WALL	05/23/85	SR85-73	Y GNF
EBD-19-H12	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y GNF
EBD-19-H148	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y GNF
EBD-19-H65	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y GNF
EBD-19-H26	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y GNF
EBD-19-H22	CONCRETE CRACK IN WALL	05/23/85	SR85-73	Y GNF
EBD-19-H20	CONCRETE CRACK IN WALL	05/23/85	SR85-77	Y GNF
EBD-20-H1	LOOSE SWAY STRUT JAM NUT	06/05/85	85-0088	Y SJO
EBD-20-H1	BROKEN FIREPROOFING	06/05/85	85-0089	Y TWH
EBD-19-H134	BROKEN FIREPROOFING	06/05/85	85-0089	Y TWH
EBD-19-H18	SWAY STRUT ROTATES ON THREADS	06/06/85	85-0092	Y SJO

REV. 15

SUPPORT NO.	DESCRIPTION	DATE WRITTEN	NCR NO.	DISP'D IND	RESP
EBD-20-H1	LOOSE SWAY STRUT JAM NUT	06/06/85	85-0092	Y	830
EBD-19-H16	SWAY STRUT JAM NUT LOOSE, PIPE CLAMP LOOSE	06/11/85	85-0094	Y	830
EBD-19-H13A	SWAY STRUT EYELET CONTACTS PIPE CLAMP	06/11/85	85-0094	Y	830

DAVIS - BESSIE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
4/04	LOWER RIGHT NUT LOOSE	08/02/85	85-0124	USE-48-18 (1), REWORK-400 2 PLATES AND 2 ANCHOR BOLTS (2)
EBD-19-H131	LEVELING NUTS INSTALLED IMPROPERLY	08/21/85	85-0138	USE-48-18 (3)
3A-EBD-19-H81	NON-STANDARD PIPE CLAMP, SWAY STRUT DIM INACCURATE	09/05/85	85-0220	USE-48-18 (3)
3A-EBD-19-H80	WLDG UNDSZ. BOLT BRACING OFF	09/06/85	85-0249	USE-48-18 (3)
3A-EBD-19-H78	3/8" PLATE IN LIEU OF 1/2", INTERFERENCE WITH DUCT SUPPORT, WLDG UNDSZ	09/06/85	85-0251	USE 48 18 (3)
3A-EBD-19-H79	WLD DEFECTS & UNDSZ	09/07/85	85-0274	USE-48-18 (3)
3A-EBD-19-H134	NO INSPECTION HOLE IN STRUT, NON STD PIPE CLAMP	09/07/85	85-0282	USE-48-18 (3)
3A-EBD-19-H100	3/4" STUD IN LIEU OF RED HD WLDG NOT PER DWG	09/09/85	85-0292	
A-709	LOOSE BOLT	09/09/85	85-0296	USE-48-18 (3)
3A-EBD-19-H103	WLD UNDSZ, MEMBER SIZE INCORRECT	09/09/85	85-0301	USE-48-18 (3)
3A-EBD-19-H129	BASEPLATE GAP, WELDS NOT PER DWG	09/09/85	85-0302	
3A-EBD-19-H102	3/8" PLATE IN LIEU OF 1/2", WLD NOT PER DWG, WLD UNDSZ	09/09/85	85-0303	
3A-EBD-19-H84	WHRFS MISSING, WLDG NOT PER DWG, GROUT BROKEN	09/09/85	85-0304	USE 48 18 (3)
3A-EBD-19-H101	WLDG UNDSZ, WLD NOT PER DWG, MISSING JAM NUTS, THDS STAKED, CLMP TWIST	09/09/85	85-0308	USE-48-18 (3), REWORK-ADJ. CLAMP (4)
3A-EBD-19-H124	MISSING JAM NUT, CHIPPED CONCRETE	09/10/85	85-0310	USE-48-18 (3)
3A-EBD-19-H125	WLDG UNDSZ, WLD DETAILS INCORRECT	09/10/85	85-0311	
3A-EBD-19-H105	THDS STAKED, MISSING JAM NUT, STRUT DIM INCORRECT, WLD UNDSZ.	09/10/85	85-0312	USE-48-18 (3)
3A-EBD-19-H83	DWG INCORRECT & LACKS DIMENSIONS, WLD UNDSZ, WLD DETAILS INCORRECT	09/10/85	85-0313	
3A-EBD-19-H76	NON-STD CLAMP, WLD NOT PER DWG, MEMBER DEFLECTED	09/10/85	85-0319	

DAVIS - BEESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	WCR/SR NUMBER	DISPOSITION
TA-ESD-19-H106	POD END BUSHING BINDING, LOCAL DIM INCOR, WLD 09/10/85 UNOSZ	09/10/85	85-0328	USE-48-18 (7)
TA-ESD-19-H65	POD EYE BUSHING BINDING LOCK RING ON LOAD BOLT MISSING	09/10/85	85-0330	REWORK-ADJUST CLAMP, ADD RING (8)
TA-ESD-19-H104	JAM NUTS & SPACER MISSING, WLD UNOSZ, THDS STAKED	09/10/85	85-0332	USE-48-18 (7), REWORK-ADD, PIVOT (4)
TA-ESD-2-H36	WLD STS NOT ON DWG, NON-STD CLAMP, WLD UNOSZ, 09/10/85 GROUT THICKNESS, SPACER LOOSE	09/10/85	85-0334	USE-48-18 (7)
TA-ESD-19-H77	THDS STAKED, WLD ALL AROUND VS 2 SIDES, MISSING JAM NUT, NON-STD CLAMP	09/10/85	85-0335	USE-48-18 (3)
TA-ESD-2-H37	MEMBER SZ & LOC DIM NOT PER DWG, WLD DETAILS 09/10/85 INCOR	09/10/85	85-0336	
TA-ESD-19-H127	BASEPLATE GAP, MISSING WLD, INTERFERENCE, DIM INCOR	09/10/85	85-0337	
TA-ESD-19-H123	JAM NUTS MISSING	09/10/85	85-0338	USE-48-18 (7)
TA-ESD-19-H85	WLD NOT PER DWG, STRUCT MEMBER ANGLE INCOR	09/10/85	85-0340	
TA-ESD-2-H19	WLD UNOSZ, BASEPLATE GAP	09/11/85	85-0342	USE-48-18 (7)
TA-ESD-19-H130	BASEPLATE GAP, WLD UNOSZ	09/11/85	85-0346	USE-48-18 (7)
TA-ESD-19-H131	WLD UNOSZ	09/11/85	85-0347	USE-48-18 (7)
TA-ESD-2-H30	MOD. CLAMP, NO JAM NUT, PLATE GAP, MOVE WELD	09/11/85	85-0348	USE-48-18 (7)
TA-ESD-2-H27	JAM NUT ONE END, THREAD STAKED, UNDERSIZE WELD, MOD. CLAMP	09/11/85	85-0352	USE-48-18 (3)
TA-ESD-19-H126	THINNER PLATE, WELD DETAIL & UNDERSIZE, CLEARANCE	09/11/85	85-0353	USE-48-18 (7)
TA-ESD-19-H128	PLATE GAP, WELD DETAIL	09/11/85	85-0354	
TA-ESD-19-H87	NO LOCKNUT, THDS STAKED, STIFF PL, NOT ON DWG	09/11/85	85-0358	
TA-ESD-19-H66	CLEARANCE	09/11/85	85-0361	USE-48-18 (3)
TA-ESD-19-H82	GAP ATTACHED TO SUPPORT, NO LOCKNUT	09/11/85	85-0362	USE-48-18 (7)

DAVIS - 88888 PIPING & SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	WCR PR NUMBER	DISPOSITION
3A-888-19-H151	MOREWELD, WELD DETAIL & UNDERSIZE, NO WASHER	09/12/85	85-0349	USE-48-18 (3), REWORK-ADJUST (4)
3A-888-19-H15	WELD DETAIL, THREAD STAKED, STRUT BINDS, DIMS'S, NONSTD, CLAMP, JAM NUT MISSING	09/12/85	85-0367	USE-48-18 (3)
3A-888-2-H21	ADD L WELD, WELD DETAIL & UNDERSIZE, DIMENSIONS, CLEARANCE, GROUT THICK, EMBED	09/12/85	85-0364	
3A-888-19-H108	NO WASHER, NO JAM NUT, THREAD STAKED	09/12/85	85-0370	USE-48-18 (3)
3A-888-2-H22	WELD SIZE, TRVL SCALE MISSING, PLATE GAP, CONC. BOUSE	09/12/85	85-0372	USE-48-18 (3)
3A-888-2-H17	WELD DETAIL, CLEARANCE, PL. NOT DETAILED	09/12/85	85-0373	USE-48-18 (3)
3A-888-2-H26	WELD UNDERSIZE, PLATE GAP	09/12/85	85-0374	USE-48-18 (3)
3A-888-2-H29	PLATE GAP, WELD UNDERSIZE	09/12/85	85-0378	USE-48-18 (3)
3A-888-2-H29	NON-STD, CLAMP, THDS STAKED, ALL-AROUND VS, 2 09/12/85 SIDE WLD, BASEPLATE GAP	09/12/85	85-0380	USE-48-18 (3)
3A-888-2-H31	MOD. CLAMP, CLAMP STUD MOV'T, THREAD STAKED, UNDERSIZE WELD, NO WASHER	09/12/85	85-0381	
3A-888-19-H151	WLDG UNDSI, WSHRS MISSING	09/12/85	85-0387	USE-48-18, REWORK-REPLACE DAMAGED COMPONENTS (4)
3A-888-19-H107	JAM NUT LOOSE, EVO BUSHING JAMMED, WLDG MISSING & UNDERCUT	09/12/85	85-0388	
3A-888-2-H16	WLD DEFECTS, ITEMS NOT PER SPEC, BASEPLATE DIM INCORRECT	09/12/85	85-0390	USE-48-18 (3)
3TC-HCC-91-H16	WLD SZ NOT ON DWG, NO GROUT, WSHR MISSING	09/12/85	85-0391	USE-48-18 (3)
3A-888-2-H19	WELD DEFECTS	09/12/85	85-0393	USE-48-18 (3)
3A-888-2-H17	BASEPLATE GAPS, WLD DEFECTS	09/12/85	85-0394	USE-48-18 (3)
3A-888-2-H10	WLD DEFECTS, CONCRETE CRACKS	09/12/85	85-0396	USE-48-18 (3)
3A-888-19-H120	DETAIL 'A' INCDR DIM, NO WELD VS WELD PRESENT	09/14/85	85-0398	USE-48-18 (3)
3A-888-19-H118	THD ENGAGEMENT, STRUT JAMMED	09/14/85	85-0399	USE-48-18 (3) REWORK-REPLACE BUSHING (4)

15

15

DAVIS - BASE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 13

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SP NUMBER	DISPOSITION
3A-E80-19-H117	THDS STAKED, ANCHOR BOLTS LACK THD ENGAGEMENT	09/14/85	85-0401	USE AS IS (3)
3A-E80-19-H111	WSHR MISSING, WLDS NOT PER DWG & UNDSZ	09/14/85	85-0414	
3A-E80-19-H122	ITEM DIM INCORRECT, WLDS UNDSZ & NOT PER DWG	09/14/85	85-0421	USE-AS-IS (3)
3A-E80-19-H119	WLD UNDSZ & NOT PER DWG	09/14/85	85-0422	
3A-E80-19-H110	STANCHION CLEARANCE, WELDS NOT PER DWG	09/14/85	85-0424	
3A-E80-19-H153	THDS STAKED, NO SIGHT HOLE IN TOP OF STRUT	09/16/85	85-0431	USE-AS-IS (3)
3A-E80-2-H8	THDS STAKED ON SKAY STRUT JAM NUT	09/16/85	85-0432	USE-AS-IS (3)
3A-E80-2-H9	SITUATION DOESN'T ALLOW FOR DWG WLD THDS STRIPPED ON BASEPLATE NUTS/BOLTS MISSING	09/16/85	85-0433	
3A-E80-2-H6	WSHRS MISSING, STRUT SOUND, THDS STAKED, BASEPLATE GAP	09/16/85	85-0434	USE AS IS, REWORK-INSTALL WASHERS AND ADJUST TOLERANCES
3A-E80-2-H7	BASEPLATE GAP UNACCEPTABLE	09/16/85	85-0435	USE AS IS (3)
3A-E80-19-H439	BASEPLATE GAP UNACCEPTABLE DIMENSION NOT PER DWG	09/16/85	85-0436	
3A-E80-19-H438	WELDS UNDSZ	09/16/85	85-0437	USE AS IS (3)
3A-E80-2-H25	BASEPLATE NOT PER DWG BASEPLATE GAP UNACCEPTABLE	09/16/85	85-0438	USE-AS-IS (3)
3A-E80-19-H152	BASEPLATE GAP UNACCEPTABLE THDS STAKED, 'S' DIM NOT PER SPEC	09/16/85	85-0439	USE-AS-IS (3)
3A-E80-19-H109	BASEPLATE DIM UNDSZ, STANCHION CLEARANCE NOT PER DWG, WLDS UNDERCUT & NOT PER DWG	09/17/85	85-0440	
3A-E80-19-H116	ALL-ROUND WLDS NOT POSS, STRUT BOLT HAS BEEN STAKED	09/17/85	85-0441	USE-AS-IS (3)
3A-E80-2-H3	WLDS NOT PER DWG, THDS STAKED ON SKAY STRUT JAM NUT, STRUT SOUND UP	09/17/85	85-0450	USE-AS-IS (3), REWORK-REPLACE CORRODED END (4)
3A-E80-2-H2	THDS STAKED, STRUT SOUND UP, ITEM #2 HAS DEFORMED AREA	09/17/85	85-0451	
3A-E80-19-H91	ITEM #1 HAS STRUCTURAL DAMAGE, WLD UNDSZ	09/17/85	85-0450	

DAVIS - 66366 PIPING / SUPPORTS
INSPECTOR FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	WCR/SR NUMBER	DISPOSITION	
3A-ESS-19-469	WLDG CRACKED, ITEM #4 NOT PER DWG, WLD UNDER	09/17/85	85-0461		
3A-ESS-2-45	SWAY STRUT BOUND UP, THDS STAKED	09/17/85	85-0465	USE 48 IS (3)	15
3A-ESS-2-44	JAM NUTS LOOSE, WLDG UNDER	09/17/85	85-0466	USE-48-IS (3), REWORK-TIGHTEN JAM NUT (4)	
3A-ESS-2-474	THDS STAKED, PIPE CLAMP LOOSE, WLD UNDER	09/17/85	85-0467	USE 48 IS, REWORK-TIGHTEN LOOSE NUTS ON CLAMP (+)	15
3A-ESS-2-464	WGRS INSTALLED WRONG, THDS STAKED, BASEPLATE BAR UNACCEPTABLE	09/17/85	85-0468		
3A-ESS-2-412	PIPE CLAMP MIS-ALLIGNED, WLD MISSING, THDS STAKED	09/17/85	85-0470	USE-48-IS (3), REWORK-ADJUST CLAMP (4)	
3A-ESS-2-414	CONCRETE FALLING OUT, WLDG UNDER & NOT PER DWG	09/17/85	85-0471		
3A-ESS-2-413	STRUT BOUND UP, THDS STAKED, WLD NOT PER DWG, "W" DIM INCORRECT	09/17/85	85-0472	USE-48-IS (3), REWORK-REPLACE ROD END (4)	
3A-ESS-2-415	WLD UNDER, ITEM #7 INCORRECT DIM	09/17/85	85-0473		
3A-ESS-2-411	JAM NUT LOOSE, STRUT BOUND UP, WLD NOT PER DWG	09/17/85	85-0474	USE 48 IS (3), REWORK-TIGHTEN JAM NUT (4)	
3A-ESS-19-468	BASEPLATE BAR UNACC, LOCK NUTS MISSING, THDS STAKED	09/17/85	85-0475	USE-48-IS (3)	
3A-ESS-2-41	SWAY STRUT BOUND UP & THDS STAKED, WLD NOT PER DWG	09/17/85	85-0476		
3A-ESS-2-420	NON-STD CLAMP INSTALLED, WLD NOT PER DWG	09/17/85	85-0484		
3A-ESS-19-4121	BOLT NOT VERT, BOLT ROTATES, DIM MISSING FROM DWG, WLD NOT PER DWG, DIM DIFFERENCES	09/18/85	85-0489		
3A-ESS-19-496	NO LOCK NUTS, SWB-CLAMP ORIENTATION EXCEEDS RECOM	09/18/85	85-0494	USE-48-IS (3), REWORK-ADJUST (4)	
3A-ESS-19-494	SCM DESCRIP, WLD NOT COMPLETE PER DWG, CLEARANCE 1/32" VS 1/16"	09/18/85	85-0496	USE-48-IS (3)	
3A-ESS-19-495	LOCKNUTS MISSING	09/18/85	85-0497	USE-48-IS (3)	
3A-ESS-19-498	BASEPLATE BAR, STRUT OFFSET, MISSING LOCK NUT, STRUT BODY LOOSE	09/18/85	85-0498	USE-48-IS (3), REWORK-ADJUST CLAMP AND STRUT (4)	

DW15 - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/CR NUMBER	DISPOSITION
7A-E5D-19-H98	WLD MISSING ON FLG. WLD UNDSZ. CLEARANCE NOT PER DWG	09/18/85	85-0499	USE-48-18 (3)
8C-E5D-14-H10A	BASEPLATE DIM NOT ON DWG. 9WAY STRUT SOUND. PIPE CLAMP MIS-ALIGNED WITH STRUT	09/18/85	85-0507	USE-48-18 (3), REWORK-ADJUST (4)
7A-E5D-19-H113	BASEPLATE DIM INCOR. WLD UNDSZ. CLEARANCE NOT PER DWG. UNDERCUT	09/18/85	85-0508	USE-48-18 (3)
7A-E5D-19-H115	DIM PROBLEMS. WLD T-SIDES VS ALL-ROUND ON LUGS. WLD UNDSZ	09/18/85	85-0509	USE-48-18 (3)
7A-E5D-19-H97	STANCHION DAMAGED	09/18/85	85-0510	USE-48-18 (3)
7A-E5D-19-H93	THIS STAKED. STRUT OFFSET. LOCKNUT MISSING. WLOS NOT PER DWG. 3 WSHRS/ANCHOR BLT	09/18/85	85-0511	USE-48-18 (3), REWORK-ADJUST (4)
7A-E5D-19-H90	WLD UNDSZ	09/18/85	85-0512	USE-48-18 (3)
7A-E5D-19-H112	TAP BOLTS REPLACED BY STUDS. WLD DETAIL. DIMENSION PROBLEMS	09/20/85	85-0545	
M-1114-H16	DIM NOT PER DWG. STRUT SOUND UP	09/25/85	85-0685	USE-48-18 (3)
M-1114-H3	WLD & DIM NOT PER DWG	09/25/85	85-0688	USE-48-18 (3)
M-1114-H5	LOCKNUT & BOLT MISSING. DIM NOT PER DWG	09/25/85	85-0689	USE-48-18 (3)
M-1114-H40	STRUT SOUND UP	09/25/85	85-0704	
M-1114-H22	NOT FULL BASEPLATE BEARING. DIM & WLOS NOT PER DWG. UNACC BOLT EDGE DISTANCE	09/25/85	85-0707	
M-1114-H2	DIM NOT PER DWG. LOCKWIRES NOT INSTALLED	09/25/85	85-0708	USE-48-18 (3), REWORK-INSTALL LOCKWIRE (4)
M-1114-H1	WLD NOT PER DWG. LOCKWIRE NOT INSTALLED	09/25/85	85-0717	USE-48-18 (3), REWORK-INSTALL LOCKWIRE (4)
M-1114-H6	DIMEN. WELD, & CLEARANCE NOT PER DWG.	09/26/85	85-0727	
M-1114-H7	BOLT ANGLED. MISSING NUTS.	09/26/85	85-0728	USE-48-18 (3)
M-1114-H47	DIMEN NOT PER DWG. MISSING LOCKWIRE. ROTATED CLAMP.	09/26/85	85-0729	USE-48-18 (3), REWORK-ADJUST CLAMP (4)
M-1114-H8	DIMEN & WELD NOT PER DWG.	09/27/85	85-0767	

04W18 - BESSIE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-1114-H23	DIMEN & WELDS NOT PER DWG.	09/28/85	85-0775	USE 48-18 (3), REWORK-INSTALL LOCKWIRE (4)
M-1114-H24	DIMEN, WELDS, & BOLT NOT PER DWG, BOLT SPACING VIOLATION.	09/28/85	85-0776	
M-1114-H25	DIMEN & WELD NOT PER DWG, MISSING LOCKWIRE.	09/28/85	85-0788	
M-1114-H26	SNUBBER UNSATISFACTORY.	09/30/85	85-0796	USE 48-18, REWORK-INSTALL LOCKWIRE & ADJUST SNUBBER
M-1114-H29	WELDS & DIMEN NOT PER DWG, BRACKET NOT ROTATED PER DWG.	09/30/85	85-0798	
M-1114-H4	PIPE ELEVATION INCORRECT, SPACERS ADDED TO CLAMP	10/01/85	85-0747	USE 48-18 (3)
M-1114-H37	WLDG UNDSGT, MISSING SPACER, BASEPLATE BEARING UNSAT	10/03/85	85-0809	USE 48-18, REWORK-INSTALL SPACER
M-1114-H13	BOLT SPACING VIOLATION, BASEPLATE BEARING UNSAT	10/03/85	85-0640	
M-1114-H36	BASEPLATE BEARING UNSAT	10/03/85	85-0841	USE 48-18 (3)
M-1114-H11	BOLT SPACING NOT PER SPEC, BASEPLATE BEARING UNSAT & NOT PER DWG	10/03/85	85-0643	
M-1114-H32	WLDG NOT PER DWG, BOLT #4 REQUIRED & FULL TURN	10/03/85	85-0644	USE 48-18 (3)
M-1114-H15	BASEPLATE GAP	10/07/85	85-0922	USE 48-18 (3)
M-1114-H16	BASEPLATE GAP	10/07/85	85-0922	USE 48-18 (3)
M-1114-H38	UNDSGT WLD, INTERFERENCE WITH STRUT, MIN. BOLT SPACING VIOLATION	10/07/85	85-0944	
M-1114-H41	BASEPLATE GAP, WLD UNDSGT, STRUT GIVEN, INCORRECT	10/07/85	85-0945	USE 48-18 (3)
TA-850-10-H147	3/4" BOLTS VS. 1/2", BASEPLATE GAP, WLD UNDSGT, RIGHT HOLE MISSING	10/07/85	85-0946	
M-1114-H17	BASEPLATE GAP, WLD UNDSGT, MIN BOLT SPACING VIOLATION	10/07/85	85-0947	

15

15

15

15

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	WER/BR NUMBER	DISPOSITION
3A-E80-19-H11	WLD DETAIL INCORRECT, PIPE CLAMP WASHERS TOO THICK, GAP IN FIREPROOFING	10/08/85	85-0955	
3A-E80-19-H15	WLD DETAIL NOT ON DWG, WLD DETAIL INCORRECT	10/08/85	85-0956	USE AG 18 (3)
3A-E80-19-H12	3/4" BOLT VS 1/2", ADDITIONAL WASHER PLATES, MEMBER SIZE INCORRECT, WELD DETAIL	10/08/85	85-0957	
M1114/H20	WLD DETAIL INCORRECT, LOOSE JAM NUT, BOLT MIN. DIST. VIOLATION	10/08/85	85-0959	
A221	WEEP HOLE OUT IN STANCHION, FIREPROOFING CRACKED, DIMEN INCORRECT	10/08/85	85-0960	
3A-E80-19-H47	DIMENSIONS WELD DETAIL & UNDERSIZE	10/09/85	85-0975	
3A-E80-19-H136	WELD DETAIL	10/09/85	85-0976	
3A-E80-19-H53	DIMENSIONS WELD SYMBOL WELD DETAIL & SIZE	10/09/85	85-0977	
3A-E80-19-H55	WELD DETAIL & SIZE ANCHOR EMBED	10/09/85	85-0978	USE AG 18 (3)
3A-E80-19-H49	DIMENSIONS SUBSET INSTALLED WELT VS. SHEL TYPE	10/09/85	85-0979	USE AG 18 (3)
3A-E80-19-H51	C.L. SETTING	10/09/85	85-0980	
3A-E80-19-H17	DIMENSION WELD DETAIL & UNDERSIZE TWO STAKED BOLT LOOSE ON STRUT	10/09/85	85-0981	USE AG 18 (3), RERWORK-TIGHTEN NUT.
3A-E80-19-H54	WELD DETAIL	10/09/85	85-0982	USE AG 18 (3)
3A-E80-19-H52	PL GAP DIMENSIONS	10/09/85	85-0985	USE AG 18 (3)
3A-E80-19-H50	WELD DETAIL PL GAP WELT VS. SHEL	10/09/85	85-0987	
3A-E80-19-H17A	DIMENSIONS, TWO STAKED, WELD DETAIL	10/09/85	85-0987	USE AG 18 (3)

15

15

15

15

Page No. 9
11/01/85

SYSTEM: APPT STEAM SUPPLY AND EXHAUST

DAVIS - BESSE PIPING / SUPPORTS
INSPECTOR FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION	
3A-E80-19-H57	WELD DETAIL	10/09/85	85-1004	USE AS IS (3)	15
3A-E80-19-H57	WELD DETAIL & SIZE, DIMENSION, BOLT SPACE	10/09/85	85-1000		
3A-E80-19-H20	WELD DETAIL, B/M PROBLEM, THREAD STAKED, DIMENSION	10/09/85	85-1001		
3A-E80-19-H56	DIMENSION CLEARANCE ANCHOR BOLT SPACE	10/09/85	85-1002	USE AS IS (3)	15
3A-E80-19-H38	WELD DETAIL & SIZE	10/09/85	85-1007		
3A-E80-19-H22	DIMENSION FL. GAP WAS NOT LOOSE SPACER THREAD ENGAGE.	10/09/85	85-1009		
M1114/H47	FL. GAP DIMENSION NOT LOOSE	10/09/85	85-1010		
M1114/H18	DIMENSION, STRUT BUSHING NO MOVEMENT	10/09/85	85-1011		
A-762	ANCHOR BOLT SPACE, WELD SIZE	10/09/85	85-1012		
3A-E80-19-H10	FL. GAP, DIMENSION, NO FL. THICK ON DRAWING, WELD DETAIL, INTERFERE	10/09/85	85-1013		
3A-E80-19-H142	3/4" BOLT VS. 1/2", FL. GAP, WELD DETAIL	10/09/85	85-1014	USE AS IS (3)	15
3A-E80-20-H1	WELD DETAIL, THREAD STAKED	10/09/85	85-1015	USE AS IS (3)	15
3A-E80-19-H6	B/M PROBLEM, FL. THICK, WELD DETAIL	10/09/85	85-1016		
3A-E80-20-H2	WELD DETAIL	10/09/85	85-1017	USE AS IS (3)	15
A-001	BOLT SPACE, WELD SIZE	10/09/85	85-1025		
3A-E80-19-H59	WELD DETAIL & SIZE	10/09/85	85-1026	USE AS IS (3)	15
3A-E80-19-H9	ATTACHMENT NOT CENTERED ON PLATE, SPRING SETTINGS	10/09/85	85-1028		
3A-E80-19-H11	MEMBER LENGTH, WELD SIZES	10/09/85	85-1029		

DAVIS - 88888 PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	WCR/SP NUMBER	DISPOSITION
3A-E80-19-H34	ADDITIONAL MEMBER INSTALLED	10/09/85	85-1070	
3A-E80-19-H35	SWAY STRUT PROBLEMS	10/09/85	85-1071	USE AS IS (1)
3A-E80-19-H37	WELD DEFECTS, MEMBER LENGTHS ANCHOR BOLT SPACING	10/09/85	85-1072	
3A-E80-19-H38	ANCHOR BOLTS SIZE INCREASED	10/09/85	85-1073	
3A-E80-19-H33	STAKED THREADS SWAY STRUT	10/09/85	85-1034	USE AS IS (1)
3A-E80-19-H30	WELD SIZES	10/09/85	85-1075	
3A-E80-19-H28	WELD SIZES, MEMBER SIZE	10/09/85	85-1076	USE AS IS (1)
3A-E80-19-H32	WELD SIZE	10/09/85	85-1077	
3A-E80-19-H40	WELD SIZES & TYPES, DIMENSION CHANGES	10/09/85	85-1041	
3A-E80-19-H70	WELDS, SPRINGS, WASHERS AT ANCHORS	10/09/85	85-1044	
M-1114-H42	BOLT SPACING, WELD & STRUT PROBLEMS	10/09/85	85-1048	
3A-E80-19-H46	DIMENSIONS & WELD SIZES	10/09/85	85-1050	
M-1114-H28	DIMENSIONS & WELDS	10/10/85	85-1051	
M-1114-H27	PIPE CLAMP	10/10/85	85-1052	
3A-E80-19-H16	DIMENSIONS & STRUT PROBLEMS	10/10/85	85-1053	
3A-E80-19-H17	ADDITIONAL WELD AT STRUT BRACKET	10/10/85	85-1054	
3A-E80-19-H150	SNUGGER, BASE PLATE & WELD PROBLEMS	10/10/85	85-1055	
3A-E80-19-H144	WELD SIZES & SNUGGER PROBLEMS	10/10/85	85-1056	
3A-E80-19-H12	DIMENSIONS, WELD SIZE, SNUGGER PROBLEMS	10/10/85	85-1065	
3A-E80-19-H21	NO WASHERS FOR ANCHOR BOLTS	10/10/85	85-1078	
3A-E80-19-H69	WELDS AND DIMENSIONS	10/10/85	85-1079	
3A-E80-19-H71	WELDS, ANCHOR BOLTS, SNUGGER PART NO.	10/10/85	85-1087	
3A-E80-19-H18	WELD DETAIL & SIZE	10/11/85	85-1100	

15

15

15

DAVIS - BESSE RIPPING / SUPPORTS
INSPECTION FINDINGS

REV. 13

SUPPORT NUMBER	DESCRIPTION	DATE	WPR/BR NUMBER	DISPOSITION
ESB-1-H1	PIPE CLAMP - NO SPACER, STK. TWO, GAP AT SPACER	10/19/85	85-1336	
ESB-1-BR7	ADDED WELD, WELD DETAIL NOT SHOWN ON DETAIL DRAWING	10/19/85	85-1337	
ESB-1-H5	WELD DETAIL NOT ON DRAWING, WELD TYPE CHANGE, 10/19/85 GAPS ON CLAMP NOT PER DRAWING	10/19/85	85-1338	
ESB-1-BR4	EASE PLATE NOT PER DWG., GAP, SNUBBER LEAKING 10/27/85 & HAS NO NUMBER	10/27/85	85-1400	
ESB-1-H3	WELDS & CLAMPS NOT PER DRAWING, STAKED THREADS	10/27/85	85-1413	
ESB-1-BR-1	SNUBBER, BASE PLATE SIZE REDUCED, SHEAR LUG WELD, WELD UNDERSIZED, A.BLT. W/DWAS	10/24/85	85-1424	
ESB-1-BR-7	WELDS UNDERSIZED, STAKED CLAMP THREAD, SNUB, MUNT.	10/24/85	85-1425	
ESB-1-H2	WELDS UNDERSIZED, NOTCHED STEEL	10/24/85	85-1426	
ESB-1-H5	WELDS UNDERSIZED, SNUBBER MVMT. & BUSHING	10/24/85	85-1427	
ESB-1-BR-8	WELDS UNDERSIZED & TYPE CHANGED, SNUBBER LEAK 10/24/85	10/24/85	85-1428	
ESB-1-BR-9	SNUBBER SEAL	10/24/85	85-1429	
ESB-1-H4	WELD TYPE, SEAM ATT. PIN, SPRING SIZE	10/24/85	85-1440	
ESB-1-H1	SPRING W/T. STOPS, GAPS EXCESSIVE	10/24/85	85-1441	
ESB-1-BR-4	SNUBBER LEAK, WELDS UNDERSIZED, PLATE SIZES	10/24/85	85-1447	
ESB-1-BR6	BOLT SIZES, SNUBBER MOVEMENT, WELDS SIZES	10/25/85	85-1491	
ESB-1-BR2	WELD SIZES, LOOSE NUT ON CLAMP, PLATE SIZE	10/25/85	85-1492	
ESB-1-BR6	BOLT, DIMEN., BASEPLATE & SNUBBER NOT PER DWG.	10/28/85	85-1506	
DA-280-19-H61	WELD NOT PER DRAWING	10/29/85	85-1519	
DA-280-19-H62	WELD NOT PER DRAWING	10/29/85	85-1520	
ESB-1-BR2	CLAMP & GAP NOT PER DRAWING	10/29/85	85-1530	

SECTION 2.0

AUXILIARY FEEDWATER SYSTEM

01/01/88

SYSTEM: AUXILIARY FEEDWATER

DAVIS - BEEBE PIPING & SUPPORTS
INSPECTION FINDINGS

REV. 13

SUPPORT NUMBER	DESCRIPTION	DATE	ACR/BR NUMBER	DISPOSITION
ESD-14-H76	CONCRETE CHIPPED	05/08/88	88-0049	USE-48-18 (1), REWORK-REGROUT (4)
ESD-14-H80	BASEPLATE GAP/CONCRETE CHIPPED	05/08/88	88-0050	USE-48-18 (1), REWORK-ADD SHIMS (2)
ESD-14-H90	BASEPLATE GAP	05/08/88	88-0051	USE-48-18 (1), REWORK-ADD SHIMS (2)
ESD-14-H54	BOLT SIZE INCORRECT	05/23/88	88-0073	USE-48-18 (1)
ESD-14-H59	LOOSE BOLT	05/24/88	88-0075	USE-48-18 (1)
ESD-14-H65	ONE BOLT WILL NOT TORQUE	05/28/88	88-0076	USE-48-18 (1)
ESD-14-H67	BOLT TYPE INCORRECT	05/28/88	88-0077	USE-48-18 (1)
ESD-14-H77	BOLT SIZE & QUANTITY INCORRECT	06/25/88	88-0100	USE-48-18 (1), REWORK-ADD NEW ANCHOR BOLTS (2)
ESD-14-H91	BOLT SIZE INCORRECT	07/10/88	88-0106	USE-48-18 (1)
ESD-14-H93	IMMEDIATE WELD REPAIR OF BASEPLATE	08/21/88	88-0140	USE-48-18 (1)
M1155/H5	WELD ALL AROUND V8, 2 SIDES. SNUGGER BUSHINGS BINGING. BORIC ACID ACCUM.	08/02/88	88-0165	USE-48-18 (1), REWORK-REPLACE SNUG (4)
M1155/H4	WELDED 2 SIDES V8, 1 SIDE	08/07/88	88-0187	USE-48-18 (1)
60-888-4-H12	BASEPLATE GAP INSTALLATION CRITERIA VIOLATED	09/04/88	88-0198	USE-48-18 (1)
60-888-4-H4	WELDS UNDERSIZE, UNDERCUT, OVERLAP, CLEARANCE IS 1/32"	09/04/88	88-0202	USE 48 18 (1)
M1155/H6	1 WSHR NEEDED EA SIDE V8 1 WSHR 1 SIDE ACTUAL	09/04/88	88-0203	USE 48 18 (1), REWORK-INSTALL WASHER (4)
60-888-4-H7	CLEARANCES WRONG SIZE. WRONG SIZE MULTI BOLT	09/04/88	88-0204	USE-48-18 (1)
60-888-4-H16	GAP WRONG SIZE. ITEM #2 DEFORMED. WELD DEFECTS	09/04/88	88-0205	
60-888-4-H8	WELD UNDERCUT 1/32". GAP WRONG SIZE	09/04/88	88-0206	USE-48-18 (1)
60-888-4-H15	SAME OF V88. LEAKING. WELDS NOT PER DWG. WELD UNDERSIZE	09/04/88	88-0207	

DAVIS - 88386 PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NO. / SR NUMBER	DISPOSITION
60-EBD-14-H6	1/8" DIMENSION INCOR & SPACER LOOSE. THDS STAKED. MISSING JAM NUT	09/07/85	85-0284	USE-48-18 (3)
60-EBD-14-H5	WLDG NOT PER DWG, WLD UNDSZ. MISSING JAM NUT	09/07/85	85-0285	USE-48-18 (3)
60-EBD-14-H7	WLD UNDSZ & UNDERCUT, ARC STRIKER, WLDG NOT PER DWG, THDS STAKED, MISSING JM NTS	09/07/85	85-0286	
60-EBD-14-H9	THDS STAKED. MISSING JAM NUTS, WLDG NOT PER DWG	09/09/85	85-0294	USE-48-18 (3)
60-EBD-14-H7	WLDG NOT PER DWG & UNDSZ. MISSING JAM NUTS, THDS STAKED	09/10/85	85-0270	USE-48-18 (3)
60-EBD-14-H2	MISSING JAM NUTS & WLD, WELD DETAIL INCORRECT	09/10/85	85-0271	USE-48-18 (3)
60-EBD-14-H12	WLD UNDSZ	09/10/85	85-0283	USE-48-18 (3)
60-EBD-4-H14	NONSTD CLAMP, WELD UNDERSIZE, DIMENSIONS, B.O.M. PROBLEM, LOCKNUT MISSING	09/12/85	85-0375	USE-48-18 (3)
60-EBD-14-H74	BASEPLATE GAPS, NUTS NOT PER SPEC, NON-STD PIPE CLAMP	09/13/85	85-0384	
60-EBD-14-H25	BOTH SWAY STUITS LOCKED & NO WSHRS, NO WELDS 1/8 WELDS PRESENT	09/14/85	85-0400	USE-48-18, (3) REMOVR-INSTALL WASHERS (4)
60-EBD-14-H22	WLDG NOT PER DWG, #3 WRONG DIM, NO PIN TO PIN DIM ON DWG	09/17/85	85-0469	USE-48-18 (3)
60-EBD-14-H194	PIN TO PIN DIM NOT INDICATED ON DWG	09/17/85	85-0479	USE-48-18 (3), REMOVR
60-EBD-14-H19	ITEMS INCORRECT DIM'S, WLD NOT PER DWG	09/17/85	85-0480	USE-48-18 (3)
60-EBD-14-H23	NO CONCRETE ANCHORS SPEC'D, ITEMS INCOR DIM, WLDG NOT PER DWG	09/17/85	85-0481	
4-245	STIFF PLATES THICKER	09/18/85	85-0485	USE-48-18 (3)
60-EBD-14-H23	PIN-PIN DIM NOT ON DWG	09/18/85	85-0486	USE-48-18 (3)
60-EBD-14-H66	ANCHOR BOLT EDGE DIST DIFF FROM DWG, BASEPLATE GAP, THDS STAKED & NOT VISIBLE	09/18/85	85-0490	USE-48-18 (3), REMOVR-ADJUST (4)
60-EBD-14-H94	STUDS & BOLTS STAKED, B'DIM DIFF FROM CATALOG, NO SIGHT HOLE	09/18/85	85-0491	USE-48-18 (3)

15

15

SYSTEM AUXILIARY FEEDWATER

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
6C-E80-14-H91	1" HILTI VS 7/8 RED HEAD, WELD NOT PER DWG	09/18/85	85-0492	USE-48-18 (3)
6C-E80-14-H89	THROD ROD DBL NUTS, THROD ROD VS TAP SLTS, THDS STAKED, SPACER TACKED TO CLAMP	09/18/85	85-0493	USE-48-18 (3)
6C-E80-14-H81	THDS STAKED, BASEPLATE THICK NOT ON DWG, WLD NOT PER DWG, WLD UNDER	09/18/85	85-0495	USE-48-18 (3)
6C-E80-14-H21	LOCKNUT LOOSE, STRUT TURN BY HAND, PIN-PIN NOT ON DWG	09/18/85	85-0502	USE-48-18 (3), REWORK-ADJUST (4)
6C-E80-14-H00	WLDG NOT PER DWG, NO THD IN INSPECTION HOLE, NO INSPECTION HOLE	09/18/85	85-0503	
6C-E80-14-H174	PIPE CLAMP NOT TIGHT, SWAY STRUT LOOSE, ONLY ONE NUT/STRUT, PIN-PIN NOT ON DWG	09/18/85	85-0504	USE-48-18 (3), REWORK-TIGHTEN (4)
6C-E80-14-H078	PIN-PIN NOT ON DWG	09/18/85	85-0506	USE-48-18 (3)
6C-E80-14-H37	STRUT BODY LOOSE, WBR & LOCKNUTS MISSING, THDS STAKED, STRUT OFFSET	09/19/85	85-0517	USE-48-18 (3), REWORK-ADJUST (4)
A-224	FULL LENGTH VR STITCH WLD ON DWG	09/19/85	85-0518	USE-48-18 (3)
6C-E80-14-H71	THDS STAKED, PLATE GAP, WRC STRIKE	09/19/85	85-0522	USE-48-18 (3), REWORK-REMOVE ARC STRIKES (4)
6C-E80-14-H83	BASEPLATE GAP	09/19/85	85-0523	USE-48-18 (3) 15
A-8	ANCHOR TO BE REMOVED	09/19/85	85-0524	REWORK (NON-BEISMIC)
6C-E80-127-H18	WLD DETAIL, PLATE GAP	09/19/85	85-0525	USE-48-18 (3)
6C-E80-14-H56	PLATE GAP, SPACER LOOSE, THDS STAKED, CLAMP ID WRONG	09/19/85	85-0526	USE-48-18 (3) 15
6C-E80-14-H70	ANCHOR BOLT MISSING	09/19/85	85-0527	USE-48-18 (3)
6C-E80-14-H18	WLD NOT ON DWG, THD STAKED	09/19/85	85-0528	USE-48-18 (3)
6C-E80-14-H18	NO BILL/MAT'L, WLD DETAIL, NOT PER DWG, THDS STAKED, LOCKNUTS LOOSE	09/19/85	85-0529	
6C-E80-14-H48	INSTALLED SECTION VS DWG, WLD DETAIL, CLEARANCE	09/20/85	85-0536	
6C-E80-14-H37	PLATE GAP, THD STAKED, CLAMP ID WRONG	09/20/85	85-0537	USE-48-18 (3)

SYSTEM: AUXILIARY FEEDWATER

DAVIS - 88388 PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 13

REPORT NUMBER	DESCRIPTION	DATE	WORKER NUMBER	DISPOSITION
60-880-14-497	PLATE GAP, ITEM # MISSING ON DWG. WLD UNDSZ	09/20/88	88-0538	USE AS IS (3)
60-880-14-498	SPACER LOOSE, THD STAKED, CLAMP ID WRONG, WLD DETAIL, ITEM ROTATED	09/20/88	88-0539	USE AS IS (3)
60-880-14-499	THD STAKED, THICKER BASEPLATE THAN DWG, SPOUT NOT TO DWG	09/20/88	88-0540	USE AS IS (3)
60-880-14-500	PLATE GAP, WLD NOT DETAIL, ITEM # CALLOUT ON DWG	09/20/88	88-0541	
4-382	WLD UNDSZ	09/20/88	88-0542	
60-880-14-501	WLD MISSING, UNDSZ & NOT PER DWG	09/20/88	88-0543	
60-880-14-502	THDED RCD, WLD UNDSZ & DETAIL, BASE METAL REDUCTION	09/20/88	88-0544	USE AS IS (3)
60-880-14-503	BASEPLATE GAP, THD STAKED, LOCKNUT NOT TIGHT, CLAMP END BOUND UP, CLAMP ID WRONG	09/20/88	88-0545	USE AS IS (3), REMARK-TIGHTEN LOCKNUT (4)
60-880-14-504	BASEPLATE GAP, ANCHOR BOLT WRONG SZ, WLD DETAIL AND UNDSZ	09/20/88	88-0546	USE AS IS (3)
60-880-14-505	WLD UNDSZ & DETAIL, PLATE GAP, SHIM NOT ON DWG	09/20/88	88-0547	
60-880-14-506	WLD DETAIL & UNDSZ	09/20/88	88-0548	
60-880-14-507	KEEP HOLE MISSING, WLD DETAIL	09/20/88	88-0549	
60-880-14-508	18" DIM, SPACER LOOSE, WLD DETAIL & UNDSZ, THD STAKED	09/20/88	88-0550	USE AS IS (3)
60-880-14-509	WLD DETAIL, DIM DISCREP	09/20/88	88-0551	
60-880-14-510	LOCKNUTS MISSING, CLAMP DEFORMED, STRUT BOUND UP	09/20/88	88-0552	
60-880-14-511	STRUT LOCKED, PIN-PIN NOT ON DWG, DIM PROBLEMS, WLD UNDSZ	09/20/88	88-0553	USE AS IS (3)
60-880-14-512	WLD UNDSZ, LOCKNUT MISSING, THD STAKED, STRUT BOUND UP	09/20/88	88-0554	
60-880-14-513	ANCHOR BOLTS MISSING, ANCHOR SZ, BASEPLATE GAP, BASEPLATE THICKNESS	09/20/88	88-0555	

15

15

DAVIS - BESSIE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
6C-E9D-14-H42	NO WLD DETAIL ON DWG. BASEPLATE THICKNESS, WLD DETAIL & UNDER	09/20/85	85-0578	
6C-E9D-14-H36	WLD UNDER, THD STAKED, WLD DETAIL, TRAPEZE OFFSET, JAM NUT LOOSE	09/20/85	85-0579	USE-48-18 (3), REWORK-TIGHTEN JAM NUT (4)
6C-E9D-14-H25A	LOCKNUT MISSING, ANCHOR IN CONTACT W/CONDUIT, WLD DETAIL	09/21/85	85-0597	
6C-E9D-14-H71	WLD DETAIL & UNDER	09/21/85	85-0601	USE-48-18 (3)
6C-E9D-14-H60	WLD UNDER	09/21/85	85-0602	USE-48-18 (3)
6C-E9D-14-H74	THD STAKED, ROD END BUSHING JAMMED	09/21/85	85-0606	USE AS IS, REMOVE-FULLY ENGAGE ROD BUSHING (4)
6C-E9D-14-H76	THD STAKED, LOCKNUT LOOSE, CLAMP LOOSE	09/21/85	85-0607	
6C-E9D-14-H45	SPACERS WELDED, NO JAM NUTS	09/21/85	85-0608	USE-48-18 (3)
6C-E9D-14-H35	NO LOCKNUT, THD STAKED, STRUT CLAMP MIS-ALIGNED	09/21/85	85-0609	USE-48-18 (1), REWORK-ADJUST CLAMP (4)
6C-E9D-14-H26	NO WDR, WLD DETAIL, THD ENGAGEMENT, CLEARANCE	09/21/85	85-0610	
6C-E9D-14-H24	NO LOCKNUT, THD STAKED, REAR BRACKET BUSHING MISSING	09/21/85	85-0614	
6C-E9D-14-H57	WLD UNDER	09/21/85	85-0615	USE-48-18 (3)
6C-E9D-14-H30	SHIMS BEHIND BASEPLATE, WLD DETAIL & UNDER, UNDERCUT	09/21/85	85-0616	
M-1114-H45	DIMENSION, WLD DETAIL, NO LOCKNUT	09/27/85	85-0626	USE AS IS (3), REWORK-ADJUST CLAMP (4)
6C-E9D-14-H61	WLD DETAIL & UNDER	09/27/85	85-0631	USE AS IS (3)
6C-E9D-14-H87	WLD DETAIL & UNDER	09/27/85	85-0632	
6C-E9D-14-H99	THD STAKED	09/27/85	85-0633	USE-48-18 (3)
6C-E9D-14-H86	WLD DETAIL	09/27/85	85-0634	USE-48-18 (3)
6C-E9D-14-H90	SHIM NOT ON DWG	09/27/85	85-0635	

DAVIS - BESSIE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SP NUMBER	DISPOSITION
60-E80-14-H85	THD STAKED, SHOR WLD UNDSZ, SPACER NOT ON BOM	09/23/85	85-0636	USE-48-18 (3)
60-E80-14-H84	THD STAKED, WLD DETAIL	09/23/85	85-0637	USE-48-18 (3)
6A-H80-272-H1	THD STAKED, SPACER TACKED, WLD DETAIL	09/23/85	85-0639	USE-48-18 (3)
60-E80-14-H84	BASERPLATE GAP, SUPPORT MOD NOT ON DWG	09/23/85	85-0640	USE 48 18 (3)
6A-H80-22-H4	THD STAKED, PLATE GAP	09/23/85	85-0642	USE-48-18 (3)
6A-H80-272-H2	JAM NUT LOOSE, THD STAKED	09/23/85	85-0643	USE-48-18 (3), REWORK-TIGHTEN NUT (4)
60-E80-14-H78	WLD DETAIL	09/23/85	85-0645	
60-E80-14-H77	MULTI BOLT VS TAP BOLT ON DWG, WLD DETAIL	09/23/85	85-0646	
60-E80-14-H88	WLD DETAIL, PLATES NOT ON DWG, INTERNAL DWG DISCREP	09/23/85	85-0647	
60-E80-14-H72	WLD DETAIL, BASERPLATE GAP	09/23/85	85-0648	
60-E80-14-H79	JAM NUT MISSING, WLD UNDSZ & DETAIL	09/23/85	85-0649	
M-1114-H21	THD ENGAGEMENT, BOLT GAP, DIMENSIONS, SPACER MISSING, NO LOCKNUT	09/23/85	85-0651	
60-E80-14-H85	THD STAKED, THD ENGAGEMENT, BENT LOAD BOLT	09/23/85	85-0652	
60-E80-14-H27	TAP BOLT MISSING, PLATE GAP	09/23/85	85-0653	
60-E80-14-H39	PLATE GAP, WLD SZ, SHIM NOT ON DWG, BOM QUANTITY DISCREP	09/23/85	85-0654	USE-48-18 (3)
41-H80-35-H17	THD STAKED, JAM NUT MISSING, PLATE GAP	09/24/85	85-0657	USE-48-18 (3)
41-H80-35-H9	PLATE THICK, DIMENSION, WLD DETAIL	09/24/85	85-0658	USE-48-18 (3)
6A-H80-272-H7	WLD DETAIL & UNDSZ, DIMENSION, JAM NUT LOOSE	09/24/85	85-0659	USE-48-18 (3)
6A-H80-22-H3	DIMENSION, WLD NOT ON DWG, CLEARANCE, WLD DETAIL	09/24/85	85-0670	
4-215	WLD UNDSZ, 1/8" X 8 UNDER NUT	09/24/85	85-0671	USE 48 18 (3)
6A-H80-22-H6	BOLT & SPACER LOOSE, NO LOCKNUT, THD STAKED, WLD NOT ON DWG, WLD DETAIL	09/24/85	85-0672	USE 48 18, REWORK-TIGHTEN BOLT, INSTALL LOCK NUT (4)

15

15

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
6A-H8D-22-H7	WLDG NOT PER DWG, THDS STAKED, LOCK NUTS MISSING, CONC CRACKED	09/25/85	85-0678	USE AB 18 (3)
6A-H8D-272-H6	BASEPLATE GAP, WLD & DIMS NOT PER DWG	09/25/85	85-0687	
6A-H8D-272-H4	DIM NOT PER DWG, PIPE CLAMP, THDS STAKED, SPRING CAN DAMAGED	09/25/85	85-0701	USE AB 18 (3)
6A-H8D-272-H5	THDS STAKED, WLDG & DIM & ITEM #4 NOT PER DWG	09/25/85	85-0703	USE AB 18 (3)
6A-H8D-35-H55	WLDG & DIM NOT PER DWG, BOLT SPACING VIOLATION	09/26/85	85-0720	USE AB 18 (7)
A-216	BASEPLATE GAP UNACC, ANCHOR BOLT INSTALLED @ ANGLE	09/26/85	85-0702	
6A-H8D-22-H5	THDS STAKED, DIMEN & WELD NOT PER DWG, GAPS & SPACING UNACC, MISSING NO. ON BOM	09/26/85	85-0737	
6A-H8D-22-H2	DIMEN & WELDS NOT PER DWG, CONC SPALLED.	09/26/85	85-0740	
6A-H8D-35-H52	DIMEN, WELDS, & BOLTS NOT PER DWG.	09/26/85	85-0746	
A-217	BOLTS NOT PER DWG, BASEPLATE GAP UNACC.	09/26/85	85-0748	
6A-H8D-24-H2	MISSING WASHERS, WELDS NOT PER DWG, DAMAGED MEMBERS.	09/27/85	85-0761	USE AB 18 (3)
6A-H8D-22-H6	BASEPLATE GAP UNACC, WELDS NOT PER DWG, THDS STAKED.	09/27/85	85-0766	
6A-H8D-24-H1	DIMEN & WELDS NOT PER DWG, BASEPLATE GAP UNACC.	09/28/85	85-0785	
6A-H8D-35-H14	WLDG NOT PER DWG, CONCRETE BROKEN OUT, ANCHOR BOLTS NOT PER DWG	10/03/85	85-0806	USE AB 18 (3)
6A-H8D-35-H32	WLDG NOT PER DWG, THDS STAKED, DIM NOT PER DWG	10/03/85	85-0807	USE AB 18, REWORK-TIGHTEN NUT
6A-H8D-35-H33	WLDG NOT PER DWG, THDS STAKED, DIM NOT PER DWG	10/03/85	85-0808	
M-1114/H9	C-C BRACING, UNDERSIZE WELD, SPACER MISSING, "8" DIM.	10/03/85	85-0851	USE AB 18, REWORK-INSTALL SPACER (4)
M-1114/H31	BOLT SPACE, CLEARANCE, DIMENSIONS, WELD DETAIL	10/03/85	85-0852	

DAVIS - BEEBE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-1114/H35	PLATE GAP, DIMENSIONS, WELD	10/03/85	85-0853	
M-1114/H34	CLEARANCE, BOLT SPACING	10/03/85	85-0854	
M-1114/H12	ANCHOR BOLT TORQUE, PLATE GAP	10/03/85	85-0855	USE AS IS (3), REWORK-REMOVE WOOD SHIM (4)
M-1114/H10	DIMENSIONS, WELD DETAIL & UNDERSIZE	10/03/85	85-0856	
M-1114/H14	PLATE GAP, DIMENSIONS, CLAMP BOLT LOOSE, LOCKNUT LOOSE	10/04/85	85-0857	
M-1114/H19	PLATE GAP, STRUT ANGLE	10/04/85	85-0858	USE AS IS (3), REWORK-ADJUST CLAMP(4)
M-1114/H44	WELD DETAIL, PIN-PIN DIM.	10/04/85	85-0859	
6A-HBC-35-H01	S/M PROBLEMS, WELD DETAIL, DIMENSIONS, CLEARANCE, WASHER MISSING, PLATE GAP	10/05/85	85-0917	
6C-690-14-H08	WELDS, LUG CLEARANCES	10/16/85	85-1226	

SECTION 3.0

LOW PRESSURE INJECTION SYSTEM

SYSTEM: LOW PRESSURE INJECTION

DAVIS - BESSIE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
308-1-H15	ROD END ATTACHMENT LOAD PIN IS LOOSE	08/21/85	85-0139	
308-PCB-2-H1	MISSING JAM NUT, P CLAMP TWISTED, THDS ON BOLTS UPSET	08/30/85	85-0148	USE-48-18 (3)
308-CCB-6-H9	PART OF SUPPORT FLANGE REMOVED. WELD UNDERSIZE, GAP CLEARANCE.	09/02/85	85-0159	
308-CCA-4-H4	LOOSE ANCHORBOLT, ROD END BINDING, INTERFERENCE WITH ADJACENT SUPPORT.	09/02/85	85-0161	USE-48-18 (3)
308-CCB-6-H10	ATTACHMENT NOT PER DWG., WELD UNDERSIZE, SHUSHER HEAD BOLT LOOSE	09/02/85	85-0162	
308-CCB-6-H2	BOLTS STAYED IN PLACE	09/02/85	85-0163	USE-48-18 (3)
308-CCB-6-H4	BREASE FITTINGS CUT OFF OF ROD ENDS	09/02/85	85-0164	USE-48-18 (3)
308-CCB-6-H11	WELD UNDERSIZE	09/02/85	85-0186	USE-48-18 (3)
308-CCA-4-H2	NON STANDARD PIPE CLAMP, MISSING WELD, SUPPORT INTERFERS W/ANOTHER SUPPORT.	09/03/85	85-0166	USE-48-18 (3)
308-CCA-4-H3	NON-STD PIPE CLAMP, MISSING & UNDERSZ WLDG, EDGE DISTANCE LESS THAN MINIMUM.	09/03/85	85-0176	USE-48-18 (3)
308-CCB-5-H4	UNDERSIZE WELD, AS-BUILT WELD TYPE NOT PER DWG.	09/03/85	85-0178	
308-CCB-5-H401	BOLTS HAVE ONE NUT ONLY, CLEARANCE GAP AND SHIMS INACCURATE.	09/03/85	85-0179	
308-CCA-4-H10	NON-STD COMPS, 3/4" BLTS VS SPEC'D 5/8", MEMBS LONGER THAN DESIGN, WELD UNDERSZ	09/03/85	85-0184	USE-48-18 (3)
308-CLB-6-H6	WELD UNDERSZ, AS-BUILT MEMBER LENGTH AND ANGLE NOT PER DWG.	09/03/85	85-0188	USE-48-18 (3)
308-CCA-6-H6	BOLT DOES NOT HAVE FULL THREAD	09/03/85	85-0189	USE-48-18 (3)
308-CCB-6-H6	WELD DETAIL MISSING FROM DWG, SHUSHER ELEVATION INCORRECT	09/03/85	85-0190	USE-48-18 (3)
308-CCA-4-H9	POOF DUTY WLDG, NON-STD COMPONENTS USED, MEMBER LOCATIONS INACCURATE.	09/03/85	85-0191	
308-CCB-6-H7	WLD UNDERSZ, WLD DTL NOT PER DWG, MISSING WLDG, BASEPLATE GAP, CLAMP GAP NOT PER DWG	09/03/85	85-0192	USE-48-18 (3)

SUPPORT NUMBER	DESCRIPTION	DATE	WORK BR NUMBER	DISPOSITION
338-003-6-H7	ANCHORS HAVE > 2 WASHERS	09/04/85	85-0185	USE-48-18 (3)
338-004-6-H7	WILTIES W/O WASHERS, GAPS IN BASEPLATE, LOWER BASEPLATE NEEDS GROUT	09/04/85	85-0187	USE-48-18 (3)
338-803-2-H6	NO WLDG NEEDED VS ACTUAL WELDS, SWAY STRUT HAS NO MOVEMENT	09/04/85	85-0211	
338-004-4-H601	SHIM PLATE BOUGED, EXCESSIVE GAP, GAP COOKED	09/04/85	85-0214	
338-H03-11-H7	WASHERS MISSING, SWAY STRUT DOES NOT ROTATE	09/07/85	85-0273	
338-803-8-H7	BASEPLATE GAP, BUSHING BINDING, LOCATION DIMENSION NOT PER DWG	09/10/85	85-0309	USE-48-18 (3), REWORK-ADJUST CLAMP (4)
338-803-10-H29	THDS STAKED, "S" DIM INCOR, INCORRECT SNUBBER ID, SNUBBER INSTALLED AT ANGLE	09/10/85	85-0315	USE-48-18 (3), REWORK-ADJUST CLAMP (4)
338-803-10-H29	BOLTS DOUBLENUTTED W/THD DAMAGE, MISSING WELD ON SADDLE	09/10/85	85-0316	
4-764	NUTS DO NOT HAVE FULL ENGAGEMENT	09/10/85	85-0322	USE-48-18 (3)
338-803-8-H6	NO LOCKNUT, WELD DETAIL	09/12/85	85-0352	USE-48-18 (3)
338-803-10-H9	WLD NOT PER DWG, JAM NUT THDS STAKED, BUSHING BOUND UP	09/17/85	85-0442	USE-48-18 (3)
338-803-10-H6	BASEPLATE GAP EXCEEDS REQS, WLDG NOT POSS PER DWG, U BOLT THDS STAKED	09/17/85	85-0443	USE-48-18 (3)
338-803-10-H1	WLDG NOT POSS PER DWG, JAM NUTS THDS STAKED, BUSHINGS BOUND UP	09/17/85	85-0444	USE-48-18 (3)
338-803-10-H14	JAM NUTS THDS STAKED, SWAY STRUT BUSHING BOUND UP	09/17/85	85-0445	USE-48-18 (3)
338-803-10-H13	JAM NUTS MISSING, WLD ONE SIDE VS PRESENT ALL-ROUND	09/17/85	85-0446	USE-48-18 (3)
338-803-10-H15	WASHER & JAM NUTS MISSING	09/17/85	85-0447	USE-48-18 (3)
338-803-10-H16	ITEM #4 WELD NOT PER DWG	09/17/85	85-0448	USE-48-18 (3)
338-803-10-H8	JAM NUTS MISSING, THDS STAKED	09/17/85	85-0449	USE-48-18 (3)
338-803-10-H17	JAM NUTS MISSING, THDS STAKED	09/17/85	85-0452	USE-48-18 (3)

SYSTEM: LOW PRESSURE INJECTION

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33B-GCB-10-H10	WLD NOT PER DWG	09/17/85	85-0454	USE-AB-18 (3)
33B-GCB-10-H7	WLD UNDSZ, WLD NOT PER DWG	09/17/85	85-0455	USE-AB-18 (3), REWORK-REMOVE ARC STRIVE (4)
33B-GCB-10-H18	NO JAM NUT, THD STAKED	09/17/85	85-0457	USE-AB-18 (3)
33B-GCB-2-H3	JAM NUTS MISSING, BUSHING BOUND UP	09/17/85	85-0458	USE-AB-18 (3)
33B-GCB-10-H5	JAM NUTS MISSING, SPACER BOLT LOOSE, BASEPLATE GAP EXCEED REGS	09/17/85	85-0459	USE AB 18 (3), REWORK-INSTALL NUTS, TIGHTEN BOLT (4)
33B-GCB-10-H4	JAM NUTS MISSING, THDS STAKED, BASEPLATE GAP EXCEED REGS	09/17/85	85-0477	USE-AB-18 (3)
33B-GCB-10-H18	JAM NUTS MISSING, THDS STAKED	09/17/85	85-0547	
33B-GCB-2-H2	WLD UNDSZ, NO JAM NUTS, THD STAKED, PIPE CLAMP MOVED, SWAY STRUT BUSHING BOUND	09/18/85	85-0500	USE-AB-18 (3), REWORK-ADJUST CLAMP (4)
33B-GCB-2-H4	JAM NUT MISSING, THD STAKED, STRUT BUSHING BOUND	09/18/85	85-0501	USE-AB-18 (3)
33B-GCB-2-H3	RED HEADS VS WEJ-ITS, FLARE BEVEL VS FILLET WELD, WLD NOT PER DWG	09/18/85	85-0505	USE-AB-18 (3)
33B-GCB-2-H1	THDS STAKED, LUG WLD & JAM NUTS MISSING	09/19/85	85-0516	USE-AB-18 (3)
A-040	HILTI INSTALLED VS WEJ-ITS ON DWG	09/20/85	85-0546	
33C-GCB-2-H5	DIMENSIONS, MISC STRUT DISCREP, WLD DETAIL	09/20/85	85-0547	
33B-GCB-1-H4	WLD UNDSZ, WSHRS MISSING, DIMENSION DISCREP	09/20/85	85-0556	USE AB 18 (3)
33B-GCB-1-H38	THD STAKED, DIMENSION	09/20/85	85-0557	USE AB 18 (3)
33B-GCB-1-H10	DIMENSION, THD STAKED	09/20/85	85-0558	USE-AB-18 (3)
33B-GCB-1-H6	NO WSHR, THD STAKED, CLAMP BOLT LOOSE, DIMENSIONS	09/20/85	85-0559	USE-AB-18 (3), REWORK-TIGHTEN NUT (4)
33B-GCB-1-H8	CLEARANCE, EXTRA WLD, WLD UNDSZ	09/20/85	85-0569	USE AB 18
33C-GCB-10-H20	NO JAM NUTS, THD STAKED	09/20/85	85-0572	USE-AB-18 (3)
33C-GCB-10-H21	NO JAM NUTS, THDS STAKED	09/20/85	85-0573	USE-AB-18 (3)

DAVIS - BEEBE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33C-BCB-10-H03	WLD UNDSZ	09/20/85	85-0574	USE 48 IS (3)
33C-BCB-7-H41	DIMENSIONS, WLD DETAIL, PIPE CLAMP LOOSE	09/20/85	85-0580	USE-48-18 (3), RERWORK-REPLACE SPACER, TIGHTEN NUT (4)
33B-BCB-1-H47	WEAR ON WELD, WLD UNDSZ, WSHRS MISSING, PLATE GAP, DIMENSIONS	09/20/85	85-0583	
33B-BCB-1-H43	DIMENSIONS, SPACERS TACKED, THD STAKED	09/20/85	85-0587	
33B-BCB-1-H49	WLD UNDSZ	09/20/85	85-0588	USE-48-18 (3)
33A-BCB-4-H46	PLATE GAP, WLD DETAIL & UNDSZ	09/21/85	85-0593	
33B-BCB-1-H45	JAM NUT LOOSE, THD STAKED, DIMENSION	09/21/85	85-0595	USE 48 IS, RERWORK-TIGHTEN NUT (15)
34-HCB-9-H10	BOLT SPACING, WLD DETAIL	09/21/85	85-0596	
34-HCB-9-H21	WLD DETAIL	09/21/85	85-0599	USE-48-18 (3)
34-HCB-9-H20	NO WSHR, DIMENSIONS, WLD UNDSZ	09/21/85	85-0600	USE-48-18 (3)
33A-HCB-3-H14	DIMENSION, THD STAKED	09/21/85	85-0603	USE-48-18 (3)
33A-HCB-3-H16	PLATE NOT ON DWG	09/21/85	85-0604	USE-48-18 (3)
33A-HCB-3-H2	INSUFF THD ENGAGEMENT	09/21/85	85-0605	RERWORK-ADJUST (4)
33C-BCB-10-H24	NO JAM NUT, THD STAKED	09/21/85	85-0611	USE-48-18 (3)
33C-BCB-10-H25	NO JAM NUT, THD STAKED	09/21/85	85-0612	USE-48-18 (3)
33C-BCB-10-H19	NO JAM NUT, THD STAKED, SPRING SETTING	09/21/85	85-0613	
33B-BCB-1-H13	CLEARANCE	09/21/85	85-0617	
33B-BCB-1-H11	CLEARANCE, WLD DETAIL	09/21/85	85-0619	
33B-BCB-1-H37	NO WSHRS, CLAMP BOLT LOOSE, THD STAKED, WLD UNDSZ	09/21/85	85-0619	USE-48-18 (3)
33B-BCB-1-H39	THREAD STAKED, PIPE CLAMP GAP	09/21/85	85-0620	USE-48-18 (3)
33B-BCB-1-H39	THREAD STAKED	09/21/85	85-0621	USE-48-18 (3)
33B-BCB-1-H16	BOM DIMENSION, THD STAKED, CONCRETE CRACKED	09/21/85	85-0622	USE-48-18 (3)

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
33B-808-1-H15	NO WSHRS, JAM NUT LOOSE, WLD DETAIL & UNDSZ, STRUT DAMAGE, STRUT BOUND UP	09/21/85	85-0627	
33A-HCB-3-H15	ADDED PLATE NOT ON DWG	09/23/85	85-0625	USE-48-18 (1)
34-HCB-9-H31	MISSING LOCKNUT, THD STAKED, MISSING WSHR	09/23/85	85-0627	USE-48-18 (3)
A-072	DIMENSIONAL, WLD UNDSZ	09/23/85	85-0628	
34-HCB-9-H16	LOCKNUT MISSING, STRUT BINDING, WLD DETAIL	09/23/85	85-0629	USE 48 18 (3)
A-044	BOLT LENGTH & BASEPLATE GAP, WLD UNDSZ & DETAIL, EXTRA PLATE	09/23/85	85-0630	
33B-808-1-H14	DIMENSION, WLD DETAIL & UNDSZ, CLEARANCE	09/23/85	85-0638	
A-045	BASEPLATE GAP, ANCHOR BOLT TYPE, DWG DETAIL	09/23/85	85-0641	
33A-808-8-H7	ANGLE BEARING, STIFF PLATE ADDED TO ANGLE, THD ENGAGEMENT	09/23/85	85-0656	
33A-808-8-H10	INTERNAL DWG DISCREP, BOLT NOT TIGHT, PLATE GAP	09/23/85	85-0657	
33A-808-8-H15	WLD UNDSZ, DIMENSION	09/23/85	85-0658	
33A-808-8-H7	PLATE GAP, DIMENSION, PLATE THICKNESS	09/23/85	85-0659	
33A-808-8-H9	PLATE GAP, STRUT BOUND, NO WSHRS	09/23/85	85-0660	
33C-HCB-9-H14	JAM NUT STRIPPED, NO JAM NUT, THD STAKED, SHIM ON CLAMP	09/24/85	85-0662	USE 48 18 (3)
33C-HCB-9-H15	NO JAM NUT, THD STAKED	09/24/85	85-0663	USE-48-18 (3)
33C-HCB-9-H12	NO JAM NUT	09/24/85	85-0664	USE-48-18 (3)
33C-HCB-9-H13	ADDITIONAL WELD, WLD DETAIL	09/24/85	85-0665	USE 48 18 (3)
33C-808-10-H22	JAM NUTS MISSING	09/25/85	85-0673	USE-48-18 (3)
33B-808-6-H1	JAM NUTS MISSING	09/25/85	85-0674	USE-48-18 (3)
33A-HCB-3-H5	EDGE BOLT BRACING VIOLATIONS, ITEM #7 DIM NOT PER DWG	09/25/85	85-0675	USE 48 18 (3)
33A-HCB-3-H1	WSHR MISSING, 4 WSHRS/BOLT, LOOSE NUT	09/25/85	85-0680	USE 48 18 (3), REWORK-TIGHTEN NUT (4)

15

15

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/IS NUMBER	DISPOSITION
33A-HCB-3-H4	WLDG NOT PER DWG	09/25/85	85-0686	USE-48-18 (3)
33A-HCB-3-H14	WLDG NOT PER DWG	09/25/85	85-0686	
33A-HCB-3-H8	NO BEARING SURFACE AT BASEPLATE, WLDG NOT PER DWG	09/25/85	85-0686	
33B-HCB-10-H14	CONC CRACKS, WLDG NOT PER DWG, ADD'L SHIMS, GREATER BOLT EDGE DISTANCE	09/25/85	85-0700	
33B-HCB-5-H13	JAM NUTS MISSING & SPACERS, THDS STAKED	09/25/85	85-0702	USE-48-18 (3)
33C-HCB-7-H2	GAPS UNACC, DIM NOT PER DWG, SPACER MISSING, ORIENT NOT PER DWG	09/25/85	85-0716	
33B-HCC-35-H21	GAPS UNACC, MISSING JAM NUTS, THDS STAKED, WLD NOT PER DWG	09/25/85	85-0717	USE AG 18 (3)
33B-HCC-35-H3	BASEPLATE GAPS UNACC, WLDG NOT PER DWG	09/25/85	85-0718	USE AG 18 (3)
34-HCB-9-H17	DIM NOT PER DWG	09/26/85	85-0721	USE AG 18 (3)
A-254	BASEPLATE GAPS UNACC, VOID IN CONC, WELDS & DIMEN NOT PER DWG.	09/26/85	85-0726	
33C-HCB-7-H6	DIMEN NOT PER DWG.	09/26/85	85-0734	USE AG 18 (3)
33B-HCB-10-H27	MISSING PC#12 & JAM NUTS, THDS STKD, STRUT BOUND, DIMEN NOT PER DWG.	09/26/85	85-0738	
33B-HCB-10-H26	MISSING JAM NUTS, CLAMP NOT SEATED PROPERLY, STRUT BOUND.	09/26/85	85-0739	USE-48-18 (3)
A-071	DIMEN NOT PER DWG.	09/26/85	85-0741	
33B-HCC-35-H5	WELDS & CLEAR. NOT PER DWG.	09/26/85	85-0745	
33C-HCB-7-H3	WELDS & DIMEN NOT PER DWG, LOOSE CLEVIS, SHIMMER DAMAGED.	09/26/85	85-0749	
33B-HCC-35-H2	WELDS NOT PER DWG, ARC STRIKES	09/26/85	85-0750	USE AG 18 (3), REWORK-REMOVE ARC STRIKE (4)
33B-HCC-35-H4	WELDS NOT PER DWG.	09/26/85	85-0751	USE-48-18 (3)
33B-HCC-35-H13	WELDS NOT PER DWG.	09/27/85	85-0759	USE AG 18 (3)

SYSTEM: LOW PRESSURE INJECTION

DAVIS - BESSIE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NO. BR NUMBER	DISPOSITION
33B-HCC-34-H1	DIMEN & WELD NOT PER DWG.	09/27/85	85-0760	USE AS IS (3)
33C-GCB-7-H13	DIMEN & WELDS NOT PER DWG.	09/27/85	85-0764	
33B-HCC-35-H17	BOLTS NOT PER DWG, LOOSE BOLT, ITEM #4 ON WELD.	09/27/85	85-0768	USE AS IS (3)
33B-HCC-35-H1	WELD NOT PER DWG.	09/27/85	85-0769	USE AS IS (3)
33B-HCC-35-H7	WELD NOT PER DWG.	09/27/85	85-0770	USE AS IS (3)
33B-HCC-35-H27	NOT PER DWG.	09/27/85	85-0771	USE AS IS (3)
33B-HCC-35-H22	WELD NOT PER DWG.	09/27/85	85-0772	USE AS IS (3)
33B-HCC-35-H6	WELD NOT PER DWG.	09/27/85	85-0773	USE AS IS (3)
33C-GCB-7-H11	DIMEN & WELDS NOT PER DWG, MISSING WASHERS.	09/27/85	85-0774	USE AS IS (3)
33C-HCB-24-H54	WELDS & DIMEN NOT PER DWG, MISSING LOCKWIRE, MAT'LS NOT PER BOM.	09/28/85	85-0777	
74-1155-H1	DIMEN NOT PER DWG, THD ENGAGE UNACC.	09/28/85	85-0778	
33B-GCB-1-H21	THDS OF ROD NOT VISIBLE, WELDS NOT PER DWG.	09/28/85	85-0779	USE AS IS (3), REMARK-ADJUST ROD (4)
33B-GCB-1-H22	WELDS NOT PER DWG, GREASE FITTINGS DAMAGED, SNUBBER LEAKING.	09/28/85	85-0780	USE AS IS, REMARK-REPLACE FITTINGS & REPAIR SEAL (4)
33B-HCC-35-H18	BASEPLATE GAPS UNACC, WELDS NOT PER DWG.	09/28/85	85-0782	
33B-HCC-26-H12	WELDS NOT PER DWG.	09/28/85	85-0783	USE-AS-IS (3)
33A-GCB-8-H1	WELDS NOT PER DWG, BASEPLATE GAP UNACC.	09/28/85	85-0784	
A-084	DIMEN NOT PER DWG.	09/28/85	85-0786	
A-083	WELDS & DIMEN NOT PER DWG.	09/28/85	85-0787	
14-HCB-9-H18	WELDS NOT PER DWG.	09/28/85	85-0789	
33C-GCB-7-H45	WELDS & DIMEN NOT PER DWG, IMPROPER BRACING SETTING.	09/30/85	85-0790	
A-41	WELDS NOT PER DWG, BOLT #7 COULD NOT BE TORQUED, STUDS CUT.	09/30/85	85-0791	

15

15

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/FR NUMBER	DISPOSITION	
33C-603-7-H4	BOLTS, DIMEN, & WELDS NOT PER DWG, ITEMS NOT PER BOM.	09/30/85	85-0792	USE AS IS (3)	15
33C-603-7-H10	MISSING WELDS & DIMEN, CLEARANCE NOT PER DWG.	09/30/85	85-0793	USE AS IS (3)	
33B-603-1-H17	WELD NOT PER DWG.	09/30/85	85-0794	USE AS IS (3)	
33B-603-1-H18	DIMEN & WELDS NOT PER DWG.	09/30/85	85-0795	USE AS IS (3)	15
33B-603-1-H22	WELDS NOT PER DWG.	09/30/85	85-0797	USE AS IS (3)	
33B-H00-34-H2	CLAMP ROTATED, THDS STAKED.	09/30/85	85-0799	USE AS IS (3)	
35-H00-27-H20	DIMEN & ITEMS NOT PER DWG.	09/30/85	85-0800	USE AS IS, REWORK-ADD OR REPLACE WASHERS(4)	15
35-H00-27-H21	WELDS & DIMEN NOT PER DWG.	10/01/85	85-0801		
34-H03-9-H19	WLDs NOT PER DWG, HEAVY CORROSION, DIMENSIONS NOT PER DWG	10/03/85	85-0804	USE AS IS (3), REWORK-REMOVE RUST & PAINT(4)	
34-H03-9-H20	WLDs NOT PER DWG & DEFECTS	10/03/85	85-0805	USE AS IS (3)	
33B-603-1-H41	WLDs NOT PER DWG	10/03/85	85-0809		
33B-603-1-H2	WELDS MISSING, BASEPLATE GAP UNACC, WLDs NOT PER DWG	10/03/85	85-0810		
33B-603-1-H1	WLDs NOT PER DWG, BASEPLATE GAP UNACC	10/03/85	85-0811	USE AS IS (3)	15
33B-603-1-H40	PLATE DIMENSIONS NOT PER DWG	10/03/85	85-0812	USE AS IS (3)	
4-222	BASEPLATE NOT ACC, NO THD ENGAGEMENT ON BOLTS, CONCRETE SPALLING	10/03/85	85-0826	USE AS IS (3)	15
33B-603-10-H31	WELDS MISSING, WLDs UNDOI	10/03/85	85-0827	USE AS IS (3)	
33B-603-10-H37	WLDs NOT PER DWG, ITEMS NOT PER BOM	10/03/85	85-0828		
33B-603-10-H33	DIM NOT PER DETAIL	10/03/85	85-0829	USE AS IS (3)	
33B-603-1-H27	BOLT STKD & THDS IN SHEAR, LOCK NUT LOOSE, WLDs NOT PER DWG, NO ID ON SPRING CAM	10/03/85	85-0834		
33B-H00-34-H5	BOLTS NOT PER BOM, WLDs NOT PER DWG	10/03/85	85-0836		
33B-H00-34-H4	FROZEN LOCKNUT, BOLT SPACING, DIM & WLDs NOT PER DWG	10/03/85	85-0837		

SYSTEM: LOW PRESSURE INJECTION

DAVIS - BESSIE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NOV/85 NUMBER	DISPOSITION
338-808-1-H26	WLDG & DIM NOT PER DWG & BOM, THDS STAKED	10/03/85	85-0838	USE AS IS (7)
338-808-10-H40	BASEPLATE GAPS UNACC, ARC STRIKES ON PIPE NEAR WELD	10/03/85	85-0842	USE AS IS (3), REWORK-REMOVE ARC STRIKES (4)
4-187	CONC CRACKED	10/03/85	85-0845	USE AS IS (3)
338-808-1-H36	WSHR MISSING, ITEM #4 NOTCHED	10/03/85	85-0846	USE AS IS (7)
4-211	GUSSET PLATES, WLDG & PIPE SADDLE NOT PER DWG, BASEPLATE GAP UNACC	10/03/85	85-0847	
338-808-10-H36	DIMENSIONS, WELD DETAIL & UNDERSIZE	10/03/85	85-0848	USE AS IS (7)
338-808-1-H12	DIMENSIONS, WELD DETAIL B/M PROB.	10/03/85	85-0849	USE AS IS (7)
338-808-10-H41	WELD DETAIL	10/03/85	85-0857	USE AS IS (7)
338-808-10-H38	WELD SIZE, TRUNNION LENGTH & THICK	10/04/85	85-0867	
338-808-10-H42	TRUNNION LENGTH & THICK	10/04/85	85-0884	
4-043	DIMENSION, WELD DETAIL	10/04/85	85-0885	
338-808-10-H1	BOLT NOT INSTALLED, PLATE WELD TO EMBELL, WELD DETAIL & UNDERSZ, ITEM ROTATED	10/04/85	85-0886	
338-808-1-H27	MISALIGNMENT OF 3 DEG., THD STAKED, DIMEN. INCORRECT	10/05/85	85-0927	USE AS IS (7)
338-808-1-H24	BASEPLATE GAP, LOOSE JAMNUT, STRUT @ 6 DEG. ANGLE & IS BOUND UP	10/05/85	85-0924	
338-808-1-H33	MEMBER LOCATION DIMENSIONS INCORRECT	10/05/85	85-0925	
338-808-10-H32	WELDS UNDERSZ	10/05/85	85-0926	
338-808-1-H34	WLD MISSING, THDS STAKED, STRUT BOUND	10/05/85	85-0927	
338-808-1-H25	MISSING WASHERS, WLD DETAIL MISSING, WLD UNDERSZ, SWAY STRUT BOUND 100%	10/05/85	85-0928	USE AS IS (7)
338-808-1-H31	THDS STAKED, MEMBER DIMEN. INCORRECT	10/05/85	85-0929	USE AS IS (7)
338-808-10-H35	DWG DETAILS INCORRECT	10/05/85	85-0930	
459	LACK FULL AND ENGAGE, BASEPLATE GAP, MEMBER INSTALLED NOT PER DWG.	10/08/85	85-0963	

15

15

15

Page No. 10
11/01/85

SYSTEM: LOW PRESSURE INJECTION

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	WCR/BR NUMBER	DISPOSITION
33C-HCC-129-H2	ANCHOR BOLT TYPES CHANGED WELD LENGTH SHORTENED	10/17/85	85-1269	
33C-HCC-129-H2	1 1/2" GROUT WELDS UNDERSIZED OR NOT SYMBOL SHOWN, SUPPORT CONFIG. CHANGE	10/17/85	85-1270	
M-1166-H2	WELD UNDERSIZE, WELD TYPE CHANGED	10/17/85	85-1271	
33C-HCC-129-H3	INSTALLED AS 4" CHANNELS NOT T2X2, WELDS	10/17/85	85-1274	
33B-GCB-10-H39	ANCHOR BOLTS NUTS RUSTED, WELD NOT PER DWG., PLAN INCORRECT	10/28/85	85-1518	

115

SECTION 4.0

HIGH PRESSURE INJECTION SYSTEM

SYSTEM: HIGH PRESSURE INJECTION

DAVIS - BESSIE PIPING / SUPPORTS
INSPECTOR FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
33C-CCB-2-H47	WELD UNDERSIZE, PIPE CLAMP DETAIL	08/30/85	85-0149	USE-46-18 (3)
33C-CCB-2-H40	WELD DETAIL, BOLT LOCATION ON ANGLE INCORRECT	08/30/85	85-0151	USE-46-18 (3)
33C-CCB-2-H45	WELDS UNDERSIZE AND CONTAIN AREAS OF UNDERCUT, WELD SIZE MISSING	09/02/85	85-0152	USE-46-18 (3)
33C-CCB-2-H43	WELDS UNDERSIZE, WELD SIZE MISSING	09/02/85	85-0153	USE-46-18 (3)
33C-CCB-2-H46	PLATE DIM INCORRECT, MEMBER SIZES INCORRECT, BOLT LOCATION NOT PER DWG	09/02/85	85-0154	
33C-CCB-2-H44	GAP DIM INACCURATE	09/02/85	85-0155	USE-46-18 (3)
33C-CCB-2-H260	MEMBER SIZES INCORRECT, 1 SIDE WELD VS. DESIGNED 3 SIDES.	09/02/85	85-0156	USE-46-18 (3)
33C-CCB-2-H76	WELD UNDER SIZE AND CONTAINS AREAS OF UNDERCUT	09/02/85	85-0157	USE-46-18 (3)
33C-CCB-2-H41	ONE SIDE WELD VS. 3 SIDES	09/02/85	85-0158	USE-46-18 (3)
A-056	WELD UNDERSIZE	09/02/85	85-0160	USE-46-18 (3)
33C-CCB-2-H51	SPRING SETTING QUESTIONABLE	09/02/85	85-0165	USE-46-18 (3)
33C-CCB-2-H50	UNDERSIZE WELD, NUT DOES NOT HAVE FULL THREAD ENGAGEMENT.	09/02/85	85-0177	USE-46-18 (3)
33C-CCB-2-H37	MISSING WELD SYMBOL, BOLT LOCATION INACCURATE	09/03/85	85-0167	USE 46 18 (3)
33C-CCB-2-H39	ANCHORBOLT LOCATION INACCURATE	09/03/85	85-0168	USE-46-18 (3)
33C-CCB-2-H72	CLEARANCE GAP INCORRECT, WELD UNDERSIZE.	09/03/85	85-0169	USE 46 18
33C-CCB-2-H27	MEMBER SIZE IS INACCURATE, WELDS MISSING	09/03/85	85-0170	USE-46-18 (3)
33C-CCB-2-H30	SUP MEMBER LOCAT. IS INACCURATE, WLD MISSING & POOR QTY WLDs, 3 WASHERS/1 BOLT	09/03/85	85-0171	USE-46-18 (3)
33C-CCB-2-H49	WELDS UNDERSIZE, NO CLEARANCE & PAINT ON GRAPHITE SURFACE	09/03/85	85-0172	USE-46-18 (3)
33C-CCB-2-H48	WELDS UNDERSIZE, WELD ONE SIDE VS. 3, PAINT ON GRAPHITE SURFACE	09/03/85	85-0173	USE-46-18 (3)
33C-CCB-2-H42	WELD UNDERSZ. WELD SO NOT ON DWG, BOLT DOES NOT HAVE FULL THREAD ENGAGEMENT	09/03/85	85-0174	USE 46 18 (3)

SYSTEM: HIGH PRESSURE INJECTION

DAVIS - BESSE PIPING / SUPPORTS
INSPECTOR FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
A-257	WELD UNDERSIZE, WELD NOT ON DWG.	09/03/85	85-0175	USE AS IT (3)
33C-CCB-2-H52	LOOSE ANCHORBOLT, WELDS UNDERSIZE.	09/03/85	85-0180	USE-48-18 (3)
33C-CCB-2-H53	WELDS UNDERSIZE	09/03/85	85-0181	USE-48-18 (3)
33C-CCB-2-H55	ITEM I.D. ON DWG INCORRECT	09/03/85	85-0182	USE-48-18 (3)
33C-CCB-2-H56	CLANCE GAPS NOT PER DWG, MISSING WELD, NUT DOES NOT HAVE FULL THREAD ENGAGEMENT.	09/03/85	85-0183	USE-48-18 (3), REMOVED-SHIM (4)
33C-CCB-2-H54	WELDS UNDST, STRUCT MEMBER LENGTHS & INSTALLED ANGLES NOT PER DWG.	09/03/85	85-0193	USE-48-18 (3)
33-CCB-2-H34	FLD WELDS NOT WELDED PER DWG	09/04/85	85-0196	USE-48-18 (3)
A255	UNDERSIZE WELD	09/04/85	85-0199	USE-48-18 (3)
33C-CCB-2-H33	FIELD WELDS UNDERSIZE, FIELD WELDS NOT WELDED PER DWG.	09/04/85	85-0200	USE-48-18 (3)
33C-CCB-2-H35	ANCHORS HAVE > 2 WASHERS, BEARING GAP WRONG DIM.	09/04/85	85-0201	
33C-CCB-2-H29	WELDS UNDERSIZE, WELD MISSING	09/04/85	85-0208	USE-48-18 (3)
33C-CCB-2-H28	LOAD FLANGE ANGLED	09/04/85	85-0209	USE-48-18 (3)
33C-HCB-2-H43	SHIMS WRONG, CLEARANCE IS REVERSE OF DETAIL DWG.	09/04/85	85-0213	USE-48-18 (3)
33C-HCB-2-H42	WLOS UNDST, MEMBER SIZE LARGER THAN DRAWING	09/05/85	85-0215	USE-48-18 (3)
33C-CCB-2-H14	WLD UNDST, MEMBERS LONGER TAN SPECIFIED	09/05/85	85-0218	USE-48-18 (3)
33C-CCB-2-H7	BASEPLATE GAP, WLD UNDST & NOT PER DWG, 1/2" DROP IN ANCHORS	09/05/85	85-0229	USE-48-18 (3)
33C-HCC-124-H6	BUSHING FROZEN, MISSING JAM NUT, CLAMP BOLT THDS STAKED, WLDs NOT PER DWG	09/05/85	85-0230	USE 48-18 (3)
33CCB-2-H8	DIMENSIONS NOT PER DWG	09/05/85	85-0231	USE-48-18 (3)
33C-HCC-124-H4	SPACERS INACCURATE, WLD PROBLEMS	09/05/85	85-0232	USE-48-18 (3)
33C-CCB-2-H20	WLD UNDST	09/05/85	85-0233	

SYSTEM: HIGH PRESSURE INJECTION

DAVIS - 66366 PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR / SR NUMBER	DISPOSITION
33C-HCC-R1-H1	BASEPLATE GAP, WLD8 WRONG SIZE	09/05/85	85-0235	USE-48-18 (3)
33C-HCC-124-H5	SPACERS & JAM NUT MISSING, WELD PROBLEMS	09/05/85	85-0236	USE-48-18 (3), REWORK-400 BUSHING SPACERS (4)
33C-HCB-19-H1	NON-STD PIPE CLAMP, BASEPLATE GAP, INTERFERENCE WITH CONDUIT	09/05/85	85-0237	
A-392	WELDS NOT PER DWG	09/05/85	85-0241	USE-48-18 (3)
A-053	BASEPLATE GAPS, WLD UNDSZ, FULL PEN WELD NOT FLUSH	09/06/85	85-0228	
33C-HCB-2-H41	WLD8 NOT PER DWG, GROUT CRACKED, WASHERS MISSING	09/06/85	85-0247	USE-48-18 (3)
33C-HCB-2-H37	JAM NUT MISSING	09/06/85	85-0246	USE-48-18 (3)
33C-HCB-2-H39	WLD8 UNDSZ & DETAILS INCORRECT, VOID IN GROUT	09/06/85	85-0247	USE-48-18 (3)
33C-HCB-2-H38	WLD DETAIL INCORRECT	09/06/85	85-0248	USE-48-18 (3)
33C-HCB-12-H1	BUTT WELD IN LIEU OF FILLET, 2 NUTS INSTALLED PER ANCHORBOLT	09/06/85	85-0251	
33C-HCB-2-H19	BASEPLATE GAP, WLD UNDSZ & INCORRECT DETAIL	09/06/85	85-0253	USE-48-18 (3)
A-046	WELD UNDSZ	09/06/85	85-0254	USE-48-18 (3)
A-048	WELD UNDSZ	09/06/85	85-0255	
A-047	WELD UNDSZ	09/06/85	85-0256	USE-48-18 (3)
A-190	ANCHORBOLTS HAVE 3 WASHERS, BASEPLATE GAPS	09/06/85	85-0257	
33C-HCB-2-H6	NO WASHERS ON TAP BOLTS, 1/2" STUD IN LIEU OF 1/2" TAP BOLT, WLD UNDSZ	09/06/85	85-0258	USE-48-18 (3)
33C-HCC-124-H7	WELD UNDSZ & DETAIL INCORRECT	09/06/85	85-0259	USE-48-18 (3)
33C-HCB-2-H40	WLD8 UNDSZ	09/06/85	85-0261	
33C-HCC-R1-H2	BEAMS WRONG SIZE	09/06/85	85-0262	USE-48-18 (3)
33C-HCC-R1-H3	NO WASHERS, BASEPLATE GAP, WLD8 UNDSZ	09/06/85	85-0269	
33C-CLB-2-H13	WELD NOT PER DWG	09/07/85	85-0276	

SYSTEM: HIGH PRESSURE INJECTION

DAVIS - BESSIE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
330-008-2-H21	BEAM NOT PER DWG	09/07/85	85-0277	USE-AS-IS (3)
330-008-2-H21	NON STANDARD CLAMP, MISSING JAM NUT, WLD UNDSZ, THDS STAKED, GROUT CRACKED/BROWN	09/09/85	85-0291	
330-008-2-H24	WLD UNDSZ, DETAIL NOT CORRECT, TWO NUTS PER STUD	09/09/85	85-0300	USE-AS-IS (3)
A-51	WELDS UNDSZ	09/09/85	85-0305	USE-AS-IS (3)
330-008-2-H16	DIM NOT ON DWG, MISSING JAM NUTS, NON STANDARD CLAMP, CLEVIS CONTACTING CLAMP	09/09/85	85-0307	USE-AS-IS (3), REWORK-INSTALL SPACER (4)
330-008-2-H11	WLD UNDSZ, 1/2" TAP BOLTS IN LIEU OF 1/2" STUDS, WLD DETAIL NOT PER DWG	09/10/85	85-0314	USE-AS-IS (3)
330-008-2-H9	ARC STRIKES PRESENT, WLD UNDSZ, DIM NOT PER DWG	09/10/85	85-0317	USE AS IS, REWORK-REMOVE ARC STRIKES & PERFORM NDE
A-50	WLD UNDSZ	09/10/85	85-0318	USE-AS-IS (3)
330-008-2-H10	WASHER MISSING, BOLTS IN LIEU OF STUDS (4 IN LIEU OF 6), WLD NOT PER DWG	09/10/85	85-0320	
330-008-2-H12	STRUT DIM INCORRECT, THDS STAKED, NON-STD CLAMP, MISSING JAM NUT & WELD	09/10/85	85-0321	USE-AS-IS (3)
334-008-8-H4	MISSING WASHERS, WLD UNDSZ, DIM NOT PER DWG	09/10/85	85-0326	USE AS IS
334-008-8-H2	WLD DETAIL NOT PER DESIGN, MEMBER LOCAT DIM NOT PER DWG	09/10/85	85-0327	USE-AS-IS (3)
334-008-8-H6	PIPE CLAMP LOOSE, WLD OVERSZ BY 1/8"	09/10/85	85-0328	USE-AS-IS (3), REWORK TIGHTEN CLAMP (4)
334-008-8-H11	WLD ALL AROUND VS 2 SIDES	09/10/85	85-0329	USE AS IS (3)
330-008-12-H2	WLD NOT PER DWG, BASEPLATE GAP, LOCKNUTS FROZEN, ITEMS MISSING FROM BOM	09/10/85	85-0331	
330-008-19-H7	MEMBER DIM & LOC INCORRECT, WLD DETAILS INCORRECT, WASHERS MISSING	09/10/85	85-0333	
330-008-2-H13	NON-STD CLAMP, JAM NUT MISSING, MISSING WELD	09/10/85	85-0339	
330-008-2-H17	DISTORTION, UNDERCUT, HOLE IN MEMBER, WELD DETAIL, NO LOCKNUT, NON STD CLAMP	09/11/85	85-0355	USE AS IS (3)

SYSTEM: HIGH PRESSURE INJECTION

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/GR NUMBER	DISPOSITION
33C-HCC-P1-H6	WELD DETAIL	09/11/85	85-0359	USE-48-18 (3)
33C-HCC-P1-H6	WELD DETAIL	09/11/85	85-0360 "	USE-48-18 (3)
33C-HCC-P1-H9	WELD DETAIL & UNDERSIZE	09/12/85	85-0363	USE-48-18 (3)
33C-HCC-P1-H10	WELD DETAIL, SO.HD BOLT VS. HEY	09/12/85	85-0366	USE-48-18 (3)
33C-HCC-P1-H5	WELD DETAIL & UND. SIZE	09/12/85	85-0367	USE-48-18 (3)
33C-HCC-P1-H7	WELD DETAIL	09/12/85	85-0368	USE-48-18 (3)
33C-HCC-P1-H4	WELD DETAIL, BIGGER WELD, HGR ASSEMBLY LOOSE	09/12/85	85-0376	USE-48-18 (3), REWORK-ADJUST (4)
33C-COB-19-H2	CONC. CHIP., WELD QUALITY, NONSTD CLAMP, NO COONUT, DIMENSIONS	09/12/85	85-0377	USE-48-18 (3)
33C-HCC-P1-H12	ORIENTATION ON DWG, WELD DETAIL & UNDERSIZE, COPING, CLEARANCE	09/12/85	85-0379	USE-48-18 (3)
A-054	PIPE HOLE MADE W/TORCH NOT DRILL, WLDs NOT PER DWG & UNDSZ, SUPP NOT PER DWG	09/17/85	85-0388	
33C-HCC-P1-H13	WELD DEFECTS	09/13/85	85-0390	USE-48-18 (3)
33C-HCC-P1-H14	WLD UNDSZ, BASEPLATE SPACING VIOLATION	09/14/85	85-0397	
33C-HCC-P1-H15	WLDs NOT PER DWG, CORROSION ON BASEPLATE NUTS	09/17/85	85-0483	
33C-COB-2-H18A	STDIM NOT PER CATALOG, LOCKNUTS & WASHERS MISSING	09/18/85	85-0487	USE-48-18 (3)
33C-COB-19-H17	HGR BINDING, JAM NUTS MISSING	09/18/85	85-0488	USE-48-18 (3), REWORK-ADJUST (4)
33C-COB-19-H9	ITEMS REVERSED ON DWG, WLD UNDSZ, WLD DETAIL NOT POSS	09/19/85	85-0519	
33C-COB-19-H11	WLD UNDSZ, GAPS, WLD DETAIL MISSING ON DWG, CLEARANCE, NO WASHER	09/19/85	85-0520	
A-055	SADDLE LENGTH, WLD UNDSZ, DWG DETAIL DISCREP	09/19/85	85-0521	USE-48-18 (3)
33C-COB-2-H1	01MB, WLD DETAIL, SADDLE LENGTH, DWG REFERENCE	09/20/85	85-0525	

SYSTEM: HIGH PRESSURE INJECTION

DAVIS - BESSE PIPING / SUPPORTS
INSPECTOR FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
330-CCB-19-H7	WLD UNDER, WLD DETAIL, SHIMS NOT ON DWG, BASEPLATE THICKER THAN DWG	09/20/85	85-0540	
330-CCB-2-H2	EXTRA GROUT, CLEARANCE, DIMENSION PROBLEMS, NO WSHRS, WLD DETAIL	09/20/85	85-0541	
330-CCB-3-H2	DIM DISCREP, WLD DETAIL	09/20/85	85-0552	USE-46-18 (3)
A-56	DIMENSION DISCREP	09/20/85	85-0553	USE-46-18 (3)
A-57	DIMENSION DISCREP	09/20/85	85-0554	
330-CCB-2-H4	LOCKNUT & WSHR MISSING, WLD DETAIL	09/20/85	85-0561	USE 46 18 (3)
330-CCB-3-H1	DIM PROBLEMS, WLD DETAILS, ARC STRIKE, BASEPLATE CRACK	09/20/85	85-0576	
330-CCB-2-H3	WLD DETAIL, DIM PROBLEM	09/20/85	85-0584	
330-CCB-19-H5	WLD UNDER	09/20/85	85-0585	USE-46-18 (3)
330-CCB-19-H8	WLD UNDER, DETAIL, PLATE GAP	09/20/85	85-0586	USE 46 18 (3)
330-CCB-2-H6	DIMENSIONS, THD STAKED, STRUT LACKS MOV'T	09/20/85	85-0589	USE-46-18 (3)
330-CCB-19-H6	WLD UNDER, MAT'L NOT ON BOM	09/21/85	85-0594	USE 46 18 (3)
330-CCB-3-H4	DIMENSION, MORE WELD, THD STAKED	09/21/85	85-0596	USE-46-18 (3)
330-CCB-2-H23	SHIM DIM, PLATE GAP, WLD DETAIL & UNDER	09/23/85	85-0644	
330-CCB-2-H22	ANCHOR BOLT SPACING WITH OTHER BOLT, DIMENSIONS, PLATE BEARING	09/23/85	85-0650	
330-CCB-3-H6	WLD DETAIL, DIMENSIONS	09/23/85	85-0655	
31-HCC-36-H9	WELDS NOT PER DWG.	09/23/85	85-0742	USE 46 18 (3)
31-HCC-36-H2	PLATE GAP, WLD DETAIL	09/24/85	85-0666	USE 46 18 (5)
31-HCC-36-H5	BOLT SPACING, WLD & DIMENSIONS NOT PER DWG	09/25/85	85-0679	USE-46-18 (3)
31-HCC-36-H6	WLD UNDER	09/25/85	85-0680	USE-46-18 (3)
31-HCC-36-H3	WSHRS MISSING, BASEPLATE GAP UNACC, WLD PER DWG NOT POSSIBLE	09/25/85	85-0681	

15

15

SYSTEM: HIGH PRESSURE INJECTION

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION	
31-HCC-36-H4	WSHRs MISSING, ITEMS 2&3 AND DIMENSIONS NOT PER DWG	09/25/85	85-0682	USE-AS-IS (3)	
37C-CCB-3-H18	WLDs NOT PER DWG, GAPS UNACC, MISSING WSHRS & LOCKNUTS	09/25/85	85-0699	USE AS IS (3)	
37C-CCB-3-H3	NOT FULL BASEPLATE BEARING, DIM & WLDs NOT PER DWG	09/25/85	85-0705	USE AS IS (3)	15
31-HCC-36-H10	DIMEN & WELD NOT PER DWG.	09/25/85	85-0709	USE AS IS (3)	
31-HCC-36-H8	WLDs & ITEM #3 NOT PER DWG	09/25/85	85-0710	USE AS IS (3)	
31-HCC-36-H7	BASEPLATE GAP UNACC, ITEM #5 NOT PER DWG	09/25/85	85-0712	USE AS IS (3)	15
37C-CCB-19-H12	WLDs & DIM NOT PER DWG, STRUT BOUND UP, BOLT SPACING VIOLATION	09/25/85	85-0719		
31-HCC-36-H11	BOLT SPAC, THDS, DIM, BRACKETS NOT PER DWG, BASEPLATE GAP UNACC.	09/26/85	85-0723	USE AS IS (3)	
31-HCC-36-H12	BOLT SPAC & WELDS NOT PER DWG, THDS STAKED, MISSING LOCK NUTS.	09/26/85	85-0724	USE-AS-IS (3)	
31-HCC-36-H13	WELDS & DIMEN NOT PER DWG, THDS STAKED, MISSING LOCK NUTS.	09/26/85	85-0725	USE-AS-IS (3)	
31-HCC-36-H14	GAP UNACC, DIMEN & WELDS NOT PER DWG, PIN STAKED, STRUT BOUND.	09/26/85	85-0730		
31-HCC-36-H16	WELD NOT PER DWG.	09/26/85	85-0731	USE AS IS (3)	
31-HCC-36-H17	WELD & DIMEN NOT PER DWG.	09/26/85	85-0732		
31-HCC-36-H15	WELD & DIMEN NOT PER DWG.	09/26/85	85-0733	USE AS IS (3), REWORK-REPLACE ROD (4)	
31-HCC-36-H19	WELDS & DIMEN NOT PER DWG, PINS & THDS STAKED.	09/26/85	85-0735	USE-AS-IS (3)	
31-HCC-36-H18	WELDS & DIMEN NOT PER DWG, ADD'L PLATE NOT ON DWG.	09/26/85	85-0736	USE AS IS (3)	
A-68	WELDS NOT PER DWG, CONC CHIPPED.	09/27/85	85-0762		
31-HCC-36-H20	ABANDONED ANCHORS, WELDS & DIMEN NOT PER DWG.	09/27/85	85-0763	USE AS IS (3)	15

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
4-191	GROUT LOOSE, DIMENSIONS, WRAPPER THICK, PLATE THICK	10/04/85	85-0861	
M-1117-H27	DIMENSIONS	10/11/85	85-1116	
M-1117-H26	ADDITIONAL PLATE, DIMENSION	10/11/85	85-1117	
M-1117-H9	DIMENSION	10/11/85	85-1119	
M-1117-H10	ANCHOR BOLT C-C DIMENSION, DIMENSION	10/11/85	85-1120	
M-1117-H11	ANCHOR BOLT C-C DIMENSION, DIMENSION	10/11/85	85-1121	
M-1117-H12	ANCHOR BOLT C-C DIMENSION, DIMENSION	10/11/85	85-1122	
M-1117-H25	TACK WELD, B/M PROBLEM	10/11/85	85-1123	
35-HCC-21-H6	PLATE GAP, DIMENSION	10/11/85	85-1129	
35-HCC-21-H14	PLATE GAP	10/11/85	85-1130	
35-HCC-21-H10	WELD VS TACK ON SHIM	10/12/85	85-1136	
35-HCC-21-H15	WELD DETAIL & SIZE, DIMENSION	10/12/85	85-1137	
35-HCC-21-H9	WELD DETAIL, DIMENSION	10/12/85	85-1138	
35-HCC-21-H12	PL. GAP, WELD DETAIL	10/12/85	85-1139	
35-HCC-21-H11	EDGE DISTANCE, WELD DETAIL, DIMENSION	10/12/85	85-1140	
C-900A-511	DIMENSIONS FOR ANCHOR BOLT LOCATION	10/12/85	85-1144	
35-HCC-75-H8	WELD SIZE	10/12/85	85-1145	
M-1117/H3	DRAWING DETAIL	10/12/85	85-1146	
35-HCC-21-H7	DIMENSIONS, WELD SIZE	10/12/85	85-1147	
M-1117/H5	DIMENSION	10/12/85	85-1148	
M-1117/H7	DIMENSION, C-C BOLT SPACE	10/12/85	85-1149	
35-HCC-21-H8	WELD DETAIL	10/12/85	85-1151	USE AS IS (J)
M-1117/H4	C-C BOLT SPACE, DIMENSION, BOLT DETAIL, CLAMP BOLT LOOSE	10/12/85	85-1153	

SYSTEM: HIGH PRESSURE INJECTION

DAVIS - BESSIE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	WCR SR NUMBER	DISPOSITION
M-008-11-3-H	MATERIAL & CONFIGURATION -- DETAIL A	10/12/85	85-1154	USE AS IS (D)
M-008-11-3-H	MATERIAL & CONFIGURATION -- DETAIL B	10/12/85	85-1155	
M-1117/H6	CHC BOLT SPACE, NO WEEP HOLD, DIMENSION	10/12/85	85-1156	
35-H00-75-H6	DIMENSIONS, WELD DETAIL	10/14/85	85-1166	
A-012	FILLET WELD CHANGED TO FLARE BEVEL	10/14/85	85-1167	
A-205	SHIMS UNDER BASE PLATE	10/14/85	85-1168	
35-H00-21-H16	MEMBER LENGTHS SHORTENED WELD SIZE	10/14/85	85-1170	
A-308	PIPE LOCATION	10/22/85	85-1375	
00A-18-1-H2	DIMEN., CLEAR, NOT PER DWG., RUST & FRICTION MARKS ON CYLINDER	10/28/85	85-1498	
00A-18-1-H1	MEMBER NOT PER DRAWING, LOOSE NUT	10/28/85	85-1499	
00A-18-1-H3A	BOLT & SPRING TRAVEL SETTINGS NOT PER DRAWING	10/28/85	85-1516	
00A-18-1-H3B	WRONG MATERIAL	10/28/85	85-1517	

15

15

SECTION 5.0

BORATED WATER STORAGE TANK SUPPLY

(COMMON SUCTION FOR HPI AND LPI SYSTEMS)

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33B-GCB-2-H7	WLD UNDSEZ, WLD MISSING, BRG SETTING OFF	09/05/85	85-0219	USE-48-18 (3)
33A-HCB-1-H1	ANCHORBOLTS OFF, BASEPLATE GAPS, JAM NUT NOT INSTALLED	09/05/85	85-0254	USE-48-18 (3)
33B-GCB-2-H11	WELD NOT PER SPEC	09/05/85	85-0239	
33B-GCB-2-H10	WLDG UNDERSIZE	09/05/85	85-0240	USE-48-18 (3)
33B-GCB-2-H8	ITEMS NOT PER DWG, BEAM UNDSEZ	09/05/85	85-0242	USE-48-18 (3)
33A-HCB-2-H19	ANCHORBOLTS DEFORMED, BASEPLATE BOWED	09/05/85	85-0262	USE-48-18 (3), REWORK-INSTALL BEVELED WASHERS (4)
33A-HCB-2-H18	PIPE TO PLATE WELD INACCURATE	09/05/85	85-0263	USE-48-18 (3)
33B-GCB-2-H9	WELD UNDSEZ, SWAY STRUT BINDING	09/06/85	85-0244	USE-48-18 (3)
33A-HCB-2-H20	WLD UNDSEZ	09/06/85	85-0250	USE-48-18 (3)
33A-GCB-4-H3	WASHERS INTERFERE WITH WELD, JAM NUT MISSING	09/06/85	85-0264	
33A-HCB-2-H21	WLD UNDSEZ	09/06/85	85-0267	USE 48 18 (3)
33A-GCB-4-H2	ACTUAL WELD VS NO WELD SPECIFIED	09/06/85	85-0272	USE-48-18 (3)
33A-GCB-4-H1	SWP > 1/8", NO WELD SPECIFIED VS. ACTUAL WELD	09/07/85	85-0275	USE-48-18 (3)
33A-HCB-2-H22	WASHERS NOT INSTALLED PER PROC, EDGE DIM NOT PER DWG	09/07/85	85-0278	USE-48-18 (3)
33A-GCB-4-H5	ROD END BUSHING BIND, WLDG NOT PER DWG	09/09/85	85-0287	USE-48-18 (3)
33A-GCB-4-H4	THDS STAKED, MISSING JAM NUT	09/09/85	85-0288	USE-48-18 (3)
33A-HCB-2-H17	WLDG NOT PER DWG	09/09/85	85-0289	
33A-GCB-2-H17A	ROD END BUSHING BIND, MISSING JAM NUT, WLD NOT PER DWG, SWAY STRUT INTERFERENCE	09/09/85	85-0290	
33B-HCB-7-H12	WLD UNDSEZ	09/09/85	85-0295	USE-48-18 (3)
33A-HCB-3-H9	3/8" PLATE IN LIEU OF 1/4", WLDG UNDSEZ & NOT PER DWG	09/09/85	85-0297	USE-48-18 (3)
33A-HCB-3-H8	WLD UNDSEZ	09/09/85	85-0298	USE 48 18 (3)

SYSTEM: BORATED WATER STORAGE TANK SUPPLY

DAVIS - BESSE PILING / SUPPORTS
INSPECTION FINDINGS

REV. 13

SUPPORT NUMBER	DESCRIPTION	DATE	ICR/BR NUMBER	DISPOSITION
33A-HCB-2-H13	WLDG NOT PER DWG	09/09/85	85-0299	
33A-HCB-2-H33	WLD UNDSZ, BWAY STRUT BINDING, MEMBER DIM INCOR, INTERFERENCE W/OTHER SUPPORT	09/09/85	85-0306	USE-48-18 (3)
4-079	BOLTS HAVE 3 WASHERS, BASEPLATE GAP, WLD UNDSZ	09/10/85	85-0323	
4-078	BOLTS HAVE 3 WASHERS, BASEPLATE GAP, WLD UNDSZ	09/10/85	85-0324	
33A-HCB-2-H44	NO WASHERS, MISSING JAM NUT, THDS STAKED, DIM NOT PER SPED	09/11/85	85-0343	USE 48 18 (3) 15
33A-HCB-2-H16	'S DIM NOT PER SPED, LOCKNUT & JAM NUTS MISSING	09/11/85	85-0344	USE-48-18 (3), REWORK-TIGHTEN NUTS (4)
33A-HCB-2-H5	'S DIM NOT PER SPED, THDS STAKED, LOCKNUT MISSING	09/11/85	85-0345	USE-48-18 (3)
33A-HCB-2-H29	WELD UNDERSIZE	09/11/85	85-0350	USE-48-18 (3)
33A-HCB-2-H27	PLATE GAP, NO LOCK NUT	09/11/85	85-0351	USE-48-18 (3)
3A-E50-19-H108	WELD DETAIL & UNDERSIZE, ARC STRIKE, UNDERCUT, DIMENSION	09/12/85	85-0369	USE-48-18 (3)
33A-HCB-2-H28	WELD UNDERSIZE & DETAIL, DIMENSIONS, AND STAKED, FIG 88 ROTATED	09/12/85	85-0371	USE-48-18 (3)
33A-HCB-2-H49	BASEPLATE GAP, THDS STAKED, WLDG UNDSZ	09/14/85	85-0402	USE 48-18 (3)
33A-HCB-2-H44	ANCHOR BOLTS NOT TORQUED, WLDG UNDSZ	09/14/85	85-0403	USE-48-18 (3) REWORK - STAMP HANGER # ON SUPPORT (4)
33A-HCB-2-H12	BASEPLATE GAP, THDS STAKED	09/14/85	85-0404	USE-48-18 (3) REWORK-ADJUST CLAMP (4)
33A-HCB-2-H11	THDS STAKED, WLD UNDSZ	09/14/85	85-0405	USE-48-18 (3) REWORK
33A-HCB-2-H15	BRUT THCK NOT PER DWG, WLD UNDSZ	09/14/85	85-0406	
33A-HCB-2-H10	BASEPLATE GAP, WLD UNDSZ & NOT PER DWG	09/14/85	85-0407	USE-48-18 (3)
33A-HCB-2-H71	NO DWG SPECS ON BASEPLATE, WLD UNDSZ	09/14/85	85-0408	USE-48-18 (3) REWORK-

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33A-HCB-2-H1	ANCHORS NOT PER DWG	09/14/85	85-0409	USE-48-18 (3)
33A-HCB-2-H14	WLD UNDSZ, THDS STAKED	09/14/85	85-0410	USE-48-18 (3)
33A-HCB-2-H30	BASEPLATE GAP, WLD NOT PER DWG	09/14/85	85-0411	USE-48-18 (3)
33A-HCB-2-H26	ITEM UNDSZ	09/14/85	85-0412	
33A-HCB-2-H24	WLD UNDSZ	09/14/85	85-0413	USE-48-18 (3)
33A-HCB-2-H32	WLD NOT PER DWG	09/14/85	85-0415	USE-48-18 (3)
33A-HCB-2-H25	WLD9 NOT PER DWG	09/14/85	85-0416	USE-48-18 (3) REWORK-REMOVE ARC STRIKE (4)
33A-HCB-2-H7	WASHS & JAM NUTS MISSING, LUGS UNDSZ, THDS STAKED, WLD UNDSZ	09/14/85	85-0417	
33A-HCB-2-H23	ITEM #1 WRONG DIM, SHIMS INSTALLED INCOR, WLD UNDSZ	09/14/85	85-0418	UTE-48-18 (3)
33A-HCB-2-H8	THDS STAKED, CLAMP INCOR DIM	09/14/85	85-0419	USE-48-18 (3)
33A-HCB-2-H13	WLD9 NOT PER DWG & UNDSZ, BASEPLATE GAP	09/14/85	85-0420	

SECTION 6.0

SERVICE WATER SYSTEM

SYSTEM: SERVICE WATER

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 12

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SA NUMBER	DISPOSITION
41-HBB-7-H1	WLDG NOT PER DWG	09/14/85	85-0423	USE-48-18 (3), REWORK-TIGHTEN (4)
41-HBB-7-H3	DETAILS & ITEMS INCORRECT	09/14/85	85-0424	
41-HBB-7-H2	DETAILS INCORP, LOCK NUTS MISSING, CLAMP MISALIGNED	09/14/85	85-0425	USE-48-18 (3) REWORK-ADJUST CLAMP (4)
41-HBC-35-H40	WLDG NOT PER DWG, LOOSE JAM NUT	09/14/85	85-0426	USE-48-18 (3) REWORK-TIGHTEN JAM NUT (4)
41-HBC-35-H39	WLDG NOT PER DWG	09/14/85	85-0427	USE-48-18 (3)
41-HBC-35-H41	WLDG NOT PER DWG, STRUT IS BOUND	09/14/85	85-0428	USE-48-18 (3)
41-HBC-35-H36	WLDG NOT PER DWG	09/17/85	85-0462	USE-48-18 (3)
41-HBB-7-H4	WLD SYMBOL NOT ON DWG, CLEARANCE, WLD DETAIL	09/19/85	85-0531	
41-HBB-7-H5	WLD DETAIL, LOCKNUT MISSING, STRUT BINDING, INSTALLED SECTION VS DWG	09/19/85	85-0533	
41-HBB-7-H6	WLD DETAIL, STRUT BINDING, LOCKNUT MISSING, PLATE THICKNESS	09/19/85	85-0534	
41-HBC-35-H38	WLD DETAIL, BILL OF MAT'L DISCREP	09/20/85	85-0546	USE-48-18 (3)
A-197	BASEPLATE GAP	09/20/85	85-0575	USE-48-18 (3) 15
41-HBC-35-H50	NO WLD SYMBOL ON DWG	09/20/85	85-0581	USE-48-18 (3)
A-312	WLD UNDSZ, PLATE GAP	09/20/85	85-0582	USE-48-18 (3) 15
41-HBC-35-H49	DIMENSION	09/21/85	85-0592	USE-48-18 (3)
41-HBC-35-H12	THDS STAKED, WLDG NOT PER DWG, BOLTS SENT, ORIENTATION DISCREP ON DWG	09/25/85	85-0676	USE-48-18 (3), REWORK-REPLACE BOLTS (4)
41-HBC-35-H8	THDS STAKED, WLDG NOT PER DWG	09/25/85	85-0677	USE-48-18 (3) 15
A-141	WHRB MISSING, BASEPLATE GAP, WLDG NOT PER DWG	09/25/85	85-0684	
41-HBC-35-H3	WHRB MISSING, BASEPLATE GAP, THDS STAKED	09/25/85	85-0690	USE-48-18 (3)
41-HBC-35-H1	THDS STAKED	09/25/85	85-0691	USE-48-18 (3)

DAVIS - PESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR / SR NUMBER	DISPOSITION
41-H8C-35-H1	BOLTS INSTALLED IN EMBED PLATE. WLDG UNDER	09/25/85	85-0692	USE AS IS (3)
41-H8C-35-H8	THDS STAKED, WSHRS MISSING. ITEM 43 NOT PER DWG	09/25/85	85-0693	USE AS IS (3)
41-H8C-35-H10	WLDG NOT PER DWG	09/25/85	85-0697	USE AS IS (3)
41-H8C-35-H54	THDS STAKED, DIM NOT PER DWG, LOOSE SPACER	09/25/85	85-0714	USE-AS-IS (3)
41-H8C-35-H53	THDS STAKED, CLAMP JAMMED	09/25/85	85-0715	USE-AS-IS (3)
A-198	NO WELD DET.	09/26/85	85-0744	
41-H8C-44-H1	BASEPLATE GAP UNACC.	09/26/85	85-0752	USE-AS-IS (3)
41-H8C-35-H7	WELDS & DIMEN NOT PER DWG, MISSING WASHERS, DAMAGED STEEL MEMBER.	09/26/85	85-0753	
41-H8C-44-H2	DIMEN & WELDS NOT PER DWG.	09/26/85	85-0754	
41-H8C-35-H104	BASEPLATE GAP UNACC, WELD NOT PER DWG.	09/26/85	85-0755	USE AS IS (3)
41-H8C-35-H11	THDS STAKED, DIMEN NOT PER DWG.	09/27/85	85-0765	USE-AS-IS (3)
A-7	WELD ALL-ROUND VS TWO SIDES	09/30/85	85-0761	USE AS IS (3)
41-H8C-46-H52	MEMBER SIZE, WELD DETAIL	10/04/85	85-0868	
41-H8C-47-H53	THD STAKED, DIMENSIONS	10/04/85	85-0870	
41-H8C-47-H10	THD STAKED	10/04/85	85-0871	
157	SADDLE PLATE THICK	10/04/85	85-0872	
A-155	SADDLE PLATE THICK, WELD UNDERSIZE	10/04/85	85-0873	
A-151	WELD NOT GROUNDED & UNDERSIZE	10/04/85	85-0874	
A-152	PLATE SIZE, WELD UNDERSIZE	10/04/85	85-0875	
A-149	SADDLE PLATE THICK	10/04/85	85-0876	
A-150	SADDLE PLATE THICK	10/04/85	85-0877	
41-H8C-47-H52	MEMBER SIZE, WELD SIZE 1/4 DETAIL	10/04/85	85-0878	
A-159	WELD UNDERSIZE	10/04/85	85-0879	

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 13

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/GR NUMBER	DISPOSITION
4-156	PLATE DIMENSION, WELD UNDERSIZE	10/04/85	85-0880	
41-H8C-46-H10	THD STAKED	10/04/85	85-0881	
4-160	WELD UNDERSIZE	10/04/85	85-0882	
41-H8C-46-H32	SHIM DETAIL	10/05/85	85-0896	
41-H8C-46-H33	SHIM DETAIL	10/05/85	85-0897	
41-H8C-47-H33	SHIM DETAIL	10/05/85	85-0898	
41-H8C-47-H32	PLATE GAP, 8 BOLTS VS. 10, 2 BOLTS VS. 4, WELD DETAIL & UNDERSI	10/05/85	85-0899	
41-H8C-46-H74	SHIM DETAIL, WELD DETAIL	10/05/85	85-0900	
41-H8C-47-H34	WELD DETAIL	10/05/85	85-0901	
41-H8C-46-H37	SHIM DETAIL	10/05/85	85-0902	
41-H8C-46-H36	SHIM DETAIL	10/05/85	85-0903	
41-H8C-46-H35	SHIM DETAIL	10/05/85	85-0904	
41-H8C-47-H35	PLATE GAP, WELD DETAIL & UNDERSIZE	10/05/85	85-0905	
41-H8C-46-H35	SHIMS NOT PER SPEC	10/07/85	85-0948	USE AS IS (3)
41-H8C-47-H24	WLD DETAIL NOT ON DWG, EXCESS WLD METAL	10/07/85	85-0949	USE AS IS (3)
41-H8C-46-H24	SHIMS NOT PER SPEC	10/07/85	85-0950	USE AS IS (3)
41-H8C-47-H27	BASEPLATE GAP, WLD MISSING	10/07/85	85-0951	
41-H8C-47-H25	BASEPLATE GAP, SHIMS NOT PER SPEC	10/07/85	85-0952	
41-H8C-46-H50	CLEARANCE WELD DETAIL & UNDERSIZE B/M PROBLEMS	10/07/85	85-0974	
41-H8C-46-H29	SHIM SIZE NOT ON DWG, WLD MISSING ON SHI	10/08/85	85-0965	
41-H8C-46-H31	SHIM SIZE NOT ON DWG, WLD MISSING ON SHI	10/08/85	85-0966	
41-H8C-47-H30	SHIM NOT SHOWN ON DWG.	10/08/85	85-0967	USE AS IS (3)

15

15

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 13

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/CR NUMBER	DISPOSITION
41-HBC-46-H30	SHIM SIZE NOT ON DWG, WLD MISSING ON SHIM	10/06/85	85-0968	
41-HBC-47-H15	WLD DETAIL INCORRECT, MEMBER LOCATION NOT PER DWG.	10/06/85	85-0969	USE AS IS (3)
41-HBC-46-H15	SHIM SIZE NOT ON DWG, WLD DETAIL INCORRECT	10/08/85	85-0970	USE AS IS (3)
41-HBC-47-H16	WELD DETAIL & SIZE CLEARANCE	10/09/85	85-0984	
41-HBC-47-H11	B/W PROBLEM DIMENSIONS WELD DETAIL & SIZE UNDERCUT	10/09/85	85-0986	
41-HBC-46-H28	SHIM DETAIL	10/09/85	85-0989	
41-HBC-47-H27	LUG SIZE DIMENSION	10/09/85	85-0990	
41-HBC-46-H27	SHIM DETAIL	10/09/85	85-0991	
41-HBC-47-H26	WELD DETAIL & SIZE, UNDERCUT, PL. GAP	10/09/85	85-0992	
41-HBC-46-H22	WELD DETAIL & SIZE, DIMENSION	10/09/85	85-0995	
41-HBC-47-H22	WELD DETAIL & SIZE	10/09/85	85-0996	
41-HBC-47-H49	WELD DETAIL, PL. GAP, DIMENSION	10/09/85	85-0997	
41-HBC-46-H49	WELD DETAIL	10/09/85	85-0998	
41-HBC-47-H29	BOLT SPACE WELD DETAIL & SIZE PL. GAP SHIM INSTALLED	10/09/85	85-1005	
41-HBC-46-H26	WELD SIZE SHIM DETAIL LUG SIZE	10/09/85	85-1006	
41-HBC-46-H1	WELD DETAIL	10/09/85	85-1018	
41-HBC-47-H1	WELD DETAIL, CLEARANCES	10/09/85	85-1019	
41-HBC-46-H47	WELD SIZE	10/09/85	85-1039	

DAVIS - BESSE FIRING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SP NUMBER	DISPOSITION
41-HBC-47-H46	WELD SIZE	10/09/85	85-1040	
41-HBC-46-H46	WELD SIZES	10/09/85	85-1042	
41-HBC-47-H45	WELD SIZES	10/09/85	85-1043	
41-HBC-47-H45	WELD SIZES	10/09/85	85-1044	
41-HBC-47-H47	BASE PLATE SHIMS & GAPS, WELDS	10/09/85	85-1045	
41-HBC-47-H7	WELD PROBLEMS	10/10/85	85-1066	
41-HBC-47-H6	WELD PROBLEMS	10/10/85	85-1067	
41-HBC-47-H18	WELD SIZES ON LUGS	10/10/85	85-1068	
41-HBC-47-H19	WELD SIZES	10/10/85	85-1069	
41-HBC-46-H18	WELD MISSING	10/10/85	85-1070	
41-HBC-46-H19	WELDS ON LUGS	10/10/85	85-1071	
41-HBC-46-H20	WELD SIZES & TYPES	10/10/85	85-1072	
41-HBC-47-H21	WELD SIZES	10/10/85	85-1073	
41-HBC-46-H21	WELD SIZES, END OF BEAM CLIPPED	10/10/85	85-1074	
41-HBC-46-H7	CONFLICTING INFORMATION ON WORK WITH DRAWINGS FOR MEM'S & WELD	10/10/85	85-1077	
41-HBC-47-H4	SHIMS UNDER BASE PLATE	10/10/85	85-1084	
41-HBC-47-H9	WELD SIZE, DIMENSIONS	10/10/85	85-1085	
41-HBC-47-H3	WELD SIZES, DIMENSIONS	10/10/85	85-1086	
41-HBC-47-H51	WRAPPER PLATE THK, INCREASED	10/10/85	85-1087	
41-HBC-46-H4	SHIM DETAIL	10/10/85	85-1092	
41-HBC-46-H13	WELD DETAIL	10/10/85	85-1093	
41-HBC-46-H2	WELD DETAIL, DIMENSION	10/10/85	85-1094	
41-HBC-47-H12	WELD DETAIL	10/10/85	85-1095	

DAVIS - BESSIE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 13

SUPPORT NUMBER	DESCRIPTION	DATE	WORKER NUMBER	DISPOSITION
41-HBC-47-H17	DIMENSION, WELD DETAIL	10/10/85	85-1096	
41-HBC-47-H20	WELD SIZE & DETAIL	10/10/85	85-1108	
41-HBC-47-H17	3 WASHERS ON BOLT, PL. GAP, WELD DETAIL & SIZE	10/11/85	85-1107	
41-HBC-46-H38	WELDER SIZE, ANCHOR BOLT, PLATE GAP, WELD DETAIL, DIMENSION QUANTITIES VS. S/M	10/15/85	85-1178	
41-HBC-47-H41	SHIM DETAIL	10/15/85	85-1181	
41-HBC-47-H40	DRAWING CONFLICT/ SHIM	10/15/85	85-1182	
41-HBC-46-H40	DRAWING CONFLICT/SHIM	10/15/85	85-1183	
41-HBC-46-H39	SHIM DETAIL, DRAWING CONFLICT/ SHIM	10/15/85	85-1184	
41-HBC-47-H39	SHIM DETAIL, DRAWING CONFLICT/ SHIM	10/15/85	85-1185	
41-HBC-47-H38	SHIM DETAIL, DRAWING CONFLICT/SHIM	10/15/85	85-1186	
41-HBC-46-H44	SHIM DETAIL	10/15/85	85-1187	
41-HBC-47-H43	SHIM DETAIL	10/15/85	85-1188	
41-HBC-47-H42	SHIM DETAIL	10/15/85	85-1189	

SECTION 7.0

CONTAINMENT SUMP -- ECCS SUPPLY

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
33B-HCB-1-H4	WASHERS MISSING, WLDG NOT PER DWG	09/17/85	85-0386	USE-AB-18 (3)
33A-GCB-8-H12	PIPE CLAMP NOT TIGHT, WLD UNDSZ	09/17/85	85-0387	USE-AB-18 (3), REWORK-TIGHTEN (4)
33B-HCB-1-H2	ITEMS NOT PER DWG, NO WASHERS UNDER ANCHOR BOLTS	09/17/85	85-0395	USE-AB-18 (3), REWORK-ADJUST (4)
33F-GCB-7-H7	WLDG NOT PER DWG	09/17/85	85-0456	USE-AB-18 (3)
33C-GCB-7-H9	WLD SYMBOLS NOT SPEC'D VS WLDG PRESENT	09/17/85	85-0463	
33A-GCB-8-H13	ITEM #15 NOT PER DWG	09/17/85	85-0464	USE AB 18 (3)
33C-GCB-7-H6	BASEPLATE UNACC, SWAY STRUT BOUND	09/17/85	85-0476	USE AB 18 (3)
33B-HCB-1-H3	BASEPLATE UNACC BEARING SURFACE	09/17/85	85-0482	USE AB 18 (3)
10B-HCC-6F-H22	NUT MISSING	09/19/85	85-0515	REWORK-REPLACE NUT (4)
4307	MIN. BOLT SPACING VIOLATION	10/07/85	85-0978	
46-HBB-2-H4	IMPROPER SHIM, UNDSZ & MISSING WLDG, CLR GAP INCORRECT, WLD DETAIL MISSING	10/07/85	85-0939	
46-HBB-2-H1	WLDG UNDSZ, BOLT LOCATION INCORRECT	10/07/85	85-0947	USE AB 18 (3)
46-HBB-2-H2	NO WELD SYMBOL	10/09/85	85-0988	

SECTION 8.0

HYDROGEN DILUTION SYSTEM

Page No. 1
11/01/85

SYSTEM: HYDROGEN DILUTION

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR / SR NUMBER	DISPOSITION
29-HBC-73-H5	JAM NUT MISSING. CLAMP NEEDS REALIGN. BUSHING FREE TO ROTATE	09/19/85	85-0514	
29-HBB-15-H10	ITEMS 1&2 NOT PER DWG. WLDs NOT PER DWG	10/03/85	85-0617	
29-HBB-15-H9	WLDs NOT PER DWG. BASEPLATE GAP	10/03/85	85-0601	
29-HCB-47-H1	WLDs NOT PER DWG. WLD GAPS. SLAG ON WLDs. CAULKING UNDER BASEPLATE.	10/03/85	85-0603	
29-HBB-15-H8	WHR MISSING. DIM NOT PER DWG	10/03/85	85-0605	USE 49 IS. REMARK-INSTALL WHRs
29-HBB-15-H7	DIMENSIONS	10/04/85	85-0663	USE 49 IS (3)

SECTION 9.0

PRESSURIZER RELIEF SYSTEM

DAVIS - 88888 RIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
30-CC4-B-H4	THD STAKED	10/05/85	85-0909	
30-CC4-B-H5	PLATE GAP, WELD UNDERSIZE, THD STAKED	10/05/85	85-0910	
30-800-B-H4	PLATE GROUTED, WELD DETAIL & UNDERSIZE, WASHER MISSING, NO I.D. TAG	10/05/85	85-0911	
30-800-B-H16	PLATE GROUTED, DIMENSION, WELD DETAIL & UNDERSZ, CLAMP BOLT/SPACER LOOSE, THD STK	10/05/85	85-0912	
30-800-B-H5	WELD DETAIL & UNDERSIZE, CONCRETE SPALLING	10/05/85	85-0914	
30-800-B-H13	PLATE GROUTED, PLATE GAP, WELD DETAIL & SIZE, FLUID LEAK	10/05/85	85-0919	
30-800-B-H10	BLT ANGLE, PL. GAP, NO SHAPPING, STRUT BINDING, CL. SPACER BOLT LOOSE	10/05/85	85-0920	
30-800-B-H6	PL. OVERLAPS CONC., PL. GAP & GROUTED, WELD DET. & UNDERSZ, THD STKD, LOOSE NUT,	10/05/85	85-0921	
30-800-B-H4	THDS STAKED, BASEPLATE 8X8 VS 10 X 10, WLD8 UND8Z	10/07/85	85-0935	
30-800-B-H3	THDS STAKED, 5/8" MILTI VS. 1/2" NET-IT, WLD MISSING, CLAMP SPACER LOOSE	10/07/85	85-0936	
30-800-B-H17	MISSING BUSHING WASHERS, LOOSE SPACERS, WLD8 UND8Z, MIN. THD ENGAGEMENT	10/07/85	85-0941	
30-800-B-H1	GROUT ALONG BASEPLATE, WLD DETAILS INCORRECT	10/08/85	85-0960	
30-800-B-H2	BOLT MIN. DIST. VIOLATION, GROUT ALONG BASEPLATE	10/08/85	85-0961	
M1140/H1	BOLT MIN. DIST. VIOLATION, LOOSE JAM NUT, BASEPLATE GAP	10/08/85	85-0964	
30-CC4-B-H6	PL. THICK	10/09/85	85-1020	
A-304	WELD DETAIL & SIZE	10/09/85	85-1021	
A-307	WELD SIZE	10/09/85	85-1022	
PRN-W-008-25-1	MATERIAL CHANGE, WELD ADDED, DIMENSIONS	10/22/85	85-1387	
M-1140-H02	ANCHOR BOLT THD, ENGAGE & WELD NOT PER DRAWING	10/28/85	85-1571	

Page No. 2
11/01/85

SYSTEM: PRESSURIZER RELIEF SYSTEM

DAVIS - 6666 PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	MCR/BR NUMBER	DISPOSITION
M-1142-H23	WELD NOT PER DRAWING	10/29/85	85-1572	15

SECTION 10.0

PRESSURIZER SURGE SYSTEM

DAVIS - BESSIE PIPING / SUPPORTS
INSPECTOR FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
PSU-H1	BASEPLATE GAP, SPRING LOAD COLUMN MISALIGNED	10/07/85	85-0937	
JA-ESD-1P-H154	WLDG UNDSZ, SHIM TACK WELDED	10/07/85	85-0940	USE AS IS (3)
PSU-F1	WLDG UNDSZ, BASEPLATE BP, MISSING ID TAG	10/07/85	85-0942	
PSU-R3	BASEPLATE GAP, WLD UNDSZ	10/08/85	85-0958	
PSU-R2	TAG PL-GAP THREAD STAKED CLAMP BOLT LOOSE	10/09/85	85-1003	

15

SECTION 11.0

CONTAINMENT SPRAY SYSTEM

DAVIS - 8538E PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR / CR NUMBER	DISPOSITION	
34-HCB-4-H17	GAPS NOT PER DWG. ITEM NOT PER DWG. WLDG NOT PER DWG. PIPE SOUGED	10/03/85	85-0814		
34-HCB-4-H21	SUPP NOT PAINTED. WLDG ARE: UNDSZ, NOT POSS. & NOT PER DWG	10/03/85	85-0815		
34-HCB-4-H27	WLDG NOT PER DWG	10/03/85	85-0816		
34-HCB-4-H33	WLDG NOT PER DWG. THDS STAKED	10/03/85	85-0817	USE AG 18 (3)	15
34-HCB-4-H35	WLDG NOT PER DWG	10/03/85	85-0818	USE AG 18 (3)	
34-HCB-4-H22	ANCHOR BOLTS STAKED. WLDG UNDSZ & NOT PER DWG	10/03/85	85-0819		
34-HCB-4-H34	WLDG NOT PER DWG	10/03/85	85-0820	USE AG 18 (3)	15
30-GCC-8-H8	WSHRG INSTALLED INCORR. BASEPLATE GAP GROUTED	10/03/85	85-0821		
30-GCC-8-H7	WLDG UNDSZ. PIPE CLAMP BINDING. BASEPLATE DIM INCORR	10/03/85	85-0822	USE AG 18 (3). REWORK-ADJUST CLAMP (4)	
34-HCB-4-H5	WLDG NOT PER DWG & NOT POSS	10/03/85	85-0823		
34-HCB-4-H7	WLDG NOT PER DWG	10/03/85	85-0824	USE AG 18 (3)	15
34-HCB-4-H6	WLDG NOT PER DWG & NOT POSS	10/03/85	85-0825	USE AG 18 (3)	
34-HCB-4-H28	SPACERS TACK WELDED. ITEMS DMS DON'T HAVE FULL THD ENGAGEMENT	10/03/85	85-0830	USE AG 18 (3). REWORK-ADJUST RODS (4)	
34-HCB-4-H9	WLDG NOT PER DWG & UNDSZ. SLAG ON WLDG	10/03/85	85-0832	USE AG 18 (3)	15
34-HCB-4-H44	PLATE SPE, DIMENSIONS, NO SIGHT HOLE, CLAMP LOCATION, WELDGS VS. DWG. "S" DIMENSIO	10/03/85	85-0858		
34-HCB-4-H15	WELD DETAIL	10/03/85	85-0859		
34-HCB-4-H16	CLEARANCE, WELD DETAIL & UNDERSIZE	10/04/85	85-0860		
34-HCB-4-10	WELD DETAIL, SLAG	10/04/85	85-0862		
34-HCB-4-H8	WELD DETAIL, BASE METAL REDUCTION, SLAG, UNDSZ, OVERLAP, CLEARANCE	10/04/85	85-0864		
34-HCB-4-H42	WELD DETAIL & SIZE, CLEARANCE	10/04/85	85-0865		
34-HCB-4-H4-WE	LD DETAIL & SIZE	10/04/85	85-0866	USE AG 18 (3)	

DAVIS - BESSIE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 13

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION	
34-HCB-4-H29	NO TACK WELD	10/04/85	85-0867	REWORK-TACKWELD(4)	15
A-77	CAULKING COVERS GAP	10/04/85	85-0869		
34-HCB-4-H11	ARC STRIKE, WELD DETAIL & UNDERSIZE, CLEARANCE	10/05/85	85-0906		
34-HCB-4-H71	DWG SHOWS NO WELD SIZE, DIMENSIONS, WELD DETAIL, FLUID LEAKAGE	10/05/85	85-0908	USE AS IS (3)	15
34-HCB-4-H40	WELD DETAIL & SIZE, NO SITE HOLE, TWO STAKED, LOOSE NUT	10/05/85	85-0915		
34-HCB-4-H14	WELD DETAIL & SIZE	10/05/85	85-0916		
34-HCB-4-H30	MEMBER SIZE, WELD DETAIL, CLEARANCE	10/05/85	85-0917	USE AS IS (3)	
34-HCB-4-H13	WELD DETAIL & SIZE	10/05/85	85-0918		
34-HCB-4-H20	BASEPLATE 1/2" VS 1", 4 BOLTS VS 6, UNDERSZ MISSING WELDS	10/07/85	85-0914		
34-HCB-4-H19	UNDERSZ WELD, WELD DETAIL NOT ON DWG, MEMBER SIZE INCORRECT	10/07/85	85-0953	USE AS IS (3)	15
34-HCB-4-H41	WELD DETAIL & SIZE	10/09/85	85-0983		
34-HCB-4-H18	PL. GAP	10/11/85	85-1115		
34-HCB-4-H194	NO S.D.M., WELD & DIMEN. NOT PER DRAWING, MISSING BOLT LOCATIONS	10/26/85	85-1313		

SECTION 12.0

MISCELLANEOUS WASTE DRAIN SYSTEM

Page No. 1
11/01/85

SYSTEM: MISC WASTE DRAIN

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
Unidentified	EXTRA HANGER	10/04/85	85-0891	

SECTION 13.0

SPENT FUEL POOL PIPING SYSTEM

Page No. 1
11/01/85

SYSTEM: SPENT FUEL POOL PIPING

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SA NUMBER	DISPOSITION
Unidentified	EXTRA HANGER	10/04/85	85-0890	USE AS IS (1)
A-219	ANCHOR LOCATION	10/04/85	85-0894	

SECTION 14.0

MAKEUP WATER TREATMENT SYSTEM

DAVIS - BESSE TIRING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
10B-HCB-DT--7	REACHHEAD VS. WEIGHT WELD DETAIL DIMENSION EXTRA HOLES IN PLATE	10/09/85	85-1004	

SECTION 15.0

PRESSURIZER SPRAY SYSTEM

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
PS-H7	WELD SIZE, UNDERCUT, PL-GAP	10/09/85	85-1023	
PS-H6	WELD DETAIL & SIZE, PL. GAP, UNDERCUT	10/09/85	85-1024	
PS-H5	PIPE CLAMP	10/10/85	85-1037	
PS-H4	PIPE CLAMP	10/10/85	85-1058	
PS-H21	BASE PLATE GAPS	10/10/85	85-1059	
PS-H20	WELD TYPES, DIMENSIONS, GROUT ADDED	10/10/85	85-1060	
PS-H23	DIMENSIONS FOR PIPE OFFSET	10/10/85	85-1061	
PS-H10	WELD TYPE, BASE PLATE & BOLTS	10/10/85	85-1062	
PS-H9	WELDS, SLAG & GROUT	10/10/85	85-1067	
PS-H8	WELD TYPE & GROUT ADDED	10/10/85	85-1064	
PS-H22	PIPE CLAMP	10/10/85	85-1075	
PS-H27	WELDS & SNUBBER PROBLEMS	10/10/85	85-1076	
PS-H19	BENT ROD, ANCHOR BOLT SPACING	10/10/85	85-1080	
PS-H18	WELD, SNUBBER SETTING, PIPE OFFSET, BASE PLATE	10/10/85	85-1081	
PS-H17	WELDS, PIPE OFFSET, SNUBBER ASS	10/10/85	85-1082	
PS-H1	WELD DETAIL & SIZE, PL. GAP	10/10/85	85-1097	
PS-H2	TORQUE FAILS 1 BOLT, WELD DETAIL, PL. GAP	10/10/85	85-1098	
PS-H3	PL. GAP, WELD DETAIL	10/10/85	85-1099	
PS-H13	GROUT, THREAD ENGAGEMENT, 3 WASHER ON BOLT, PL GAP, WELD SYMBOL	10/10/85	85-1104	
PS-H12	GROUT, WELD SYMBOL	10/10/85	85-1105	
PS-H14	GROUT, HILTI VS. WEJ-IT, WELD SYMBOL	10/10/85	85-1106	
PS-H11	GROUT	10/10/85	85-1107	
PS-H32	WELD DETAIL	10/10/85	85-1110	

DAVIS - BESSIE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
PS-H03	PL. GAP, WELD SYMBOL	10/10/85	85-1111	
PS-H04	MIN. EDGE DIST, GROUTED, THREAD STAKED	10/10/85	85-1112	
PS-H11	GROUT, WELD DETAIL	10/11/85	85-1114	
PS-H05	WLD DETAIL, LOCKNUT LOOSE	10/11/85	85-1119	
PS-H30	C-C ANCHOR SPACING, WLD DETAIL & SIZE	10/11/85	85-1124	
PS-H19	GROUT, WELD DETAIL & SIZE, CLAMP BEARING, SPACER MISSING, GREASE FITTING DAMAGE	10/11/85	85-1125	
PS-H15	WELD SIZE, F-P DIMENSIONS, DIMENSIONS, TAG	10/11/85	85-1126	
PS-H16	DIMENSION, DRAWING NOTE, THREAD ENGAGEMENT, GROUT	10/11/85	85-1127	
PS-H07	DIMENSION, WELD DETAIL, GREASE FITTING DAMAGE	10/12/85	85-1141	
PS-H28	WELD SIZE & DETAIL, GREASE FITTING DAMAGE, EXTRA PLATE	10/12/85	85-1142	
PS-H06	ANCHOR BOLT NO TORQUE, PC GAP, WELD DETAIL & SIZE, BOLT MISSING, GREASE FIT, DAM	10/12/85	85-1147	

SECTION 16.0

REACTOR COOLANT SYSTEM

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/GR NUMBER	DISPOSITION
40-CCB-16-45	THREAD ENGAGE, WELD DETAIL & SIZE, HILTI VS. WEL-17, DIMENSIONS	10/12/85	85-1150	
40-CCB-16-41	DIMENSION	10/12/85	85-1151	
40-CCB-16-42	CLEARANCE, DIMENSION, WELD DETAIL	10/14/85	85-1159	
40-CCB-16-43	FL. GAP, ANCHOR BOLT NO TORQUE, DIMENSION, WELD DETAIL	10/14/85	85-1160	
40-CCB-16-44	THREAD STAKED, "W" DIMENSION	10/14/85	85-1161	
40-CCB-16-48	DIMENSION, WELD DETAIL	10/14/85	85-1162	
A-260	THREAD ENGAGE, WELD DETAIL, DIMENSION	10/14/85	85-1163	
40-CCB-23-41	BOLT SPACING, WELDS, CLEARANCE DIMENSIONS	10/16/85	85-1224	
40-CCB-16-47	WELDS, DIMENSIONS	10/16/85	85-1225	
A-261	WELDS, PIPE LOCATIONS	10/16/85	85-1227	
40-CCA-18-H1	BOLT EDGE DISTANCE, WELD SIZE, PLATE SHAPE	10/16/85	85-1235	
40-CCA-18-H2	BOLT EDGE DISTANCE, GROUT THK, OVERSIZE SHIM ADDED, WELDS UNDERSIZED LOG PLAN REV	10/17/85	85-1260	
40-CCB-23-H2	HILTI BOLTS, INSTALLED, DIM'S SHORTENED CLEARANCES INCREASED	10/17/85	85-1261	
40-CCB-16-H6	IT-2 LENGTH DECREASED, IT-10 SIZE INCR, WELDS UNDERSIZED	10/17/85	85-1262	
M-1113-H3	BOLT SPRING, PIPE STRAP TRIMMED	10/17/85	85-1263	
M-1113-H2	1/8" GAP NOT PER DRAWING	10/17/85	85-1272	
M-1113-H1	STRAP TRIMMED, BASEPLATE WELDED IN LIEU OF 2-BOLTS.	10/17/85	85-1273	
J1-CCB-16-H9	BASEPLATE GAPS, WELD UNDERSIZE, MATERIAL SIZE CHANGE	10/18/85	85-1307	
J1-CCB-16-H10	BASEPLATE WARRAGE, WELD UNDERSIZE, MATERIAL SIZE CHANGE	10/18/85	85-1308	
M-1113-47	ANCHOR BOLT SPACING	10/19/85	85-1314	

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-1113-H9	ANCHORBOLT SPACING & PLATE GAPS	10/19/85	85-1313	
M-1113-H11	1-BOLT IS 3/4" NOT 5/8", BOLT SPACING BASEPLATE GAPS	10/19/85	85-1316	
M-1113-H12	GAP NOT PER DRAWING	10/19/85	85-1317	
M-1113-H13	ANCHOR BOLT SPACING	10/19/85	85-1318	
M-1113-H15	WELD UNDERSIZED	10/19/85	85-1319	
M-1113-H17	BOLT SPACING, WELDS UNDERSIZED, PLATE SIZE NOT PER DRAWING	10/19/85	85-1320	
M-1113-H18	WELDS UNDERSIZED	10/19/85	85-1321	
M-1113-H20	INSTALLATION NOT PER DRAWING, WELD DELETED	10/19/85	85-1322	
M-1113-H21	LOOSE NUT ON U-BOLT	10/19/85	85-1323	
M-1113-H22	INSTALLATION NOT PER DRAWING	10/19/85	85-1324	
31-CCB-23-H4	STRUT "W" INCREASE 1/2" STAKED THD. ON ROD ALL CLAMP THD. ARE STAKED	10/19/85	85-1325	
FSK-M-CCA-3-H1	WELD NOT PER STANDARD DETAIL	10/19/85	85-1327	
F-CCA-3-2-H7	REV. PIPE LOC. & CLEARANCE	10/21/85	85-1350	
F-CCA-3-2-H10	SUPPORT CONFIGURATION	10/21/85	85-1351	
31-CCA-18-H4	UNDERSIZE WELD, GROUT THICKNESS	10/21/85	85-1352	
31-CCA-18-H6	1-ANCHORBOLT NOT FULL THREAD ENGAGEMENT SPRING CAN SPACING, WELDS, PLATE GAPS	10/21/85	85-1353	
31-CCB-16-H11	HILTI BOLTS NOT WEJ-ITS, WELDS UNDERSIZED, DIM.'S AND MAT'L LENGTHS	10/21/85	85-1354	
31-CCB-23-H5	CLEARANCE INCREASED, WELD DELETED	10/21/85	85-1355	
31-CCA-18-H13	STRUT "W" DECREASED & DIM.'S, PLATE SIZE REDUCED 1/4"	10/21/85	85-1356	
31-CCB-23-H3	BOLT SPACING, WELDS UNDERSIZED GROUT THICKNESS	10/21/85	85-1357	

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
31-CCA-18-H9	WELD TYPES, SECTION A-A NOT PER DRAWING, BASE PLATE GAPS	10/21/85	85-1358	
31-CCA-18-H12	BOLT EDGE DISTANCE, PIPE LOCATION	10/21/85	85-1359	
31-CCB-18-H12	BOLTS INSTALLED WITH T-WASHERS, PLATE GAPS, WELDS UNDERSIZED, LOCATING DIM. 'S	10/21/85	85-1360	
FSK-M-CCA--3-2	BASEPLATE GAPS	10/21/85	85-1361	
M-1113-H32	BOLT SPACING, WELD DELETED	10/21/85	85-1372	
M-1113-H30	ANCHOR BOLT SPACING	10/21/85	85-1373	
M-1113-H25	BOLT SPACING, WELD UNDERSIZED	10/21/85	85-1374	
31-CCB-18-H10	CLEARANCE REDUCED, WELDS UNDERSI	10/22/85	85-1388	
31-CCA-18-H11	WELDS UNDERSI	10/22/85	85-1389	
31-CCA-18-H5	WELDS UNDERSI	10/22/85	85-1390	
31-CCA-18-H6	SNUBBER SETTING	10/22/85	85-1391	
M-1113-H28	WELDS, DIMEN., & BOLT SPACING NOT PER DWG., BASE PLATE GAP UNACCEPTABLE.	10/23/85	85-1401	
M-1113-H35	GAP NOT PER DRAWING	10/23/85	85-1402	
M-1113-H36	GAP NOT PER DRAWING	10/23/85	85-1403	
M-1113-H37	BOLT SPACING, GROUT, & U-BOLT, NOT PER DRAWING	10/23/85	85-1404	
M-1113-H38	U-BOLT NOT PER DRAWING	10/23/85	85-1405	
M-1113-H40	ANCHOR BOLT SPACING & GROUT NOT PER DRAWING	10/23/85	85-1406	
M-1113-H41	DIMENSION NOT PER DRAWING	10/23/85	85-1407	
M-1113-H42	DIMENSION & CLAMP NOT PER DRAWING	10/23/85	85-1408	
M-1113-H43	LOOSE NUTS & U-BOLT NOT PER DRAWING	10/23/85	85-1409	
M-1113-H44	ANCHOR BOLT SPACING, GROUT, WELDS, & U-BOLT NOT PER DRAWING	10/23/85	85-1410	

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
M-1113-H45	U-BOLT NOT PER DRAWING	10/23/85	85-1411	
M-1113-H46	WELD & U-BOLT NOT PER DRAWING	10/23/85	85-1412	
M-1113-H47	WELD & CLEAR. NOT PER DRAWING	10/23/85	85-1413	
M-1113-H49	WELDS NOT PER DRAWING	10/23/85	85-1414	
31-CCB-18-H3	CLEAR, DIMEN., WELDS NOT PER DRAWING	10/23/85	85-1419	
CCB-21-H27	SUPPORT OFFSET, NON-STANDARD PIPE CLAMP	10/24/85	85-1437	
F-CCA-3-1-H2	WELD UNDERSIZED, STRAP CLEARANCE	10/24/85	85-1442	
F-CCA-3-1-H3	WELD UNDERSIZED, STRAP CLEARANCE	10/24/85	85-1443	
F-CCA-2-1-H4	SNUB. MGMT., PLATE GAPS, WELD NOT ON DRAWING	10/24/85	85-1444	
F-CCA-2-1-H1	SNUBBER MOVEMENT	10/24/85	85-1445	
31-CCB-21-H18	WELDS UNDERSIZED, CLIP ANGLE SIZE INCREASED	10/24/85	85-1446	
F-CCB-8-11-H14	STRAP DIMENSIONS, STEEL NOTCHED, WELDS & MEM. SIZE	10/24/85	85-1448	
F-CCB-8-11-H13	SUPPORT GREIT, MEMBER SIZES	10/24/85	85-1449	
F-CCB-28-4-H10	WELD SIZES, MATERIAL SIZE, BOLT SPACING	10/24/85	85-1458	
M-1113/H54	BOLT SPACING, WELDS UNDERSIZED, SNUBBER MATERIAL	10/25/85	85-1457	
M-1113/H51	BOLT SPACING, UNDERSIZE WELDS, GROUT ADDED	10/25/85	85-1458	
M-1113/H57	BOLT SPACING, GROUT ADDED	10/25/85	85-1459	
M-1113/H27	WELDS UNDERSIZED	10/25/85	85-1460	
M-1113/H50	WELDS UNDERSIZED	10/25/85	85-1461	
M-1113/H53	BOLT SPACING, BASE PLATE GROUTED	10/25/85	85-1462	
M-1113/H55	BOLT SPACING, CLAMP BOLT LOOSE, GROUT ADDED	10/25/85	85-1463	
M-1143/H6	WELDS UNDERSIZED, PLATE EDGE DISTANCE & GAPS	10/25/85	85-1464	
M-1143/H9	ANCHOR BOLT SPACING	10/25/85	85-1465	

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-1143/H10	ANCHOR BOLT SPACING, WELDS UNDERSIZED	10/25/85	85-1466	
M-1143/H12	ANCHOR BOLT SPACING, WELDS UNDERSIZED	10/25/85	85-1467	
M-1143/H14	MEMBER - 6 SHORTENED	10/25/85	85-1468	
M-1143/H15	MEMBER - 2 INCREASED 1 1/2"	10/25/85	85-1469	
M-1143/H17	BOLT SPACING, PLATE GAPS, WELD UNDERSIZED	10/25/85	85-1470	
M-1143/H18	BASE PLATE NOT INSTALLED, EXIST PLATE USED	10/25/85	85-1471	
F-CCB-28-4-H5	WELD UNDERSIZED	10/25/85	85-1473	
F-CCB-28-4-H6	WELD SIZES, MEMBER SUBSTITUTION	10/25/85	85-1474	
F-CCB-28-4-H7	WELD SIZE NOT ON DRAWING, MEMBER SIZE INCREASED	10/25/85	85-1475	
CCB-21-H15	BOLTS W/O WASHERS, WELD UNDERSIZED, CLR REDUCED	10/25/85	85-1478	
CCB-21-H16	WELD UNDERSIZED	10/25/85	85-1479	
CCB-21-H17	WELD UNDERSIZED, LUG CLR., ARC. STRIKE ON P.P.	10/25/85	85-1480	
A-252	BOLT SPACING, ARC. STRIKE ON PRESS PIPE	10/25/85	85-1481	
CCB-21-H10	WELD UNDERSIZED	10/25/85	85-1482	
F-CCB-26-4-H1	BASE PLATE GAP, BOLT SPACING, WELD SIZE & UNDERCUT	10/25/85	85-1483	
F-CCB-26-4-H3	WELD UNDERSIZED, PLATE GAPS, WELD SIZE & UNDERCUT	10/25/85	85-1484	
F-CCB-28-4-H9	WELD SIZES NOT PER OR ON DRAWING	10/25/85	85-1489	
F-CCB-28-4-H8	WELD SIZES NOT PER OR ON DRAWING	10/25/85	85-1490	
M-1143/H13	ITEM-2 SHORTENED (ANGLE)	10/25/85	85-1493	
HSD-164-2-H32	DIMENSION & MEMBERS NOT PER DRAWING	10/28/85	85-1500	
HSD-164-2-H6	DIMENSIONS NOT PER DRAWING	10/28/85	85-1501	

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR. NR NUMBER	DISPOSITION
CCA-(23"ID)-4-	MISSING LOCKWIRE, DIMEN. NOT PER DWG., MISSING DETAIL	10/28/85	85-1502	
CCA(26ID)-4-H2	DIMEN. NOT ON DWG.	10/28/85	85-1503	
CCA(26ID)-4-H1	MISSING LOCK WIRE	10/28/85	85-1504	
CCA(26ID)-3-H1	DIMEN. NOT PER DWG., INCOMPLETE DET., MISSING LOCKWIRE	10/28/85	85-1505	
CCA(26ID)-3-H2	INCOMPLETE DIMEN. ON DWG.	10/28/85	85-1506	
CCA(26ID)-3-H3	MISSING LOCK WIRE	10/28/85	85-1507	
CCB-7-1-H8	DIMEN. & BROUT NOT PER DRAWING	10/28/85	85-1509	
CCB-7-1-H7	BASEPLATE GAP UNACCEPTABLE, CRACKED CONC.	10/28/85	85-1510	
CCB-7-1-H2	WELD NOT PER DRAWING	10/28/85	85-1511	
CCB-7-1-H1	WELD NOT PER DRAWING	10/28/85	85-1512	
HCC-36-1-H5	WELD NOT PER DRAWING	10/28/85	85-1513	
HCC-36-1-H6	WELD, DIMEN., & PLATE NOT PER DRAWING	10/28/85	85-1514	
J1-CCB-21-H12	BASE PLATE GAP UNACCEPTABLE, WELD NOT PER DWG., NO B.O.M.	10/29/85	85-1521	
J1-CCB-21-H11	WASHERS, CLEAR., & WELDS NOT PER DRAWING	10/29/85	85-1522	
J1-CCB-21-H14	WASHERS, GAPS NOT PER DRAWING, WARPED MEMBER	10/29/85	85-1524	
J1-CCB-21-H9	WELDS NOT PER DRAWING	10/29/85	85-1525	
J1-CCB-21-H7	BROUT & WELD NOT PER DRAWING	10/29/85	85-1526	
J1-CCB-21-H13	WELD, CLEAR., & WASHERS NOT PER DRAWING	10/29/85	85-1527	
CCB-6-15-H1	MEMBERS & WELD NOT PER DRAWING	10/29/85	85-1528	
CCB-6-15-H2	MISSING WASHERS & LOCKWIRE, PAINT ON SNUGGER	10/29/85	85-1529	
M-1117-456	BOLT SPACING, WELDS, & SNUGGER NOT PER DRAWING	10/29/85	85-1530	
CCB-6-15-H4	DIMENSION NOT PER DRAWING	10/29/85	85-1542	

SYSTEM: REACTOR COOLANT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
CCB-8-15-H3	MEMBERS, WELD, & DIMEN. NOT PER DRAWING	10/29/85	85-1543	
CCB-8-15-H1	MISSING WASHERS & LOCK WIRE, PAINT ON TUBESER, WELD & MEMBER NOT PER DRAWING	10/29/85	85-1544	
CCB-8-15-H10	MEMBER & WELD NOT PER DRAWING	10/29/85	85-1550	
M-1113-H60	GROUT & WELDS NOT PER DRAWING, LOOSE CLAMP, SPACER & LOAD PIN	10/29/85	85-1551	
CCB-8-15-H9	MEMBERS, DIMENS., & WELDS NOT PER DRAWING	10/29/85	85-1552	
CCB-8-15-H7	WELDS NOT PER DRAWING	10/29/85	85-1553	
CCB-8-15-H6	BOLTS NOT PER DRAWING	10/29/85	85-1554	
CCB-8-15-H5	DIMEN. & WELD NOT PER DRAWING	10/29/85	85-1555	
M-1113-H24	BOLT, SPACING, & GROUT NOT PER DRAWING	10/29/85	85-1556	
M-1113-H61	SPACING, GROUT, & WELD NOT PER DRAWING, LOOSE CLAMP	10/29/85	85-1557	
M-1113-H59	WELD NOT PER DRAWING	10/29/85	85-1558	
M-1113-H58	SPACING & GROUT NOT PER DRAWING, GAP UNACCEPTABLE	10/29/85	85-1559	
CCB-7-4-H11	WELD, CONFIG., & CLEAR. NOT PER DRAWING	10/29/85	85-1560	
CCB-7-4-H12	MATERIAL & CLEAR. NOT PER DRAWING	10/29/85	85-1561	
CCB-7-4-H13	SPACING, WELDS, MATERIAL, & CLEAR. NOT PER DRAWING	10/29/85	85-1562	
CCB-7-4-H14	WELD & DIMEN. NOT PER DRAWING	10/29/85	85-1563	
CCB-7-4-H15	WELD, DIMEN, MATERIAL, CLEAR. NOT PER DRAWING	10/29/85	85-1564	
CCB-7-4-H16	DIMENSION & CLEARANCE NOT PER DRAWING	10/29/85	85-1565	
CCB-7-4-H17	DIMEN. & CLEAR. NOT PER DRAWING	10/29/85	85-1566	
HCC-56-5-H10	INCORRECT WELD SYMBOL	10/29/85	85-1567	
HCC-56-5-H11	INCORRECT WELD SYMBOL	10/29/85	85-1568	

SYSTEM: REACTOR COOLANT SYSTEM

DAVIS - BESSIE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
HCC-56-5-H13	WELD NOT PER DRAWING	10/29/85	85-1569	
HCC-56-5-H14	WELD NOT PER DRAWING	10/29/85	85-1570	
CCS-27-3-H1	WELD NOT PER DRAWING	10/29/85	85-1571	
CCS-7-4-H18	MEMBER, WELD, DIMEN., & CLEAR. NOT PER DRAWING	10/29/85	85-1572	

15

SECTION 17.0

QUENCH TANK DRAIN SYSTEM

DAVIS - BESSIE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SP NUMBER	DISPOSITION
40-HCS-22-H2	WELD DETAIL	10/14/85	85-1165	
40-HCS-22-H1	ANCHORBOLT BRACING, WELDS, PIPE LOC, DIMENSIONS	10/16/85	85-1204	
A-393	ANCHORBOLT, WELDS, DIMENSIONS	10/16/85	85-1205	
40-HCS-22-H3	ANCHORBOLT LOCATION, WELD, GAP DIMENSION	10/16/85	85-1206	

SECTION 18.0

COMPONENT COOLING WATER SYSTEM

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	WCR/BR NUMBER	DISPOSITION
A-124	WELD CHANGES, BOLT SPACING VIOLATIONS AND STIFFENER DIMENSIONS	10/14/85	85-1169	
36-HBB-12-H4	MEMBER LENGTHS AND WELD SIZES AND CONFIGURATIONS	10/14/85	85-1171	
36-HBB-12-H7	DIMENSIONS, WELD DETAIL & SIZE	10/15/85	85-1177	
36-HBB-12-H9	ANCHORBOLTS, PLATE SIZE DIMENSION	10/16/85	85-1199	
36-HBB-1-H4	BASEPLATE GAPS, MEM. WELDS & DIMENSIONS	10/16/85	85-1209	
A-126	WRAPPER PLATE LENGTH, DRAWING ERRORS	10/16/85	85-1210	
36-HBB-12-H8	ANCHORBOLTS, WELDS	10/16/85	85-1215	
A-125	WELDS, GROUT MISSING (PARTIAL)	10/16/85	85-1229	
36-HBB-1-H3	WELDMENTS UNDERSIZED	10/16/85	85-1230	
36-HBB-12-H3	WELDS AND CLEARANCE DIMENSION	10/16/85	85-1231	
A-122	BOLT LOCATIONS, WELDS UNDERSIZED, DIMENSIONS	10/17/85	85-1249	
A-335	LOC. DIM. 'S WELDS UNDERSIZED BOLT LOC. SUPPORT EL.	10/17/85	85-1268	
36-HBB-4-H204	WELDS UNDERSIZED, PLATES TACK WELDED TO SUPPORT, BASE PLATE GAPS	10/18/85	85-1279	
36-HBB-3-H205	ANCHOR BOLTS W/O-WASHERS, WELDS ARE UNDERSIZE, BASE PLATE GAPS	10/18/85	85-1280	
36-HBB-3-H112	MATERIAL SIZE REDUCED, PLATE GAPS, LOOSE L.NUT	10/18/85	85-1281	
36-HCB-40-H1	WELDS UNDERSIZE & ADDITIONAL WELD	10/18/85	85-1285	
36-HBB-4-H205	WELDS UNDERSIZE, BASE PLATE GAPS, ANCHOR BOLT W/O-WASHERS	10/18/85	85-1286	
36-HBB-3-H106	MATERIAL SIZE DECREASED	10/18/85	85-1291	
36-HBB-3-H203	WELDS UNDERSIZE, PLATES ADDED UNDER CHANNELS	10/18/85	85-1292	
36-HBB-4-H206	WELDS UNDERSIZE	10/18/85	85-1293	

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/CR NUMBER	DISPOSITION
36-HBB-3-H204	WELDS UNDERSIZE, SPACERS ADDED, BOLT SPACING	10/18/85	85-1294	
36-HBB-3-H206	WELDS UNDERSIZED, 1-ANCHOR BOLT NUT BOT. OUT & 3/4" INST. NOT 5/8"	10/18/85	85-1295	
36-HBB-3-H207	WELDS UNDERSIZED, INSTALLED BOLTS ARE 3/4" NOT 5/8" ALL W/3-WASHERS	10/19/85	85-1296	
36-HBB-3-H209	5/8" SPACERS ADDED, WELDS UNDERSIZED, BOLT SPACING	10/18/85	85-1297	
36-HBB-3-H211	MATERIAL SIZE INCREASED, WELDS UNDERSIZED WEST IT-2 NOT PER DRAWING	10/18/85	85-1298	
36-HBB-4-H209	PLATES ADDED, WELDS UNDERSIZED, BOLT EDGE DISTANCE INCREASED	10/18/85	85-1299	
36-HBB-3-H208	BOLT SPACING, WELD DELETED	10/18/85	85-1300	
36-HBB-4-H207	WELDS UNDERSIZED	10/18/85	85-1301	
36-HBB-3-H210	PLATES ADDED, WELDS UNDERSIZED, BOLT SPACING, 3-HILTI'S & 1-WEJ-IT INST.	10/18/85	85-1302	
36-HBB-3-H201	3-WASHERS ON ANCHOR BOLTS, PLATE GAPS	10/18/85	85-1303	
36-HBB-4-H200	MATERIAL CHANGED, WELD UNDERSIZED	10/18/85	85-1304	
36-HBB-4-H202	3-WASHERS ON ANCHOR BOLTS	10/18/85	85-1305	
36-HBB-12-H6	WELD DELETED, PLATE CUT TO AVOID INTF. SHOUBER PLATE & TAG PLAGE DO NOT AGREE	10/18/85	85-1306	
36-HBB-3-H111	MATERIAL SIZE REDUCED, NOT FULL THD. ENGAGEMENT 1-BOLT	10/19/85	85-1328	
36-HBB-4-H214	WELDS UNDERSIZED	10/19/85	85-1331	
36-HBB-4-H217	WELDS UNDERSIZED	10/19/85	85-1332	
36-HBB-3-H219	WELD UNDERSIZED, IT-3 ROATED 180 DEGREES	10/19/85	85-1333	
36-HBB-4-H216	WELDS UNDERSIZE	10/19/85	85-1334	
36-HBB-3-H224	WELD SYMBOL MISSING, WELD UNDERSIZED, ANCHOR BOLT SIZE INCREASED	10/19/85	85-1335	

DAVIS - BESSIE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
36-HBB-3-H216	WELD UNDERSIZED, HOLES EXIST IN IT-1, ANCHOR BOLTS TRIMMED	10/19/85	85-1339	
36-HBB-4-215	WASHER PLATE THK. DECREASED, WELD UNDERSIZED, ANCHOR BOLTS TRIMMED	10/19/85	85-1340	
36-HBB-4-H213	3 WASHER ON ANCHOR BOLTS, UNDERSIZE WELDS, WASHER PLATE THK. REDUCED	10/19/85	85-1341	
36-HBB-3-H217	ANCHOR BOLTS NOT PER CATALOG	10/19/85	85-1342	
36-HBB-3-H223	ANCHOR BOLTS TRIMMED, WELDS ARE UNDERSIZE AND NOT PER DRAWING	10/21/85	85-1347	
36-HBB-3-H222	BASEPLATE SIZE INCREASED, WELDS ARE UNDERSIZED	10/21/85	85-1348	
36-HBB-3-H214	BASEPLATE SIZE INCREASED, WELD UNDERSIZED, PLATE ADDED FOR STABILITY	10/21/85	85-1349	
36-HBB-3-H216	WELD NOT ON DRAWING, UNDERSIZED WELD	10/21/85	85-1362	
36-HBB-3-H116	1/2" HILTI'S INSTALLED NOT WEJ-ITS, BOLT-1 TRIMMED, BAR ADDED TO STABILIZE SFT.	10/21/85	85-1364	
36-HBB-4-H211	BOLT WITH NO WASHER, PLATE GAPS, WELDS UNDERSIZED	10/21/85	85-1365	
36-HBB-3-H215	BOLTS NOT PER DRAWING, PLATE GAPS, WELDS UNDERSIZED	10/21/85	85-1367	
36-HBB-4-H210	PLATE GAPS, BOLT TRIMMED, WELDS UNDERSIZED	10/21/85	85-1368	
36-HBB-3-H213	PLATE SIZE INCREASED, WELD DELETED	10/21/85	85-1369	
36-HBB-4-H221	WELDS NOT PER DRAWING & UNDERSIZED	10/21/85	85-1370	
36-HBB-4-H220	WELDS NOT PER DRAWING	10/21/85	85-1371	
36-HBB-4-H218	ROD NOT PER DRAWING, STAKED THREADS	10/23/85	85-1416	
D-867-A-126	ANCHOR BOLTS SPACING UNACCEPTABLE, DIMEN. NOT PER DRAWING	10/23/85	85-1417	
36-HBB-4-H219	BASE PLATE GAP UNACCEPTABLE, WELD & DIMEN. NOT PER DRAWING	10/27/85	85-1418	

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
H88-J-H221	WELDS UNDERSIZED, STAKED THREADS, GROUT J-SIDES	10/25/85	85-1455	
A-125	WELDS UNDERSIZED, PLATE THK. INCREASED	10/25/85	85-1456	
H88-J-H220	ANCHOR BOLTS W/2 NUTS, BOLT W/3-WASHERS, 1/2 PAINTED	10/25/85	85-1472	

SECTION 19.0

STEAM GENERATOR DRAIN SYSTEM

DAVIS - BESEE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
4-20-1-42	WELD NOT PER DWS	10/29/85	85-1538	
M-1147-47	ANCHOR BRACING, SHIM INSTALLED, EMBED.	10/15/85	85-1172	
M-1147-44	DIMENSIONS	10/15/85	85-1173	
7-888-5-43	WELD SIZE & DETAIL	10/15/85	85-1174	
M-1147-45	DIMENSION, WELD DETAIL	10/15/85	85-1175	
M-1147-46	DIMENSION	10/15/85	85-1176	
7-888-5-48	THREAD STAKED, BASE PLATE GROUTED, GREASE FITTING DAMAGE	10/15/85	85-1179	
7-888-5-47	NO WASHER, BASE PL. GROUTED, DIMENSION, WELD SIZE, SNAP RING DAMAGED	10/15/85	85-1180	
M-1147-48	ADDITIONAL ANGLE	10/15/85	85-1190	
7-888-5-412	WELDS, GAP	10/16/85	85-1196	
7-888-5-410	ANCHOR BOLTS, WELDS, LOOSE CLAMP BOLT	10/16/85	85-1197	
7-888-5-414	WELD SIZE	10/16/85	85-1198	
7-888-5-416	ANCHOR BOLT, WELDS, STAKED THREAD	10/16/85	85-1201	
7-888-5-415	ARC STRIKE ON PIPE, WELDS	10/16/85	85-1202	
M-1147-42	ANCHOR BOLT BRACING, ADDED WELD	10/16/85	85-1203	
7-888-5-413	PIN TO PIN, WELDS, CLAMP TO PIPE DIMENSION	10/16/85	85-1208	
7-888-5-417	WELDMENTS UNDERSIZED	10/16/85	85-1211	
M-1147-41	ANCHOR BOLT EMB., BASEPLATE GAPS, DIMENSIONS	10/16/85	85-1212	
M-1147-49	ANCHOR BOLT & BASEPLATE SIZE, WELDS, DIMENSIONS	10/16/85	85-1213	
M-1147-410	ADDED WELD	10/16/85	85-1214	
7-888-5-418	WELDS UNDERSIZE	10/16/85	85-1216	
7-888-5-411	PLATE GROUTED, WELDS, SNUGGER & CLAMP	10/16/85	85-1218	

DAVIS - BEBEE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
M-1147-H13	ANCHORBOLT EMB. WELDS, DIMENSIONS	10/16/85	85-1219	
M-1147-H14	ATTACHMENT LOCATION ON BASEPLATE	10/16/85	85-1220	
M-1147-H12	WELD, BOLT EMB., DIMENSIONS, PLATE SIZE	10/16/85	85-1221	
M-1147-H15	ANCHORBOLT SPACING, WELD, PIPE LOCATION	10/16/85	85-1222	
M-1147-H11	ANCHORBOLT EMB. AND EDGE DISTANCE	10/16/85	85-1223	
7-BEB-5-H4	WELDS, GAP INCREASED	10/16/85	85-1272	
7-BEB-5-H5	WELDS, MATERIAL SIZE	10/16/85	85-1277	
7-BEB-5-H6	WELDS UNDERSIZED	10/16/85	85-1274	
M-1147-H17	BOLT EMB. & LOCATIONS, WELD DETAIL	10/17/85	85-1243	
M-1147-H16	BOLT THREAD ENGAGEMENT & LOCATION DIMENSION & LENGTH	10/17/85	85-1244	
M-1147-H18	WELD TYPE, MEM. LOCATION DIMENSION & LENGTH	10/17/85	85-1245	
7-BEB-5-H27	WELDS UNDERSIZED, LOCATING DIMENSIONS	10/17/85	85-1246	
7-BEB-5-H26	BOLT SIZE, WELD LENGTH, GAPS INCREASED	10/17/85	85-1250	
7-BEB-5-H9	WELDS UNDERSIZE, PIPE CLEARANCES	10/17/85	85-1252	
M-1147-H19	BASE PLATE SIZE, SUPPORT DIMENSIONS, WELD TYPES	10/17/85	85-1253	
7-BEB-5-H73	WELD SYMBOL MISSING, WELDS UNDERSIZE, SUPPORT DIMENSIONS	10/17/85	85-1254	
7-BEB-5-H20	WELD UNDERSIZE, MEMBER LENGTH SHORTENED	10/17/85	85-1256	
7-BEB-5-H21	WELDS UNDERSIZED AND MISSING SYMBOL	10/17/85	85-1257	
7-BEB-5-H34	WELD LENGTH DECREASED	10/17/85	85-1258	
7-BEB-5-H72	WELDMENTS UNDERSIZED	10/17/85	85-1259	
7-BEB-5-H24	W4 INSTALLED INSTEAD OF M4-4 MEM'S WELDS UNDERSIZED, GAPS INCREASED	10/17/85	85-1264	
7-BEB-5-H25	STANCHION LENGTH INCREASED 1/4"	10/17/85	85-1265	

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SA NUMBER	DISPOSITION
7-226-5-H23	W4 INSTALLED INSTEAD OF M4-2 MEM 8 WELD UNDERSIZED, MEM. LTH. CLAMP 5 DIM.	10/17/85	85-1266	
7-226-5-H22	W4 INSTALLED INSTEAD OF M4-2 MEM 8 WELD UNDERSIZED MEM. LTH. CLAMP 5-DIM.	10/17/85	85-1267	
M-1142/H7	LOCATION DIMENSION, WELD UNDERSIZE, GAPS REDUCED	10/25/85	85-1476	
M-1142/H10	DIMENSION SHORTENED, NO WEEP HOLE, WELD UNDERSIZED	10/25/85	85-1477	
CCA(36"10)-2-H	WELDS UNDERSIZED, LOCK WIRE MISSING	10/25/85	85-1486	
CCA(36"10)-2-H	SNUGGER INTERFERENCE, DIMENSIONS SHORTEN, WELD SIZES	10/25/85	85-1487	
CCA-20-1-H7	MISSING LOCKWIRE, WELD NOT PER DRAWING	10/29/85	85-1523	
CCA-20-1-H1	WELDS NOT PER DRAWING, MISSING LOCK WIRE	10/29/85	85-1534	
CCA-20-1-H3	WELDS & WASHERS NOT PER DRAWING, MISSING LOCK WIRE	10/29/85	85-1535	
CCA-20-1-H5	WELDS, GAP, WASHERS, & BOLT NOT PER DRAWING	10/29/85	85-1536	
CCA-20-H12	WELDS & SHIM NOT PER DRAWING	10/29/85	85-1537	
CCA-20-1-H6	WELD NOT PER DRAWING	10/29/85	85-1539	
CCA-20-1-H8	WELD NOT PER DRAWING	10/29/85	85-1540	
CCA-20-1-H10	WELD NOT PER DRAWING	10/29/85	85-1541	

SECTION 20.0

CONTAINMENT BUILDING VENT SYSTEM

SYSTEM: CONTAINMENT BUILDING VENT SYSTEM

DAVIS - BESSE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SR NUMBER	DISPOSITION
40-HCB-12-H2	MATERIAL CHANGE, WELD, STRUT ANGLE	10/16/85	85-1200	
40-HCB-12-H4	WELD TYPE & SIZE, MEM, LENGTH SHORTENED	10/17/85	85-1247	
40-HCB-12-H3	WELD LENGTH SHORTENED & MEM'S SHORT BOLT LOC.	10/18/85	85-1277	
40-HCB-12-H6	LOC. OF ATT. ON BASEPLATE GAPS, WELDS	10/18/85	85-1278	

SECTION 21.0

REFUELING CANAL SYSTEM

Page No. 1
11/01/85

SYSTEM: REFUELING CANAL SYSTEM

DAVIS - BEBEE PIPING / SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/SP NUMBER	DISPOSITION
A-069	ANCHOR BOLT BRACING	10/12/85	85-1786	

SECTION 22.0

HANGER LOCATION DISCREPANCIES

SECTION 23.0
MAIN FEEDWATER SYSTEM

DAVIS - BEEBE PIPING & SUPPORTS
INSPECTION FINDINGS

REV. 15

SUPPORT NUMBER	DESCRIPTION	DATE	NCR/BR NUMBER	DISPOSITION
SP-17	WELDS UNDERSIZED, GAPS	10/24/85	85-1428	
EBB-3-SP-21	WELDS, LOCATION & SIZE DIMENSIONS, GAPS	10/24/85	85-1429	
EBB-3-SP-20	WELD REDUCED, MEM. SHORTENED	10/24/85	85-1430	
EBB-3-H7	ANCHOR BOLTS W/3-WASHERS, BEAM ATT. W/PIN	10/24/85	85-1431	
EBB-3-H6	WELD REDUCED, BEAM ATT. W/PIN, B. PLATE GAPS	10/24/85	85-1432	
H6	ANCHOR BOLT W/3 WASHERS, STAKED THREADS, GROUT CRACK	10/24/85	85-1450	
SP-22	WELDS UNDERSIZED, STAKED THREADS, BOLT MATERIAL & TYPE	10/24/85	85-1451	
EBB-3-SP268	DIMENSION NOT PER DRAWING	10/29/85	85-1545	
EBB-3-SP-248	WELDS NOT PER DRAWING	10/29/85	85-1546	
EBB-3-H10	WELDS NOT PER DRAWING	10/29/85	85-1547	
EBB-3-SP259	MEMBERS & DIMEN. NOT PER DRAWING	10/29/85	85-1548	
EBB-3-H9	WELDS NOT PER DRAWING	10/29/85	85-1549	

15