

FEB 10 1986

License: 35-23147-01
Docket: 30-20309/85-01
30-20309/85-02

Petro-Log
ATTN: Mr. Robin Kidd
Box 337
Hominy, Oklahoma 74035

Gentlemen:

This refers to the routine, unannounced radiation safety inspection conducted by W. L. Holley of this office on October 31 and November 1, 1985 of the activities authorized by NRC License 35-23147-01, and to the discussion of our findings held by the inspector with members of your staff at the conclusion of the inspection.

This also refers to the Enforcement Conference held in the Region IV office on December 19, 1985, between Mr. Robin Kidd and staff members of our office to discuss the findings of the NRC inspection. The enclosed Inspection Report 30-20309/85-02 documents this conference.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations, and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observations by the inspector.

During this inspection certain of your activities were found not to be conducted in full compliance with NRC requirements. These violations reflect a lack of management control over licensed activities. Consequently, you are required to respond to this matter in writing in accordance with provisions of Section 2.201 of the NRC "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Your response should be based on the specifics contained in the Notice of Violation enclosed with this letter.

RIV: *[Signature]*
WHolley
1/31/86

C: NMSS
RJEvet
2/3/86

C: RSPB
REHall
2/10/86


EO *[Signature]*
DAPowers
2/4/86

B602180271 B60210
REG4 LIC30
35-23147-01 PDR

IE07
116

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

Sincerely,

Original Signed by: 

R. L. BANGART

Ramon E. Hall, Chief, Radiological
and Safeguards Programs Branch

Enclosures:

Appendix A - Notice of Violation

Appendix B - NRC Inspection Report

30-20309/85-02

cc:

Oklahoma Radiation Control Program Director

bcc:

DMB - Original (IE-07)

RMartin

RBangart

DPowers

DWeiss, LFMB (AR-2015)

*Inspector

*MIS System

*RIV Files

*NMSS

*RSTS Operator

*w/766