

WATERFORD OPEN ISSUE

Task: A-296, A-306a, A-306k, A-306L, A-306m

Ref. No.: 4-84-A-06/177, 184a, 184k, 184L, 184m

Characterization: It is alleged that Tompkins-Beckwith (T-B) may have violated the ASME Code requirements by failing to visually examine the shop pipe welds for leaks during hydrostatic tests.

Initial Assessment of Significance: Potential ASME code violation.

Source:

Approach to Resolution:

1. Review requirement, codes, specifications, etc.
2. Obtain procedures, test records, etc.
3. Determine validity of allegation.

Status: under review - Hubbard assigned

Review Lead: L. Shao (RWH)

Support:

Estimate Resources: (1) man 2 days

Estimated Completion: April 9, 1984

CLOSURE:

Document Name:

A-296

Wm Allen

Requestor's ID:

JOYCE

Author's Name:

RETYPE DRAFT 4 (FINAL)

Document Comments:

WATERFORD OPEN ISSUE

Task: A-296, A-306a, A-306k, A-306l, A-306m

Ref. No.: 4-84-A-06/177, 184a, 184k, 184l, 184m

Characterization: It is alleged that Tompkins-Beckwith (T-B) may have violated the ASME Code requirements by failing to visually examine the shop pipe welds for leaks during hydrostatic tests.

Initial Assessment of Significance: Potential ASME code violation.

Source:

Approach to Resolution:

1. Review requirement, codes, specifications, etc.
2. Obtain procedures, test records, etc.
3. Determine validity of allegation.

Status: under review - Hubbard assigned

Review Lead: L. Shao (RWH)

Support:

Estimate Resources: (1) man 2 days

Estimated Completion: April 9, 1984

CLOSURE:

Document Name:
A-296

Requestor's ID:
JOYCE

Author's Name:

Document Comments: