

**LOUISIANA**  
POWER & LIGHT

317 BARONNE STREET • P. O. BOX 60340  
NEW ORLEANS, LOUISIANA 70160 • (504) 595-3100

November 15, 1985

W3P85-2598  
3A-25.01.02  
A4.10  
QA

Mr. Roger C. Hartung, Chief  
Enforcement Branch, 6W-E  
U. S. Environmental Protection Agency  
Region VI  
Interfirst Two Building  
1201 Elm Street  
Dallas, Texas 75270

SUBJECT: Waterford Steam Electric Station - Unit Number 3  
NPDES Permit Number LA0007374

Dear Mr. Hartung:

As required by Part I.C.2 of the subject permit as administratively modified by your letter of September 12, 1983, Discharge Monitoring Reports (DMR's) for October 1985 are enclosed. Copies of this letter and the DMR's are also being submitted to the Office of Water Resources of the Louisiana Department of Environmental Quality. Also attached is a discussion of permit noncompliances occurring between September 24-30, 1985.

Please note that although I have signed each DMR, I am making the following certification which appears in 40 CFR 122.22(d) (published at 48 FR 39619 on September 1, 1983) in lieu of that printed on the DMR (EPA Form 3320-1 (Rev. 10-79)):

I certify under penalty of law that this document and all attachments were prepared under [my] direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.


8512090077 851115  
PDR ADOCK 05000382  
R PDR

IE 25  
11

Mr. Roger C. Hartung  
W3P85-2598  
Page 2.

Should you have any questions or comments, please contact Ms. Chadi Groome  
of our Nuclear Licensing Office at (504) 595-2846.

Yours very truly,



R. P. Barkhurst  
Plant Manager-Nuclear

RPB/CDG/smb

Attachment

cc (w/Attachments): J. D. Givens - LA DEQ  
R. D. Martin - Region IV  
C. W. Knighton - NRR

NS40674SEG

## NONCOMPLIANCES

OCTOBER 1985

On October 3, 1985, approximately 200 gallons of oil were inadvertently discharged from the yard oil separator through outfall 002. The release was terminated immediately upon discovery. Although no analysis was performed on the discharge, it was obvious that the concentration of oil and grease exceeded the effluent limitation of 20 mg/l. Sorbent booms in place in the ditch contained the oil in the immediate vicinity of the outfall (still on Waterford 3 property) until the oil was removed from the ditch. The cause of the incident was a failed gasket in the separator, which was repaired immediately upon discovery, prior to restarting the separator.