

file

NOV 26 1985

Henry Ford Hospital
ATTN: L. E. Preuss
Room 3053 E & R Building
2799 West Grand Boulevard
Detroit, MI 48202

Gentlemen:

We have reviewed your letter dated October 15, 1985 requesting amendment to License Number 21-04109-16 and find that we will need additional information as follows:

1. Identify the locations by address where the bone mineral analyzer and Lixiscope devices will be used.
2. Indicate whether or not these devices will be transported between locations. If so, provide procedures to be followed for safe transportation. You may reference your established procedures as described in letter dated October 30, 1984 and state that these procedures will apply to all devices.
3. Describe who will perform repair or maintenance on the Lixiscope and bone mineral analyzer devices. If someone other than the manufacturer will perform these services, describe their training and experience servicing these devices.
4. Describe the procedures to be followed when replacing source holders in the devices. You may state that each manufacturer's source replacement procedures will be followed.

If you have any questions or require clarification on any of the information stated above, you may contact us at (312) 790-5625.

We will continue our review of your application upon receipt of this information. Please reply in duplicate, within 30 days, and refer to Control Number 79999.

Sincerely,

Original Signed By
Evelyn R. Matson
Materials Licensing Section

8602180411 861212
REG3 LIC30
21904109-16 PDR

RIII

EM
Matson/cm
11/25/85