


IE07


TULSA GAMMA RAY, INC.

1127 SOUTH LEWIS
TULSA, OKLAHOMA 74104
918/585-3228 FAX #918/584-5598



JAMES C. MOSS
PRESIDENT

April 3, 1997



USNRC Regional Administrator
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

Docket No. 30-12319
License No. 35-17178-01
EA-96-535

RE: Reply to a notice of violation.

1. Reason for Violation:
Radiation survey was not performed because the technician believed this function had been completed by another technician.
2. Corrective steps taken and results achieved:
Tulsa Gamma Ray employees have been instructed to perform a survey whenever walking into a vault whether or not they have unlocked or used the radioisotope that is stored in that facility. The results achieved are, no employees have been overexposed since implementing this instruction.
3. Corrective steps that will be taken to avoid further violations:
Employees will continue to survey the vault at the beginning of work shift.
4. Date of full compliance: November 21, 1996

9704160157 970403
PDR ADOCK 03012319
C PDR

Sin. dy,

Peter J. Moss
President
Tulsa Gamma Ray, Inc.

1/0

97-0946

