

DEC 02 1985

Docket No. 50-29

Yankee Atomic Electric Company
ATTN: Mr. L. H. Heider
Vice President of Operations
1671 Worcester Road
Framingham, Massachusetts 01701


Gentlemen:

Subject: Inspection Report No. 50-29/85-23

A routine safety inspection of the radiation protection program during a plant outage at the Yankee Nuclear Power Station was conducted on October 28 to November 1, 1985. Areas inspected included ALARA implementation, radiation work permits, frisking, control of high radiation exclusion areas, control of radioactive material, and the evaluation methods for workers uptake of dust.

The inspection report is attached. Management emphasis is recommended to ensure implementation of certain key elements of the ALARA program to promote exposure reductions. No violations were identified and no reply to this letter is required. Your cooperation with us is appreciated.

Sincerely,
Original Signed By:

for 
Thomas T. Martin, Director
Division of Radiation Safety
and Safeguards

Enclosure: NRC Inspection Report No. 50-29/85-23

cc w/encl:

N. N. St. Laurent, Plant Superintendent
J. E. Tribble, President
G. J. Papanic, Jr., Senior Project Engineer - Licensing
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
Commonwealth of Massachusetts (2)

8512090231 851202
PDR ADOCK 05000029
Q PDR

OFFICIAL RECORD COPY

IR YR 85-23 - 0010.0.0
11/27/85

JEOK
11

bcc w/encl:

Region I Docket Room (with concurrences)

Management Assistant, DRMA (w/o encl)

DRP Section Chief

M. McBride, RI, Pilgrim

W. Raymond, SRI, Vermont Yankee

J. Clifford, LPM, NRR

RI:DRSS *AW for*
McFadden/mmb

11/27/85

HD
RI:DRSS
Dragoun

11/27/85

RI:DRSS
Shapbaky *MS*

11/27/85

RMH
RI:DRSS
Bellamy

11/27/85

OFFICIAL RECORD COPY

IR YR 85-23 - 0011.0.0
11/27/85