

~~SAFEGUARDS INFORMATION~~

FEB 14 1986

Docket No. 50-315

Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering and Construction
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the reactive safeguards inspection conducted by Messrs. T. J. Madeda and J. R. Kniceley of this office on January 13-16, 1986, of activities at the Donald C. Cook Nuclear Power Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with Mr. W. Smith, Jr. and other members of his staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

Areas examined during this inspection concern a subject matter which is exempt from disclosure according to Part 73, Title 10, Code of Federal Regulations, Section 73.21(c)(2). This information must be handled and protected in accordance with the provisions of 10 CFR 73.21. Consequently, the enclosure to this letter, our report of the inspection, and your response to the violation(s) identified in the enclosure to this letter will not be placed in the NRC Public Document Room. Therefore, your statement of corrective action regarding the violation(s) identified in the enclosure should be submitted as a separate enclosure to your transmittal letter in the manner prescribed.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

8602190217 860214
PDR ADOCK 05000315
G PDR

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled

IE04

1/1

~~SAFEGUARDS INFORMATION~~

~~SAFEGUARDS INFORMATION~~


American Electric Power
Service Corporation

2

FEB 14 1986

We will gladly discuss any questions you have concerning this inspection.

Sincerely,


W. L. Axelson, Chief
Nuclear Materials Safety
and Safeguards Branch

Enclosures:

1. Notice of Violation
 2. Inspection Reports
No. 50-315/86003(DRSS);
No. 50-316/86003(DRSS)
- (UNCLASSIFIED SAFEGUARDS INFORMATION)


cc w/enclosures:

W. G. Smith, Jr., Plant Manager
IE File
IE/DI/ORPB
IE/ES
NMSS/SGPL
NRR/DL/SSPB
ACRS


cc w/enclosures, w/o

UNCLASSIFIED SAFEGUARDS
INFORMATION:
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Nuclear Facilities and
Environmental Monitoring
Section


RIII


Madaeda/rr
2/11/86


RIII


Kniceley


RIII


Creed

RIII


Suermann
for Axelson

RIII


Axelson

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled

~~SAFEGUARDS INFORMATION~~