

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

Reports No. 50-315/86003(DRSS); 50-316/86003(DRSS)

Docket Nos. 50-315; 50-316 Licenses No. DPR-58; DPR-74 Safeguards Group IV

Licensee: American Electric Power Service Corporation
Indiana and Michigan Electric Company
1 Riverside Plaza
Columbus, OH 43216

Facility Name: Donald C. Cook Nuclear Power Plant, Units 1 and 2

Inspection At: Donald C. Cook Site, Bridgman, MI

Inspection Conducted: January 13-16, 1986

Date of Last Physical Protection Inspection: November 18-21, 1985

Type of Inspection: Unannounced, Reactive Physical Security

Inspectors:

T. J. Madede
T. J. Madede
Physical Security Inspector

2/11/86
Date

J. R. Kniceley
J. R. Kniceley
Physical Security Inspector

2/11/86
Date

Approved By:

J. R. Creed
J. R. Creed, Chief
Safeguards Section

2/11/86
Date

Inspection Summary

Inspection on January 13-16, 1986 (Reports No. 50-315/86003(DRSS);
50-316/86003(DRSS))

Areas Inspected: Included a review of Security Management Effectiveness;
Security Organization; Security Program Audit; Testing and Maintenance;
Physical Barriers - Vital Areas; Access Control - Personnel and Vehicles;

8602190230 860214
PDR ADDCK 05000315
PDR
Q

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled

Communications; Compensatory Measures; and Personnel Training and Qualifications - General Requirements. These areas were selected for review based on previously identified problems. The inspection involved 60 direct inspection-hours by two NRC inspectors.

Results: The licensee was found to be in compliance with NRC requirements in the areas inspected, except for the following two items:

- a. Testing and Maintenance: The licensee failed to correct deficiencies with security equipment in a timely manner.
- b. Access Control - Personnel: The licensee failed to adequately search some individuals and failed to utilize operational access control equipment.

(Details: UNCLASSIFIED SAFEGUARDS INFORMATION)

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled