

September 9, 1985

Dr. Thomas E. Murley  
Regional Administrator  
United States Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406


RE: Docket 50-220  
SPECIAL REPORT

Gentlemen:

In accordance with Technical Specification 3.6.10.1, we hereby submit the following Special Report concerning fire barrier penetrations:

On August 8, 1985, it was determined that penetration I-849 and new penetration I-2310 should be opened and rendered non-functional so that maintenance modifications involving floor drains could be fulfilled. Both penetrations were declared inoperable in compliance with Tech. Spec. 3.6.10.1 (Fire Barrier Penetrations). Fire watch patrols were established in accordance with Tech. Specs. to perform hourly inspections until the modifications were completed on August 30, 1985.

Very truly yours,



Thomas E. Lempges  
Vice President  
Nuclear Generation

TEL/tg  
cc: Document Control Desk