

SEP 26 1985

Docket No.: 50-423

Mr. John F. Opeka  
Senior Vice President  
Nuclear Engineering and Operations  
Northeast Nuclear Energy Company  
P. O. Box 270  
Hartford, Connecticut 06141-0270

Dear Mr. Opeka:

Subject: Failure to submit information requested by the staff in a timely manner.

Representatives of your staff committed to provide all additional information requested by the staff related to Technical Specification by September 25, 1985.

Nine items of requested information required by the staff to continue our review have not been submitted to date and two items submitted did not satisfactorily address our concerns. These are identified in Enclosure 1 to this letter.

Because of NNECo's failure to provide the requested information in a timely manner we will be unable to issue our Final Draft Technical Specification on September 30 as we had previously intended.

Additional delay in submitting requested information or the submittal of inadequate information could result in a delay in issuance of the final version of the Technical Specifications needed for issuance of an operating license for Millstone Unit 3.

Sincerely,

B. J. Youngblood, Chief  
Licensing Branch No. 1  
Division of Licensing

Enclosure: As stated

cc: See next page

DISTRIBUTION:

**Docket File**

NRC PDR  
Local PDR  
PRC System  
NSIC  
LB#1 R/F  
EDoolittle

LB#1 R/F  
EDoolittle/mac  
9/26/85

OELD  
ACRS (16)  
JPartlow  
EJordan  
BGrimes

LB#1 R/F  
BJYoungblood  
9/26/85

8510030372 850926  
PDR ADOCK 05000423  
A PDR

Enclosure 1

STATUS OF MILLSTONE 3  
TECHNICAL SPECIFICATION REVIEW

Information Requested and not Provided

1. Revised Boron Dilution Analysis to support revised SDM
2. Flow Uncertainty Values and Analysis
3. Table 3.3-1 ACTION 2 (dependent upon setpoint methodology)
4. Justification for 10% S/G secondary side water level
5. Air Temperature Monitor locations in containment
6. Bases for C.R. Envelope Pressurization System
7. Values and new statement on boron dilution p. B 3/4 1-1 and 1-2
8. Instrument error value p. B 3/4 7-7
- 9 Section 6 (Figure 6.2.2 or revised FSAR)

Inadequate Information Provided

1. Table 3.3.5 Response times
2. Seismic Instrument (Table 3.3-7 consistent with FSAR)

Other Information Requested

1. SLCRS (95% filter efficiency)
2. PIVs (MEB relaxed requirements if justified)

Mr. J. F. Opeka  
Northeast Nuclear Energy Company

Millstone Nuclear Power Station  
Unit No. 3

cc:  
Gerald Garfield, Esq.  
Day, Berry & Howard  
City Place  
Hartford, Connecticut 06103-3499

Ms. Jane Spector  
Federal Energy Regulatory Commission  
825 N. Capitol Street, NE  
Room 8608C  
Washington, D.C. 20426

Mr. Maurice R. Scully, Executive  
Director  
Connecticut Municipal Electric  
Energy Cooperative  
268 Thomas Road  
Groton, Connecticut 06340

Robert W. Bishop, Esq.  
Corporate Secretary  
Northeast Utilities  
Post Office Box 270  
Hartford, Connecticut 06141

Mr. T. Rebelowski  
Senior Resident Inspector Office  
U. S. Nuclear Regulatory Commission  
Millstone III  
P. O. Box 615  
Waterford, Connecticut 06385

Mr. Michael L. Jones, Manager  
Project Management Department  
Massachusetts Municipal Wholesale  
Electric Company  
Post Office Box 426  
Ludlow, Massachusetts 01056

Regional Administrator  
U. S. NRC, Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Mr. Karl Abraham  
Public Affairs Office, Region I  
U. S. Nuclear Regulatory Commission,  
King of Prussia, Pennsylvania 19406