

APPENDIX A

NOTICE OF VIOLATION

Erie Nuclear Cardiology Center
Erie, Pennsylvania 16508

Docket No. 030-20851
License No. 37-21489-01

As a result of the inspection conducted on August 9, 1985, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violations were identified:

- A. Condition 15 of License No. 37-21489-01 requires that licensed material be possessed and used in accordance with statements, representations and procedures contained in the application dated October 5, 1983.

1. Item 10 of the application requires survey meter calibrations to be conducted quarterly.

Contrary to the above, as of August 9, 1985, the Eberline E-130A in the hot lab was last calibrated on March 26, 1985, a period greater than three months.

This is a Severity Level IV violation (Supplement VI)

2. Item 10.2 of the application requires that tests of dose calibrator accuracy be conducted quarterly with a 10 millicurie cobalt-57 source.

Contrary to the above, the accuracy tests of the dose calibrator were not conducted during the fourth quarter of 1984 nor for the first and second quarters of 1985.

This is a Severity Level IV violation (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Erie Nuclear Cardiology Center is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8510040016 850919
REG1 LIC30
37-21489-01 PDR