

DEC 0 5 1985

Docket No. 50-409

Dairyland Power Cooperative
ATTN: Mr. J. W. Taylor
General Manager
2615 East Avenue - South
LaCrosse, WI 54601

Gentlemen:

This refers to the routine safety inspection conducted by Mr. L. J. Hueter of this office on November 12-15, 1985, of activities at LaCrosse Boiling Water Reactor authorized by NRC Operating License No. DPR-45 and to the discussion of our findings with Mr. Kelly and other members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by W.D. Shafer"

W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection Branch

Enclosure: Inspection
Report No. 50-409/85020(DRSS)

See Attached Distribution

TEOL
11

8512100152 851205
PDR ADOCK 05000409
Q PDR

Distribution

cc w/enclosure:

J. Parkyn, Plant Superintendent

DCS/RSB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

John J. Duffy, Chief

Boiler Section

Ness Flores, Chairperson

Wisconsin Public Service

Commission

Spark Burmaster, Coulee

Region Energy Coalition

RIII

L.H. Huetter
Huetter/jlk
12/04/85

RIII

M. J. Schumacher
Schumacher

RIII

Boyd
Boyd

RIV

Shafer
Shafer