

ENCLOSURE 1

NOTICE OF DEVIATION

Duke Power Company
McGuire Units 1 and 2

Docket Nos. 50-369 and 50-370
License Nos. NPF-9 and NPF-17

The following deviations were identified during an inspection conducted on October 15 - November 8, 1985.

McGuire FSAR Section 6.4.3 and Table 6.2.3-4 stipulate that inplace testing of the Control Room Area Ventilation Systems (CV) were in compliance with Regulatory Guide 1.52 (Revision 2, March 1978) which in turn obligates the licensee to ANSI N510-1975.

Contrary to those commitments, a review of completed preoperational tests performed on McGuire Control Room Area Ventilation Trains A and B revealed that Regulatory Guide 1.52 and/or ANSI N510-1975 were not adhered to in that the air-aerosol uniformity tests were not performed as specified.

This deviation is applicable to Units 1 and 2.

Please provide, in writing within 30 days of the date of this Notice, a description of corrective actions regarding these deviations, actions taken to avoid further deviations, and the dates when these actions were or will be completed.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: DEC 04 1985

8512100197 851204
PDR ADOCK 05000369
Q PDR