


**TEXAS UTILITIES GENERATING COMPANY**  
SKYWAY TOWER • 400 NORTH OLIVE STREET, L.B. #1 • DALLAS, TEXAS 75201

Log # TXX-4628  
File # 10110

November 20, 1985

WILLIAM G. COUNCIL  
EXECUTIVE VICE PRESIDENT

Mr. R. P. Denise, Director  
Division of Reactor Safety and Projects  
U.S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76012



SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION  
DOCKET NOS. 50-445 AND 50-446  
REBAR DAMAGE  
QA FILE: CP-85-45, SDAR-207

Dear Mr. Denise:

On September 26, 1985, we verbally notified your Mr. I. Barnes of a deficiency regarding the use of core boring equipment during the installation of shear lugs which could have resulted in undocumented damaged reinforcing steel. We have submitted an interim report logged TXX-4603, dated October 16, 1985. The concern is being evaluated under CPRT Program Plan Item II.e. Our evaluation to date has revealed no condition adverse to safety.

We are continuing our evaluation and anticipate completion by February 5, 1986.

Very truly yours,

*W.G. Council*

W. G. Council

By: *D.R. Woodlan*  
D. R. Woodlan  
Licensing Supervisor

JCH/grr

c - NRC Region IV (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8512100313 851120  
PDR ADOCK 05000445  
S PDR

85-1065

LE-27

1/0