

APPENDIX A

NOTICE OF VIOLATION

Portland General Electric Company
121 S. W. Salmon Street
Portland, OR 97204

Docket No. 50-344
License No. NPF-1

As a result of the inspection conducted during the period of October 3 - November 16, 1985, and in accordance with the NRC Enforcement Policy, 10 CFR Part 2, Appendix C, the following violation was identified.

10 CFR 50.59, paragraph (b) requires in part that changes to the facility as described in the safety analysis report include a written safety evaluation which provides the bases for the determination that the change does not involve an unreviewed safety question.


Contrary to the above, on October 3, 1985, two helium gas bottles were observed strapped to the Seismic Category I supply and return lines of the 'B' train containment hydrogen analyzer without a supporting safety evaluation having been performed.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Portland General Electric Company is hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which will be taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

NOV 22 1985

Date


R. T. Dodds, Chief
Reactor Projects Section 1

8512100473 851122
PDR ADOCK 05000344
Q PDR