



Entergy

Entergy Operations, Inc.

River Bend Station

5485 U. S. Highway 61

P.O. Box 220

St. Francisville, LA 70775

Tel 504 336 6225

Fax 504 635 5068

Rick J. King

Director

Nuclear Safety & Regulatory Affairs

April 17, 1997

U.S. Nuclear Regulatory Commission

Document Control Desk

Mail Stop P1-37

Washington, D.C. 20555

Subject: River Bend Station - Unit 1
Docket No. 50-458
License No. NPF-47
Licensee Event Report 50-458/96-014-01
File Nos. G9.5, G9.25.1.3

RBG-43875

RBF1-97-0149

Ladies and Gentlemen:


In accordance with 10CFR50.73 enclosed is Revision 1 to Licensee Event Report (LER) 50-458/96-14-00. The original LER was submitted on August 9, 1996, reporting missed surveillances. Subsequent corrective actions included additional review of completed surveillances. Based on this review, the following changes to the original LER are required:

- Include one additional reportable condition identified during the review.
- Remove one reportable condition from the original LER which was subsequently determined not reportable
- Revise corrective actions related to prefilter pressure drop measurement in the original LER

The enclosed LER 50-458/96-14-01, incorporates the changes listed above. These changes are marked by side-bars. The text of the remaining report remains the same as the original LER.

Sincerely,

230075



RJK/SVD/kvm

enclosure

9704230272 970417
PDR ADOCK 05000458
S PDR



Licensee Event Report 50-458/96-014-01
April 17, 1997
RBG-43875
RBF1-97-0149
Page 2 of 2

cc: U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

NRC Sr. Resident Inspector
P. O. Box 1050
St. Francisville, LA 70775

INPO Records Center
700 Galleria Parkway
Atlanta, GA 30339-3064

Mr. G. Dishong
Public Utility Commission of Texas
7800 Shoal Creek Blvd., Suite 400 North
Austin, TX 78757

Louisiana Department of Environmental Quality
Radiation Protection Division
P.O. Box 82135
Baton Rouge, LA 70884-2135
ATTN: Administrator