

Colt Industries



DMB  
Fairbanks Morse  
Engine Division  
701 Lawton Avenue  
Beloit, Wisconsin 53511-5492  
Telephone: 608/364-4411  
Telecopier: 608/364-0382

December 2, 1985

Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Ill. 60137

Attention: Mr. James G. Keppler, Director, Region III

Subject: Colt Industries-Fairbanks Morse Engine Division  
Emergency Diesel Generators  
Possible Thermostatic Valve Malfunction  
Fail Safe To "Full Cooling Position"  
Part 21 Report  
Supplemental Report No. 10  
Alabama Power Co., Farley Units 1 and 2

Reference: May 25, 1982; June 28, 1982 and September 17, 1982  
Part 21 Reports - Robertshaw Valves - same subject


Gentlemen:

The lower overrun assemblies in the Robertshaw valves installed on the Diesel Generator Sets at Alabama Power Co., Farley Units 1 and 2 have been replaced with overrun assemblies utilizing cotter pins to positively lock the nut to the stem.

The units are now free of the reported potential defect.

A copy of this report is being forwarded to the utility involved.

Very truly yours,

  
J.M. Moriarty  
MANAGER UTILITY SALES

JMM/jl

cc: Alabama Power Co.  
P.O. Box 2641  
Birmingham, AL 35291  
Attn: W.G. Hairston, III

U.S. Nuclear Regulatory Commission  
c/o Document Management Branch  
Washington, D.C. 20555

Robertshaw Controls Company  
P.O. Box 400  
Knoxville, TN 37901  
Attn: T.T. Howell, Quality Mgr.

DEC 6 1985

8512120215 851202  
PDR ADCK 05000348  
S PDR

A division of the Colt Industries Operating Corp.

1/0  
1E19