

Docket No.: 50-423

OCT 25 1985

Mr. John F. Opeka
Senior Vice President
Nuclear Engineering and Operations
Northeast Nuclear Energy Company
P. O. Box 270
Hartford, Connecticut 06141-0270

Dear Mr. Opeka:

Subject: Request for Additional Information for Millstone Nuclear
Power Station, Unit No. 3

Enclosed are requests for additional information which the staff requires to complete its evaluation of your application for an operating license for Millstone 3.

Please advise the staff of your schedule to provide responses to this information by November 1, 1985.

For further information or clarification, please contact the Licensing Project Manager, Elizabeth L. Doolittle at (301) 492-4911.

Sincerely,

ORIGINAL SIGNED BY:

B. J. Youngblood, Chief
Licensing Branch No. 1
Division of Licensing

Enclosures: As stated

cc: See next page

DISTRIBUTION:

Docket File EDoolittle
NRCPDR OELD
LPDR ACRS (16)
NSIC EJordan
PRC System JPartlow
LB#1 R/F BGrimes
MRushbrook

LB#1:DL
EDoolittle:kab
10/24/85

LB#1:DL
BJYoungblood
10/24/85

8510310048 851025
PDR ADOCK 05000423
A PDR

OCT 25 1985

Mr. J. F. Opeka
Northeast Nuclear Energy Company

Millstone Nuclear Power Station
Unit No. 3

cc:
Gerald Garfield, Esq.
Day, Berry & Howard
City Place
Hartford, Connecticut 06103-3499

Ms. Jane Spector
Federal Energy Regulatory Commission
825 N. Capitol Street, NE
Room 8608C
Washington, D.C. 20426

Mr. Maurice R. Scully, Executive
Director
Connecticut Municipal Electric
Energy Cooperative
268 Thomas Road
Groton, Connecticut 06340

Robert W. Bishop, Esq.
Corporate Secretary
Northeast Utilities
Post Office Box 270
Hartford, Connecticut 06141

Mr. T. Rebelowski
Senior Resident Inspector Office
U. S. Nuclear Regulatory Commission
Millstone III
P. O. Box 615
Waterford, Connecticut 06385

Mr. Michael L. Jones, Manager
Project Management Department
Massachusetts Municipal Wholesale
Electric Company
Post Office Box 426
Ludlow, Massachusetts 01056

Regional Administrator
U. S. NRC, Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Mr. Karl Abraham
Public Affairs Office, Region I
U. S. Nuclear Regulatory Commission,
King of Prussia, Pennsylvania 19406

ENCLOSURE

630.0 Licensee Qualification Branch

In a letter to B. J. Youngblood from John F. Opeka dated October 16, 1985, an outline of the training program for personnel who will be utilized as Shift Advisors (SA) at Millstone 3 was provided. Based on the staff's review of the elements contained in the SA training program, it was determined that the following information is needed to complete this review.

- 630.12 A resume of each shift advisor which highlights his previous operating experience.
- 630.13 A copy of the procedure which describes the duties and authority of the shift advisors and the working relationships between the advisors and the operating shift personnel.
- 630.14 A copy of the training program presented to the shift advisors to assure they have adequate knowledge of plant specific matters to properly perform their duties.
- 630.15 When available, a copy of written examination(s) administered to the shift advisor and the results of the examinations(s).
- 630.16 When available, copies and notes of the oral/simulator evaluation administered to the shift advisors.
- 630.17 A description of the training program presented to the operating shift crews to assure that they understand the role of the shift advisors.
- 630.18 A statement regarding the medical qualification requirements for the shift advisors.
- 630.19 A description of the procedures that will be used to evaluate the performance of the shift advisors during plant start-up.

ENCLOSURE

440.0 Reactor Systems Branch

440.72 N-1 Loop Operation

We request the applicant to review each AOO and PA to assure that all equipment and systems specifically required by Millstone 3 Technical Specifications to mitigate those events during Mode 1 and 2 would also be available and provide the same level of protection for Modes 3 and 4. Otherwise, provide additional information to show that the proposed N-1 loop technical specifications for Modes 3 and 4, would not allow the plant to operate in an unanalyzed condition and are consistent with the safety analyses.