

OCT 25 1985

Docket No. 50-2

University of Michigan
ATTN: Dr. William Kerr, Director
Michigan Memorial - Phoenix
Project
Phoenix Memorial Laboratory
Ann Arbor, MI 48105

Gentlemen:

This refers to the routine safety inspection conducted by N. A. Nicholson of this office on October 2-4, 1985, of activities at Ford Nuclear Reactor authorized by NRC Operating License No. R-28 and to the discussion of our findings with Mr. R. R. Burn and other staff members at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC's Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by W.D. Shafer"

W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection Branch

Enclosures:

1. Appendix, Notice of Violation
2. Inspection Report No. 50-2/85003(DRSS)

8510310292 851025
PDR ADOCK 05000002
G PDR

cc w/enclosures:
DCS/RSB (RIDS)
Licensing Fee Management Branch

RIII
Nicholson/lis
10/16/85

RIII
Greger

YES
RIII
EAS for
Ridgway
10-25-85

YES
RIII
Wiel
10/25/85

RIII
Shafer

10/16 delete RMH