

Freysinet

THE PRESCON CORPORATION

October 31, 1985

United States
Nuclear Regulatory Commission
Washington, DC 20555

Attention: Mr. Gary G. Zech
Chief Vendor Program Branch
Division of Quality Assurance, Vendor,
and Technical Training Center Programs
Office of Inspection and Enforcement

Subject: Docket No. 99901007/85-01

Gentlemen:

In response to your letter of October 3, 1985, and the above inspection report, The Prescon Corporation has taken the following steps to correct item 1.C. Violation (85-01-01) noted on Page 2 of 7.

Procedures to review and evaluate deviations for reportability have been established (reference QC-P21-09, Rev. 0, dated August 22, 1985). These procedures have been posted throughout the various departments located at the corporate offices and the field offices located at the South Texas Project. In addition, copies of these procedures will be made a part of any purchase orders issued for nuclear related components or services. (Copy attached.)

All of the remaining items in the inspection report have been addressed to you in our letter of July 23, 1985.

Should you have any further questions relating to the inspection report, please contact us.

Sincerely,

THE PRESCON CORPORATION



J. Oiknine
President

8511050138 851031
PDR GA999 EECPRESC
99901007 PDR

JO/kf

cc: H. E. Williams

1338 north w. w. white road, p. o. box 20800, san antonio, texas 78220-0800
phone (512) 662-8500, telex 767550, telecopy (512) 662-6036, a freysinet international company

IE09
11