

Appendix

NOTICE OF VIOLATION

Isomedix Incorporated

License No. 29-15364-02

As a result of the inspection conducted on October 23, 1985, and in accordance with the General Policy and Procedures for NRC Enforcement Actions, (10 CFR Part 2, Appendix C), the following violation was identified:

10 CFR 20.203(c)(6)(v) requires that a clearly identified control device be maintained in a high radiation area which, when activated, can prevent the source of radiation from being put into operation.


Contrary to the above, the emergency cable, mounted in the irradiator cell for the purpose of preventing source operation, was not adequately functional during the October 23, 1985 inspection.

This is a Severity Level IV violation (Supplement IV).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated

10/31/85


W. L. Axleson, Chief
Nuclear Materials Safety
and Safeguards Branch

8511050254 851101
REG3 LIC30
29-15364-02 PDR