

*Doctors Diagnostic Center*

28671 Plymouth Road  
Livonia Michigan 48150

DMS COPY

03028615

2 December 1985

D.G. Wiedeman, Chief  
Nuclear Materials Safety  
U.S. Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr. Wiedeman:


Lic.No. 21-24482-01

This reply is to confirm corrective action taken following an inspection conducted on 28 October 1985.

The barium-133 reference source has been leak tested and will be leak tested at semi-annual intervals. The leak test certificate is enclosed.

The reason the barium-133 source was not leak tested is due to confusion as to the need for its use in daily constancy tests. It is now used, and will be leak tested semi-annually.

Sincerely,



Helen Halpin  
Assistant Director

8512240286 851202  
REG3 LIC30  
21-24482-01 PDR

IE07  
DEC 13 1985