

DEC 12 1985

License: 35-19593-01
Docket: 30-18934/85-01

Sunset Wireline Corporation
ATTN: S. A. McMahon, President
P. O. Box 2
Henrietta, Oklahoma 74437

Gentlemen:

This refers to the routine, unannounced radiation safety inspection conducted by Lorenzo Wilborn of this office on October 30, and November 8, 1985, of the activities authorized by NRC Byproduct Material License 35-19593-01, and to the discussion of our findings held by the inspector with members of your staff at the conclusion of the inspection.

This also refers to the Enforcement Conference held in the Region IV office on November 27, 1985, between Messrs. McMahon and Pierce and staff members of our office to discuss the findings of the NRC inspection. The enclosed Inspection Report 30-18934/85-02 documents this conference.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations, and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observations by the inspector.

During this inspection certain of your activities were found not to be conducted in full compliance with NRC requirements. Consequently, you are required to respond to this matter in writing in accordance with provisions of Section 2.201 of the NRC "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Your response should be based on the specifics contained in the Notice of Violation enclosed with this letter.

During this inspection it was found that certain of your activities appeared to deviate from commitments made to the NRC. This item and reference to the commitment is identified in the enclosed Notice of Deviation. You are requested to respond to this deviation in writing. Your response should be based on the specifics contained in the Notice of Deviation enclosed with this letter.

RIV:NMBS
LWilborn/vlg
12/10/85

NMSS
RJEverett
12/10/85

RSPB
REHa1
12/10/85

EO xlp
DAPowers
12/11/85

8512240306 851212
REG4 LIC30
35-19593-01 PDR

1E07
1/1

Mr. Wilborn also reviewed the action you had taken with respect to previous violations observed during our previous inspection which was conducted January 4, 1982. He verified that the corrective action with respect to these items was implemented as stated in your replies of March 1 and 22, 1982, to our letters dated February 24 and March 12, 1982.

The response directed by this letter and accompanying Notice is not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

Sincerely,

"Original Signed by:"

R. J. Everett, for

Ramon E. Hall, Chief, Radiological
and Safeguards Programs Branch

Enclosures:

1. Appendix A - Notice of Violation
2. Appendix B - Notice of Deviation
3. Appendix C - NRC Inspection Report 30-18934/85-02

cc:

Oklahoma Radiation Control Program Director

bcc:

DMB - Original (IE-07)
RMartin
RBangart
DPowers
D. Weiss, LFMB (AR-2015)
*Inspector
*MIS System
*RIV Files
*NMSS
*RSTS Operator

*w/766