

| TEXAS UTILITIES GENERATING CO CPSES | PROCEDURE NUMBER | REVISION | ISSUE DATE | PAGE |
|--|---------------------|----------|---------------|--------|
| | CP-QP-11.16 | 1 | AUG 12 1983 | 1 of 2 |

INSPECTION OF
SEISMIC CATEGORY II
SUPPORTS AND STRUCTURAL
STEEL

PREPARED BY: Michael D. Lamer 8-10-83
DATE

APPROVED BY: C. J. [Signature] for [Signature] 8/11/83
DATE

1.0 REFERENCES

- 1-A CP-QP-2.1, "Training and Certification of Inspection Personnel"
- 1-B CP-QP-13.0, "Control of Measuring and Test Equipment"
- 1-C CP-QP-16.0, "Nonconformances and Deficiencies"
- 1-D CP-QP-17.0, "Corrective Action"

2.0 GENERAL

CONTROLLED COPY

2.1 PURPOSE AND SCOPE

CONTROL NO. 11-2

The purpose of this procedure is to describe the inspection program utilized by Quality Control personnel while performing inspections of structural steel members (including pipe supports) designated as Seismic Category II.

2.2 RESPONSIBILITY AND AUTHORITY

The Quality Engineering Supervisor, or his designee, is responsible for the development of specific inspection instructions for inspector use.

The Quality Control Supervisor is responsible for the implementation and administration of inspection activities.

3.0 PROCEDURE

3.1 PERSONNEL TRAINING AND CERTIFICATION

Personnel training shall be provided in accordance with Reference 1-A to assure that structural steel inspection personnel achieve and maintain inspection proficiency.

| TEXAS UTILITIES GENERATING CO. CPSES | PROCEDURE NUMBER | REVISION | ISSUE DATE | PAGE |
|---|---------------------|----------|---------------|--------|
| | CP-QP-11.16 | 1 | AUG 12 1983 | 2 of 2 |

3.2 INSPECTION DETAILS

Quality Instructions supplementing this Procedure identify the structural steel inspection activities and delineate inspection criteria to assure that construction activities comply with design specifications and applicable codes and standards.

3.3 MEASURING AND TEST EQUIPMENT

Measuring and test equipment is calibrated, adjusted and maintained at prescribed intervals to provide confidence in the accuracy of the resulting data. Calibration responsibilities and requirements are defined in Reference 1-B.

3.4 STATUS INDICATORS

The status of inspected items is identified on appropriate documentation as defined by the applicable Quality Instruction.

3.5 NONCONFORMING ITEMS

Nonconformances shall be reported as outlined in each Quality Instruction.

3.6 DOCUMENTATION METHODS

Quality Instructions specify the documentation required to provide objective evidence of compliance with specified Engineering/Construction criteria. Upon completion, these records shall be submitted to the Permanent Plant Records Vault for processing and filing in accordance with CPSES requirements for QA records.

3.7 CORRECTIVE ACTION

The Quality Engineering Supervisor, or his designee, shall review deficiencies and nonconformances and recommend required corrective action in accordance with Reference 1-D.