

5-22-84

NOTE TO: T. Ippolito, NRR (Comanche Peak Task Force) (492-7014)

FROM: Richard L. Bangart, Director, Region IV Task Force

SUBJECT: NRC INSPECTION REPORT _____

(or)
LETTER 2UEC - w/ BNH report

As discussed with you on April 17, 1984, the attached subject correspondence is being sent to you for concurrence. If we do not hear from you within 2 working days (_____) then we will consider that you concur with the correspondence. We will send you a final copy of the attachment after the 10-day proprietary review.

ATTACHMENT:

As stated

(2 pages)

Fax to Phillips Bldg.
Rapid Fax 492-8110
Panafax 492-4994
Verify 492-7371

FOIA-85-59
(A48)



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
811 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76011

Matthews

~ 5/23/84

Dockets: 50-445
50-446

Texas Utilities Electric Company
ATTN: M. D. Spence, President, TUGCO
Skyway Tower
400 North Olive Street
Lock Box 81
Dallas, Texas 75201

Gentlemen:

In January 1984, the NRC Region IV office began a special inspection of the coatings program at the Comanche Peak Steam Electric Station in response to allegations that had been received regarding the adequacy of the coatings. To assist us in this inspection, we have contracted with Brookhaven National Laboratory (BNL) for assistance in the onsite inspection program.

The principal purpose of this special inspection is to examine the adequacy of the applied protective coatings. Our contractors have now completed three trips to the Comanche Peak Steam Electric Station to review your procedures and practices for the application and inspection of protective coatings. In order to complete our review, we require additional information, as identified in Section III of the enclosed "Interim Report on Protective Coatings" prepared by Brookhaven National Laboratory, dated April 25, 1984. We request that you provide this to us, or have it available at the Comanche Peak site for review by our contractor, within 14 days from your receipt of this letter.

As documented in the interim BNL report, our contractor has identified two general areas of concern which are summarized as items 2 and 3 of interim report Section V. Within 30 days from the date of this letter, please respond to this office with your evaluation of the safety significance of these findings. Your response should address the specific concerns identified in the interim report and for each concern provide: (1) information that supports your position as to the safety significance of the concern, (2) a description of corrective actions that will be taken to alleviate safety questions associated with any safety significant concern, and (3) a description of actions that will be taken to prevent any safety significant concerns from recurring in the remaining coatings program work. Your response should also describe the actions that will be taken to modify the backfit program so that its conclusions will address the adequacy of applied coatings as far as the total coating system is concerned.

~~8405300331~~ 3PP'

A copy of this letter has been filed with the ASLB and parties to the hearing.

The responses directed by this letter are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Should you have any questions regarding this matter, please contact Mr. D. M. Hunnicutt at 817/860-8137.

Sincerely,

Richard L. Bangart, Director
Region IV Fask Force

Enclosure:
As stated

cc w/enclosure:
Texas Utilities Electric Company
ATTN: B. R. Clements, Vice
President, Nuclear
Skyway Tower
400 North Olive Street
Lock Box 81
Dallas, Texas 75201

Texas Utilities Electric Company
ATTN: H. C. Schmidt, Manager
Nuclear Services
Skyway Tower
400 North Olive Street
Lock Box 81
Dallas, Texas 75201