

Farley 1

840951

7-71

LICENSEE EVENT REPORT

DCS-

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CONT

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

1 At 1730 on 2/9/83, during the performance of FNP-2-STP-33.0 (Solid State Protection
2 System Train B Operability Test), "B" train Power Range High Setpoint Trip logic
3 was declared inoperable when a failed card indication was received by the automatic
4 tester. Tech. Spec. 3.3.1, in part, requires this trip logic to be operable. Tech.
5 Spec. 3.3.1 action statement requirements were met. Health/safety of the public
6 was not affected.

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

1 This event was caused by the failure of universal card A404. The card was replaced
2 and following the satisfactory performance of FNP-2-STP-33.0, the "B" train Power
3 Range High Setpoint Trip logic was declared operable at 1800 on 2/9/83.

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NAME OF PREPARED: W. G. Hairston, III

PHONE: (205) 899-5156


8511070103 830308
PDR ADOCK 05000364
S PDR

IE22

1/1

Mailing Address
Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Alabama 35291
Telephone 205 783-6081

F. L. Clayton, Jr.
Senior Vice President
Flintridge Building



March 8, 1983

Docket No. 348
Docket No. 364

0000600G02

LER

LER # 364-83008

EVENT DATE 830209

INPO RCVD DATE 830314 SP

NRC RCVD DATE _____

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, N.W.
Suite 3100
Atlanta, Georgia 30303

Dear Sir:

Joseph M. Farley Nuclear Plant, Unit 1, Licensee Event Report No. LER 83-008/03L-0 and Unit 2, Licensee Event Report Nos. 83-006/03L-0, 83-007/03L-0, 83-008/03L-0, and 83-011/03L-0 are forwarded with three (3) copies in accordance with NRC Technical Specification 6.9.1.13 to provide thirty (30) days written notification of the occurrence.

If you have any questions, please advise.

Yours very truly,

F. L. Clayton, Jr.
F. L. Clayton, Jr.

FLCJr/KWM:cd

Enclosures

xc: Director, IE (30 copies)
Director, MIPC (3 copies)

bc: Mr. J. M. Farley
Mr. W. O. Whitt
Mr. S. E. Bradley
Mr. W. H. Bradford
Mr. R. P. McDonald
Mr. H. O. Thrash
Mr. O. D. Kingsley, Jr.
Mr. J. W. McGowan
Mr. D. S. Mask
Mr. W. G. Hairston, III.
Mr. Lee Williams
Mr. W. G. Ware
INPO Records Center
File: 91A3.01

IE22
1/1
83 RETROFIT
1/1