

Mobil Oil Corporation

P.O. BOX 874
JOLIET, ILLINOIS 60434

Certified Mail

August 23, 1985

Amendment of NRC
License No. 12-13914-01

RECEIVED

'85 SEP -3 A9:32

U. S. Nuclear Regulatory Commission
Region III
Radioisotopes Licensing Section
799 Roosevelt Rd.
Glen Ellyn, Illinois 60137

U.S. N.R.C.
LIC. FEE MGMT. BRANCH

Gentlemen:

Mobil Oil Corporation's Joliet Refinery has an NRC materials license which was amended May 3, 1985, to revise our designated Radiation Protection Officer.

Please amend our NRC Radioactive Material License No. 12-13914-01 to show R. W. Bahr as a secondary responsible individual to act as the radiation protection officer in the event that D. E. Sheppard is not available in the refinery. Mr. Bahr attended and completed The OHMART Radiation Safety School that was conducted from July 8 through July 12, 1985. A detailed outline of this program is shown on Attachment 1.

We still plan to have P. D. Hall serve as an additional secondary responsible individual upon his completion of The OHMART Radiation Safety School as stated in our previous NRC License Amendment request letter of April 22, 1985.

All procedures concerning the handling and use of radioactive sources as stated in previous license renewal correspondence will be continued with the new amended license.

Enclosed is a check in the amount of \$60 to cover the amendment fee.

Applicant Sept 2 III
Check No. 0199-101273
Amount/Fee Category \$60. (3P) 15
Type of Fee Amendment
Date Check Rec'd 9/3/85
Received By SK / Cap

Very truly yours,


T. D. Cole

T. D. Cole
Refinery Manager

RECEIVED

AUG 26 1985

REGION III



JLL/jw
Attachments
1665R

AUG 26 1985

8511180018 851001
REG3 LIC30
12-13914-01 PDR

CONTROL NO. 7 9 6 3 1



radiation™

SAFETY SCHOOL

RADIATION SAFETY TRAINING MANUAL TABLE OF CONTENTS

SECTION

TOPIC

PAGE

1

Introduction

1

*Principles and Practices of Radiation Protection

1-1

2

*Radioactivity Measurement Standardization and Monitoring Techniques and Instruments

2-1

3

*Mathematics and Calculations Basic to the Use and Measurement of Radioactivity

3-1

4

*Biological Effect of Radiation

4-1

5

Regulations of the US-NRC and License Interpretation

5-1

6

Waste Disposal and Shipping

6-1

7

Emergency Procedures

7-1

8

US-NRC Rules and Regulations
Title 10, Chapter 1, CFR-Energy

8-1

PART 19 NOTICES, INSTRUCTION, AND REPORTS
TO WORKERS; INSPECTIONS

PART 20 STANDARDS FOR PROTECTION AGAINST
RADIATION

PART 30 RULES OF GENERAL APPLICABILITY TO
DOMESTIC LICENSING OF BY-PRODUCT
MATERIAL

PART 31 GENERAL LICENSES FOR BY-PRODUCT
MATERIAL

9

Laboratory Exercises

9-1

*These items are listed in item 16 of US-NRC form 3131
(Formal Training in Radiation Safety).

10

How To Get A License

10-



DENSITY AND LEVEL
TRAINING MANUAL
TABLE OF CONTENTS

<u>SECTION</u>	<u>TOPIC</u>	<u>PAGE</u>
1	The Basic Principle of Nuclear Gaging. Use of the Ionization Chamber.	
	. General	1 1
	. The Radiation Transmission Equation	1 1
	. The Basic Transmission Curve.	1 2
	. Calibration of Nuclear Gages.	1 2
	. Measurement of Total Mass	1 2
	. The Ionization Chamber.	1 3
	. Delta I	1 3
2C	The Basic Principle of Continuous Level Measurement.	
	. General	2C 1
	. Basic Theory of Operation	2C 1
	. Multiple Point Source - Strip Detector.	2C 1
	. Strip Source - Strip Detector	2C 1
	. Strip Source in a Well-strip Detector	2C 1
2D	The Basic Principle of Density Measurement.	
	. General	2D 1
	. Density Gage Uses	2D 1
	. . Specific gravity measurement	2D 1
	. . Slurry measurement	2D 1
	. . Mass flow measurement.	2D 2
	. . Pipeline interface measurement	2D 2
	. . The "axial" density gage	2D 2
2P	The Basic Principle of Point Level Measurement.	
	. General	2P 1
	. Basic Theory of Operation	2P 1
	. Single Point Source - Multiple Point Detectors.	2P 1
	. Local vs. Remote Point Level Gages.	2P 1

SECTION

TOPIC

PAGE

3

Major gage components, basic description

. Sources used in density and level gages and in belt scales	3	1
. General	3	1
. Point source construction	3	1
. Strip source construction	3	1
. Source material used	3	1
. Source Holders	3	3
. General	3	3
. Sourceholder construction	3	3
. Types of sourceholders	3	3
. Detectors	3	5
. General	3	5
. The Geiger Mueller (GM) tube	3	5
. The Ionization Chamber	3	6
. The cell temperature controller (CTC)	3	6
. Amplifiers	3	11
. Remote vs. local	3	11
. Electronics Enclosures	3	15
. General	3	15
. The Controls	3	15
. Options	3	19
. Linearizer	3	19
. E/I Converters	3	19
. Temperature Compensation	3	20
. Source Decay Compensation	3	21
. The Alarm Circuit Board	3	22

3A

Amplifiers, detailed circuit theory.

. The FA amplifier	3A	1
. General	3A	1
. Theory of operation	3A	1
. Amplifier sensitivity	3A	2
. The VA amplifier	3A	2
. General	3A	2
. Theory of operation	3A	2
. Amplifier sensitivity	3A	3

30

The major options, detailed theory and calibration procedures.

. The model L3 fixed breakpoint linearizer	30	1
. General	30	1
. Theory of operation	30	1
. Linearizer calibration, L3	30	3
. The model L5 linearizer	30	6
. General	30	6
. Circuit operation	30	6
. Operational amplifier	30	6
. Linearizer calibration, L5	30	10

<u>SECTION</u>	<u>TOPIC</u>	<u>PAGE</u>
	. The model L6 linearizer	30 13
	. . General	30 13
	. . Linearizer calibration, L6	30 13
	. The ground referenced E/I converter	30 15
	. . General	30 15
	. . Circuit description	30 15
	. . Calibration procedure	30 15
	. The output isolated E/I converter	30 17
	. . General	30 17
	. . Circuit description	30 17
	. . Calibration procedure	30 17
	. The model TC-3 temperature compensation	30 23
	. . General	30 23
	. . Theory of operation	30 23
	. . Installation	30 27
	. . Calibration procedures, TC-3	30 28
	. Source decay compensation	30 31
	. . General	30 31
	. . Theory of operation	30 31
	. . Procedure for resetting the source decay compensation	30 32
	. The alarm circuit board	30 34
	. . General	30 34
	. . Connecting the alarm circuit board	30 34
	. . Circuit description	30 35
	. . Calibration procedure, the alarm circuit board	30 36

4C

Installation of the LevelART 2000 series

. Caution	4C 1
. Preliminary	4C 1
. Mounting considerations	4C 1
. Mounting the measuring assembly	4C 2
. Mounting the electronics enclosure	4C 3
. Use of an isolation transformer	4C 3

4D

Installation of the DensART 3000 series

. Caution	4D 1
. Preliminary	4D 1
. Mounting the measuring assembly	4D 1
. Mounting the electronics enclosure	4D 2