

DEC 20 1985

Docket No. 50-412

Duquesne Light Company
ATTN: Mr. J. J. Carey
Vice President
Nuclear Group
Robinson Plaza Building No. 2
Suite #210, PA Route 60
Pittsburgh, Pennsylvania 15077

Gentlemen:

Subject: Inspection 50-412/85-25

This refers to the routine inspection conducted by Messrs. G. A. Walton, L. J. Prividy, and G. Meyer of this office on October 23 - December 2, 1985, at the Beaver Valley Power Station, Unit 2, Shippingport, Pennsylvania of activities authorized by NRC License No. CPPR-105 and to the discussions of our findings held by Messrs. Walton and Prividy with Mr. D. Denning and other members of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the NRC Region I Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Based on the results of this inspection, it appears that certain of your activities involving the use of the wrong terminal blocks for the feedwater isolation valve actuators were not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation enclosed herewith as Appendix A and the Notice of Deviation enclosed herewith as Appendix B. The violation has been categorized by severity level in accordance with the revised NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register Notice (49 FR 8583) dated March 8, 1984. You are required to respond to Appendix A and in preparing your response, you should follow the instructions in Appendix A.

We note that the Notice of Deviation identifies a potential problem with one group of non-safety-related equipment (i.e., monorails) and their interaction with safety-related equipment during a seismic event. You are requested to respond to this deviation in the matter outlined below and in Appendix B. In your response to this matter, we request that you describe how the potential interaction of non-safety-related structures, systems, and components with safety-related systems during a seismic event has been properly considered.

The responses directed by this letter and the accompanying Notices are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

8512270112 851220
PDR ADOCK 05000412
G PDR

111
LEO

DEC 20 1985

Your cooperation with us in this matter is appreciated.

Sincerely,

Original Signed By:

Edward C. Wenzinger, Chief
Projects Branch No. 3
Division of Reactor Projects

Enclosures:

1. Appendix A, Notice of Violation
2. Appendix B, Notice of Deviation
3. NRC Region I Inspection Report 50-423/85-25

cc w/encls:

E. J. Woolever, Vice President, Nuclear Construction Division
E. Ewing, Quality Assurance Manager
R. J. Swiderski, Manager, Startup Group
R. E. Martin, Manager, Engineering
E. F. Kurtz, Jr., Manager, Regulatory Affairs
P. RaySircar, Stone and Webster Engineering Corporation
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
Commonwealth of Pennsylvania

bcc w/encl:

Region I Docket Room (with concurrences)
Management Assistant, DRMA (w/o encl)
DRP Section Chief
T. Rebelowski, SRI, Millstone 3
W. Troskoski, SRI, BV-1
B. Singh, LPM, NRR

RI:DRP

Troskoski/meo
12/17/85

RI:DRP

Tripp

12/17/85

RI:DRP

Wenzinger

12/20/85

OFFICIAL RECORD COPY

IEO1