

Northeast  
Nuclear Energy

Rope Ferry Rd. (Route 156), Waterford, CT 06385

Millstone Nuclear Power Station  
Northeast Nuclear Energy Company  
P.O. Box 128  
Waterford, CT 06385-0128  
(860) 447-1791  
Fax (860) 444-4277

The Northeast Utilities System

MAR 3 1997

Docket No. 50-336

B16113

Re: 10 CFR 50.73(A)(2)(iv)

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555


This letter forwards Licensee Event Report (LER) 95-020-01, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 2 on May 16, 1995. This LER is being submitted pursuant to 10 CFR 50.73(A)(2)(iv). This supplement provides clarification of the causal factor and corrective action which resulted from further review and evaluation of the event.

The following are NNECO's commitments made within this letter. All other statements made within this letter are for information only.

B16113-01: A design change to simplify maintenance activities will be implemented during the next refueling outage, RFO13.

Very truly yours,


NORTHEAST NUCLEAR ENERGY COMPANY

  
\_\_\_\_\_  
J. A. Price

Director Millstone Unit No. 2

cc: see page 2

9703070132 970303  
PDR ADOCK 05000336  
S PDR



IE221

Attachment: LER 95-020-01

cc: W. D. Travers, Director of Special Projects  
H. J. Miller, Region I Administrator  
D. P. Beaulieu, Senior Resident Inspector, Millstone Unit No. 2  
D. G. McDonald, Jr., NRC Senior Project Manager, Millstone Unit No. 2