

Harbo



Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. E. MORGAN
STATION MANAGER

RECEIVED
NRC

1985 DEC 16 PM 12:48

REGION V I&E TELEPHONE
(714) 368-6241

December 12, 1985

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject: Docket Nos. 50-361 and 50-362
Follow-up Report, Inoperable Fire Doors - November 1985
San Onofre Nuclear Generating Station, Units 2 and 3

Reference: Letter, H. E. Morgan (SCE) to J. B. Martin (NRC),
dated November 13, 1985

In accordance with our referenced letter, this submittal provides the follow-up report of fire-rated assemblies (specifically fire doors) found inoperable during routine surveillances in November 1985.

Fire doors found inoperable during the November routine surveillances are identified in the Attachment and include 9 latching mechanism failures and 2 closure mechanism failures. No doors were found blocked open in November. As each of these deficiencies was identified, compensatory fire watches, pursuant to Technical Specification 3.7.9, Action Statement 'a', were established. We are continuing previously reported corrective actions to upgrade door latches and closure mechanisms.

This monthly follow-up report and those sent previously provide updated information associated with an ongoing condition initially reported in 1983. The follow-up report covering inoperable fire doors identified in December 1985 will be submitted by January 15, 1986.

8512300152 851212
PDR ADDCK 05000361
S PDR

From RV-


11
IEOI

Mr. J. B. Martin

-2-

If you require any additional information, please so advise.

Sincerely,

A handwritten signature in dark ink, appearing to read "H. E. May", followed by a horizontal line.

Enclosure

cc: F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)

U. S. Nuclear Regulatory Commission
Document Control Desk

Institute of Nuclear Power Operations (INPO)

ATTACHMENT
SOUTHERN CALIFORNIA EDISON COMPANY
INOPERABLE FIRE DOORS FOR THE MONTH OF NOVEMBER 1985
SAN ONOFRE NUCLEAR GENERATING STATION
UNITS 2 AND 3, DOCKET NOS. 50-361 and 50-362

I. Latching Mechanism Failures:

Number of doors inoperable - 9, as follows:

<u>Door Number</u>	<u>Inoperable</u>	<u>Operable</u>
AR-301	10/24/85	-----
AR-401	10/24/85	11/05/85
AC-442	10/28/85	11/09/85
AR-401	11/10/85	11/13/85
AC-442	11/15/85	11/21/85
AR-401	11/15/85	11/17/85
AR-401	11/20/85	-----
FH3-103	11/24/85	-----
AC-416	11/28/85	-----

ATTACHMENT
SOUTHERN CALIFORNIA EDISON COMPANY
INOPERABLE FIRE DOORS FOR THE MONTH OF NOVEMBER 1985
SAN ONOFRE NUCLEAR GENERATING STATION
UNITS 2 AND 3, DOCKET NOS. 50-361 and 50-362
(Continued)

II. Closure Mechanism Failures:

Number of doors inoperable - 2, as follows:

<u>Door Number</u>	<u>Inoperable</u>	<u>Operable</u>
AC-417	11/20/85	11/21/85
AC-455	11/21/85	11/25/85

ATTACHMENT
SOUTHERN CALIFORNIA EDISON COMPANY
INOPERABLE FIRE DOORS FOR THE MONTH OF NOVEMBER 1985
SAN ONOFRE NUCLEAR GENERATING STATION
UNITS 2 AND 3, DOCKET NOS. 50-361 and 50-362
(Continued)

III. Doors Blocked Open:

Number of doors blocked open - None