

Appendix

NOTICE OF VIOLATION

Doctors Diagnostic Center

License No. 21-24482-01

As a result of the inspection conducted on October 28, 1985, and in accordance with the General Policy and Procedures for NRC Enforcement Actions, (10 CFR Part 2, Appendix C), the following violation was identified:

10 CFR 35.14(e)(1)(i) states that any licensee who possesses sealed sources as calibration or reference sources shall cause each sealed source containing byproduct material, other than hydrogen-3, with a half-life greater than thirty days in any form other than gas to be tested for leakage and/or contamination at intervals not to exceed six months. In the absence of a certificate from a transferor indicating that a test has been made within six months prior to the transfer, the sealed source shall not be used until tested.

Contrary to this requirement, the licensee failed to leak test a sealed calibration source which was received from a transferor and put into use, without a valid leak test certificate. Specifically, you failed to leak test, prior to use, a nominal 200 microcurie barium-133 sealed calibration source, received from Plymouth Community Clinic without a valid leak test certificate, in May 1985.


This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance:

(1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

NOV 14 1985

Dated _____


for D. G. Wiedeman, Chief
Nuclear Materials Safety
Section 1

8511190405 851114
REG3 LIC30
21-24482-01 PDR