

URANIUM REDUCTION COMPANY

INTER-OFFICE CORRESPONDENCE

To R. W. Unger

From L. A. Painter

Date August 31, 1957

Subject Radiation monitor (in reactor area)

Please instruct the mill supervisors that the following radiation control measures for the product reactor should be explained to the operators and should be checked frequently for compliance:

- 1) When opening doors on the Shiner Reactor, a pan provided for the purpose should be slid into place beneath the door.
- 2) The dust falling from the door opening onto the pan should be picked up by a vacuum hose.
- 3) Pans not in use should not be left in place but should be stored in some convenient location.
- 4) Operators should wear respirators when opening the reactor doors.

cc: B. E. Wiza
Radiation file

9612230026 590831
PDR ADOCK 04003453
C PDR