

APPENDIX A
NOTICE OF VIOLATION

Thomas J. Lipton, Inc.
Englewood Cliffs, New Jersey

Docket NO. 30-05381
License No. 29-10218-02

As a result of the inspection conducted on September 23, 1985, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

Condition 17.A of License No. 20-10218-02 requires that each chromatograph detector containing nickel-63 be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, as of September 23, 1985, a chromatograph detector containing 200 millicuries of nickel-63 was not tested for contamination or leakage since July, 1982.

This is a Severity Level IV violation. (Supplement VI)

8601230442 860113
REG1 LIC30
29-10218-02 PDR

OFFICIAL RECORD COPY

DL LIPTON 85-01 - 0002.0.0
12/30/85