

UNITED STATES ATOMIC ENERGY COMMISSION

DIVISION OF COMPLIANCE

1. LICENSEE Atlas Minerals Division of Atlas Corporation P. O. Box 488 Moab, Utah 84532	2. REGIONAL OFFICE U. S. ATOMIC ENERGY COMMISSION REGION IV, DIVISION OF COMPLIANCE 10395 W. COLFAX, ROOM 200 DENVER, COLORADO 80215
3. LICENSE NUMBER R-161 (Dycker No. 40-3453)	4. DATE(S) OF INSPECTION November 9 and 10, 1966

5. The following activities under your license (identified in Item No. 3 above) appear to be in noncompliance with AEC regulations or license requirements, as indicated.

During the period June 10, 1964 to November 9, 1966, surveys were inadequate to demonstrate compliance with 10 CFR 20.105(a), "Concentrations in effluents to unrestricted areas", in that no correlation of sample data to existing weather conditions was made, contrary to 10 CFR 20.201(b), "Surveys".

9612230139 661202
 PDR ADOCK 04003453
 C PDR

ORIGINAL SIGNED BY

G. D. BROWN *for*

Supplementary page None attached. George H. Smith

AEC Compliance Inspector

DEC 2 1966

Date

ORIGINAL LICENSEE.

COPIES: ☐ CO REGION ☐ CO HEADQUARTERS ☒ L&R HEADQUARTERS.