



Portland General Electric Company  
Trojan Nuclear Plant  
P.O. Box 439  
Rainier, Oregon 97048  
(503) 556-3713

June 8, 1984  
CPY-561-84

Mr. John B. Martin  
Regional Administrator - V  
U. S. Nuclear Regulatory Commission  
1450 Maria Lane - Suite 210  
Walnut Creek, California 94596-5368

Dear Sir:

Limiting conditions for operation (LCO) 3.7.9 of the Trojan Technical Specifications require that a special report be provided if certain fire barrier penetrations become nonfunctional and cannot be returned to functional status within seven days.

As a result of surveillance during Plant Modifications on May 31, 1984, a three hour rated barrier between the Computer Room and the Cable Spreading Room in the Control Building was identified as being nonfunctional. It had been degraded during scheduled modification activities on May 18, 1984. Compensatory fire protection was provided during the period of degradation as required by the Trojan Technical Specifications. This barrier was restored to a functional status on May 31, 1984.

Sincerely,

C. P. Yundt  
General Manager

CPY/JKA/SPS:pjj

c: LER Distribution

File 93.24a (Q)