



Paul Fessler
Plant Manager

Fermi 2
6400 North Dixie Hwy
Newport, Michigan 48166
(313) 586-5325



10CFR50.73

June 6, 1997
NRC-97-0058

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington D. C. 20555

Reference: Fermi 2
NRC Docket No. 50-341
NRC License No. NPF-43

Subject: Licensee Event Report (LER) No. 97-011

Pursuant to 10CFR50.73, Detroit Edison is submitting the enclosed LER No. 97-011 which documents the late performance of the Turbine Stop Valve (TSV) Closure and Turbine Control Valve (TCV) Fast Closure Channel Functional Tests. This is being reported as a condition prohibited by the Technical Specifications.

The following commitments are being made in this LER:

1. The Channel Functional Test surveillance procedure for the TSV Closure and TCV Fast Closure scram functions (24.110.05) will be modified by June 30, 1997 to reflect the Operational Condition 1 Applicability for these functions.
2. The change in the interpretation of the Applicability for this specification will be included in the Operating Experience segment of Licensed Operator Requalification Training, Cycle 97-04. The training is scheduled to be completed by August 15, 1997.

If you have any questions, please contact Norm Peterson at (313) 586-4258.

9706100425 970606
PDR ADOCK 05000341
S PDR

Sincerely,

P. Fessler *IEDD*

cc: A. B. Beach
G. A. Harris
M. J. Jordan
A. J. Kugler
M. V. Yudas, Jr.
Region III
Wayne County Emergency Management Division

100045

