

June 10, 1997

Mr. John K. Wood
Vice President - Nuclear, Davis-Besse
Centerior Service Company
c/o Toledo Edison Company
Davis-Besse Nuclear Power Station
5501 North State Route 2
Oak Harbor, OH 43449-9760

DISTRIBUTION:

PD3-3 R/F
ACRS
EAdensam (EGA1)
TMarsh, SPLB
TMarsh, SPLB

Docket File
PUBLIC
JRoe
OGC
GGrant, RIII

SUBJECT: DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1 - ULTIMATE HEAT
SINK/SERVICE WATER TEMPERATURE (TAC NO. M94621)

Dear Mr. Wood:

In a letter to you dated October 12, 1995, the NRC staff noted an apparent inconsistency between the water temperature for the ultimate heat sink analysis and the service water system temperature used for containment response analysis following a loss-of-coolant accident (LOCA). In that letter, you were requested to provide information regarding this apparent discrepancy.

By letter dated January 31, 1996, you responded to the request. The staff has reviewed your response, and requires additional information to complete the review. The staff would like to meet with members of your staff to discuss the following items:

- (1) the design basis of the ultimate heat sink, including its principal safety functions, and how these functions are assured during and following the most severe natural phenomena postulated for the site, such as a safe shutdown earthquake;
- (2) the equipment (and its qualification) taken credit for in response to a LOCA; and
- (3) the seismic evaluation of the intake canal and intake conduit described in your January 31, 1996, letter.

Please contact Allen Hansen at (301) 415-1390 to schedule a meeting here at NRC headquarters.

Sincerely,

Original signed by:

Gail H. Marcus, Director
Project Directorate III-3
Division of Reactor Projects III/IV
Office of Nuclear Reactor Regulation

NRC FILE CENTER COPY

Docket No. 50-346

cc: See next page 120075
DOCUMENT NAME: G:\DAVISBES\DB94621.LTR

OFFICE	PD3-3:LA	PD3-3:PM	PD3-3:PD
NAME	CBoyle RB	AHansen AEN	GMarcus GHM
DATE	6/9/97	6/10/97	6/10/97

OFFICIAL RECORD COPY

9706120308 970610
PDR ADOCK 05000346
P PDR

June 10, 1997

Mr. John K. Wood
Vice President - Nuclear, Davis-Besse
Centerior Service Company
c/o Toledo Edison Company
Davis-Besse Nuclear Power Station
5501 North State Route 2
Oak Harbor, OH 43449-9760

DISTRIBUTION:
PD3-3 R/F
ACRS
EAdensam (EGA1)
TMarsh, SPLB
TMarsh, SPLB
Docket File
PUBLIC
JRoe
OGC
GGrant, RIII

SUBJECT: DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1 - ULTIMATE HEAT
SINK/SERVICE WATER TEMPERATURE (TAC NO. M94621)

Dear Mr. Wood:

In a letter to you dated October 12, 1995, the NRC staff noted an apparent inconsistency between the water temperature for the ultimate heat sink analysis and the service water system temperature used for containment response analysis following a loss-of-coolant accident (LOCA). In that letter, you were requested to provide information regarding this apparent discrepancy.

By letter dated January 31, 1996, you responded to the request. The staff has reviewed your response, and requires additional information to complete the review. The staff would like to meet with members of your staff to discuss the following items:

- (1) the design basis of the ultimate heat sink, including its principal safety functions, and how these functions are assured during and following the most severe natural phenomena postulated for the site, such as a safe shutdown earthquake;
- (2) the equipment (and its qualification) taken credit for in response to a LOCA; and
- (3) the seismic evaluation of the intake canal and intake conduit described in your January 31, 1996, letter.

Please contact Allen Hansen at (301) 415-1390 to schedule a meeting here at NRC headquarters.

Sincerely,

Original signed by:
Gail H. Marcus, Director
Project Directorate III-3
Division of Reactor Projects III/IV
Office of Nuclear Reactor Regulation

Docket No. 50-346

cc: See next page
DOCUMENT NAME: G:\DAVISBES\DB94621.LTR

OFFICE	PD3-3:LA	C	PD3-3:PM	E	PD3-3:PD
NAME	CBoyle	AB	lansen	AB	GMarcus
DATE	6/9/97		10/97		6/10/97

OFFICIAL RECORD COPY

John K. Wood
Toledo Edison Company

cc:

Mary E. O'Reilly
Centerior Energy Corporation
300 Madison Avenue
Toledo, Ohio 43652

James L. Freels
Manager - Regulatory Affairs
Toledo Edison Company
Davis-Besse Nuclear Power Station
5501 North State - Route 2
Oak Harbor, Ohio 43449-9760

Gerald Charnoff, Esq.
Shaw, Pittman, Potts
and Trowbridge
2300 N Street, N.W.
Washington, D.C. 20037

Regional Administrator
U.S. NRC, Region III
801 Warrenville Road
Lisle, Illinois 60523-4351

Robert B. Borsum
Babcock & Wilcox
Nuclear Power Generation Division
1700 Rockville Pike, Suite 525
Rockville, Maryland 20852

Resident Inspector
U. S. Nuclear Regulatory Commission
5503 North State Route 2
Oak Harbor, Ohio 43449

James H. Lash, Plant Manager
Toledo Edison Company
Davis-Besse Nuclear Power Station
5501 North State Route 2
Oak Harbor, Ohio 43449-9760

Donna Owens, Director
Ohio Department of Commerce
Division of Industrial Compliance
Bureau of Operations and Maintenance
6606 Tussing Road
P.O. Box 4009
Reynoldsburg, Ohio 43068-9009

Davis-Besse Nuclear Power Station
Unit 1

Robert E. Owen, Chief
Bureau of Radiological Health
Service
Ohio Department of Health
P. O. Box 118
Columbus, Ohio 43266-0118

James R. Williams
Chief of Staff
Ohio Emergency Management Agency
2855 West Dublin Granville Road
Columbus, Ohio 43235-2206

Roy P. Lessy, Jr., Esq.
Andrew G. Berg, Esq.
Akin, Gump, Strauss, Hauer
& Feld, L.L.P.
1333 New Hampshire Ave., NW, Ste. 400
Washington, D.C. 20036

Ohio Environmental Protection Agency
DERR--Compliance Unit
ATTN: Zack A. Clayton
P. O. Box 1049
Columbus, Ohio 43266-0149

State of Ohio
Public Utilities Commission
180 East Broad Street
Columbus, Ohio 43266-0573

Attorney General
Department of Attorney
30 East Broad Street
Columbus, Ohio 43216

President, Board of County
Commissioner of Ottawa County
Port Clinton, Ohio 43252