

DMB COPY

MAR 26 1986

Hannibal Testing Laboratories
ATTN: Ronald Craven
President
4500 Paris Gravel Road
Hannibal, MO 63401

License No. 24-23444-01
03021086

Gentlemen:

This refers to the routine safety inspection conducted by William P. Reichhold of this office on March 3, 1986, of activities authorized by NRC Byproduct Material License No. 24-23444-01 and to the discussion of our findings with you at the conclusion of the inspection.


The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

The responses directed by this letter and the accompanying Notice (Order) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. J. Sreniawski, Chief
Nuclear Materials Safety
Section 2

Enclosure: Notice of Violation

cc w/enclosure:
DCS/RSB (RIDS)

R111 *yes*
PDR 3/25
Reichhold/mj

R111
3/25
Sreniawski

8604010108 860326
REQ3 LIC30
24-23444-01 PDR

IE07
1/1