



Entergy

Entergy Operations, Inc.  
P.O. Box 8  
Kilbuck, LA 70066-0751  
Tel 504 464 3120

T.R. "Ted" Leonard  
General Manager  
Plant Operations  
Waterford 3

W3F1-97-0092  
A4.05  
PR

May 7, 1997

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D.C. 20555

Subject: Waterford 3 SES  
Docket No. 50-382  
License No. NPF-38  
Reporting of Licensee Event Report

Gentlemen:

Attached is Licensee Event Report (LER) Number 97-013-00 for Waterford Steam Electric Station Unit 3. The LER reports the discovery that the refueling machine's overload protection features had not been fully operable. Furthermore, a Surveillance Procedure for testing the lift capacity of the Control Element Assembly (CEA) hoist has been determined to be deficient. These conditions are being reported pursuant to 10 CFR 50.73(a)(2)(i)(B).

Very truly yours,

T.R. Leonard  
General Manager  
Plant Operations

TRL/MKG/tjs  
Attachment

9705120279 970507  
PDR ADOCK 05000382  
S PDR

120072



*Lev*

Reporting of Licensee Event Report

W3F1-97-0071

Page 2

May 7, 1997

cc:

E.W. Merschhoff, NRC Region IV

C.P. Patel, NRC-NRR

A.L. Garibaldi

J.T. Wheelock - INPO Records Center

J. Smith

N.S. Reynolds

NRC Resident inspectors Office

Administrator - LRPD