

Northeast  
Utilities System

Millstone Offices • Rope Ferry Rd., Waterford, CT

P.O. Box 138  
Waterford, CT 06385-0128  
(203) 447-1791

June 12, 1997

Docket No. 50-213  
CY-97-070

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555


Haddam Neck Plant  
Correction to Letter Transmitted to the Nuclear Regulatory Commission

The purpose of this letter is to correct page one of Connecticut Yankee Atomic Power Company's (CYAPCO) letter dated June 10, 1997.<sup>(1)</sup> The subject letter is incorrectly identified on page one as CY-97-056. The enclosed replacement page correctly identifies the letter as CY-97-057. We apologize for any inconvenience that this may have caused you.

Please contact Mr. W. J. Temple at (860) 437-5904 should you have any questions regarding this this matter.

Very truly yours,

CONNECTICUT YANKEE ATOMIC POWER COMPANY

  
\_\_\_\_\_  
J. K. Thayer, Recovery Officer  
Nuclear Engineering and Support

Attachments (1)

1. Corrected Page 1 to Letter Dated June 10, 1997

cc: G. W. Meyer, Chief of Operator Licensing, NRC Region I

9706180092 970612  
PDR ADOCK 05000213  
P PDR

(1) J.K. Thayer letter to the NRC, "Update to Response to Confirmatory Action Letter 1-97-010," dated June 10, 1997.




Docket No. 50-213  
CY-97-070

Haddam Neck Plant  
Correction to Letter Transmitted to the Nuclear Regulatory Commission

Attachment 1  
Corrected Page 1 to Letter Dated June 10, 1997

June 1997



June 10, 1997

Docket No. 50-213

CY-97-057

Re: CAL 1-97-010

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

Haddam Neck Plant  
Update to Response to Confirmatory Action Letter 1-97-010

Reference (a) J. K. Thayer letter to USNRC, "Response to Confirmatory Action Letter," dated March 31, 1997

By a letter dated March 31, 1997 [Reference (a)], Connecticut Yankee Atomic Power Company (CYAPCO) provided the results of reviews concerning the apparent inconsistencies in licensed operator training records in response to the NRC Confirmatory Action Letter 1-97-010.

In accordance with the Nuclear Training LOIT/LOUT Audit Review process instruction, additional information is being provided concerning the status of one of the license candidate's reported in Reference (a).

A licensed operator from the 1993/1994 LOIT class questioned the validity of his credited reactivity manipulations following conversations with other control room operators. This licensed operator informed the Operations Manager of his concern on April 10, 1997. The Operations Manager removed the licensed operator from licensed duties, pending an assessment of the licensed operator's reactivity manipulations. Interviews were conducted with all current licensed operators from the 1993/1994 and 1995/1996 LOIT classes to determine the validity of the candidates' credited reactivity manipulations. The interviews with the operators identified one operator who was credited with fewer than the required five reactivity manipulations specified in 10 CFR 55.31.

Upon notification, CYAPCO management assessed the training and subsequent experience of the licensed operator. We determined that 1.) as a licensed operator, the individual has subsequently performed sufficient creditable reactivity manipulations, by current standards, to exceed the five required by 10 CFR 55.31; and 2.) the licensed operator in question is fully trained and qualified to discharge his duties as a licensed reactor operator on the Haddam Neck Plant.