



MetroHealth Medical Center
2500 MetroHealth Drive, Cleveland, Ohio 44109-1998

216 398-6000

Radiology

June 10, 1997

Kevin Ramsey
USNRC

RE: Response USNRC Bulletin 97-01

This is a follow-up to our E-mail message to Mr. Wiedeman which we posted immediately following our receipt of Bulletin 97-01 in April of 1997 regarding our required responses delineated on Page 3 of the bulletin. All exposure and exposure rate measurements employing the device ceased immediately. A review of the operational history of the instrument indicated that the exposure and exposure rate measurement modes of the device were never employed at MetroHealth. Nevertheless, the device was returned to Victoreen in Solon, Ohio for repair of the resistor network. Repairs were completed and the device returned to service. We continue to employ the device only for charge measurements at MetroHealth Medical Center.

Sincerely,

Douglas M.D. Frye, Ph.D.

cc: Ridge Conant, BA, CNMT
Surendra Rustgi, Ph.D.
Michael Samuels, M.D.

9706180317 970610
PDR ADOCK 03000410
C PDR

16
N0006
per:
Kevin
Ramsey

Post-it® Fax Note 7671		Date	6/10	# of pages	1
To	Kevin Ramsey	From	Dr. Frye		
Co./Dept.	USNRC	Co.			
Phone #		Phone #	216 778 4434		
Fax #	301 515 5369	Fax #	5748		

170019

